

INDEX		
Sr. No.	Particulars	Page No.
1.	Report in matter of OA NO. 607/2018 (VINOD KUMAR JANGRA VERSUS STATE OF HARYANA AND ORS.)	1
2.	Annexure-1	4

11934

BEFORE THE NATIONAL GREEN TRIBUNAL

PRINCIPAL BENCH NEW DELHI

OA NO. 607/2018 (VINOD KUMAR JANGRA VERSUS

STATE OF HARYANA AND ORS.)

AS PER HON'BLE NGT ORDER DATED 20.09.2023

Hon'ble NGT passed the following directions in order dated 20.09.2023 in OA NO. 607/2018 (Vinod Kumar Jangra Versus State of Haryana And Ors.): -

"11. The Learned Counsel appearing for State of Haryana has submitted that he will look into each of the I.As relating to each of the stone crusher units which have been impleaded as respondents in these original applications and tabulate all the relevant information in a chart form including the compliance by each of the units in respect of the pollution norms, obtaining CTE/CTO, inter-se distance between the units and compliance of the environmental guidelines for stone crusher units.

12. Let the same be filed within a period of 08 weeks by e-mail at judicialngt@gov.in preferably in the form of searchable PDF/ OCR Support PDF and not in the form of Image PDF."

Action Taken Report dated 15.11.2023 in compliance with Hon'ble National Green Tribunal, Principal Bench, New Delhi order dated 20.09.2023 in the matter of OA NO. 607/2018 (Vinod Kumar Jangra Versus State of Haryana and Ors).

The stone crushers are located in the district of Charkhi Dadri, Haryana in the various villages of 02 Nos. of Tehsil namely i) Charkhi Dadri ii) Bhadraand mainly in five major cluster in District Charkhi Dadri. There are total 343 Nos. stone crushing units in district Charkhi Dadri as per order of Hon'ble NGT since 2013. The Action Taken Report in compliance with the above directions, passed by Hon'ble National Green Tribunal, New Delhi, is as under:-

1. In compliance of Order dated 20.09.2023, all the stone crushers were inspected by the Officers of the HSPCB between 26th Sep to 5th Nov, 2023. Status of these 343 units are summarized below:

A.	Units found Complying as per provision of notification dated 11.05.2016	222
B.	Units found non-complying as per provision of notification dated 11.05.2016	121

(i). Units under Show Cause Notice issued by HSPCB for closure, withdrawal of CTO	18
(ii). Units closed by Board	24
(iii). Units found dismantled	70
(iv). Plant & Machinery not installed and CTE expired	9

2. The requisite information of 343 stone crushing units in tabular form regarding status of compliance in respect of the pollution norms, CTE/CTO, inter-se distance between the units and the compliance regarding notification dated 11.05.2016 for stone crusher units is attached as **Annexure R-1**.
3. All the stone crushing units of district Charkhi Dadri are presently lying closed in compliance of CAQM order No. 120017/27/GRAP 2021/CAQM dated 02.11.2023.

It is humbly prayed that the above Action Taken Report may be considered please.

Dated:15.11.2023



Regional Officer
HSPCB, Charkhi Dadri

Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
1	8	Shree Balaji Stone Crusher, Village Kaliyana, Charkhi Dadri, Latitude : 28.570603 , Longitude : 76.264	17.02.21-31.03.25	100 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 740 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 325 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 156 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
2	9	Rao Stone Crusher Co., Village Kaliyana Charkhi Dadri, Latitude : 28.55752 , Longitude : 76.201481	30/03/2022 - 31/03/2026	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 220 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 315 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA

Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
3	10	Zamidar Stone Crusher Village Kaliyana, Charkhi Dadri , Latitude : 28.573868 , Longitude : 76.207194	01.04.23-31.03.28	65 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 185 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 270 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 155 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
4	11	New Baba Sita Nath Stone Crusher, Village Kaliyana, Charkhi Dadri , Latitude : 28.57026 , Longitude : 76.20651	02.06.21-31.03.26	100 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 287 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 386 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 156 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA

Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
5	12	Pardhan Stone Crusher Village Kaliyana, Charkhi Dadri , Latitude : 28.5731267 , Longitude : 76.20173	28.10.21-31.03.26	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 205 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 250 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
6	13	New Bharat Stone Crushing Company, VPO PICHOPA KALAN, Charkhi Dadri , Latitude : 28.552265 , Longitude : 76.082644	01.04.23-31.03.28	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 225 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water spriknkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA

Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
7	14	Abhishek Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.56432 , Longitude : 76.18638	01.04.21-31.03.26	35 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 240 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 360 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 130 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
8	15	Bhagwati Stone Crusher, Vill, Kheri Battar, Charkhi Dadri , Latitude : 28.5645 , Longitude : 76.18822	30.01.21-31.03.25	62 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 325 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 370 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
9	16	Pokhar Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.56368 , Longitude : 76.18484	01.04.21-31.03.26	38 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 550 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 315 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
10	17	QEM Processing Pvt Ltd., Pichopa Kalan, Charkhi Dadri , Latitude : 28.551736 , Longitude : 76.085414	20.07.19-31.03.24	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 380 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 337 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 145 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
11	18	Vijay Stone Crusher, Village Pichopa kalan, Charkhi Dadri, , Latitude : 28.54935 , Longitude : 76.09084	01.04.21-31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 290 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 145 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
12	19	Sohna Aggregate Solutions (18C RD63956) Vill Pichopa Kalan Charkhi Dadri , Latitude : 28.551021 , Longitude : 76.079544	23.10.19-31.03.24	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 240 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 261 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
13	20	Soorya Stone Crusher Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.551836 , Longitude : 76.084153	04.07.20-31.03.24	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
14	21	Saraswati Stone Crusher, Vill Kheri Battar, Charkhi Dadri , Latitude : 28.568261 , Longitude : 76.184435	01.04.21-31.03.26	58 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 310 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 280 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 138 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
15	22	Triupati Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.84816 , Longitude : 76.54641	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA
16	23	R.B.S Stone Crusher Village Kaliyana, Charkhi Dadri , Latitude : 28.57092 , Longitude : 76.20239	01.04.22-31.03.27	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 260 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 325 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 90 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
17	24	Royal Stone Crusher Village Kaliyana Distt Charkhi Dadri , Latitude : 28.5522 , Longitude : 76.1972	28.05.22-31.03.27	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 340 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 325 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 107 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
18	25	Shree Luxmi Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.56728 , Longitude : 76.1842	01.10.20-31.03.25	27 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
19	26	Pal stone Crusher Vill. Atela Kalan Charkhi Dadri , Latitude : 28.57497 , Longitude : 76.09651	01.04.21-31.03.26	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 300 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 320 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
20	27	Pardhan Stone Crusher Village Pichopa Kala Charkhi Dadri , Latitude : 28.554161 , Longitude : 76.089974	Not having valid CTO & dismantled	40 feet	Unit was found dismantled at the time of inspection	Unit was found dismantled at the time of inspection	Unit was found dismantled at the time of inspection	Unit was found dismantled at the time of inspection	Unit was found dismantled at the time of inspection	Unit was found dismantled at the time of inspection	Unit was found dismantled at the time of inspection	Unit was found dismantled at the time of inspection	Non-operational	Dismantled	NA
21	28	Maman Stone Crusher, VPO Kheri Battar, Charkhi Dadri , Latitude : 28.56447 , Longitude : 76.18577	01.04.22-31.03.27	38 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 285 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA

Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
22	29	Partap Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.56948 , Longitude : 76.18424	01.04.21-31.03.26	92 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 318 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 310 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 201 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
23	30	Millan Stone Cusher, Village Kaliyana, Charkhi Dadri , Latitude : 28.575207 , Longitude : 76.205681	01.04.22-31.03.27	42 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 250 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
24	31	Mahadev grit Udyog, Pichopa Kalan, Charkhi Dadri , Latitude : 28.553237 , Longitude : 76.086766	01.04.21-31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 290 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 264 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
25	32	J M and Company, Vill- Pichopa Kalan, Charkhi Dadri , Latitude : 28.552187 , Longitude : 76.083212	01.04.23-31.03.28	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 220 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 160 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
26	33	Ajanta Stone Crusher, Vill. Atela Kalan, Charkhi Dadri , Latitude : 28.5771 , Longitude : 76.10196	Not having valid CTO & Closed by Board	40 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	Unit has been closed by the Board	Unit has been closed by the Board

Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
27	34	Shree Nanak Stone Crusher, VPO Kheri Battar, Charkhi Dadri , Latitude : 28.56557 , Longitude : 76.18495	01.04.21-31.03.26	15 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 410 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 365 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 160 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
28	35	Shree Balaji Stone Crusher, Village Bilawal, Charkhi Dadri , Latitude : 28.57579 , Longitude : 76.09317	01.04.21-31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 305 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 380 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 128 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
29	36	Shivji Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.5325832 , Longitude : 76.0756637	04.08.22-31.03.27	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 260 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 160 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
30	37	Shiv Stone Crusher, Vill. Atela Kalan, Charkhi Dadri , Latitude : 28.57457 , Longitude : 76.09589	27.04.20-31.03.25	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 280 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 285 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
31	38	Shiv Stone Crushing Co., Village Pichopa kalan, Charkhi Dadri , Latitude : 28.55091 , Longitude : 76.08968	01.06.20-31.03.25	60 feet	Not provided cover shed with sprinklers	Provided Wind breaking wall of 16 feet height & 230 feet Length and telescopic chute about three feet below the Wind breaking wall	The unit is found under repair & maintence at the time of inspection & shed found removed	The unit is found under repair & maintence at the time of inspection & shed found removed	The unit is found under repair & maintence at the time of inspection & shed found removed	Provided 95 Water sprinklers for dust suppression	Not provided Interlocking system of water sprinkler with stone crusher machine and not maintained logbook for water & energy consumption	The unit is found under repair & maintence at the time of inspection & shed found removed	Non-Operational	Non complying	SCN for closure and revocation of consent to operate issued to unit vide letter no. 1133-34 dt. 07.11.2023
32	39	Satayvir Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.55032 , Longitude : 76.09043	01.04.21-31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 290 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 378 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water spriknkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
33	40	QEM Processing Pvt Ltd. Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.554354 , Longitude : 76.184195	01.04.21-31.03.26	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 480 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 380 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 260 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
34	41	Rakesh Malik Stone Cruhser Vill-Pichopa Kalan, Charkhi Dadri , Latitude : 28.551639 , Longitude : 76.08365	01.04.23-31.03.28	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 350 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 210 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 130 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
35	42	Mahashay Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.554097 , Longitude : 76.082666	04.07.19-31.03.24	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 172 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
36	43	Omkara Mines and Crushers, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.55111 , Longitude : 76.08887	Valid upto 31.03.27 & revocation in process	60 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	Unit has been closed by the Board	Unit has been closed by the Board



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
37	44	Swastik Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.603337 , Longitude : 76.139204	01/04/2022 - 31/03/2027	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 385 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 115 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
38	45	Krishna Stone Crusher, Vill. Pichopa Kalan, Charkhi Dadri , Latitude : 28.54935 , Longitude : 76.08884	29.06.21- 31.06.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 295 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 191 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
39	46	Jai Ambey stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.56807 , Longitude : 76.183519	23.01.23-31.03.27	26 feet	Unit has not provided Covered sheds over machinery	Unit has not provided proper & adequate size wind breaking wall & telescopic chute as per norms	Unit has provided roads for vehicular movement within the premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 320 Plants and plantation plan obtained from DFO vide letter dated 14.01.2021 & same is also verified by DFO	Not provided sufficient number of water sprinklers	Not provided Interlocking system of water sprinkler with stone crusher machine and not maintained logbook for water & energy consumption	No vehicle reported during inspection	Non-Operational	Non complying	SCN for closure and revocation of consent to operate issued to unit vide letter No. 1034-35 dt. 31.10.23
40	47	Shiv Stone Crusher, Village Asawari, Charkhi Dadri , Latitude : 28.55377 , Longitude : 76.14362	01.04.23-31.03.28	500 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 500 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 280 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 250 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA




Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
41	48	Neelam Stone Crusher Vill Pichopa Kalan, Charkhi Dadri , Latitude : 28.551722 , Longitude : 76.084058	01.04.23-31.03.28	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 400 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 175 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
42	49	Mahaluxmi Mines and Stone Crusher VPO Pichopa Kalan, Charkhi Dadri , Latitude : 28.539506 , Longitude : 76.08865	01.04.23-31.03.28	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 450 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 193 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA




Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
43	50	Maha Luxmi Stone Cruhser, Village Bilawal, Charkhi Dadri , Latitude : 28.57592 , Longitude : 76.09377	01.04.21-31.03.26	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 440 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
44	51	Krishna Stone Crusher-1, Vill. Kheri Battar Charkhi Dadri , Latitude : 28.5654866 , Longitude : 76.184395	01.04.21-31.03.26	32 feet	Unit has provided two shed with water sprinkler for dust suppression	Provided Wind breaking wall of about 16 feet height & 408 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 357 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 157 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
45	52	Jai Balaji Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.551772 , Longitude : 76.0873	01/04/2022 - 31/03/2027	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 350 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 203 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
46	53	Dharampal Stone Crusher, pichopa Kalan, Charkhi Dadri , Latitude : 28.54263 , Longitude : 76.09261	01.04.21- 31.03.26	170 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 265 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 333 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
47	54	Dada shakti Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.551809 , Longitude : 76.081648	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA
48	55	Chetna Stone Crusher, Village Atela Kalan, Charkhi Dadri , Latitude : 28.57575 , Longitude : 76.0959	01.04.21-31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 290 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 421 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
49	56	Balaji Stone Crusher, Village Birhi Kalan, Charkhi Dadri , Latitude : 28.614862 , Longitude : 76.141384	01.04.21-31.03.26	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 260 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 660 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
50	57	Shree Ganesh Crusher Udyog, Village Kheri Battar, Charkhi Dadri , Latitude : 28.543 , Longitude : 76.1428	Latest CTO granted vide No. 9283110 revoked vide order No. HSPCB-050004/737/2021 dated 04.04.2022	27 feet	Not provided proper covered sheds on all machinery	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 315 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 42 Water sprinklers for dust suppression & same are not sufficient as per norms	Interlocking system of water sprinkler system with stone crusher machine provided and not maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-Operational	Non complying	SCN for closure and revocation of consent to operate issued to unit vide letter No. 1032-33 dt. 31.10.23



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
51	58	Shiv Bhole Stone Crushing Co., Kaliyana, Charkhi Dadri , Latitude : 28.533825 , Longitude : 76.18432	10.09.20-31.03.25	300 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 360 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 325 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 160 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
52	59	Shree Ganesh Stone Crusher Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.5703 , Longitude : 76.1867	Not having valid CTO & dismantled	-	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
53	60	Shree Laxmi Stone Crusher, Pichopa Kalan, Charkhi Dadri , Latitude : 28.547055 , Longitude : 76.089785	Valid upto 31.03.24 & revocation in process	90 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	Unit has been closed by the Board	Unit has been closed by the Board
54	61	Sangwan Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.5697 , Longitude : 76.18614	01.04.21-31.03.26	56 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 340 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 130 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
55	62	Om Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.570125 , Longitude : 76.183246	01.04.23-31.03.28	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 225 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
56	63	Khatu Shyam Stone Crusher, Village Pichopa Kala Charkhi Dadri , Latitude : 28.553472 , Longitude : 76.083056	01.07.19-31.03.24	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 310 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 170 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water spriknkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA

Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
57	64	Jai Durga Stone Crusher, Vill. Kheri Battar, Ch.Dadri , Latitude : 28.56876 , Longitude : 76.18543	01.04.21-31.03.26	48 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 260 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 340 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 188 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
58	65	Bed Stone Crusher Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.551698 , Longitude : 76.087951	Valid upto 31.03.27 & revocation in process	80 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	Unit has been closed by the Board	Unit has been closed by the Board



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
59	66	Balaji Stone Crusher, VPO Kaliyana, Charkhi Dadri , Latitude : 28.57309 , Longitude : 76.20328	02/04/2022 - 31/03/2027	36 feet	Unit has provided shed with water sprinkler for dust suppression	Provided Wind breaking wall of about 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 450 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 80 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
60	67	Asawari Stone Crushing Co., Vill-Asawari Tehsil & Charkhi Dadri , Latitude : 28.553868 , Longitude : 76.142276	05.02.20-31.03.24	100 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 500 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 535 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
61	68	Jai Shree Ram Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.554398 , Longitude : 76.187539	12.05.20-31.03.25	102 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 205 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
62	69	Jai Shree Ganesh Stone Crusher Vill-Kheri Battar, Charkhi Dadri , Latitude : 28.57034 , Longitude : 76.18692	01.10.20-31.03.25	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 348 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 360 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 72 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
63	70	Jai Baba Sita Nath Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.57041 , Longitude : 76.18556	16.03.21-31.03.25	56 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 380 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 370 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 138 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
64	71	Jagdish Pahal Stone Crusher Village Birhi Kalan Charkhi Dadri , Latitude : 28.607937 , Longitude : 76.138801	13.01.21-31.03.26	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 330 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 138 Water sprinklers for dust suppression	Interlocking system of water spriknkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
65	72	Jai Bajrangbali Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.56708 , Longitude : 76.1849	01.04.21-31.03.26	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 350 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 408 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
66	73	Vishal Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.55785 , Longitude : 76.18547	01.10.19-31.03.24	42 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 305 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 305 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
67	74	Gohana Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.5593 , Longitude : 76.18896	01.04.23-31.03.28	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 185 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
68	75	Suryawanshi Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.55385 , Longitude : 76.18701	01.04.22-31.03.27	105 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 250 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 360 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
69	76	Silver Stone Crusher Village Kheri Battar Charkhi Dadri, Latitude : 28.557664 , Longitude : 76.189411	14.07.20-31.03.25	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 280 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 90 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
70	77	Shri Shyam Stone Crusher Village Kaliyana Charkhi Dadri , Latitude : 28.533912 , Longitude : 76.179481	01/04/2023 - 31/03/2028	35 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 225 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 325 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 128 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
71	78	Shree Maha Luxmi Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.568555 , Longitude : 76.184065	01.04.21-31.03.26	84 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 410 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 385 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
72	79	Durga Stone Crusher Mills, Village Kaliyana, Charkhi Dadri , Latitude : 28.57244 , Longitude : 76.20219	25.10.21-31.03.26	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 278 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 296 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 196 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA




Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
73	80	Diamond Stone Crusher Village Kheri Battar, Charkhi Dadri , Latitude : 28.55559 , Longitude : 76.18394	28.10.21-31.03.26	54 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 245 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
74	81	Bijender Singh Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.56848 , Longitude : 76.18196	15/03/2022 - 31/03/2026	95 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 270 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 340 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
75	82	Anand Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.568192 , Longitude : 76.18293	01.04.22-31.03.27	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 255 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
76	83	Dada Syonand Maharaj Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.551608 , Longitude : 76.085955	01.04.22-31.03.27	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 300 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 180 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 99 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
77	84	Hari Om Stone Crusher Pichopa Kalan , Charkhi Dadri , Latitude : 28.542551 , Longitude : 76.088542	06.05.21- 31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 180 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
78	85	Sheoran Stone Crusher, Village Atela Kalan, Charkhi Dadri , Latitude : 28.57571 , Longitude : 76.09494	01.04.21- 31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 185 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
79	86	MDN Stone Crusher Vill-Pichopa Kalan, Charkhi Dadri , Latitude : 28.553348 , Longitude : 76.082677	01.04.22-31.03.27	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Not provided Wind breaking wall of adequate height & length	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 190 Plants and plantation plan obtained from DFO & same is also verified by DFO	Not provided sufficient number of water sprinklers	Not provided Interlocking system of water sprinkler with stone crusher machine and not maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-operational	Non complying	SCN for closure and revocation of consent to operate issued to unit vide letter no. 1131-32 dt. 07.11.2023
80	87	Shyam Stones Vill-Pichopa Kalan, Charkhi Dadri , Latitude : 28.539039 , Longitude : 76.08998	06.05.21-31.03.26	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 245 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 151 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 140 Water sprinklers for dust suppression	Interlocking system of water spriknkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA




Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
81	88	Caps Tradelink Pvt. Ltd., Kheri Battar, Charkhi Dadri , Latitude : 28.556542 , Longitude : 76.184849	11.07.19-31.03.24	18 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 235 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
82	89	Maha Singh Stone Crusher Village Kheri Battar Charkhi Dadri , Latitude : 28.56967 , Longitude : 76.18204	31.10.21-31.03.26	120 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 90 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
83	90	Baniwal Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.565271 , Longitude : 76.184592	Valid upto 31.03.26 & revocation in process	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	The unit was closed by board & found dismantled	The unit was closed by board & found dismantled
84	-	Alpha Stone Crusher Vill-Kaliyana, Charkhi Dadri , Latitude : 28.57206 , Longitude : 76.210626	31.10.21-31.03.24	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 320 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA




Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
85	-	Amarnath Stone Crusher Vill-Kheri Battar,Distt Charkhi Dadri , Latitude : 28.553422 , Longitude : 76.184178	01.04.21-31.03.26	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 205 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
86	-	Anup Stone Crusher-I, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.56838 , Longitude : 76.17488	01.04.20-31.03.25	100 feet	Unit has not provided proper coverd shed over machinery	Provided Wind breaking wall of about 16 feet height & Length not as per norms and not provided telescopic chute	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 500 Plants and plantation plan obtained from DFO & same is also verified by DFO	Unit has not provided sufficient number of water sprinklers.	Not provided Interlocking system of water sprinkler with stone crusher machine and not maintained logbook for water & energy consumption	No vehicle reported during inspection	Non-Operational	Non complying	SCN for closure and revocation of consent to operate issued to unit vide letter No. 1030-31 dt. 31.10.23



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
87	-	Baba Ramdass Stone Crusher Village Kaliyana, Charkhi Dadri , Latitude : 28.573058 , Longitude : 76.20666	18.01.22-31.03.26	102 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 225 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 250 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
88	-	Bhavishay Stone Crusher Village Kaliyana, Charkhi Dadri , Latitude : 28.57524 , Longitude : 76.196693	01.04.23-31.03.28	110 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 480 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 180 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
89	-	Choudhary Construction Company, Village Kalayana, Charkhi Dadri , Latitude : 28.57103 , Longitude : 76.20591	27.09.20-31.03.24	105 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 215 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 87 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
90	-	Choudhary Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.55989 , Longitude : 76.18926	22.03.21-31.03.25	110 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 310 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 98 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
91	-	Classic Mobile Stone Crusher Village Kheri Battar Charkhi Dadri , Latitude : 28.56034 , Longitude : 76.18539	09.02.21-31.03.25	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 280 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 306 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 140 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
92	-	Dada Dhola Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.55251 , Longitude : 76.18755	01.04.21-31.03.26	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 205 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 150 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
93	-	Dada Ram Prasad Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.58227 , Longitude : 76.182708	10.09.20-31.03.25	110 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 390 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 285 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
94	-	Dada Stone Crusher, Village Kheri Battar, Tehsil Charkhi Dadri , Latitude : 28.552229 , Longitude : 76.183488	01.04.21-31.03.26	120 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 245 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 380 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
95	-	Dev Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.558261 , Longitude : 76.18614	27.12.19-31.03.24	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 230 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
96	-	Dhanpat Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.56904 , Longitude : 76.18968	01.04.22-31.03.27	73 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 310 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 160 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
97	-	EDDY Builders Private Limited, VPO Kheri Battar, Charkhi Dadri (Old Name Ompati , Latitude : 28.3411 , Longitude : 76.105176	03.08.22-31.03.27	120 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 240 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 250 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
98	-	Ekta Stone Crusher Village kheri Battar, Charkhi Dadri , Latitude : 28.56886 , Longitude : 76.17724	01.04.21-31.03.26	90 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 90 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA

Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
99	-	Jai Baba Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.56934 , Longitude : 76.18834	01.04.21-31.03.26	42 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 330 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 420 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 180 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
100	-	Jai Mahadev Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.567074 , Longitude : 76.189924	25.10.19-31.03.24	130 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 298 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 128 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
101	-	Jai Shiv Shankar Stone Crusher, VPO Kheri Battar, Charkhi Dadri , Latitude : 28.557391 , Longitude : 76.189126	11/06/2023 - 31/03/2028	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 357 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
102	-	Jai Shree Shyam Stone Crusher. Village Kheri Battar, Charkhi Dadri , Latitude : 28.561845 , Longitude : 76.185164	01.04.19- 31.03.24	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 220 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 430 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
103	-	Jai Siya Ram Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.57047 , Longitude : 76.18317	01.04.21-31.03.24	85 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 285 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 260 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 156 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
104	-	Jhandewala Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.568486 , Longitude : 76.17585	21.03.21-31.03.25	51 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
105	-	Krishana Stone Crusher and Supplier Village Kheri Battar Charkhi Dadri , Latitude : 28.565286 , Longitude : 76.184301	01/04/2023 - 31/03/2028	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 220 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
106	-	Krishna Stone Crusher-II, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.564879 , Longitude : 76.186896	01.04.21- 31.03.26	26 feet	Unit has provided shed with water sprinkler for dust suppression	Provided Wind breaking wall of about 16 feet height & 350 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 360 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 167 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
107	-	Luxmi Stone Crusher, Vill. Kaliyana, Charkhi Dadri , Latitude : 28.57339 , Longitude : 76.1976	13.12.21-31.03.26	250 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 205 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 325 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
108	-	Maa Stone Crusher, Kaliyana, Charkhi Dadri , Latitude : 28.57372 , Longitude : 76.20456	31.03.2023-31.03.25	110 feet	Unit has provided shed with water sprinkler for dust suppression	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 88 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
109	-	Mahadev stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.56667 , Longitude : 76.18853	01.04.21-31.03.26	120 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 485 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 380 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
110	-	Nandu Stone Crusher, VPO Kheri Battar, Charkhi Dadri , Latitude : 28.550901 , Longitude : 76.187666	01.04.22-31.03.27	55 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 80 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
111	-	Neelkanth Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.56432 , Longitude : 76.18774	05.04.21-31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 315 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 75 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
112	-	New Jai Shree Bala ji Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.564214 , Longitude : 76.186811	01.04.23-31.03.28	55 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 230 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 337 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 180 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
113	-	Om Shivam Stone Crusher, Kaliyana, Charkhi Dadri , Latitude : 28.573475 , Longitude : 76.200381	23.06.21-31.03.25	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 308 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 295 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
114	-	Parvat Stone Crusher, Village Kheri Battar,Charkhi Dadri , Latitude : 28.558892 , Longitude : 76.185958	04.01.20-31.03.24	62 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 240 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 220 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
115	-	Pooja Stone Crusher, Village Kaliyana, Charkhi Dadri , Latitude : 28.57135 , Longitude : 76.20255	06.10.21-31.03.26	22 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 850 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 325 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
116	-	Prithvi Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.583434 , Longitude : 76.22989	30.08.20-31.03.25	100 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 325 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
117	-	Raj Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.56249 , Longitude : 76.18851	01.04.21-31.03.26	120 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 205 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 365 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
118	-	Rajbir Stone Crusher VPO Kheri Battar, Charkhi Dadri , Latitude : 28.557 , Longitude : 76.185	25.10.21-31.03.26	58 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 348 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 490 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 260 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
119	-	S K Stone Crusher, Vill-Kheri Battar,Tehsil & Distt-Charkhi Dadri , Latitude : 28.335257 , Longitude : 76.11502	18.08.22-31.03.27	38 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 550 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 248 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
120	-	Salasar Stone Crusher Vill-Kheri Battar, Charkhi Dadri , Latitude : 28.551 , Longitude : 76.186	01.03.21-31.03.25	32 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 80 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
121	-	Sanjay Stone Crusher, Village- Kheri Battar, Charkhi Dadri , Latitude : 28.56652 , Longitude : 76.188029	10.02.21-31.03.25	76 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 650 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
122	-	Sanskar Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.550327 , Longitude : 76.186378	01.04.19-31.03.24	78 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
123	-	Sarvotam Group, Village Kheri Battar, Charkhi Dadri , Latitude : 28.18989 , Longitude : 76.22184	12.05.20-31.03.24	220 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 560 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 180 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
124	-	Shakti Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.568 , Longitude : 76.188	01/04/2022 - 31/03/2027	72 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 230 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 250 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 78 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
125	-	Shanti Mobile Stone Crusher, VPO Kheri Battar, Charkhi Dadri , Latitude : 28.56072 , Longitude : 76.18582	01.04.22-31.03.27	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 220 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
126	-	Sheranwali Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.56122 , Longitude : 76.18755	01/04/2022 - 31/03/2027	110 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 250 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 390 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
127	-	Shiv Bhole Shankar Stone Crusher Village Kheri Battar, Charkhi Dadri , Latitude : 28.57345 , Longitude : 76.19479	01.04.19-31.03.24	102 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 387 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 330 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 157 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
128	-	Shiv Ganga Stone Crusher, Kaliyana, Charkhi dadri , Latitude : 28.573312 , Longitude : 76.201866	01.04.22-31.03.27	102 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 195 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 335 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 63 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
129	-	Shiv Gorakh Stone Crusher, Vill Kheri Battar, Charkhi Dadri , Latitude : 28.56218 , Longitude : 76.18848	01.04.21-31.03.26	55 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 260 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 87 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
130	-	Shiv Shakti Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.832583 , Longitude : 76.0757637	01/04/2023 - 31/03/2028	102 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 195 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 465 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
131	-	Shiv Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.56976 , Longitude : 76.18414	01.04.23-31.03.28	66 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 290 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 250 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 250 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
132	-	Shree Dada Dhola Stone Crusher Vill Kheri Battar, Charkhi Dadri , Latitude : 28.55251 , Longitude : 76.18755	01.04.23-31.03.28	78 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 215 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 185 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA




Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
133	-	Shree Partap Stone Crusher, Kaliyana, Charkhi Dadri , Latitude : 28.573518 , Longitude : 76.199868	12.11.20 to 31.03.25	115 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 820 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
134	-	Shree Ram Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.33'6.61968 , Longitude : 76.11'18.7533 6	01.04.21- 31.03.26	44 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 230 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 260 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
135	-	Shree Satyam Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.552194 , Longitude : 76.18184	01.04.23-31.03.28	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 280 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 470 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 260 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
136	-	Shree Shyam Grit Udyog Village Kheri Battar Charkhi Dadri , Latitude : 28.5011 , Longitude : 76.1465	31.03.21-31.03.25	62 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 230 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 82 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
137	-	Shree Shyam Stone Crusher Village Kheri Battar Charkhi Dadri , Latitude : 28.552194 , Longitude : 76.18184	27.04.22-31.03.25	362 feet	Unit has provided covered sheds over machinery but without water sprinklers	Provided Wind breaking wall less than 16 feet height & 164 feet Length and not provided telescopic chute.Wind breaking wall is not adequate as per norms.	Metalled road provided for Vehicular movement within premises	Unit has provided cleaning but not proper Wetting of the ground within the premises during inspection	Provided Green belt of 260 Plants and plantation plan obtained from DFO vide ltter dated 24.03.2023 & same is also verified by DFO	Provided 40 Water sprinklers for most of them not operational due to broken pipe and water sprinklers are not sufficient as per norms	Not provided Interlocking system of water sprinkler with stone crusher machine and not maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Non complying	SCN for closure and revocation of consent to operate issued to unit vide letter No. 1016-17 dt. 27.10.23
138	-	Shri Giriraj Stone Crusher, Vill. Kheri Battar, Charkhi dadri , Latitude : 28.57041 , Longitude : 76.18381	01.04.2021-31.03.26	95 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 240 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 150 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 75 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
139	-	Shri Hari Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.552126 , Longitude : 76.187598	01.04.21-31.03.26	85 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 380 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
140	-	Shri Sai Baba Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.55196 , Longitude : 76.18688	28.02.21-31.03.26	38 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 235 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
141	-	Shri Shivam Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.55282 , Longitude : 76.18681	01.04.21-31.03.26	38 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
142	-	Sita Nath Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.57041 , Longitude : 76.18556	01.04.21-31.03.25	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 310 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 315 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 180 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
143	-	Siwach Stone Cruhser, Vill. Kheri battar, Charkhi Dadri , Latitude : 28.56859 , Longitude : 76.18981	01/04/2022 - 31/03/2027	82 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 170 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 320 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 210 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
144	-	Subham Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.554403 , Longitude : 76.189477	01.04.21- 31.03.26	77 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 240 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 250 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 98 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
145	-	Taj Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.56178 , Longitude : 76.18863	01.04.21-31.03.26	38 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 220 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 368 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
146	-	United Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.552834 , Longitude : 76.183333	01.04.21-31.03.26	28 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 255 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 380 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
147	-	Venus Stone Crusher Village Kheri Battar Charkhi Dadri , Latitude : 28.55959 , Longitude : 76.18474	01.04.22-31.03.27	28 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 358 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
148	-	Yash Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.575427 , Longitude : 76.194513	Valid upto 31.03.25 & revocation under process	25 feet	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	Non-Operational	Unit has been closed by the Board	Unit has been closed by the Board




Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
149	-	Jai Shri Shivam Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.564874 , Longitude : 76.186535	Valid upto 31.03.25 & revocation under process	26 feet	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	Non-Operational	Unit has been closed by the Board	Unit has been closed by the Board
150	-	New Baba Pir Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.55394 , Longitude : 76.18944	Valid upto 31.03.27 & revocation under process	22 feet	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	Non-Operational	Unit has been closed by the Board	Unit has been closed by the Board



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
151	-	OmPati Stone Crusher Co., VPO Kheri Battar Charkhi Dadri , Latitude : 28.55846 , Longitude : 76.18061	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	Dismantled	NA
152	-	Shanker Stone Crusher, Village Kheri Battar, Tehsil Charkhi Dadri , Latitude : 28.571 , Longitude : 76.182	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
153	-	Hari Dass Grit udyog , Village Kheri Battar, Charkhi Dadri , Latitude : 28.57034 , Longitude : 76.18493	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	Dismantled	NA
154	-	Hanuman Stone Crusher, Vill Kheri Battar, Charkhi Dadri , Latitude : 28.56941 , Longitude : 76.18501	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	Dismantled	NA




Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
155	-	Lucky Minerals Unit III 28/13 14 Vill: Kalyana, Charkhi Dadri , Latitude : 28.572698 , Longitude : 76.205117	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	Dismantled	NA
156	-	Lucky Minerals, U-II, VILL - KALIYANA, Charkhi Dadri , Latitude : 28.572698 , Longitude : 76.205117	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
157	-	Lucky Minerals Unit-I Khasra No. 28/3/2,4/2/2,7,8 Village : Kalyana Charkhi Dadri , Latitude : 28.572665 , Longitude : 76.203147	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	Dismantled	NA
158	-	Darshana Stone Crusher, Vill. Kaliyana, Charkhi Dadri , Latitude : 28.34015 , Longitude : 76.115308	Not having valid CTO & dismantled	-	The unit was closed by board & found dismantled at the time of inspection	The unit was closed by board & found dismantled at the time of inspection	The unit was closed by board & found dismantled at the time of inspection	The unit was closed by board & found dismantled at the time of inspection	The unit was closed by board & found dismantled at the time of inspection	The unit was closed by board & found dismantled at the time of inspection	The unit was closed by board & found dismantled at the time of inspection	The unit was closed by board & found dismantled at the time of inspection	Non-Operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
159	-	Baba Stone Crusher-1, Village Kaliyana,Charkhi Dadri , Latitude : 28.56681 , Longitude : 76.19818	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	Dismantled	NA
160	-	Shiv Durga Stone Crusher, Village Kheri Battar Charkhi Dadri , Latitude : 28.565898 , Longitude : 76.188518	Valid upto 31.03.24 & revocation in process	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
161	-	KSC Buildcon Pvt Ltd., Village Kheri Battar, Charkhi Dadri , Latitude : 28.552847 , Longitude : 76.178643	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	Dismantled	NA
162	-	Anjani Stone Crusher, VPO Kheri Battar, Charkhi Dadri , Latitude : 28.56958 , Longitude : 76.17738	Valid upto 31.03.27 & revocation in process	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	Unit has been closed by the Board and at present theDismantled	Unit has been closed by the Board and at present theDismantled



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
163	-	New Era Solutions Pvt. Ltd. Village Kheri Battar, Charkhi Dadri New Name Metro Stone Crusher , Latitude : 28.914884 , Longitude : 75.85163	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	Dismantled	NA
164	-	Shree Luxmi Stone Crushing Co., -II, Village Kheri Battar, Charkhi Dadri , Latitude : 28.629802 , Longitude : 76.165625	Not having valid CTO & Closed by Board	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	The unit was closed by board & found dismantled	The unit was closed by board & found dismantled



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
165	-	New Sunrise Stone Crusher, Village Kheri Battar, Tehsil Charkhi Dadri , Latitude : 28.55846 , Longitude : 76.18475	Not having valid CTE & Plant & Machinery not installed	-	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Non-Operational and not installed plant & machinery	Non-Operational and not installed plant & machinery	NA
166	-	Shivalaya Construction Pvt Ltd Co., Village Kheri Battar, Charkhi Dadri , Latitude : 28.566251 , Longitude : 76.188204	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
167	-	Aravali Hills Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.56893 , Longitude : 76.18216	Not having valid CTE & Plant & Machinery not installed	-	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Non-Operational and not installed plant & machinery	Non-Operational and not installed plant & machinery	NA
168	-	DCC Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.56619 , Longitude : 76.18533	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	Dismantled	NA




Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
169	-	Himalya Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.577332 , Longitude : 76.149779	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	Dismantled	NA
170	-	Maha Dev Stone Crusher Village Kaliyana , Charkhi Dadri , Latitude : 28.572605 , Longitude : 76.206037	Not having valid CTO	28 feet	Not provided Covered shed over machinery	Unit has not provided proper & adequate wind breaking wall as per norms.	Unit has provided roads for vehicular movement within the premises	Unit has provided Wetting & Cleaning of the ground provided during inspection	Unit has not provided proper green belt as per norms.	Not provided sufficient number of water sprinklers	Not provided Interlocking system of water sprinkler with stone crusher machine and not maintained logbook for water & energy consumption	No vehicle found at the time of inspection	Non-Operational	Non complying	SCN for closure and revocation of consent to operate issued to unit vide letter No. 1024-25 dt. 31.10.23



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
171	-	Maruti Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.56995 , Longitude : 76.18523	Not having valid CTO	29 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 76 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-Operational	Unit is complying, Closed its own	NA
172	-	Vishnu Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.55275 , Longitude : 76.178529	Valid upto 31.03.27 & revocation in process	39 feet	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	Non-Operational	Unit has been closed by the Board	Unit has been closed by the Board



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
173	-	Anup Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.56838 , Longitude : 76.17488	10.02.21-31.03.25	52 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
174	-	Bhartho Devi Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.55106 , Longitude : 76.1856	01.04.23-31.03.28	37 feet	Unit has not provided proper coverd shed over machinery	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 290 Plants and plantation plan obtained from DFO vide letter dated 03.04.2023 & same is also verified by DFO	Provided 70 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and not maintained logbook for water & energy consumption	No vehicle reported during inspection	Non-Operational	Non complying	SCN for closure and revocation of consent to operate issued to unit vide letter No. 1018-19 dt. 27.10.23

Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
175	-	Dhankaur Stone Crusher,Village Kheri Battar, Charkhi Dadri , Latitude : 28.56966 , Longitude : 76.17709	01.04.21-31.03.26	32 feet	Unit has not provided proper covered shed over machinery	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO vide letter dated 04.01.2021 & same is also verified by DFO	Unit has not provided sufficient number of water sprinklers.	Not provided Interlocking system of water sprinkler with stone crusher machine and not maintained logbook for water & energy consumption	No vehicle reported during inspection	Non-Operational	Non complying	SCN for closure and revocation of consent to operate issued to unit vide letter No. 1036-37 dt. 31.10.23
176	-	Shiv Bhole Stone Crusher Village Kalali, Charkhi Dadri , Latitude : 28.5333 , Longitude : 76.18471	Valid upto 31.03.26	1154 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 200 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 168 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
177	-	Jai Shree Shyam Stone Crusher, Village Kalai, Charkhi Dadri , Latitude : 28.53405 , Longitude : 76.1797	01.04.21-31.03.26	141 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 165 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
178	-	Sadbhawna Stone Crusher, Village Kalali, Charkhi Dadri , Latitude : 28.53286 , Longitude : 76.179	19.08.21-31.03.26	144 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 270 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 340 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
179	-	Jai Mata Di Stone Crusher, Village Kalali, Charkhi Dadri , Latitude : 28.533516 , Longitude : 76.179246	23.03.21-31.03.25	120 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 310 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 380 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
180	-	Baljit Stone Crusher Vill- Kalali,Distt Charkhi Dadri , Latitude : 28.530254 , Longitude : 76.17961	01.04.23-31.03.28	742 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 328 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 128 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
181	-	Subh Ram Stone Crusher Village Kheri Battar, Charkhi Dadri , Latitude : 28.55793 , Longitude : 76.189	01.04.20-31.03.25	28 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 195 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 60 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
182	-	Baba Shyam Stone Crusher, Village Kaliyana, Charkhi Dadri Lat: 28.572609 Long: 76.25050	Not having valid CTO & dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Non-Operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
183	-	Bijender Singh Quarry Contractor Stone Crusher Village Kheri Battar Charkhi Dadri Lat: 28.5688 Long: 76.1817	Not having valid CTO & dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Non-Operational	Dismantled	NA
184	-	Dalawas Stone Crusher, Vill Tiwala, Charkhi Dadri , Lat: 28.57375 Long: 76.113843	Not having valid CTO & Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Non-Operational	closed by Board	closed by Board




Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
185	-	Dhanluxmi Stone Crusher, Kalali, Charkhi Dadri Lat: 28.3218244 Long: 76.41986	Valid upto 31.03.25 & revocation in process	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Non-Operational	closed by Board	closed by Board
186	-	Ganga construction company, Village Kheri Battar, Charkhi Dadri, (Unit not found during inspection)	Not having valid CTE & Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Non-Operational and not installed plant & machinery	Non-Operational and not installed plant & machinery	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
187	-	Haryana Stone Crusher, Village Tiwala, Charkhi Dadri, , Latitude : 28.334992 , Longitude : 76.71338	Valid upto 31.03.26	910 feet	Obtained vide No. 9625377 valid upto 31.3.2026	Provided Wind breaking wall of about 16 feet height & 220 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Unit has provided Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 310 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 157 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
188	-	Jai Hanuman Stone Crusher, Village Kheri Battar, Charkhi Dadri (Unit not found during inspection.	Not having valid CTO & dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Non-Operational	Dismantled	NA

Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
189	-	K V R Minerals Pvt Ltd Unit 2 Vill Kaliyana Charkhi Dadri , Latitude : 28.343629 , Longitude : 76.12177	Valid upto 31.03.2028	21 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 175 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Unit has provided Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 200 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 80 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
190	-	K V R Minerals Pvt. Ltd., Village Kaliyana, Charkhi Dadri , Latitude : 28.343629 , Longitude : 76.12177	Valid upto 31.03.2027	23 feet	Unit has not provided proper Covered sheds for dust suppression.	Provided Wind breaking wall of about 16 feet height & 178 feet Length and not provided telescopic chute as per norms .	Metalled road provided for Vehicular movement within premises	Unit has not provided wetting & cleaning of the ground within the premises.	Provided Green belt of 145 Plants and same is not as per plantation plan approved from DFO vide letter dated 13.01.2021	Unit has provided 24 water sprinkler and not provided sufficient number of water sprinklers for dust suppression	Not provided Interlocking system of water sprinkler with stone crusher machine and not maintained logbook for water & energy consumption	No Vehicle reported during inspection as unit lying closed.	Non-Operational	Non Complying	SCN for closure and revocation of consent to operate issued to unit vide letter No. 1026-27 dt. 31.10.23

Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
191	-	Laxmi Mining Company, Village Tiwala, Charkhi Dadri Lat: 28.5672 Long: 77.119906	Valid upto 31.03.26 & revocation in process	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Non-Operational	closed by Board	closed by Board
192	-	Kundu Construction CO., Village Tiwala, Charkhi Dadri Lat: 28.572 Long: 76.117	Not having valid CTO & dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Non-Operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
193	-	Larsen and Toubro Limited, Vill Kheri Battar Charkhi Dadri , Latitude : 28.333099 , Longitude : 76.111652	Valid upto 31.03.2024	29 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 260 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Unit has provided Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
194	-	Laxmi Stone Crusher, Village Kheri Battar, Charkhi Dadri Lat: 28.33586638 Long: 77.11385656	Not having valid CTO & Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Non-Operational	Closed by Board	Closed by Board



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
195	-	Nihal Stone Crusher, Village Khei Battar, Charkhi Dadri Lat: 28.565 Long: 76.185	Not having valid CTO & dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Non-Operational	Dismantled	NA
196	-	Shivam Stone Crusher, Village Kheri Battar, Charkhi Dadri	Not having valid CTE & Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Non-Operational and not installed plant & machinery	Non-Operational and not installed plant & machinery	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
197	-	Shree Laxmi Stone Crusher, Kheri Battar, Charkhi Dadri Lat: 28.568228 Long: 76.184475	Not having valid CTO & dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Non-Operational	Dismantled	NA
198	-	Sunrise stone Crusher, Village Kheri Battar, Charkhi Dadri Lat: 28.558610 Long: 184577	Not having valid CTO & dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Non-Operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
199	-	Super White Stone Crusher, Village Tiwala, Charkhi Dadri , Latitude : 28.334991 , Longitude : 76.71337	Valid upto 31.03.27	300 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 310 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Unit has provided Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
200	-	Arya Stone Crusher , Jhojhu Kalan, Charkhi Dadri , Latitude : 28.519273 , Longitude : 75.998983	25.10.19-31.03.24	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 250 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 360 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 130 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-Operational	Unit is complying, Closed its own	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
201	-	Avtar & Company Stone Crusher, Village jhojhu Kalan, Charkhi Dadri , Latitude : 28.49764 , Longitude : 76.15373	01.04.21-31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 255 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 245 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 160 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
202	-	Baba Hari Dass Stone Crushing Co Vill-Birhi Kalan, Charkhi Dadri , Latitude : 28.615755 , Longitude : 76.140889	01.04.21-31.03.26	35 feet	Unit has not provided proper Covered sheds for dust suppression.	Provided Wind breaking wall of about 16 feet height & 340 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 190 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 115 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Non complying	SCN for closure and revocation of consent to operate issued to unit vide letter no. 913-14 dt. 20.10.2023



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
203	-	Baba Raghu Nath Stone Crusher Vill- Birhi Kalan, Charkhi Dadri , Latitude : 28.609568 , Longitude : 76.139991	01.04.22-31.03.27	40 feet	Unit has not provided proper Covered sheds for dust suppression.	Provided Wind breaking wall of about 16 feet height & 370 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 250 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-operational	Non complying	SCN for closure and revocation of consent to operate issued to unit vide letter no. 972-73 dt. 23.10.2023
204	-	Baba Shyam Crushing Co Vill Jhojhu Kalan, Charkhi Dadri , Latitude : 28.497149 , Longitude : 76.157605	03.08.21-31.03.26	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 230 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 285 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 140 Water sprinklers for dust suppression	Interlocking system of water spriknkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
205	-	Bhai Ji Stone Crusher Village Ramalwas, Charkhi Dadri , Latitude : 28.499361 , Longitude : 76.149556	19.12.19-31.03.24	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 200 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 325 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
206	-	Chander Mukhi Stone Crusher, Kila/Khasra No. 102//23 & 104//3/1, Asawari, Patwari Halka 83, Charkhi Dadri , Latitude : 28.5355 , Longitude : 76.17822	01.04.21-31.03.26	500 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 245 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 428 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA




Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
207	-	Dada Shakti Stone Crusher Vill-Birhi Kalan, Charkhi Dadri , Latitude : 28.607624 , Longitude : 76.1401165	01.04.21-31.03.24	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 340 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 240 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
208	-	Gitesh Stone Crusher Vill-Birhi Kalan,Distt Charkhi Dadri , Latitude : 28.603857 , Longitude : 76.138952	01/04/2022 - 31/03/2027	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 350 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 210 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 90 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
209	-	Indian Stone Crusher, Jhojhu Kalan, Charkhi Dadri , Latitude : 28.495667 , Longitude : 76.155408	Not having valid CTO & dismantled	50 feet	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	Dismantled	NA
210	-	Jai Baba Jamna Giri Stone Crusher, Vill. Birhi Kalan, Charkhi Dadri , Latitude : 28.607536 , Longitude : 76.139411	Not having valid CTO & dismantled	-	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Non-Operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
211	-	Jai Baba Jamna Giri Stone Crusher, Vill. Birhi Kalan, Charkhi Dadri , Latitude : 28.607636 , Longitude : 76.139411	01.04.22-31.03.27	30 feet	Unit has not provided proper Covered sheds for dust suppression.	Provided Wind breaking wall of 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 250 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-operational	Non complying	SCN for closure and revocation of consent to operate issued to unit vide letter no. 970-71 dt. 23.10.2023
212	-	Jai Dada Budha Stone Crusher, Village Birhi Kalan, Charkhi Dadri , Latitude : 28.599282 , Longitude : 76.153726	01.04.21-31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 350 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 330 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
213	-	Jai Hind Stone Crushing Co., Village Birhi Kalan, Charkhi Dadri , Latitude : 28.605863 , Longitude : 76.139633	01.04.21-31.03.26	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 240 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 170 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
214	-	Jai Mata Di Stone Crusher, Village Birhi Kala, Charkhi Dadri , Latitude : 28.533466 , Longitude : 76.179315	01.04.21-31.03.26	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 360 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 470 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
215	-	Jai Shivam Stone Crusher Village Pandwan, Charkhi Dadri , Latitude : 28.616439 , Longitude : 76.162705	01.04.23-31.03.28	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 260 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 290 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
216	-	Jai Shree Ram Stone Crusher Village Manakawas Charkhi Dadri , Latitude : 28.630911 , Longitude : 76.168219	01.04.23-31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 315 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 180 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
217	-	Jai Shree Shyam Stone Crusher Vill- Jhojhu Kalan, Charkhi Dadri , Latitude : 28.49693 , Longitude : 76.15373	01.04.21-31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 350 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 270 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
218	-	Jai Shree Shyam Stone Crusher, Vill- Pichopa Kalan, Charkhi Dadri , Latitude : 28.503195 , Longitude : 76.152287	22.08.21-31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 335 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 200 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
219	-	Jhojhu Stone Crusher, Village Jhojhu Kalan, Charkhi Dadri , Latitude : 28.49786 , Longitude : 76.15549	14.12.19-31.03.24	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 300 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 195 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
220	-	Kanhaiya Stone Crusher Vill-Birhi Kalan, Charkhi Dadri , Latitude : 28.60889 , Longitude : 76.14006	01..04.21-31.03.24	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 370 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 285 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA




Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
221	-	Karan Stone Crusher, Village Asawari, Charkhi Dadri , Latitude : 28.55442 , Longitude : 76.14017	18.11.21-31.03.24	200 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 270 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 420 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
222	-	Maa Pitambara Mines And Cruhsers LLP, Vill Mankawas, Charkhi Dadri , Latitude : 28.633537 , Longitude : 76.169682	01.06.19-31.03.24	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 380 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 182 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
223	-	Maha Laxmi Stone Mills, Vill Mankawas, Charkhi Dadri , Latitude : 28.633178 , Longitude : 76.168507	25/02/2022 - 31/03/2026	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 230 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 180 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 80 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
224	-	Mahadev Stone Crusher, Birhi Kalan, Chakrhi Dadri , Latitude : 28.609674 , Longitude : 76.138763	01.04.23- 31.03.28	90 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 290 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 380 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 115 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
225	-	Mahaluxmi Stone Crusher Village Birhi Kalam, Charkhi Dadri , Latitude : 28.610786 , Longitude : 76.139212	01.04.19-31.03.24	90 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 245 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 290 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
226	-	Mayur Stone Crusher, Village Birhi Kala, Charkhi Dadri , Latitude : 28.608907 , Longitude : 76.140478	01.04.21-31.03.26	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 280 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 258 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 160 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
227	-	Murliwala Stone Crushing Mills, Vill. Jhojhu Kalna, Charkhi Dadri , Latitude : 28.485661 , Longitude : 76.143406	01.04.21-31.03.24	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 310 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 240 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
228	-	NECC Mines & Mineral, Village Manakawas, Charkhi Dadri , Latitude : 28.632135 , Longitude : 76.167686	01.04.21-31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 200 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 229 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
229	-	NECC Mining Corporation Unit 2, Village Pandwan Charkhi Dadri , Latitude : 28.614952 , Longitude : 76.161624	01.04.22-31.03.24	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 290 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 272 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
230	-	NECC Mining Corporation, Village Pandwan, Charkhi Dadri , Latitude : 28.61474 , Longitude : 76.160548	01.04.22-31.03.24	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 335 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 290 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
231	-	NECC Roadways, Village Pandwan, Charkhi Dadri , Latitude : 28.615901 , Longitude : 76.160498	01.04.22-31.03.24	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 300 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 130 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 145 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
232	-	Neel Kanth Stone Crusher Mill, Village Jhojhu Kalan, Charkhi Dadri , Latitude : 28.486557 , Longitude : 76.142372	Not having valid CTO & dismantled	30 feet	Unit was found dismantled at the time of inspection.	Unit was found dismantled at the time of inspection.	Unit was found dismantled at the time of inspection.	Unit was found dismantled at the time of inspection.	Unit was found dismantled at the time of inspection.	Unit was found dismantled at the time of inspection.	Unit was found dismantled at the time of inspection.	Unit was found dismantled at the time of inspection.	Non-Operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
233	-	Neelkanth Mahadev Grit Udyog Vill- Birhi Kalan, Charkhi Dadri , Latitude : 28.604664 , Longitude : 76.139804	01/04/2022 - 31/03/2027	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 360 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 180 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
234	-	New Avtar Stone Crusher, Vill-Pichopa Kalan, Charkhi Dadri , Latitude : 28.538899 , Longitude : 76.089353	30.04.19- 31.03.24	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 370 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 188 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 115 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA

Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
235	-	New Rapid Stone Crusher old Name Jai baba Shyam Stone Crusher, Birhi kalan, Charkhi Dadri , Latitude : 28.609588 , Longitude : 76.139908	01/04/2022 - 31/03/2027	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 340 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 280 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
236	-	Om Shiv Stone Crusher, Village Jhojhu Kalan, Charkhi Dadri , Latitude : 28.4953 , Longitude : 76.15334	14.12.19- 31.03.24	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 330 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 310 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
237	-	Pritam Stone Crusher, Asawari, Charkhi Dadri , Latitude : 28.799522 , Longitude : 76.124419	26.08.22- 31.03.27	500 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 225 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 385 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
238	-	Purpal Stone Crusher, Village Birhi Kala, Charkhi Dadri , Latitude : 28.608239 , Longitude : 76.141785	01.04.21- 31.03.26	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 315 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 410 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA




Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
239	-	Rajesh Stone Crusher, Pichopa Kalan, CharkhiDadri , Latitude : 28.5325 , Longitude : 76.0891	01.04.23-31.03.28	470 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 395 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 265 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
240	-	Rudhra Stone Crusher, Village Jhojhu Kalan, Charkhi Dadri , Latitude : 28.53762 , Longitude : 76.201883	01/04/2022 - 31/03/2027	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 380 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA




Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
241	-	Sangwan Stone Crusher, Vilalge Birhi Kalan, Charkhi Dadri , Latitude : 28.84815 , Longitude : 76.5464	19.12-19-31.03.24	90 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 285 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 297 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
242	-	Shiv Bhole Stone Crusher Vill-Asawari, Charkhi Dadri , Latitude : 28.533582 , Longitude : 76.184439	25.08.21-31.03.26	500 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 300 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
243	-	Shiv Shakti Grit Udyog, Village Birhi Kala, Charkhi Dadri , Latitude : 28.610259 , Longitude : 76.139208	01.04.21-31.03.26	90 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 300 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 595 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
244	-	Shiv Shakti Stone Crusher Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.832583 , Longitude : 76.0757637	28.05.20-31.03.24	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 253 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 90 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
245	-	Shiv Shankar Stone Crusher Vill-Birhi Kalan, Charkhi Dadri , Latitude : 28.604583 , Longitude : 76.139016	01.04.23-31.03.26	80 feet	Unit has not provided proper Covered sheds for dust suppression.	Unit has not provided proper & adequate wind breaking wall as per norms.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 280 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 140 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-operational	Non complying	SCN for closure and revocation of consent to operate issued to unit vide letter no. 974-75 dt. 23.10.2023
246	-	Shiv Stone Crusher, Village Jhojhu Kalan, Charkhi Dadri , Latitude : 28.4982 , Longitude : 76.1592	01.04.22-31.03.27	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 284 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 310 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 160 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
247	-	Shiva Stone Crusher, Village Birhi Kalan, Charkhi Dadri , Latitude : 28.607476 , Longitude : 76.139843	06/05/2023 - 31/03/2028	100 feet	Unit has not provided proper Covered sheds for dust suppression.	Provided Wind breaking wall of 16 feet height & 350 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 285 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-operational	Non complying	SCN for closure and revocation of consent to operate issued to unit vide letter no. 976-77 dt. 23.10.2023
248	-	Shree Radhe Stone Crusher, Birhi Kalan, Charkhi Dadri , Latitude : 28.84816 , Longitude : 76.59641	25.07.19-31.03.24	100 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 250 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 560 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 180 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
249	-	Shree Ram Stone Crusher, Vill. Mankawas, Charkhi Dadri , Latitude : 28.62986 , Longitude : 76.16616	09.02.23-31.03.27	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 280 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 138 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
250	-	Shree Shyam Stone Crusher Village Jhojhu Kalan, Charkhi Dadri , Latitude : 28.534031 , Longitude : 76.17939	17.10.22-31.03.27	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 295 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 200 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 115 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
251	-	Shri Ram Stone Crusher, Village Jhoju Kalan, Chakrhi Dadri , Latitude : 28.5525 , Longitude : 76.1886	25/02/2022 - 31/03/2026	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 370 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 209 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
252	-	Shri Rattan Grit Udyog Village Birhi Kala Charkhi dadri , Latitude : 28.592062 , Longitude : 76.265289	15.05.21- 31.03.26	90 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 380 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 325 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 160 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA





Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
253	-	Shyam King Stone Crusher Village Jhoju Kalan Charkhi Dadri , Latitude : 28.502497 , Longitude : 76.109166	01.10.21-31.03.26	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 340 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 245 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
254	-	Sohna Stone Crusher, Village Ramalwas, Charkhi Dadri , Latitude : 28.488275 , Longitude : 76.142962	01.04.21-31.03.26	60 feet	Unit has not provided proper Covered sheds for dust suppression.	Provided Wind breaking wall of 16 feet height & 230 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 290 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-operational	Non complying	SCN for closure and revocation of consent to operate issued to unit vide letter no. 844-45 dt. 19.10.2023



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
255	-	Suraj Stone Crushing CO., Village Mankawas, Charkhi Dadri , Latitude : 28.63098 , Longitude : 76.16718	27.09.22-31.03.27	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 185 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 170 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
256	-	Swastik Stone Crusher, Village Birhi Kalan, Charkhi Dadri , Latitude : 28.607697 , Longitude : 76.137811	01/04/2022 - 31/03/2027	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 420 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 385 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
257	-	Trishul Stone Crushing Mills Vill-Jhojhu Kalan, Charkhi Dadri , Latitude : 28.48553 , Longitude : 76.14218	01.04.21-31.03.26	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 300 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 340 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 80 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
258	-	Uma Stone Crusher, Village Asawari, Charkhi Dadri , Latitude : 28.535168 , Longitude : 76.178107	13/08/2023 - 31/03/2028	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 230 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 370 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 117 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA




Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
259	-	Chaubisi Stone Crusher, Village Mankawas, Tehsil Chakrhi Dadri , Latitude : 28.61957 , Longitude : 76.16245	01.04.21-31.03.26	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 125 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
260	-	Kumar Infra & Mining Projects, Village Jhoju Kalan, Charkhi Dadri , Latitude : 28.517939 , Longitude : 76.146773	04.03.21-31.03.25	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 240 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 210 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA

Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
261	-	Durga Stone Crusher, Vill- Pichopa Kalan, Charkhi Dadri , Latitude : 28.537535 , Longitude : 76.089479	01.04.23-31.03.28	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 230 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 249 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
262	-	Shiv Shakti Stone Crusher II Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.5537 , Longitude : 76.0825	30.06.20-31.03.25	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 350 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 178 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
263	-	Shri Laxmi Ji Stone Crusher, Pichopa Kalan, Charkhi Dadri , Latitude : 28.629802 , Longitude : 76.165625	06.11.19-31.03-24	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 240 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 163 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 90 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
264	-	Ashoka Stone Crusher, Vill. Mankawas, Charkhi Dadri , Latitude : 28.63114 , Longitude : 76.16528	01..04.21-31.03.24	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 166 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
265	-	Bala Ji Stone Crusher, Vill. Pandwan, Charkhi Dadri , Latitude : 28.61692 , Longitude : 76.1634	01.10.18-31.03.25	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 187 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
266	-	Chander Stone Crusher, Village Pandwan, Charkhi Dadri , Latitude : 28.618889 , Longitude : 76.164671	01.04.21-31.03.26	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 200 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 193 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 100 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
267	-	Dadri Stone Crusher Village Manakawas Tehsil Charkhi Dadri , Latitude : 28.63064 , Longitude : 76.16746	01.04.21-31.03.25	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 185 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
268	-	Hanuman Infrastructure Pvt. Ltd., Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.551639 , Longitude : 76.083365	01.04.22-31.03.25	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 310 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 315 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
269	-	Haryana Stone Crusher, Village Asawari, Charkhi Dadri, , Latitude : 28.54821 , Longitude : 76.17971	01.04.21-31.03.26	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 142 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 80 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
270	-	Jai Baba Mungipa Stone Crusher, Pandwan, Charkhi Dadri, Latitude : 28.619224 , Longitude : 76.162767	10.05.19-31.03.24	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 180 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
271	-	Jai Bajrang Bali Stone Crusher, Village Ramlawas, Charkhi Dadri , Latitude : 28.489756 , Longitude : 76.144567	05.02.20-31.03.24	50 feet	Unit has not provided proper Covered sheds for dust suppression.	Unit has not provided proper & adequate wind breaking wall as per norms.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 410 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-operational	Non complying	SCN for closure and revocation of consent to operate issued to unit vide letter no. 842-43 dt. 19.10.2023
272	-	Jai Balaji Stone Crusher, Vill. Mankawas Charkhi Dadri , Latitude : 28.63052 , Longitude : 76.16672	01.04.21-31.03.24	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 211 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 108 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
273	-	Jai Hanuman Store Crusher, Village Pandwan, Charkhi Dadri , Latitude : 28.61809 , Longitude : 76.16354	01/04/2022 - 31/03/2027	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 200 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 156 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
274	-	Laxmi Stone Crusher, Vill. Mankawas, Charkhi Dadri , Latitude : 28.63002 , Longitude : 76.16563	01.04.21- 31.03.26	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 200 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 200 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
275	-	Om Shivam Stone Crusher, Village Asawari, Charkhi Dadri , Latitude : 28.55562 , Longitude : 76.14452	18.11.21-31.03.24	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 230 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 415 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-operational	Unit is complying, Closed its own	NA
276	-	Om Stone Crusher, Mankawas, Charkhi Dadri	01.04.21-31.03.26	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 120 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 80 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
277	-	Panchmukhi Stone Crusher, Village Mankawas, Charkhi Dadri , Latitude : 28.63248 , Longitude : 76.16487	01.10.20-31.03.25	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 150 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 80 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
278	-	Pritam Sangwan Stone Crusher, Village Asawari, Charkhi Dadri , Latitude : 28.535081 , Longitude : 76.176195	09.05.22-31.03.27	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 150 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 75 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
279	-	Shiv Shanti Stone Cruhser, Village Mankawas, Charkhi Dadri , Latitude : 28.63062 , Longitude : 76.16586	01.04.21-31.03.24	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 200 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 200 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
280	-	Shivalik Stone Crusher, Village Mankawas, Charkhi Dadri , Latitude : 28.63141 , Longitude : 76.16787	01.04.22-31.03.27	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 110 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 90 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
281	-	Shivalya Grit Udyog, Village Mankawas, Charkhi Dadri , Latitude : 28.628753 , Longitude : 76.166135	01.04.19-31.03.24	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 191 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
282	-	Shree Balaji Stone Crusher, Village Mankawas, Charkhi Dadri , Latitude : 28.63268 , Longitude : 76.16544	01/04/2022 - 31/03/2027	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 190 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
283	-	Surya Stone Crusher Vill- Pichopa Kalan, Charkhi Dadri , Latitude : 28.551699 , Longitude : 76.08242	24.11.21-31.03.26	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 310 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 280 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
284	-	Thadeshri Stone Crusher Vill- Mankawas, Charkhi dadri , Latitude : 28.63167 , Longitude : 76.16521	01.04.21-31.03.25	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 200 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 142 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 90 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
285	-	kanshi Ram Stone Crusher, Village Mankawas, Charkhi Dadri , Latitude : 28.63169 , Longitude : 76.16838	01.04.23-31.03.28	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 180 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA
286	-	Gawar Construction Ltd., Village Mankawas, Charkhi Dadri , Latitude : 28.63162 , Longitude : 76.16637	01.04.23-31.03.28	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 170 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 230 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 250 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Unit is complying	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metallad roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
287	-	Anjani Mata Stone crusher Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.55136 , Longitude : 76.09074	Valid upto 31.03.24 & revocation in process	30 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	Unit has been closed by the Board	Unit has been closed by the Board
288	-	Ashu Stone Crusher Vill. Manakawas, Charkhi Dadri , Latitude : 28.62931 , Longitude : 76.16593	Valid upto 31.03.24 & revocation in process	100 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	Unit has been closed by the Board	Unit has been closed by the Board



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
289	-	Baba Hanuman Minerals Vill-Jhojhu Kalan, Charkhi Dadri , Latitude : 28.496749 , Longitude : 76.155916	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA
290	-	Baba Hanuman Stone Crusher, Village Mankawas, Charkhi Dadri , Latitude : 28.62832 , Longitude : 76.16411	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metallled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
291	-	Bhawani Stone Crusher, Village Jhojhu Kalan, Charkhi Dadri , Latitude : 28.497356 , Longitude : 76.150203	Not having valid CTO & Closed by Board	70 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	Unit has been closed by the Board	Unit has been closed by the Board
292	-	Chander Bhan Stone Crusher, Village Asawari, Charkhi Dadri , Latitude : 28.55116 , Longitude : 76.14046	Not having valid CTO & Closed by Board	70 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	Dismantled	NA




Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
293	-	Chaudhary Stone Crusher Vill-Birhi Kalan, Distt Charkhi Dadri , Latitude :28.6036 , Longitude : 76.136005	Not having valid CTO & dismantled	--	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA
294	-	Chirag Stone Crusher, Village Birhi Kalan, Charkhi Dadri , Latitude : 28.607425, Longitude : 76.141398	01/04/2022 - 31/03/2027	80 feet	Unit has not provided proper Covered sheds for dust suppression.	Provided Wind breaking wall of 16 feet height & 300 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 325 Plants and plantation plan obtained from DFO & same is also verified by DFO	Not provided sufficient number of water sprinklers	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	Non complying	SCN for closure and revocation of consent to operate issued to unit vide letter no. 978-79 dt. 23.10.2023



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
295	-	Dada Gosai Stone Crushing Mills, Mankawas, Charkhi Dadri , Latitude : 28.62828 , Longitude : 76.16504	Valid upto 31.03.24 & revocation in process	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA
296	-	Delhi Stone Crusher, Village Mankawas, Charkhi Dadri , Latitude : 28.63039 , Longitude : 76.16512	Valid upto 31.03.24 & revocation in process	-	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
297	-	Dev Dahiya Stone Crusher, Village Jhoju Kala Charkhi Dadri , Latitude :28.5732 , Longitude : 76.208	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA
298	-	Dev Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.558261 , Longitude : 76.18614	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
299	-	Dosti Stone Crusher, Village Asawari, Charkhi Dadri , Latitude : 28.54845 , Longitude : 76.17875	Not having valid CTO & Closed by Board	70 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	Unit has been closed by the Board	Unit has been closed by the Board
300	-	Gau Mata Stone Crusher, Pichopa Kalan, Charkhi Dadri , Latitude : 28.551561 , Longitude : 76.081835	Valid upto 31.03.27 & revocation in process	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metallad roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
301	-	Goyat Stone Crusher, Village Pandwan Chakrhi Dadri , Latitude : 28.622506 , Longitude : 76.163098	Not having valid CTO & dismantled	-	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	Dismantled	NA
302	-	Hari Dass Stone Crusher Vill. Asawari Charkhi Dadri , Latitude : 28.570385 , Longitude : 76.185179	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
303	-	Himalya Stone Crusher Village Jhojhu Kalan, Charkhi Dadri , Latitude : 28.5216309 , Longitude : 76.150838	Not having valid CTE & Plant & Machinery not installed	-	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Non-operational and not installed plant & machinery	Non-Operational and not installed plant & machinery	NA
304	-	Jai Baba Thakur Dass Stone Crusher Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.53175 , Longitude : 76.09069	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containme nt cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
305	-	Jai Bajrang Bali Stone Crusher, Village Mankawas, Charkhi Dadri , Latitude : 28.627984, Longitude : 76.164989	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA
306	-	Jai Bhawani Stone Crusher, Ramalwas, Charkhi Dadri , Latitude : 28.497083 , Longitude : 76.150397	Not having valid CTO & Closed by Board	50 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	Unit has been closed by the Board	Unit has been closed by the Board



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
307	-	Jai Parkash Associates Ltd., Village Mehra, Charkhi Dadri , Latitude : 28.558235 , Longitude : 76.1674	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA
308	-	Jai Parkash Associates Ltd., Village Mehra, Khasra No. 78//3 (8K-0M),Charkhi Dadri , Latitude : 28.558235 , Longitude : 76.1674	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
309	-	Jai Parkash Associates Ltd., Village Mehra, Khasra No. 89//0, Charkhi Dadri , Latitude : 28.558241 , Longitude : 76.167	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA
310	-	Jai Parkash Associates Ltd., Village Mehra, Khasra No. 89//1,Charkhi Dadri , Latitude : 28.558241 , Longitude : 76.167	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
311	-	Jyoti Stone Crushers Village Pandwan Charkhi Dadri , Latitude : 28.614222 , Longitude : 76.162595	Not having valid CTO & dismantled	-	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	Dismantled	NA
312	-	K.M.P Stone Crusher, Vill Pichopa Kalan, Charkhi Dadri , Latitude : 28.539506 , Longitude : 76.08865	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metallad roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
313	-	Luxmi Stone Crusher, Asawari, Charkhi Dadri , Latitude : 28.53612 , Longitude : 76.1769	Not having valid CTO & Closed by Board	50 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	Unit has been closed by the Board	Unit has been closed by the Board
314	-	Mahadev Stone Crusher, Village Mankawas, Charkhi Dadri , Latitude : 28.567585 , Longitude : 76.18856	Not having valid CTE & Plant & Machinery not installed	-	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Non-operational and not installed plant & machinery	Non-Operational and not installed plant & machinery	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
315	-	Mahadev Stone Crushing Co., Village Jhojhu Kalan, Charkhi Dadri , Latitude : 28.486071 , Longitude : 76.142128	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA
316	-	Mahan Stone Crusher, Tikan Khurd, Charkhi Dadri , Latitude : 28.54921 , Longitude : 76.28843	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
317	-	Maruti Stone Crusher, Pandwan Charkhi Dadri (Old Name M/s Maruti Stone Crusher, Village Mankawas, Charkhi Dadri) , Latitude : 28.56995 , Longitude : 76.18523	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA
318	-	N K Builders & Stone Crusher Vill-Birhi Kalan, Charkhi Dadri , Latitude : 28.598239 , Longitude : 76.138952	Not having valid CTO & dismantled	--	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
319	-	Om Stone Crusher, Asawari, Charkhi Dadri , Latitude : - , Longitude : -	Not having valid CTE & Plant & Machinery not installed	-	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Non-operational and not installed plant & machinery	Non-Operational and not installed plant & machinery	NA
320	-	Peer Baba Stone Crusher, Village Asawari, Charkhi Dadri , Latitude : 28.536242 , Longitude : 76.175489	Not having valid CTO & dismantled	-	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
321	-	Pokhar Stone Crusher, Vill. Ramalwas, Charkhi Dadri , Latitude : 28.49682 , Longitude : 76.15	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA
322	-	R. K. Carriers India Private Limited, Village Mehrda Charkhi Dadri , Latitude : 28.555347 , Longitude : 76.175	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
323	-	Rapid Stone Crusher Vill- Birhi Kalan, Charkhi Dadri , Latitude : 28.60902 , Longitude : 76.13947	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA
324	-	Rattan Stone Crusher, Village Pandwan, Charkhi Dadri , Latitude : , Longitude :	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
325	-	Sajjan Singh Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.552927 , Longitude : 76.091306	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA
326	-	Shanker Stone Crusher, Village Jhojhu Kalan, Charkhi Dadri , Latitude : 28.190769 , Longitude : 76.611725	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
327	-	Shiva Stone Crushing Mills, Village Jhojhu Kalan, Charkhi Dadri , Latitude : 28.607476 , Longitude : 76.139843	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA
328	-	Shree Balaji Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.55199 , Longitude : 76.09076	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA

Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
329	-	Shree Balaji Stone Crushing Co. Village Jhojhu Kalan, Charkhi Dadri , Latitude : 28.55398 , Longitude : 76.082667	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA
330	-	Shree Ganesh Stone Crusher, Village Asawari, Charkhi Dadri , Latitude : 28.5361 , Longitude : 76.1773	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metallad roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
331	-	Shree Ganpati Stone Crushing Mills, Village Ramalwas, Charkhi Dadri , Latitude : 28.5703 , Longitude : 76.1867	Valid upto 31.03.25 & revocation in process	80 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	Unit has been closed by the Board	Unit has been closed by the Board
332	-	Shree Mahadev Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.5325832 , Longitude : 76.0756637	Valid upto 31.03.26 & revocation in process	30 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	Unit has been closed by the Board	Unit has been closed by the Board



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metallad roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
333	-	Shree Shyam Grit Udyog Vill-Ramalwas, Charkhi Dadri , Latitude : 28.501 , Longitude : 76.147	Valid upto 31.03.27 & revocation in process	30 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	Unit has been closed by the Board	Unit has been closed by the Board
334	-	Shri Dada Devi Nath Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.5325832 , Longitude : 76.0756637	Not having valid CTO & Closed by Board	40 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	Unit has been closed by the Board	Unit has been closed by the Board



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressin g system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metallad roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbo ok details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
335	-	Shri Ganesh Ji Stone Crusher Vill Pichopa Kalan Charkhi dadri , Latitude : 28.542649 , Longitude : 76.089912	Not having valid CTO & Closed by Board/Dismantled	-	The unit was found Closed by Board/Dismantled at the time of inspection.	The unit was found Closed by Board/Dismantled at the time of inspection.	The unit was found Closed by Board/Dismantled at the time of inspection.	The unit was found Closed by Board/Dismantled at the time of inspection.	The unit was found Closed by Board/Dismantled at the time of inspection.	The unit was found Closed by Board/Dismantled at the time of inspection.	The unit was found Closed by Board/Dismantled at the time of inspection.	The unit was found Closed by Board/Dismantled at the time of inspection.	Non-operational	The unit was closed by board & found dismantled	NA
336	-	Shyam Grit Udyog Village Pichopa Kalan Charkhi Dadri , Latitude : 28.552 , Longitude : 76.0883	Valid upto 31.03.26 & revocation in process	30 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	Unit has been closed by the Board	Unit has been closed by the Board



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
337	-	Suman Stone Crusher, V.P.O Pichopa Kalan, Charkhi Dadri , Latitude : 28.5325832 , Longitude : 76.0756637	Valid upto 31.03.25 & revocation in process	300 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	Unit has been closed by the Board	Unit has been closed by the Board
338	-	Surender Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.5325832 , Longitude : 76.0756637	Not having valid CTE & Plant & Machinery not installed	-	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Non-operational and not installed plant & machinery	Non-Operational and not installed plant & machinery	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
339	-	Trimbakeshwar Stone Crusher, Village Jhojhu Kalan, Charkhi Dadri , Latitude : 28.485338 , Longitude : 76.143883	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA
340	-	V K Stone Crushing Co Vill-Birhi Kalan, Charkhi Dadri , Latitude : 28.6098 , Longitude : 76.1388	Not having valid CTO & dismantled	-	TheDismantled/Plant & Machinery not installed at the time of inspection.	TheDismantled/Plant & Machinery not installed at the time of inspection.	TheDismantled/Plant & Machinery not installed at the time of inspection.	TheDismantled/Plant & Machinery not installed at the time of inspection.	TheDismantled/Plant & Machinery not installed at the time of inspection.	TheDismantled/Plant & Machinery not installed at the time of inspection.	TheDismantled/Plant & Machinery not installed at the time of inspection.	TheDismantled/Plant & Machinery not installed at the time of inspection.	Non-operational	Dismantled Plant & Machinery	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
341	-	Vijay Stone Crusher, Village Asawari, Charkhi Dadri , Latitude : 28.55005 , Longitude : 76.139633	Not having valid CTE & Plant & Machinery not installed	-	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Non-Operational and not installed plant & machinery	Non-Operational and not installed plant & machinery	NA
342	-	Vikas Stone Crusher, Mankawas, Charkhi Dadri , Latitude : 28.62698 , Longitude : 76.16418	Not having valid CTO & dismantled	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 260 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Unit has provided Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-operational	Unit is complying, Closed its own	NA



Sr No.	Respodent No.	Name and address of the unit & GPS Coordinate	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/sepa rate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Remarks	Action Taken
343	-	Vishwakarma Stone Crusher, Village Jhoju Kalan, Charkhi Dadri , Latitude : 28.5216309 , Longitude : 76.150838	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	Dismantled	NA

