

FACTUAL REPORT

BY

JOINT COMMITTEE

IN

APPLICATION NO.57/2022 (CZ)

KRISHNA SOCIAL AWARENESS WELFARE SOCIETY

V/S

STATE OF MADHYA PRADESH & ORS.

Joint Committee Report

Ref: Inspection of the joint committee dated 24.08.2022 as per the orders of Hon'ble NGT in case of OA 57/2022(CZ) Krishna Social Awareness Welfare Society V/s State of Madhya Pradesh &Ors.

Hon'ble NGT in reference to OA 57/2022 (CZ) Krishna Social Awareness Welfare Society V/s State of Madhya Pradesh & Ors. vide order dated 24.08.2022 has given following instructions:

“5. We deem it just and proper to call a report on the matter in issue in present Original Application, from a Joint Committee consisting of:-

- i. One representative from Municipal Corporation, Bhopal (M.P.)*
- ii One representative from Madhya Pradesh Pollution Control Board*

In compliance to the orders of Hon'ble NGT, a site visit of the New Chowksey Nagar, near JNCT college, Berasia road, Bhopal was conducted on dated 24.08.2022 by the joint committee consisting of the following officials of the concerned departments:

1. Shri Brajesh Sharma, Regional Officer, MPPCB, Bhopal
2. Shri Santosh Gupta, Superintendent Engineer, Nagar Nigam, Bhopal

Shri Ravi Singh, AE, BMC, Shri Jainendra Chandel, Chemist, MPPCB, RO Bhopal, and Shri Pushpendra Kumar Gupta, Assistant Engineer (C), MPPCB, RO Bhopal were present during the inspection. The joint committee conducted the inspection in presence of the residents of New Chowksey Nagar colony namely Shri A.K Saxena, President, Krishna Social Awareness Welfare Society, House no. 389, Shri T.P. Kori, House no. 254, Shri Samath Kori, H No 100, Shri Rajendra Singh, H No 283, Shri Kapil Thakur, H No 48.

The geographical location, photographs and visual observations were recorded. The committee recorded the observations during the inspection in reference to the points mentioned in the petition and observations are as follows:-

1. The New Chowksey Nagar colony is situated approx 360m away on the right side of Bhopal-Berasia road. GPS location of colony New Chowksey Nagar, Village Lambakheda, Ward 79, Tehsil huzur, Bhopal has been recorded using a

mobile-based GPS application. GPS coordinates of Society is 23.31616⁰N, 77.41206⁰E. The location is marked on Goole map and it is enclosed as **Annexure-I** and photographs taken during the inspection are enclosed as **Annexure- II**.

2. As per the information shown in petition the New Chowksey Nagar colony is developed by M/s SBI Staff Grah Nirman Sehkari Sanstha Maryadit, Bhopal in the year 1997.
3. The approx area of the colony is 27 Acre and as per petition colony is consisting approx 500 plots.
4. The approach road from main road to the colony is made of cement concrete. The internal roads of the colony are made of cement concrete having width of approx. 15 feet. The roads are found clean and in good condition.
5. It is observed during inspection that approx 03-04 small pieces of 5-8 meters of internal roads are found damaged and not having cement concrete over it.
6. New Chowksey Nagar colony is a developed colony and approx 90% plots are occupied and pucca houses are constructed. It consist of single storey, multi-storey and row houses.
7. 04 parks are provided within the colony area which are having area of approximately 100 square meter, 150 square meter, 200 square meter, and 2500 square meter. The parks are not maintained properly.
8. One overhead tank and a sump well of approx 150 KLD storage capacity is provided within the colony at a park for water supply in the colony.
9. Residents informed that the water supply system is not operative.
10. The sewer network system, chambers & manhole along with septic tank is provided in the colony. The sewage is sent to septic tank through underground drainage system.
11. The manholes and chambers are located at suitable places and are in working conditions.
12. A septic tank of approx 450 cubic meter capacity is provided on north-east corner of the colony for the sewage treatment. The location is marked on

Google map. The sewage line is connected with the septic tank. Septic was found in operational condition.

13. Water logging is observed in some vacant plots. The water is seems like rain water as there was a heavy rains in the area in previous day.
14. Residents informed the committee that sewage overflows from some manhole is collected in to a vacant plot. MPPCB has collects water samples from the stagnated water for analysis.
15. The sewage overflow from manhole is due to blocking of sewer line. Residents informed that there is no cleaning and maintenance arrangement of the sewer system in the colony.
16. Electric poles are provided in the colony but street lights are not functional.
17. The solid waste is collected by door to door arrangement of Bhopal Nagar Nigam.
18. It is observed that the sewer line over flow and street light problem is occurs due to non maintenance of these facilities. Presently there is no maintenance arrangement in the colony.
19. During inspection the residents of the colony are asked to provided documents such as allotment letter, property agreement letter, Town and Country department permission of colony to know the year of establishment of the colony and who is responsible for the operation and maintenance work of colony, but the documents are not provided.
20. The residents informed that there is no financial arrangement for the regular operation and maintenance of the colony.

Action Taken:

1. A notice is issued by MPPCB to SBI Staff Grah Nirman Sehkar Sanstha Maryadit, Bhopal for operation and maintenance work of sewage line of the New Chowksey Nagar colony. The copy of notice is enclosed as **Annexure-III**

2. For instant relief Bhopal Municipal Corporation has cleaned the sewer line of the New Chowksey Nagar colony. Photographs taken during the cleaning of sewer line in New Chowksey Nagar colony are enclosed as **Annexure-IV**

Recommendations:

1. The sewer line is required regular cleaning and maintenance so that sewage overflow from manhole should not take place.
2. For regular operation and maintenance of sewage line, street light, water supply, internal roads of colony New Chouksey Nagar Colony residents should developed a society of residents and create a financial support based on sharing basis of each resident.
3. The funds should be used for regular operation and maintenance of colony.



Brajesh Sharma
Regional Officer, MPPCB Bhopal



Santosh Gupta
Superintendent Engineer, Nagar Nigam
Bhopal

Google map showing location of New Chowksey Nagar Colony





ANNEXURE-II

**Photographs of New Chowskey Nagar colony taken during inspection
dated 24/08/2022**



**Joint committee members, Petitioner and residents of New Chowksey
Nagar colony**



Water supply tank situated in the colony



Inspection sewage Chamber inside the society premises



The flow of Sewage observed in the sewage chamber



No overflow observed from sewage chamber



Cement concrete Pavement road inside colony premises



24.08.2022 16:47
23.31841°N 77.41075°E
Altitude: 427m
8C95+HP6, near Nabibagh, New Choksey Nagar, Navi Bagh,
Bhopal, Madhya Pradesh 462038

Sewage chamber located before the septic tank



24.08.2022 16:48
23.31843°N 77.41079°E
Altitude: 424m
8C95+HP6, near Nabibagh, New Choksey Nagar, Navi Bagh,
Bhopal, Madhya Pradesh 462038

Septic Tank with air vent pipes



24.08.2022 16:49
23.31865°N 77.41071°E
Altitude: 430m
8C95+HP6, near Nabibagh, New Choksey Nagar, Navi Bagh,
Bhopal, Madhya Pradesh 462038

Concrete top of Septic Tank



Water logging above the road



Water logging in the low laying area within the colony



क्षेत्रीय कार्यालय
मध्य प्रदेश प्रदूषण नियंत्रण बोर्ड
पर्यावरण परिसर,ई-5,अरेरा कॉलोनी,भोपाल



Telephone:- 0755-2466392 Email:- romppeb_bpl@rediffmail.com

क्रमांक २५६४ / क्षेत्रा / प्रनिबो / 2022
प्रति,

भोपाल, दिनांक २५/८ / 2022

एसबीआई स्टॉफ गृह निर्माण सहकारी संस्था मर्यादित
श्री जे.एन. चौकसे, (अध्यक्ष)
पुत्र स्व. श्री सी.एल. चौकसे
31, श्यामला हिल्स
भोपाल (म.प्र.)-462010

विषय:-

न्यू चौकसे नगर कॉलोनी, जे.एन. सिटी कॉलेज के पास बैरसिया रोड़ भोपाल में सीवेज लाईन का संधारण न करने के संबंध में नोटिस।

उपरोक्त विषयांतर्गत माननीय एन.जी.टी. प्रकरण क्र. 57/2022 (कृष्णा सोशल अवेयरनेस वेलफेयर सोसायटी विरुद्ध म.प्र. शासन व अन्य) के संबंध में गठित प्रदूषण नियंत्रण बोर्ड एवं नगर निगम भोपाल की संयुक्त कमेटी द्वारा दिनांक 24.08.2022 को न्यू चौकसे नगर कॉलोनी, जे.एन. सिटी कॉलेज के पास बैरसिया रोड़ भोपाल का निरीक्षण किया गया। निरीक्षण दौरान निम्नांकित स्थिति पाई गई :-

1. कुछ सीवर लाईन के मेन होल से सीवेज का ओवर फ्लो होना पाया गया। जो समीपस्थ खाली पड़े प्लाट में भरा है।
2. सीवर लाईन की नियमित सफाई न होने से कुछ क्षेत्र में सीवेज सेप्टिक टैंक तक नहीं पहुँच रहा है।
3. कालोनी के भीतर छोटे पेच में सड़क जर्जर स्थिति में है।
4. कालोनी की स्ट्रीट लाईट बंद पड़ी है।
5. कालोनी में एक सम्पवेल तथा एक ओवर हेड टैंक स्थापित है। परन्तु कालोनी में जल प्रदाय इससे नहीं किया जा रहा है।

उपरोक्त बिन्दुओं के परिप्रेक्ष्य में लेख है कि सीवेज का उपयुक्त उपचार न होने के कारण यह जल (प्रदूषण निवारण तथा नियंत्रण) अधिनियम 1974 के प्रावधानों के अन्तर्गत दण्डनीय अपराध है। कृपया न्यू चौकसे नगर कालोनी के संबंध में उपरोक्त बिन्दुओं पर शीघ्र कार्यवाही करावें तथा कालोनी के संधारण कार्य हेतु क्या व्यवस्था है, इससे कार्यालय को 15 दिवस के भीतर उपलब्ध करावें।

(बृजेश शर्मा)
क्षेत्रीय अधिकारी

Photographs Taken during Cleaning of sewer line of New chowksey Nagar colony



