

FACTUAL REPORT BY MPPCB

IN

Original Application No. 696/2019 (PB)

Residents of Village – Jhirnia

Gandhi Nagar, Bhopal

VS

State of Madhya Pradesh

Factual Report

Ref. - Inspection as per the Hon'ble NGT order on dated 13/10/2020 in OA No 696/2019 (PB) (Villagers of Village, Jhirnia vs. State of MP)

With reference to above order dated 13/10/2020 of Hon'ble NGT, the officials of M.P. Pollution Control Board visited the site of M/s Dilip Kumar Preetmani (M/s Jhulelal Stone Crusher) on dated 14th October 2020. As per the available data / record the points related to the present status of stone crusher are observed during visit and mentioned as under:

1. As per office record, the consent is obtained by M/s Dilip Kumar Preetmani for stone boulder quarry and Stone crusher at the Survey No. 6/2, Village – Rasuliya Pathar, Tehsil –Huzur, District –Bhopal from MPPCB.
2. As per the document submitted by M/s Dilip Kumar Preetmani, with consent application the Survey No. 6/2, Village – Rasuliya Pathar, Tehsil –Huzur, District – Bhopal is having 2.52 Hectare lease area and following geographical locations are mentioned in the documents:

Points	Latitude	Longitude
P1	23 ⁰ 20' 26.88" N	77 ⁰ 14' 57.11" E
P2	23 ⁰ 20' 23.12" N	77 ⁰ 14' 57.11" E
P3	23 ⁰ 20' 24.76" N	77 ⁰ 15' 03.63" E
P4	23 ⁰ 20' 29.88" N	77 ⁰ 15' 02.44" E

3. The above geographical locations of the area of 2.52 hectare are marked on the Google map and the screen shot obtained is enclosed.
4. During the inspection, the geographical location in terms of latitude and longitude of the existing stone crusher are measured using mobile based GPS application. The measured latitude is 23.3411153 & Longitude is 77.2479737. These are marked on the Google map and the screen shot is enclosed.
5. As per the locations marked on Google map, the location of stone crusher is found approx. 120 meter away from the nearest boundary of Survey No. 6/2, Village – Rasuliya Pathar, Tehsil –Huzur, District –Bhopal. This shows the crusher is located outside the area of Survey No. 6/2, Village – Rasuliya Pathar, Tehsil –Huzur, District –Bhopal.
6. During inspection, the stone crusher was not found in operation. The conveyor belt connected the jaw crusher to nearest vibratory screen was found broken. The heaps of crushed stone were observed in the premises. The photographs of the stone crusher and surrounding are enclosed.

- The air pollution control arrangements were not appropriate. No green plantation provided around the stone crusher boundary, Jaw crusher not covered, Wind breaking wall around crusher not provided, thick layer of fine dust found all around the crusher area which indicates that dust suppression system not functional properly during operation.

Screen shots of Google Map:


Showing location of Survey No. 6/2, Village – Rasuliya Pathar, Tehsil –Huzur, District –Bhopal




Photographs of Stone Crusher:






 S S Pandya
 Scientist
 Regional Office, MPPCB ,
 Bhopal


 Brajesh Sharma
 Eexecutive Engineer,
 Head Office, MPPCB ,
 Bhopal