

Joint Committee Report

In the Matter of

Original Application No.306/2023


Priyanshu Gupta

V/s

State of Madhya Pradesh

w.r.t.

**Hon`ble National Green Tribunal [Principal Bench] New
Delhi Order dated 25.05.2023**



Date of Visit: 15 July 2023

Location: Indore (MP)

Index

S. No.	Details	Page No.
1.	Report of the Joint Committee	1-8
3.	Annexure - 01 : Geo-tagged List of water bodies i.e. baolis/stepwells/wells located within Indore Municipal Corporation Jurisdiction.	9-51
4.	Annexure - 02 : Office Order dated 31/03/2023 of IMC	52-53
5.	Annexure - 03 : List of filled-up/closed baolis/stepwells/wells	54-56
6.	Annexure - 04 : List of maintained/repared baolis/stepwells/wells	57-94
7.	Annexure - 05 : List of baolis/stepwells/wells which are under process of maintenance/rejuvenation	95-111
8.	Annexure - 06 : Photographs	112-115

Joint Committee Report

Joint Committee Report in the Matter of OA No. 306/2023 (Priyanshu Gupta V/s State of Madhya Pradesh) in compliance of the order issued by Hon'ble NGT, Principal Bench, New Delhi on dated 25/05/2023

This Original Application No. 306/2023 has been registered by the Hon'ble NGT on the basis of letter dated 12.04.2023 received from Priyanshu Gupta, a student of B.A.LL.B (Hons), Indore Institute of Law, D.A.V.V. University, Indore. The applicant has raised the issue of filling of baolis/stepwells/wells by muck/malwa arbitrarily after the incident due to collapse of covered baoli/stepwell at Indore on dated 30/03/2023. Applicant has requested to recognized the signification of these structures and take measures to conserve to restore them for sustainable water management. Hon'ble NGT Principal Bench, New Delhi issued Order on dated 25/05/2023 to submit factual report. Directions issued as in Paras No. 5-8 of the order are as under.

- “5. *In our view, a substantial question relating to environment due to implementation of Scheduled Enactments under NGT Act, 2010 has arisen but before taking any further action in matter, we find it appropriate to obtain a factual report for the purpose whereof, we constitute a Joint Committee comprising Madhya Pradesh Pollution Control Board, Central Pollution Control Board, Central Ground Water Authority, District Magistrate, Indore and a representative of Department of Environment and Forest, Madhya Pradesh.*
6. *Madhya Pradesh PCB shall be the nodal agency for co-ordination and compliance of this order.*
7. *The said Committee shall visit the site, collect relevant informations and submit factual report particularly, inventorisation of water bodies i.e., Baolis/Stepwells/wells, there geo-tagging, and further, ensuring that the sanctity and wholesomeness of these water bodies are preserved and maintained. The Report shall be submitted within two months before Registrar of Central Zonal Bench, Bhopal by e-mail at judicial-ngt@gov.in preferably in the form of searchable PDF/ OCR Support PDF and not in the form of Image PDF, who shall place the matter before the Bench for further order.*
8. *Registry is directed to transfer record of this matter to Central Zone Bench, Bhopal for further proceedings in the matter.”*

In Compliance of above directions passed by Hon'ble NGT, following Officers have been nominated in the Joint Committee by the concerned departments:

S.No.	Name	Department/Agency
1	Shri Ajaydev Sharma, ADM, Indore	Representative of Collector Indore
2	Shri Lokendra Thakkar, Senior Scientific Officer, Environment Planning and Coordination, Organization (EPCO) Bhopal	Representative of Government of Madhya Pradesh, Environment Department
3	Shri Sanjay Kumar Mukati, Scientist-B, Regional Directorate CPCB, Bhopal	Representative of CPCB
4	Shri Rakesh Singh, Scientist-D & Smt. Paisnee Patel, Scientist-C, Central Ground Water Board, Bhopal	Representative of Central Ground Water Authority (CGWA)
5	Regional Officer, M.P. Pollution Control Board, Indore	Representative of MPPCB

Joint Committee has conducted a meeting on dated 15/07/2023 at ADM Office Indore and discussed regarding sites visit. During meeting following officers of Joint Committee were present:

1. Shri Ajaydev Sharma, ADM, Indore.
2. Shri Shriniwas Dwivedi, Regional Officer, MPPCB, Indore
3. Shri Sanjay Kumar Mukati, Scientist-B, Regional Directorate CPCB, Bhopal
4. Dr. Dinesh Damde, Assistant Scientific Officer, Environment Planning and Coordination, Organization (EPCO) Bhopal (EPCO has issued a Order and deputed Dr. Damde for inspection in place of Shri Lokendra Thakkar, Senior Scientific Officer, due to his illness and not able to visit the sites).
5. Shri Kamlesh Ojha, Scientist, CGWA, Bhopal

During meeting following officers of Indore Municipal Corporation and the MPPCB were also present:

1. Shri Sunil Gupta, Superintendent Engineer, Indore Municipal Corporation, Indore
2. Shri Sanjay Jain, Scientist, Regional Office, MPPCB, Indore
3. Shri Sewakram Patidar, Indore Municipal Corporation, Indore

Issues raised by the Petitioner in the Application:

1. Applicant has submitted a letter to Hon'ble NGT stating his concern about the State Government's directions to prevent accident by filling-up the baolis/stepwells with muck/malwa on account of accidents that occurred in Indore

on 30 March 2023 in violation of environmental norms for protection of water bodies/ground water sources, which is causing a threat to their conservation.

2. The applicant has requested to Hon'ble NGT that : “ baolis/stepwells are incident structure that have been used for centuries in arid and semi arid regions, including India, to collect and store rainwater. They are not only a sustainable solution for water conservation but also an important source of ground water recharge. It is crucial to recognize the significance of these structures and take measures to conserve and restore them for sustainable water management. The incident in Indore highlighted the issue where a baoli/stepwell in a temple, which was illegally built upon and covered up, claimed numerous lives of innocent citizen. Although the Indore Development Authority had launched a scheme for rejuvenation of these baolis/stepwells, it appears that they are now being covered up by muck/malwa in collusion with plot owners.

Factual Report :-

1. Joint Committee has conducted a meeting on dated 15/07/2023 at ADM Office Indore and discussed regarding mode of compliance of the order and site visits. During meeting representative of Indore Municipal Corporation has submitted that inventorization of water bodies i.e. baolis/stepwells/wells with their Geo-tagging has been carried out and there are 595 Baolis/step wells/ wells at different locations. List of water bodies i.e. baolis/stepwells/wells located within Indore Municipal Corporation Jurisdiction is enclosed as **Annexure-1**.

Due to large number of water bodies as inventorized by Inodre Municipal Corporation, the Joint Committee decided to visit at some sites of Baolis/step wells/ wells located in different areas of the city to verify the actual status.

2. Indore Municipal Corporation (IMC) has submitted that to prevent the accidents, Corporation has filled-up some of the risky and damaged baolis after incident of 30-03-2023. Office Order dated 31/03/2023 of IMC in this regard is enclosed as **Annexure-2**. As per the order, no arbitrary order to fill all the baolis/stepwells/wells after the incident occurred on dated 30/03/2023 has been issued.
3. IMC has submitted list of filled-up/closed baolis/stepwells/wells which is enclosed as **Annexure-3**. As per information submitted, **14** baolis/stepwells/wells have been closed by refilling. Out of **14** structures, **07** are under government and

filled-up by IMC and remaining 07 are private which have been filled-up by the owners and land has been reused for the other purpose. IMC has closed those baolis/stepwells/wells which were at risk for human lives due to their location and conditions. Some of the structures were covered by slab earlier about 10-15 years past and roads were constructed over them. After the incident of 30/03/2023, to prevent any such accidents in future, the slabs over the closed wells were opened and baolis/stepwells were re-filled and there after roads have been re-constructed over them. Details of closed wells/baolis may be perused.

4. IMC has maintained/repared large number of baolis/stepwells/wells during past recent years and some of the baolis/stepwells/wells are under process of maintenance/rejuvenation. Information received from Indore Municipal Corporation is enclosed as Annexure-4 & 5. As per the information 361 baolis/stepwells/wells have been maintained and 195 are under process of maintenance in recent years. IMC has done maintenance work of large number of baolis/stepwells which shows that there is no arbitrary decision to close all the baolis.
5. IMC has submitted that under "Jal Shakti Abhiyan" water recharging/harvesting work has been done in 100 wells/baolis and this work is also continue.
6. As submitted above IMC has provided detailed information regarding inventorization, maintenance/rejuvenation of the baolis/stepwells/wells and to verify the work done inclusive of closed baolis, the Joint Committee has visited some of the sites on dated 15/07/2023 and factual status was found as follows :

S. No	Location	Latitude and Longitude	Type of water body	Status	Remark
1	Sapna Sangeeta Main Road, Opposite Capital Tower building	22.7028, 75.8717	Baoli/ Stepwell	Geo-tagged and maintained	Required cleaning of the debris from the baoli.
2	Agrawal Nagar, Sitlamata Mandir, Indore	22.7006, 75.8714	Well (Large Dia Well)	Geo-tagged and maintained	Covered with Jaali and green net, water harvesting pit constructed.

3	Vishnupuri Shiv Mandir, Indore	22.6901, 75.8621	Well (Large Dia Well)	Geo-tagged and maintained	Covered with Jaali/mesh and green net, water used in gardening.
4	Amitesh Nagar, Udham Singh Chouraha, Indore	22.6811, 75.8533	Baoli	Geo-tagged but renovation required, side walls damaged.	Covered with Jaali/mesh and green net, water used in washing. Renovation required.
5	Mukteshwar Mahadev Mandir, Amitesh Nagar, Indore	22.6812, 75.8534	Well (Large Dia Well)	Geo-tagged and maintained	Covered with Jaali/mesh. Recharge pit constructed.
6	Government Higher Secondary School Campus, Kila Maidan, Indore	22.7292, 75.8468	Baoli	Damaged and dry	The baoli is collapsed and dry. It is required to be renovated or may be used as ground water recharge structure.
7	Dhakkan wala Kuwa, Dhakkan wala Square, Indore	22.7175, 75.8778	Well	Closed and road has been constructed over it.	Earlier there was well which was covered about 15 years back and road was constructed over it. The well was located at the center of the road, hence after incident on dated 30/03/2023 this well was re-opened and filled completely with muck/malwa and road has been re-constructed again. Now there is no well, there is only road
8	Snehlata ganj Square, Near Jail,	22.7274, 75.8642	Filled up well	Closed and road was constructed	The well was completely damaged and it was below the

	Indore (Humpty Dumpty School ke samne)			over it.	road about 10 years back. After the incident dated 30-03-2023, it has been re-opened and filling-up by muck and malwa. Work was under progress. Road will again be constructed as it is located at within the road.
9	Beleshwar Mahadev Mandir, Patel Nagar, Indore	22.7017, 75.8687	Filled up well	Filled up well	Accident was occurred at this locations on dated 30/03/2023 and after the accident, the well/baoli was filled up by muck/malwa. Temple near the well has also been demolished. The site was observed and filled-up area was found.

7. Photographs of the meeting and inspection is herewith enclosed for perusal as Annexure-6.

Conclusion :-

On the basis of observations during inspection and information provided by Indore Municipal Corporation conclusion of the Joint Committee are as follows:

1. Government or Indore Municipal Corporation has not decided arbitrary to fill all the baolis/stepwells/wells after the accident occurred on dated 30/03/2023, as per information submitted by Indore Municipal Corporation. 14 baolis/wells have been closed and filled-up as explained in point no.3 above in addition to the

baoli/well at which accident dated 30/03/2023 was occurred which was located at Beleshwar Mahadev Mandir, Patel Nagar, Indore.

2. Indore Municipal Corporation has inventorized the water bodies with Geo-tagging and renovation of some of them has already been done and there is action plan to renovate the remaining and ensured to preserve and maintained the water bodies
3. Total **595** baolis/stepwells/wells are located within Municipal Corporation Indore area as per the inventorization. Out of **595** structures, **361** have been maintained/repared and **195** are under process of maintenance. As stated above, **556** baolis/stepwells/wells have been maintained/under process of maintenance out of **595**.
4. Indore Municipal Corporation has submitted that under "Jal Shakti Abhiyan" water recharging/harvesting work has been done in 100 wells/baolis and this work is also continue.
5. Indore Municipal Corporation should install water recharging system in baolies/stepwells/wells to maintain water level and time to time cleaning any debris, if found in the water body.
6. Indore Municipal Corporation shall ensure that no wastewater of any type be disposed into baolis/stepwells/wells at any time.
7. Indore Municipal Corporation should check and prevent encroachment of areas pertaining to Baolis/stepwells/Dug wells. Setup a regular maintenance schedule to monitor the condition of the structure and address any potential issues promptly.
8. Water quality and water level of the water bodies may be monitored time to time to check the contamination and their recharge status.
9. Indore Municipal Corporation should develop comprehensive conservation plan that outlines the necessary steps and guidelines for re-storation and maintenance. This plan should consider the historical significance of the structures.
10. Indore Municipal Corporation should prepare a conservation guideline for baolis and stepwells. These guideline should cover aspects such as the use of compatible materials during re-storation, techniques to retained the original architecture.

11. Indore Municipal Corporation should involve local committee in the conservation process. Engaging with the committee will raise awareness about the historical importance of these structures, foster essence of ownership and discourage any potential vandalism or encroachment.
12. The unused/collapsed baolis/stepwells/Dugwells as observed at Government Higher Secondary School Campus, Kila Maidan, Indore may be used as a GW recharge structures with respect to their recharge capacity along with adaptation of suitable safety measures. Similar recharge structures may be constructed at unused/collapsed baolis/stepwells/dugwells etc. by Indore Municipal Corporation to improve the ground water level of the city.


Encl. : As above.



(Kamlesh Ujra)
Scientist,
CGWA, Bhopal



(Sanjay Kumar Mukati)
Scientist-B,
Regional Directorate
CPCB, Bhopal



(Dr. Dinesh Damde)
Assistant Scientific Officer,
Environment Planning and
Coordination, Organization
(EPCO), Bhopal



(Shrinivas Dwivedi)
Regional Officer,
MPPCB, Indore



(Ajaydev Sharma)
ADM, Indore

Annexure-1

Geo Tagging Information Bawdi/Step-Well / Well

Sl. No.	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Length (in meters)	Unsafe or Maintenance Required Details	Type of Encroachment?	Encroachment Category	Geo-Location	Photo-Link
1	1	Near Post Office kila maidan, VIP Route	kuan	government	brickwork	10	2		Jali and cleaning required presently filled with matwa only 1m available depth	none	none	22.7768723, 75.8460579	http://swm-api.acceldash.com/uploads/repositories/1681024165127.jpeg
2	1	Near GDC police campus VIP Route	kuan	government	stone	20	4	4	Inside clean and Covered by jali, surrounding cleaning required my health department	none	none	22.7296364, 75.8456869	http://swm-api.acceldash.com/uploads/repositories/1681024555705.jpeg
3	1	Kamla nehru nager near h no. 376	bawdi	government	stone	20	6	16	covered with jaali, safai required	none	none	22.7383913, 75.8453201	http://swm-api.acceldash.com/uploads/repositories/1681024926041.jpeg
4	1	Gorshwar Mahadev Mandir Campus Khasgi Bageecha	kuan	government	stone	12	4	4	open jaali not there, major cracks in wall parapet wall damaged safai required	none	none	22.7401845, 75.8439477	http://swm-api.acceldash.com/uploads/repositories/1681024967830.jpeg
5	1	Sangam Nagar GTS Campus	bawdi	government	stone	15	10	10	Not Covered Safai Required Secured by Fencing	none	none	22.7401845, 75.8439477	http://swm-api.acceldash.com/uploads/repositories/1681025078490.jpeg
6	1	Hemu Colony Naale ke paas	kuan	government	stone	15	5		Open, Safai Not Required Munder Damaged Wall Damaged, One side House Wall with Kiwe ki wall	permanent	residential	22.7398932, 75.8430421	http://swm-api.acceldash.com/uploads/repositories/1681025449075.jpeg
7	1	Laal Kuwa Vrandavan Colony	kuan	government	stone	14	5		Jali Damaged Need Repair, Munder wall height increase safai required	none	none	22.7402905, 75.8465289	http://swm-api.acceldash.com/uploads/repositories/1681025534241.jpeg
8	1	32/34 Khasgi ka Bageecha	kuan	government	brickwork	8	5		Gardner Jali Damaged Munder required on road level safai required one column removed by removal team civil work required	Permanent	residential	22.7402905, 75.8465289	http://swm-api.acceldash.com/uploads/repositories/1681025745266.jpeg

9	1	9	MKVV School ke paas Kumbharkhadi	kuan	government	brickwork	8	3		Jaali Required, temporary material se dhaka hai road level par hai, wall required	none	none	22.7389348, 75.8479605	http://swm-api.acceldash.com/uploads/revisers/1681025863559.jpeg
10	1	9	H No 14 Kumbharkhadi Naale ke paas	kuan	private	brickwork	10	2		Jaali open Munder required	none	none	22.7379574, 75.847933	http://swm-api.acceldash.com/uploads/revisers/1681025901952.jpeg
11	1	9	147 Kumbharkhadi	kuan	private	brickwork	12	2		Farshee se covered hai munder required	none	none	22.7263534, 75.8446657	http://swm-api.acceldash.com/uploads/revisers/1681026171196.jpeg
12	1	9	vriindawan garden	kuan	government	brickwork	15	4		safa required rest ok	none	none	22.7372594, 75.8481268	http://swm-api.acceldash.com/uploads/revisers/1681026303992.jpeg
13	1	9	Gadrakhedi Khatu Shyam Mandir Footpath	kuan	government	brickwork	10	2		civil work in progress after removal	none	none	22.7398079, 75.849325	http://swm-api.acceldash.com/uploads/revisers/1681026659330.jpeg
14	1	9	15th Battalion	kuan	government	brickwork	10	3		Jaali required safai required	none	none	22.7348162, 75.8466703	http://swm-api.acceldash.com/uploads/revisers/1681027015907.jpeg
15	1	9	government school kila maidan	bawdi	government	stone	15	6	5	one side wall collapsed covered by profile sheet. need civil work	none	none	22.7306818, 75.8456348	http://swm-api.acceldash.com/uploads/revisers/168100720934.jpeg
16	1	9	Behind Girls School Open Area	kuan	government	rcc	12	3		Jaali repair munder required safai required	none	none	22.7348162, 75.8466703	http://swm-api.acceldash.com/uploads/revisers/16810072060.jpeg
17	1	9	behind gutkeshwar Tempe	kuan	government	brickwork	10	3		wall collapsed need civil work temporary covered with profile sheet	none	none	22.7283238, 75.8465222	http://swm-api.acceldash.com/uploads/revisers/168101053345.jpeg
18	1	7	Behind Sharda Kanya School	kuan	government	brickwork	12	4		Jaali repair safai required munder new required	none	none	22.7216055, 75.8412604	http://swm-api.acceldash.com/uploads/revisers/168101479573.jpeg
19	1	7	55 Mahaveerbag ke Samne	kuan	government	brickwork	12	4		Jaali repair munder height and safai required	none	none	22.7231928, 75.838449	http://swm-api.acceldash.com/uploads/revisers/168101871165.jpeg
20	1	7	Near Fire Station VIP route	kuan	government	brickwork	25	3		munder required and safai Wall must be removed at time of munder construction	temporary	none	22.7268495, 75.8401951	http://swm-api.acceldash.com/uploads/revisers/168102170416.jpeg
21	1	7	Ram Krishna Mission School Campus	kuan	private	brickwork	12	3		covered with slab and parapret wall	permanent	none	22.7263351, 75.8400834	http://swm-api.acceldash.com/uploads/revisers/1681102322483.jpeg
22	1	4	Panchwati Colony	kuan	government	brickwork	20	6		Jaali ok net ok safai required	none	none	22.7266399, 75.8332513	http://swm-api.acceldash.com/uploads/revisers/1681102322483.jpeg

23	1	4	Raptic Police line Campus	kuan	government	brickwork	10	2	jaali nhi hai, open hai 4 ft par hi sab malwa pada hai	none	none	22.7265834, 75.8331293	http://swm-api.acceldash.com/uploads/reposters/1681102454136.jpeg
24	1	4	Raptic Campus	bawdi	government	stone	20	8	jaali required safai required	temporary	religious	22.7265835, 75.8342729	http://swm-api.acceldash.com/uploads/reposters/16811024575863.jpeg
25	1	4	Shivdham Mandir Kanyakubj Garden	kuan	government	brickwork	12	2	covered I near shiv pratima	permanent	religious	22.7276044, 75.8283348	http://swm-api.acceldash.com/uploads/reposters/1681102668066.jpeg
26	1	4	Nemi Nath Villa Sadhna Nagar	kuan	private	stone	18	5	paraipret height must be increased, jaali ok	none	none	22.7278125, 75.8196626	http://swm-api.acceldash.com/uploads/reposters/1681103149660.jpeg
27	1	4	Honey Apartment 2 E Sadhna Nagar	kuan	private	brickwork	10	2	jaali repair munder required	none	none	22.7245805, 75.8270401	http://swm-api.acceldash.com/uploads/reposters/1681103278114.jpeg
28	1	4	Manpasand Colony Popal Tree Gali No 2	kuan	government	brickwork	15	5	Covered with Road	permanent	none	22.7245805, 75.8270401	http://swm-api.acceldash.com/uploads/reposters/1681103328955.jpeg
29	1	7	Shramik Colony Kandilpura Shetlshwar Mahadev Mandir	kuan	private	stone	15	3	jaali ok net ok wall height may be increased	none	none	22.723466, 75.8270937	http://swm-api.acceldash.com/uploads/reposters/1681103396703.jpeg
30	1	7	Shankargiri Ashram Kandilpura	kuan	private	stone	15	3	No Jaali open munder damage	none	none	22.723466, 75.8270937	http://swm-api.acceldash.com/uploads/reposters/1681103398339.jpeg
31	1	7	Shankargiri Ashram	kuan	private	stone	15	4	covered with jaali	none	none	22.7237712, 75.8415419	http://swm-api.acceldash.com/uploads/reposters/1681104147710.jpeg
32	1	7	Ram Bagichi kandilpura	kuan	government	brickwork	12	3	jaali repair Munder required	none	none	22.7260649, 75.8417508	http://swm-api.acceldash.com/uploads/reposters/1681104165405.jpeg
33	1	7	Hanuman Mandir Hukumchand Pehlwan Subhash Marg	kuan	Government	brickwork	15	4	jaali ok	none	none	22.7241248, 75.8444968	http://swm-api.acceldash.com/uploads/reposters/1681104485670.jpeg
34	1	7	Nigam Jinsi Workshop	bawdi	government	stone	20	5	jaali nhi hai safai required	none	none	22.7241248, 75.8444968	http://swm-api.acceldash.com/uploads/reposters/1681104929870.jpeg
35	1	7	Arjun Palitan	bawdi	government	stone	20	7	stone wall cracks jaali repair munder height required jarjar	none	none	22.7228608, 75.8442627	http://swm-api.acceldash.com/uploads/reposters/1681105094178.jpeg
36	1	7	Dalal Bag Ground VIP Route	kuan	private	stone	22	4	jaali nhi hai munder damage safai required	none	none	22.7259483, 75.8388894	http://swm-api.acceldash.com/uploads/reposters/1681105295657.jpeg
37	1	7	VeerGadi Hanuman Mandir Campus	bawdi	government	stone	18	5	Civil work required jaali ok safai	none	none	22.7252682, 75.8442845	http://swm-api.acceldash.com/uploads/reposters/1681105340849.jpeg

38	1	15	Kazam Ki Bawdi Chota Bangarda	bawdi	government	stone	15	6	16	open wall jarjar malwa mitti no water stone work collapse of staircase area	none	none	22.7245776, 75.8462504	http://swm-api.acceldash.com/uploads/reports/168110550311.jpg
39	1	16	Ram Mandir Chota Bangarda	kuan	private	stone	12	5	5	jaali naiti secured by Fencing malwa mitti no water safai required munder required	none	none	22.7245776, 75.8462504	http://swm-api.acceldash.com/uploads/reports/1681105507351.jpg
40	1	16	Chota Bangarda Petrol Pump	kuan	government	brickwork	18	6		jaali ok	none	none	22.7446792, 75.8147222	http://swm-api.acceldash.com/uploads/reports/1681105683493.jpg
41	1	16	Isha Corridor	kuan	private	brickwork	12	6		No jaali munder damaged below road level	none	none	22.7446792, 75.8147222	http://swm-api.acceldash.com/uploads/reports/1681106095703.jpg
42	1	16	Smruti Nagar Shiv Mandir Garden	kuan	government	brickwork	15	5		collapsed one year ago civil work in progress secured by Fencing	none	none	22.7446792, 75.8147222	http://swm-api.acceldash.com/uploads/reports/1681106465553.jpg
43	1	16	Hanuman Mandir Garden Vyankatesh Vihar	kuan	government	brickwork	15	4		jaali ok	none	none	22.7462332, 75.8172601	http://swm-api.acceldash.com/uploads/reports/1681106527207.jpg
44	1	16	Vandana Nagar	kuan	government	brickwork	12	7		jaali ok water dirty	none	none	22.7364589, 75.8242168	http://swm-api.acceldash.com/uploads/reports/1681106945752.jpg
45	1	7	Neelkanth Colony ke pesche	bawdi	government	stone	14	4	5	jaali not there safai required munder damaged	none	none	22.7257923, 75.8470795	http://swm-api.acceldash.com/uploads/reports/1681107058235.jpg
46	1	7	Kali masjid Jinsi	kuan	government	brickwork	12	2		covered with slab and steel cover	permanent	religious	22.7229693, 75.8467695	http://swm-api.acceldash.com/uploads/reports/1681106350129.jpg
47	1	8	Safed Masjid Jinsi Sq.	kuan	government	brickwork	12	2		covered with slab and steel cover	permanent	religious	22.7229693, 75.8467695	http://swm-api.acceldash.com/uploads/reports/1681107751981.jpg
48	1	8	tatya ki bawdi laal hospital	bawdi	government	stone	15	10	15	covered with grill and shed, minor cracks in wall	none	none	22.722933, 75.8461934	http://swm-api.acceldash.com/uploads/reports/168110786221.jpg
49	1	8	Mahant Complex Malharganj	kuan	private	brickwork	12	2		covered with slab and steel cover and used for parking	permanent	residential	22.7203136, 75.8474518	http://swm-api.acceldash.com/uploads/reports/1681108008909.jpg
50	1	8	hari heights North yashwant ganj	kuan	private	brickwork	12	2		covered with slab and used for parking	permanent	residential	22.7197294, 75.8474384	http://swm-api.acceldash.com/uploads/reports/1681108167700.jpg
51	1	8	Masjid Chhipa Bakhhal	kuan	government	brickwork	12	2		covered with slab and steel cover	permanent	religious	22.7204331, 75.8490658	http://swm-api.acceldash.com/uploads/reports/1681108226723.jpg

52	1	8	Choti Masjid Junarisala	kuan	government	brickwork	10	1.5	as per member present covered with slab nearby vaju area not able to view as said by the ones present	permanent	religious	22.7234844, 75.8504198	http://swm-api.acceldash.com/uploads/reposters/1681108275475.jpeg
53	1	8	Badi Masjid Junarisala	kuan	government	brickwork	10	2	covered with slab and steel cover	permanent	religious	22.7242495, 75.850093	http://swm-api.acceldash.com/uploads/reposters/1681108262432.jpeg
54	1	7	Hathile Hanuman Mandir Campus	kuan	government	brickwork	12	1.5	jaali covered parapret ok safai required	none	none	22.7272603, 75.8486202	http://swm-api.acceldash.com/uploads/reposters/1681108775995.jpeg
55	1	7	Dhola Kuwa	kuan	government	stone	20	5	malwa safai required jaali repair munder height required	none	none	22.7242604, 75.8501069	http://swm-api.acceldash.com/uploads/reposters/1681108780448.jpeg
56	1	7	A-15 Quarter VIP Route	kuan	government	brickwork	20	2	uncovered jaali required	none	none	22.7262799, 75.8434538	http://swm-api.acceldash.com/uploads/reposters/1681109324719.jpeg
57	1	7	A-17 VIP Route Quarter	kuan	government	brickwork	12	4	jaali ok safai required	permanent	none	22.7265693, 75.8430041	http://swm-api.acceldash.com/uploads/reposters/1681109350190.jpeg
58	1	7	Gokulganj near shiv temple	kuan	government	brickwork	20	2	covered with grill cleaning required	none	none	22.7244124, 75.8424293	http://swm-api.acceldash.com/uploads/reposters/1681109114830.jpeg
59	1	7	Mahadev Mandir Hari Parvat Gaurav nagar ke peche	kuan	government	brickwork	12	1.5	jaali mhi hai parapret wall required	none	none	22.7223601, 75.8394489	http://swm-api.acceldash.com/uploads/reposters/1681110393195.jpeg
60	1	7	Kadabeen Lal Mandir ke paas	kuan	government	stone	12	2	Covered	permanent	none	22.7204505, 75.8424164	http://swm-api.acceldash.com/uploads/reposters/1681109749261.jpeg
61	1	16	scheme no.155	kuan	government	brickwork	18	8	brickwork and grill required	none	none	22.7479664, 75.8365374	http://swm-api.acceldash.com/uploads/reposters/168111188401.jpeg
62	1	4	infront of ratlam tower vip route	kuan	government	brickwork	5	2	filled with material not covered	none	none	22.7240418, 75.828004	http://swm-api.acceldash.com/uploads/reposters/168111439608.jpeg
63	2	6	बिजानस काँलोनी उद्यान	kuan	government	brickwork	12	4	maintenance required (-cleaning, colour, sign bord, nirmaly kund, green net, etc)	permanent	none	22.7221189, 75.8319413	http://swm-api.acceldash.com/uploads/reposters/168111845148.jpeg
64	2	6	test	kuan	government	roc	10	10	testing the software	temporary	residential	22.725866, 75.8951093	http://swm-api.acceldash.com/uploads/reposters/168111967808.jpeg
65	2	6	रामचन्द्र नगर मैन उद्यान	kuan	government	brickwork	18	9	required maintenance work :-cleaning work ,green net , colour	none	none	22.7213658, 75.8347229	http://swm-api.acceldash.com/uploads/reposters/168111227673.jpeg

66	2	6	hukumchand colony sarkari school kua	bawdi	government	brickwork	10	3		not required	temporary	religious	22.7264163, 75.8322122	https://swm-api.acceldash.com/uploads/reposters/168112333508.jpg
67	2	6	panchkuva shree Ram mandir infront of goushala	kuan	government	brickwork	15	3		cleaning steel work repair required	none	none	22.7198011, 75.8329347	http://swm-api.acceldash.com/uploads/reposters/168112468623.jpeg
68	2	6	panchkuva khedapati mandir kua	kuan	government	brickwork	15	2.5		not required	none	none	22.7178998, 75.8322389	http://swm-api.acceldash.com/uploads/reposters/168112905123.jpg
69	2	6	hansdas math bawdi piliyakhal	bawdi	private	stone	20	4	2	maintenance work required..	none	none	22.721543, 75.8354197	http://swm-api.acceldash.com/uploads/reposters/168112722911.jpeg
70	2	69	1/11 mahesh nagar	kuan	private	stone	12	2.5		safe	none	none	22.7165081, 75.8429887	http://swm-api.acceldash.com/uploads/reposters/16811313978.jpg
71	2	6	sitararam park kua	kuan	private	brickwork	15	5		steel work repair and cleaning work..	none	educational	22.7198984, 75.8398103	http://swm-api.acceldash.com/uploads/reposters/168113163551.jpeg
72	2	69	18/2 new mahesh nagar	kuan	private	stone	9	2.5		Maintenance required	none	none	22.7162318, 75.8365287	http://swm-api.acceldash.com/uploads/reposters/168113306457.jpeg
73	2	69	Old rajmohalla sabji mandir	kuan	government	stone	15	6		Maintenance required	none	none	22.7143801, 75.8446685	http://swm-api.acceldash.com/uploads/reposters/168113474089.jpeg
74	2	69	44, old rajmohalla	kuan	private	stone	12	2		Unsafe	none	none	22.7162994, 75.8448617	http://swm-api.acceldash.com/uploads/reposters/16811358122.jpeg
75	2	69	saranga sarees , govardhan chok , MT cloth market 15	kuan	government	stone	15	2		safe	none	none	22.7172191, 75.8479205	http://swm-api.acceldash.com/uploads/reposters/168113775885.jpg
76	2	69	Govardhan nath mandir, yashwant road	kuan	private	stone	25	2.5		Safe	none	none	22.71805, 75.84813	http://swm-api.acceldash.com/uploads/reposters/168114311169.jpeg
77	2	69	Govardhan nath mandir , yashwant road	kuan	private	stone	12	2	2	Safe	none	none	22.7182197, 75.8473947	http://swm-api.acceldash.com/uploads/reposters/168115004630.jpeg
78	2	70	Indreshwar mahadev mandir adish indra nagar	kuan	government	brickwork	12	4	4	maintenance required	none	none	22.711944, 75.8328775	http://swm-api.acceldash.com/uploads/reposters/168115903398.jpeg
79	2	69	south yashwant ganj near naveen chitra talkies	kuan	private	stone	15	2.5		Unsafe	none	none	22.71805, 75.84813	http://swm-api.acceldash.com/uploads/reposters/16811623951.jpeg
80	2	70	190 loknayar nagar	kuan	government	brickwork	15	4	4	maintenance required	none	none	22.7131021, 75.8336038	http://swm-api.acceldash.com/uploads/reposters/16811689111.jpeg

81	2	70	jila hospital campus	kuan	government	brickwork	15	4	4	no	none	none	22.7131021, 75.8336038	http://swm-api.acceldash.com/uploads/revisers/168111697284.jpg
82	2	69	maneshwari panchayat trust gorakund	bawdi	private	stone	10	20	8	unsafe	permanent	commercial	22.71919, 75.8495233	http://swm-api.acceldash.com/uploads/revisers/1681117252366.jpg
83	2	69	tulidas ram mandir, khajuri bajar mg road	kuan	private	stone	15	1.5		Maintenance required	none2	none	22.7193956, 75.8495823	http://swm-api.acceldash.com/uploads/revisers/1681117395993.jpg
84	2	69	8.pipli bajar	kuan	private	stone	12	2.5		unsafe	permanent	commercial	22.7191395, 75.851407	http://swm-api.acceldash.com/uploads/revisers/1681117776384.jpg
85	2	69	narsingh tower, narsingh bajar chouraha	kuan	government	stone	10	2		unsafe	tempo-ary	commercial	22.7156104, 75.8496528	http://swm-api.acceldash.com/uploads/revisers/1681118018293.jpg
86	2	67	6/1 ramkrishna mandir, chhattribagh	kuan	private	stone	10	1.5		Safe	none	none	22.7124356, 75.8494237	http://swm-api.acceldash.com/uploads/revisers/1681118072398.jpg
87	2	67	50. chhattribagh (mahishi dadichi dharmshala)	kuan	private	stone	12	2.5		Safe	none	none	22.7090487, 75.8481198	http://swm-api.acceldash.com/uploads/revisers/1681118259108.jpg
88	2	67	baake bihari mandir, chhattribagh	kuan	government	stone	12	2		Maintenance required	none	none	22.7106675, 75.8497965	http://swm-api.acceldash.com/uploads/revisers/1681117863999.jpg
89	2	67	vyankatesh mandir, chhattribagh	kuan	private	stone	10	2		Maintenance required	none	none	22.711641, 75.851051	http://swm-api.acceldash.com/uploads/revisers/1681118616921.jpg
90	2	67	shree agni akhada Hanuman mandir(ramjhiri), chhattribagh	kuan	private	brickwork	9	2	2	Safe	none	none	22.7093413, 75.851418	http://swm-api.acceldash.com/uploads/revisers/1681118713233.jpg
91	2	67	nayo ki bagichi, jaipur pool ke pass, chhattribagh	kuan	private	brickwork	9	2	2	Safe	none	none	22.7097021, 75.8519324	http://swm-api.acceldash.com/uploads/revisers/1681119270292.jpg
92	2	67	59/1 kirti apartment, chhattribagh	kuan	private	stone	9	2		Maintenance required	permanent	residential	22.7107128, 75.8497303	http://swm-api.acceldash.com/uploads/revisers/1681119778555.jpg
93	2	67	narsing mandir, sai mandir ke pass chhattribagh	kuan	private	brickwork	12	2		unsafe	permanent	religious	22.7101716, 75.8495847	http://swm-api.acceldash.com/uploads/revisers/1681119803688.jpg
94	2	67	shree rameshwar mahadev mandir, chhattribagh	kuan	private	brickwork	15	1.5		safe	none	none	22.7095776, 75.8495548	http://swm-api.acceldash.com/uploads/revisers/1681119949666.jpg
95	2	67	lakshmi vyankatesh mandir, rajput bagichi ke pass chhattribagh	kuan	private	brickwork	9	1		unsafe	none	none	22.7085338, 75.8496075	http://swm-api.acceldash.com/uploads/revisers/1681119833548.jpg

96	2	67	ramdwara, chhattribagh	kuan	private	brickwork	12	2		safe	none	none	22.7088961, 75.8478514	http://swm-api.acceldash.com/uploads/revisers/1681120550745.jpeg
97	2	67	maruti mandir, bara bhai	kuan	private	brickwork	10	2		safe	none	none	22.7066811, 75.84705	http://swm-api.acceldash.com/uploads/revisers/1681120524333.jpeg
98	2	67	shaligram ka bagicha, arjuna pura laibagh k samne	kuan	government	brickwork	15	5		safe	none	none	22.7065947, 75.8463143	http://swm-api.acceldash.com/uploads/revisers/1681120727121.jpeg
99	2	69	bhakti prahalad nagar udhyan	kuan	government	brickwork	12	2		safe	none	none	22.7066851, 75.8469672	http://swm-api.acceldash.com/uploads/revisers/1681120751804.jpeg
100	2	67	trishala apartment, biyabani	kuan	private	brickwork	12	2.5		safe	none	none	22.7118378, 75.8469574	http://swm-api.acceldash.com/uploads/revisers/1681120595906.jpeg
101	2	6	Neeru nagar road no. 08 jairam kol ke makan ke samne	kuan	government	stone	20	5	5	safe	temporary	none	22.7352684, 75.8850771	http://swm-api.acceldash.com/uploads/revisers/1681121476435.jpeg
102	2	69	parasrampuria school sonuth rajmohalla	kuan	private	stone	20	3	4	unsafe	permanent	educational	22.714734, 75.8443355	http://swm-api.acceldash.com/uploads/revisers/1681121568233.jpeg
103	2	67	छोबीरा हनुमान चौक हनुमान मंदिर सहित	kuan	private	stone	10	1.5		unsafe	permanent	religious	22.7096705, 75.8484757	http://swm-api.acceldash.com/uploads/revisers/1681121520235.jpeg
104	3	56	kachi mohalla jyoti cinema ke samne	kuan	government	stone	45	15		disilting and dewatering	none	none	22.724753, 75.8619285	http://swm-api.acceldash.com/uploads/revisers/1681121807607.jpeg
105	3	56	kachi mohalla near hajari center	kuan	government	stone	12	3		dewatering disilting and new jaali	none	none	22.7250524, 75.8664923	http://swm-api.acceldash.com/uploads/revisers/1681121959461.jpeg
106	3	57	shram ayukt karyalay ke pas	kuan	government	stone	18	3		dewatering disilting and new jaali fitting	none	none	22.7250524, 75.8664923	http://swm-api.acceldash.com/uploads/revisers/16811222763068.jpeg
107	3	57	District court	kuan	government	stone	20	3	3	Desilting and dewatering of well and changing old damage jaali	none	none	22.7197004, 75.8648656	http://swm-api.acceldash.com/uploads/revisers/1681122369334.jpeg
108	3	57	Gopeshwar mahadev mandir gandhi hail	kuan	private	stone	15	3		disilting	none	none	22.7250324, 75.8664923	http://swm-api.acceldash.com/uploads/revisers/1681122504073.jpeg
109	3	56	Central jali hanuman mandir ke pas	kuan	government	stone	22	5		Desilting & dewatering of well	none	none	22.7197844, 75.8659774	http://swm-api.acceldash.com/uploads/revisers/1681122715164.jpeg
110	3	56	Srinath Niketan, Snehataganj Gali no.3	kuan	private	stone	25	4		4 no of flats are constructed above well	permanent	residential	22.7277743, 75.8645929	http://swm-api.acceldash.com/uploads/revisers/1681121174883.jpeg

111	3	56	Central Jail Shiv mandir ke पास	kuan	government	stone	15	5		Desilting & dewatering of well at present, above slab is damaged by govt authority	none	none	22.7277743, 75.8645929	http://swm-api.acceldash.com/uploads/reposters/1681123762916.jpg
112	3	56	humpy dumply school ke samne	kuan	government	stone	25	7			none	none	22.7277743, 75.8645929	http://swm-api.acceldash.com/uploads/reposters/1681123613920.jpg
113	3	57	narayan bag bawdi	bawdi	government	rcc	20	12	12	dewatering and disilting and painting	none	none	22.7271017, 75.8642257	http://swm-api.acceldash.com/uploads/reposters/168112996437.jpg
114	3	57	Lodhi mohalla shiv mandir ke पास	kuan	government	stone	15	3		Desilting and dewatering required	none	none	22.7204717, 75.8624957	http://swm-api.acceldash.com/uploads/reposters/1681123079733.jpg
115	3	57	35, Miewati mohalla	kuan	private	stone	10	3		Verandah constructed on well by cement concrete slab. Slab dismantle and cover with jaali	permanant	residential	22.7204717, 75.8624957	http://swm-api.acceldash.com/uploads/reposters/1681123170399.jpg
116	3	56	Kacchi mohalla Lal kuan	kuan	government	stone	15	4		Desilting and dewatering required	none	none	22.7223907, 75.8629203	http://swm-api.acceldash.com/uploads/reposters/1681123304109.jpg
117	3	57	Mewati mohalla masjid	kuan	private	stone	7	3		Slab and wall constructed	permanent	religious	22.7229578, 75.8639263	http://swm-api.acceldash.com/uploads/reposters/1681123357952.jpg
118	3	56	Inside Ganesh Mandal	kuan	private	stone	18	4		Slab Constructed on well	permanent	none	22.7229531, 75.863258	http://swm-api.acceldash.com/uploads/reposters/1681123514782.jpg
119	3	57	Jail road shiv mandir	bawdi	private	stone	15	4	5	Temple construction on well	permanent	religious	22.7263553, 75.8627287	http://swm-api.acceldash.com/uploads/reposters/1681123974981.jpg
120	3	57	Heera bawdi pologround	bawdi	government	stone	20	15	15	Desilting and dewatering required	none	none	22.731293, 75.8573256	http://swm-api.acceldash.com/uploads/reposters/1681123919475.jpg
121	3	58	Sedar bazar masin road Bhoot bawdi	bawdi	government	stone	20	20	20	Desilting and dewatering required	none	none	22.7399685, 75.853878	http://swm-api.acceldash.com/uploads/reposters/168112420431.jpg
122	3	58	sadar bazar masjid	kuan	private	stone	10	3		slab work on well	permanent	religious	22.7301685, 75.8492194	http://swm-api.acceldash.com/uploads/reposters/1681124772249.jpg
123	3	58	sadar bazar shiv mandir ke samne	kuan	private	stone	10	3		cleaning and new jaali	none	none	22.7273744, 75.8519862	http://swm-api.acceldash.com/uploads/reposters/1681124626353.jpg
124	3	58	Bakshibag Bawdi	bawdi	government	stone	20	15	30	Desilting and dewatering required and jaali required	none	none	22.7271229, 75.8512519	http://swm-api.acceldash.com/uploads/reposters/1681124988754.jpg
125	3	56	rajkumar mandi near compost	kuan	government	stone	25	12		dewatering disilting and jaali	none	none	22.7342184, 75.8659225	http://swm-api.acceldash.com/uploads/reposters/1681125249103.jpg

126	3	56	Rajkumar mandir Sheelinath camp well	kuan	private	stone	18	4		Desilting and dewatering required	none	none	22.7313971, 75.8571681	http://swm-api.acceldash.com/uploads/repositories/1681125516967.jpeg
127	3	56	Rajkumar Mandi Sheelinath camp bawdi	bawdi	private	stone	6	3	5	Jali required	none	none	22.7363715, 75.8655594	http://swm-api.acceldash.com/uploads/repositories/1681125552395.jpeg
128	3	57	DRP line shiv mandir ke pas	kuan	government	stone	25	7		new construction work with jaali and cleaning required	none	none	22.7316416, 75.8615654	http://swm-api.acceldash.com/uploads/repositories/16811259561388.jpeg
129	3	57	DRP line near open gym	kuan	government	stone	15	3		RCC work and jaali and cleaning required	none	none	22.7316416, 75.8615654	http://swm-api.acceldash.com/uploads/repositories/1681125947769.jpeg
130	3	57	Rambag near 15 no.govt.school	kuan	government	stone	15	4		Desilting and dewatering required	none	none	22.7319081, 75.8604761	http://swm-api.acceldash.com/uploads/repositories/1681126005867.jpeg
131	3	57	Malhar Ashram Bawdi	bawdi	government	stone	20	15	15	desilting and dewatering required	none	none	22.7246991, 75.8532138	http://swm-api.acceldash.com/uploads/repositories/1681126429337.jpeg
132	4	13	mataji ka bagicha scheme no. 51	kuan	government	brickwork	20	5		not required	none	none	22.7415203, 75.8358099	http://swm-api.acceldash.com/uploads/repositories/1681126452500.jpeg
133	4	13	sector-c well	kuan	government	brickwork	20	12		not required	none	none	22.7370524, 75.8389573	http://swm-api.acceldash.com/uploads/repositories/1681126463797.jpeg
134	4	13	laximpuri near ram mandir	kuan	government	brickwork	18	5		not required	none	none	22.7344899, 75.8425877	http://swm-api.acceldash.com/uploads/repositories/1681126927276.jpeg
135	4	10	natveshwar mahadev Mandir	kuan	government	rcc	70	4	70	naveshwar mahadev mandir free ganj	none	none	22.7350653, 75.8493219	http://swm-api.acceldash.com/uploads/repositories/1681127151006.jpeg
136	4	10	labristan banganga	kuan	government	rcc	50	10	50	kachara	none	none	22.7363417, 75.8494347	http://swm-api.acceldash.com/uploads/repositories/1681127170354.jpeg
137	4	13	laxmbai anaj mandir pwnisar	kuan	government	brickwork	20	2		needs to be covered	none	none	22.7330733, 75.837261	http://swm-api.acceldash.com/uploads/repositories/1681127556082.jpeg
138	4	10	akhada banganga main road	kuan	government	rcc	50	10	50	shukha	none	none	22.7386715, 75.8496689	http://swm-api.acceldash.com/uploads/repositories/1681127484020.jpeg
139	4	13	laxmbai anaj mandir campus near m/s road	kuan	government	brickwork	12	4		needs to be covered & partially filled with garbage restoration required	none	none	22.7304739, 75.8371997	http://swm-api.acceldash.com/uploads/repositories/1681127819158.jpeg
140	4	10	laxmi bai nagar bheru baba mandeeder	kuan	government	rcc	70	7	70	shukha	none	none	22.7403346, 75.8503321	http://swm-api.acceldash.com/uploads/repositories/1681128291925.jpeg

141	4	10	4	10	choti kumar khadianganwadi	kuan	government	rcc	40	5	40	shukha	none	residential	22.7435949, 75.8519066	http://swm-api.acceldash.com/uploads/revisers/1681128555117.jpeg
142	4	10	4	10	banganga kund jim ke pass	kuan	government	rcc	50	20	50	shukha	none	residential	22.74419, 75.8488103	http://swm-api.acceldash.com/uploads/revisers/1681128503665.jpeg
143	4	13	4	13	laxmanpura in front of latubagh tigriya badshah road	kuan	government	brickwork	20	5	20	not required	none	none	22.7260437, 75.8441975	http://swm-api.acceldash.com/uploads/revisers/1681123242000.jpeg
144	4	10	4	10	hajri sentar ujjan naka	kuan	government	rcc	45	20	45	kachara bhara he	none	residential	22.7455637, 75.8461584	http://swm-api.acceldash.com/uploads/revisers/1681129059539.jpeg
145	4	10	4	10	babu parag kabhatta	kuan	private	rcc	50	12	50	kachara	none	commercial	22.7468583, 75.8496783	http://swm-api.acceldash.com/uploads/revisers/1681128575145.jpeg
146	4	10	4	10	braj lal vyam shala	kuan	government	rcc	50	12	50	pani	none	commercial	22.7374032, 75.8496477	http://swm-api.acceldash.com/uploads/revisers/1681130134087.jpeg
147	4	10	4	10	kushi aasrem Mahesh Yadav nagar	kuan	government	rcc	45	7	45	kachara	none	residential	22.7462938, 75.8503088	http://swm-api.acceldash.com/uploads/revisers/1681130568300.jpeg
148	4	11	4	11	bawdi basti bhagiratpura	bawdi	government	stone	20	12	20	needs to be covered, raising wall height, cleaning & restoration work	none	none	22.7454188, 75.8603392	http://swm-api.acceldash.com/uploads/revisers/168113140723.jpeg
149	4	11	4	11	rafeli community aanganwadi & shani mandir campus	kuan	government	brickwork	18	2	18	not required	none	none	22.7454188, 75.8603392	http://swm-api.acceldash.com/uploads/revisers/1681185977439.jpeg
150	4	11	4	11	manindra jain mithai shop 484 bhagirathpura	kuan	private	brickwork	15	2	15	not required	none	none	22.7463296, 75.8600484	http://swm-api.acceldash.com/uploads/revisers/1681186509330.jpeg
151	4	11	4	11	mohan bagdi steel railing works in front of sachin paan near tejaji mandir	kuan	private	brickwork	18	4	18	covered jali maintenance required	none	none	22.7467718, 75.862132	http://swm-api.acceldash.com/uploads/revisers/1681186748878.jpeg
152	4	11	4	11	kashyap house behind hanuman mandir main road bhagirath pura	kuan	private	brickwork	18	4	18	not required	temporary	none	22.7470779, 75.8631252	http://swm-api.acceldash.com/uploads/revisers/168118698946.jpeg
153	4	11	4	11	khatik samaj dharmshala inside premise	kuan	private	brickwork	18	3	18	unsafe/slab needs to be dismantled & fixed by steel jali	none	commercial	22.7491593, 75.8619285	http://swm-api.acceldash.com/uploads/revisers/1681187019638.jpeg
154	4	12	4	12	govind col. gully no.2	kuan	government	brickwork	18	5.5	18	wire mesh reqd.	none	none	22.7415858, 75.847134	http://swm-api.acceldash.com/uploads/revisers/1681187486983.jpeg
155	4	12	4	12	savriya Seth mndir.govind col.	kuan	government	brickwork	21	4.5	21	wall rep.pistr.reqd.	none	none	22.741357, 75.8454211	http://swm-api.acceldash.com/uploads/revisers/1681187577182.jpeg

156	4	17	kushvah shree ngr.	kuan	private	brickwork	21	4.5		wall rep.reqd.	none	none	22.7471358, 75.8403807	http://swm-api.acceldash.com/uploads/revisers/1681187564230.jpeg
157	4	17	kushvah ngr.near purv parshad house	kuan	private	brickwork	18	6		wall rep.reqd.	none	none	22.7484732, 75.8427526	http://swm-api.acceldash.com/uploads/revisers/1681187884851.jpeg
158	4	12	maharana pratap ngr.tanki/goshala mandir	bawdi	government	stone	15	4.5	4.5	steel jali reqd.	none	none	22.747256, 75.8488563	http://swm-api.acceldash.com/uploads/revisers/1681187992476.jpeg
159	4	12	baneshvr mahadev mandir-ujain Indore road	bawdi	government	stone	7.5	9	12	wire mesh reqd.	none	none	22.7457154, 75.8493438	http://swm-api.acceldash.com/uploads/revisers/168118847414.jpeg
160	4	17	vijawarpiya ngr.Ram mandir	kuan	government	brickwork	24	3		prpt wall rising reqd.	none	none	22.7527624, 75.8412303	http://swm-api.acceldash.com/uploads/revisers/1681188740350.jpeg
161	4	11	chargiri kua mandir	kuan	private	brickwork	15	2		insice temple premise	permanent	religious	22.747501, 75.863744	http://swm-api.acceldash.com/uploads/revisers/1681189114950.jpeg
162	4	17	new Ram ngr. shiv mandir.	kuan	government	brickwork	18	6		prpt wall reqd. & steel jali reqd.	none	none	22.7566851, 75.8337436	http://swm-api.acceldash.com/uploads/revisers/1681189993517.jpeg
163	4	17	prjapaty dharmshala,dashrath bagh	kuan	private	brickwork	18	4.5		wire mesh reqd. & steel jali reqd.	none	none	22.7500033, 75.83169	http://swm-api.acceldash.com/uploads/revisers/1681190328858.jpeg
164	4	12	shiv mandir rajaram ngr gully no.2	kuan	government	brickwork	15	6		wire mesh reqd.	none	none	22.7462017, 75.84087	http://swm-api.acceldash.com/uploads/revisers/1681190603247.jpeg
165	4	11	bhagrathpura near mamaji ka bhaita	kuan	private	brickwork	15	2		to be covered steel jali	none	none	22.74923, 75.8586605	http://swm-api.acceldash.com/uploads/revisers/1681190857153.jpeg
166	5	22	M 35/A veena nagar main road triloksvar mandir	kuan	government	brickwork	22	6	6	covered with jali and parapet walk (sate)	none	none	22.7588318, 75.8689601	http://swm-api.acceldash.com/uploads/revisers/1681191254105.jpeg
167	5	21	492 shyam nagar main,	kuan	government	brickwork	24	5	5	covered with jali and parapet wall(sate)	none	none	22.7591032, 75.8694746	http://swm-api.acceldash.com/uploads/revisers/168119180943.jpeg
168	5	21	59 sundar nagar Ext. ke same	kuan	government	brickwork	20	6	6	covered with jali and parapet wall(sate)	none	none	22.7594703, 75.867991	http://swm-api.acceldash.com/uploads/revisers/1681192031942.jpeg
169	5	22	love kush E sector bandan gardn	kuan	government	brickwork	17	7	7	jali repairiy required	permanent	religious	22.7608573, 75.8693542	http://swm-api.acceldash.com/uploads/revisers/1681192465360.jpeg
170	5	22	E71 love kush and sabri g.sectar	kuan	government	brickwork	16	7	7	covered with jali and parapet wall (sate)	none	none	22.7608334, 75.8721477	http://swm-api.acceldash.com/uploads/revisers/1681192605472.jpeg

171	5	22	sukhiya C sector hanuman mandir HDFC bank	kuan	government	brickwork	10	6	6	covered with jali and parapet wall (sate)	none	none	22.7604813, 75.8725913	http://swm-api.acceldash.com/uploads/reports/1681192958762.jpeg
172	5	22	Ravidas nagar main road	kuan	government	brickwork	15	4	4	covered with jali and parapet wall (sate)	none	none	22.7613239, 75.8717996	http://swm-api.acceldash.com/uploads/reports/1681193005392.jpeg
173	5	22	lalaa baba ka mandir hira nagar poolic thana	kuan	government	brickwork	6	2	2	covered with jali and parapet wall (sate)	none	none	22.7591818, 75.8728333	http://swm-api.acceldash.com/uploads/reports/168119327273.jpeg
174	5	33	ma sarda nagar ma sarda mandir sukhiya	kuan	government	brickwork	17	4	4	covered with Rcc slab in mandir campus	permanent	religious	22.7590365, 75.8748033	http://swm-api.acceldash.com/uploads/reports/1681193844366.jpeg
175	5	33	325 c m second sukhiya	kuan	government	brickwork	13	6	6	Jali Or parapet wall required	none	none	22.7653774, 75.8761578	http://swm-api.acceldash.com/uploads/reports/1681194655073.jpeg
176	5	22	murti wala sweet ke samne sukhiya main road	kuan	government	brickwork	16	6	6	covered with jali and parapet wall (sate)	none	none	22.7617025, 75.8758663	http://swm-api.acceldash.com/uploads/reports/1681195259814.jpeg
177	5	28	megdud gardan music faunten ke pass	kuan	government	brickwork	13	7	7	Jali repairs or parapet repairing required	none	none	22.7545284, 75.8792254	http://swm-api.acceldash.com/uploads/reports/1681196098714.jpeg
178	5	28	megdud gardan ke andar	kuan	government	stone	13	7	7	covered with jali and parapet wall (sate)	none	none	22.7502856, 75.8841774	http://swm-api.acceldash.com/uploads/reports/1681203146516.jpeg
179	5	28	megdud gardan ke andar mandir ke pass	kuan	government	stone	13	6	6	covered with jali and parapet wall (sate)	none	none	22.7510551, 75.8889505	http://swm-api.acceldash.com/uploads/reports/1681203636703.jpeg
180	5	28	megdud Nagar gali no. 9 nagashvar mhadev mandir	kuan	government	brickwork	14	5	5	covered with R C C . slab in mandir campus	permanent	religious	22.7510551, 75.8889505	http://swm-api.acceldash.com/uploads/reports/1681204361257.jpeg
181	5	28	megdud Nagar gali no. 2 sitla mata mandir	kuan	government	brickwork	15	6	6	covered with R C C . slab in mandir campus,	permanent	religious	22.7509279, 75.8831975	http://swm-api.acceldash.com/uploads/reports/1681204895665.jpeg
182	5	28	Medium Nagar gali no. 12	kuan	government	brickwork	15	4	4	covered with jali and parapet wall (sate)	none	none	22.7506634, 75.8829831	http://swm-api.acceldash.com/uploads/reports/1681205695659.jpeg
183	5	28	Kelash ka bhatta Bajrang mandir	kuan	government	stone	12	5	5	Jali repairs or parapet repairing required	none	none	22.7479836, 75.885204	http://swm-api.acceldash.com/uploads/reports/1681206464576.jpeg
184	5	28	badi bhemori sindhi ka kuwa	kuan	government	brickwork	12	4	4	covered with R C C . slab in mandir campus	per-manent	religious	22.7476304, 75.8849731	http://swm-api.acceldash.com/uploads/reports/1681211678300.jpeg
185	5	28	mali samaj ki bensi bhamori sarkari school	kuan	government	brickwork	12	3	3	covered with jali and parapet wall (sate)	none	none	22.7476304, 75.8849731	http://swm-api.acceldash.com/uploads/reports/1681212003770.jpeg

186	5	22	hira nagar basti punm hardiya ke piche	kuan	government	brickwork	9	3	3	covered with R.C.C. slab in mandir campus	none	none	22.7587327, 75.868919	http://swm-api.acceldash.com/uploads/re-gisters/1681213134776.jpg
187	5	28	shiv sakti nagar gaytri mandie	kuan	government	brickwork	12	3	3	jali required	permanent	religious	22.7474149, 75.8884632	http://swm-api.acceldash.com/uploads/re-gisters/1681213909666.jpg
188	5	28	shiv sakti nagar shiv mandir bagicha	kuan	government	brickwork	15	7	7	covered with jali and parapet wall (sate)	permanent	religious	22.7474149, 75.8884632	http://swm-api.acceldash.com/uploads/re-gisters/1681214989288.jpg
189	5	22	AM sector sukhiya pipleshwar mhaddev mandir	kuan	government	brickwork	14	6	6	covered with jali and parapet wall (sate)	none	religious	22.7553899, 75.8758185	http://swm-api.acceldash.com/uploads/re-gisters/1681214989288.jpg
190	6	25	pakki chal main road	kuan	government	rcc	50	15.2	15.2	safe and covered	permanent	religious	22.7421303, 75.8674768	http://swm-api.acceldash.com/uploads/re-gisters/1681216140904.jpg
191	6	24	pipal ki chal	kuan	government	stone	32.5	15.6	15.6	safe and covered	none	none	22.7415839, 75.8653061	http://swm-api.acceldash.com/uploads/re-gisters/1681216560884.jpg
192	6	24	Kulkarni bhaitia nayi basti	kuan	government	brickwork	25.5	10	10	totally unsafe and need to construct wall for and steel work for cover.	none	none	22.7416536, 75.8635336	http://swm-api.acceldash.com/uploads/re-gisters/168121673551.jpg
193	6	26	nehru nagar road no 08 near Mahadev temple	kuan	government	stone	20	5	5	Safe (slab removed on 04.04.2023)	none	none	22.7352684, 75.8850771	http://swm-api.acceldash.com/uploads/re-gisters/168121673551.jpg
194	6	26	Nehru nagar Road no 04 near temple	kuan	government	stone	20	5	5	Safe	none	none	22.7355244, 75.8829502	http://swm-api.acceldash.com/uploads/re-gisters/1681278156083.jpg
195	6	26	Nehru nagar Road no 04	kuan	government	rcc	20	5	5	Safe	none	none	22.7355244, 75.8829502	http://swm-api.acceldash.com/uploads/re-gisters/1681278156083.jpg
196	6	26	Nehru nagar inside laiapura temple campus	kuan	government	brickwork	20	5	5	Safe	none	none	22.7354006, 75.8799538	http://swm-api.acceldash.com/uploads/re-gisters/1681281674694.jpg
197	6	26	Patrapura main road basti	kuan	government	stone	20	4	4	Safe	none	none	22.7365263, 75.878784	http://swm-api.acceldash.com/uploads/re-gisters/1681282156506.jpg
198	6	25	Janta Quarter Main road inside Garden	kuan	private	brickwork	15	4	4	Safe	none	none	22.741033, 75.878784	http://swm-api.acceldash.com/uploads/re-gisters/1681282557001.jpg
199	6	25	Janta Quarter inside motibaba Garden	kuan	government	stone	10	4	4	Safe	none	none	22.741033, 75.8767357	http://swm-api.acceldash.com/uploads/re-gisters/1681282901038.jpg
200	6	25	Manda nagar post office Garden	kuan	government	brickwork	20	5	5	Safe	none	none	22.7439918, 75.8769985	http://swm-api.acceldash.com/uploads/re-gisters/1681283128110.jpg

201	6	25	Nanda nagar Jhanda chowk garden	kuan	government	brickwork	20	5	5	Slab covered over well which is situated in front of shiv mandir inside jhanda chowk garden.	permanent	religious	22.7427608, 75.879527	http://swm-api.acceldash.com/uploads/re-gisters/16812892954066.jpg
202	6	25	Nanda nagar Road no 13 govt. school ke saamna shiv mandir	kuan	government	brickwork	15	4	4	safe, cleaning required	none	none	22.7427383, 75.8794766	http://swm-api.acceldash.com/uploads/re-gisters/16812876184478.jpg
203	6	25	Nanda nagar behind gurudwara	kuan	government	brickwork	12	5	5	Safe, maintenance required	none	none	22.7405392, 75.881615	http://swm-api.acceldash.com/uploads/re-gisters/1681287378247.jpg
204	6	25	Nanda nagar road no 08 vijeshwar mandir	kuan	government	brickwork	20	5	5	Covered with slab, inside temple campus open area	permanent	religious	22.740686, 75.881432	http://swm-api.acceldash.com/uploads/re-gisters/1681287649365.jpg
205	6	25	Nanda nagar road no 08 vijeshwar mandir	kuan	government	brickwork	20	5	5	Covered with slab, inside temple campus open area	permanent	religious	22.740686, 75.881432	http://swm-api.acceldash.com/uploads/re-gisters/1681287855170.jpg
206	6	25	Nanda nagar, Road no 09, shiv mandir	kuan	government	brickwork	30	5	5	Covered by slab, situated inside temple activities area	permanent	religious	22.7441134, 75.8792991	http://swm-api.acceldash.com/uploads/re-gisters/1681288072172.jpg
207	6	27	Nanda nagar siliamata mandir Garden	kuan	government	brickwork	15	4	4	Half covered with slab, Maintenance required	permanent	religious	22.7447762, 75.8808941	http://swm-api.acceldash.com/uploads/re-gisters/1681289623114.jpg
208	6	27	Geeta bawdi hanuman mandir bajrang nagar	bawdi	government	stone	30	10	10	Very Unsafe, Bawdi is covered with slab and paver blocks are sinking also the place is used for activities and functions, Maintenance required urgently	permanent	religious	22.7481443, 75.883145	http://swm-api.acceldash.com/uploads/re-gisters/1681289097591.jpg
209	6	27	Nanda nagar, Chandan chowk garden	kuan	government	brickwork	20	4	4	Safe	none	none	22.7463408, 75.8780751	http://swm-api.acceldash.com/uploads/re-gisters/1681289769671.jpg
210	6	24	parshad office ke peeche	kuan	government	brickwork	35	5	5	safe maintenance required	none	none	22.7427163, 75.8664296	http://swm-api.acceldash.com/uploads/re-gisters/1681294307613.jpg
211	6	24	shivshakti nagar Kulkarni bhatta	kuan	government	brickwork	35	10	10	Totally unsafe uncovered civil work requirement.	none	none	22.739209, 75.864407	http://swm-api.acceldash.com/uploads/re-gisters/1681298196176.jpg
212	6	24	Shyama Charan Shukla nagar	kuan	government	brickwork	35	12	12	safe And covered.	none	none	22.7383005, 75.8656725	http://swm-api.acceldash.com/uploads/re-gisters/1681363092863.jpg
213	6	24	Mali mohalla	kuan	government	brickwork	10	5	5	unsafe need to be covered and Civil work requirement.	permanent	residential	22.7424819, 75.8653682	http://swm-api.acceldash.com/uploads/re-gisters/1681366595254.jpg

214	7	29	AD Mandloi Garden Scheme No. 74 C	kuan	government	brickwork	12	4	4	No Maintenance Required	none	none	22.7575019, 75.8864446	api.acceldash.com/uploads/re gisters/1681368138567.jpg
215	7	29	Panchmukhi Hanuman Mandir	kuan	government	brickwork	20	4	4	No Maintenance Required	none	none	22.7557873, 75.894666	api.acceldash.com/uploads/re gisters/1681368143007.jpg
216	7	32	Near Nari Masand	kuan	government	brickwork	10	4	4	No Maintenance Required	none	none	22.7593095, 75.897611	api.acceldash.com/uploads/re gisters/1681372807261.jpg
217	7	34	Bawdi Balaji Hanuman Mandir Scheme no 78	bawdi	government	brickwork	15	7	7	Jali Damaged, Jali Maintenance Required	none	none	22.7650481, 75.887336	api.acceldash.com/uploads/re gisters/1681377824244.jpg
218	7	29	Neelkantheshwar Mahadev Mandir Behind Jani Mandir Vijay nagar	kuan	government	brickwork	14	4	4	Unsafe, RCC Slab, Room Constructed on kuan	permanent	residential	22.765045, 75.8873412	api.acceldash.com/uploads/re gisters/16814469248281.jpg
219	7	29	Vijayeshwari Mata Mandir, Vijay Nagar	kuan	government	brickwork	15	4	4	Unsafe, Room Constructed On Kuan	permanent	residential	22.7544389, 75.8911285	api.acceldash.com/uploads/re gisters/16814469248281.jpg
220	7	29	Zone -08 Campus Vijay Nagar Square	kuan	government	brickwork	15	5	6	No Maintenance Required	none	none	22.7528769, 75.8955122	api.acceldash.com/uploads/re gisters/16814469248281.jpg
221	7	29	Manglit Bhawan, Vijay Nagar	kuan	government	brickwork	15	4	4	Unsafe, RCC Slab	permanent	commercial	22.750934, 75.8947683	api.acceldash.com/uploads/re gisters/1681448078782.jpg
222	8	35	Lasudiya Mori Gaon, Behind SS Infinitus	kuan	private	rcc	30	20	25	located in farm	none	none	22.7885516, 75.9297612	api.acceldash.com/uploads/re gisters/1681448192593.jpg
223	8	37	Tulsi nagar Maa Saraswati mandir ke pass	kuan	government	brickwork	24	4,5		Covered with jali	none	religious	22.752979, 75.9173989	api.acceldash.com/uploads/re gisters/1681448336473.jpg
224	8	37	Tulsi Nagar main road	kuan	government	rcc	30	5		Covered with jali	none	none	22.752979, 75.9173989	api.acceldash.com/uploads/re gisters/1681448600680.jpg
225	8	37	Behind Deep palace Palm green	kuan	government	rcc	21	4		covered with jali	none	none	22.752979, 75.9173989	api.acceldash.com/uploads/re gisters/1681448943505.jpg
226	8	30	Behind shreemaya hotel, malviya nagar gali no.02	kuan	government	rcc	24	6		Covered with jali	none	none	22.7494107, 75.8952609	api.acceldash.com/uploads/re gisters/1681448848565.jpg
227	8	30	Behind ghnger hotel Ayodhyepuri colony	kuan	government	rcc	24	6		Covered with jali	none	none	22.7381007, 75.8956181	api.acceldash.com/uploads/re gisters/1681449143183.jpg
228	8	37	Swarn bag colony Scheme 94	kuan	government	rcc	30	6		Covered with jali	none	none	22.7381007, 75.8956181	api.acceldash.com/uploads/re gisters/1681449150872.jpg

229	8	35	Panchwati main kuwa	kuan	government	brickwork	24	6.5		damaged parapet and jali required	none	none	22.7937912, 75.9028174	http://swm-api.acceldash.com/uploads/replisters/1681449280011.jpeg
230	8	35	Panchwati mandir garden ke samne	kuan	government	rcc	20	9		jali required	none	none	22.7943106, 75.9046032	http://swm-api.acceldash.com/uploads/replisters/1681449349623.jpeg
231	8	35	Talawali gaon near dream city	kuan	government	stone	18	5	6	jali required	none	none	22.7999096, 75.9112993	http://swm-api.acceldash.com/uploads/replisters/1681449385032.jpeg
232	8	35	Talawali hamman mandir Govt school	kuan	government	brickwork	15	6		Jali required	none	educational	22.7999096, 75.9112993	http://swm-api.acceldash.com/uploads/replisters/1681449618444.jpeg
233	8	35	bhagat Singh market AB road	kuan	private	brickwork	15	3		parapet and jali required	none	none	22.7858891, 75.9073307	http://swm-api.acceldash.com/uploads/replisters/1681449626367.jpeg
234	8	35	Lasudiya Mori Gaon anganwadi ke samne	kuan	government	brickwork	30	4		safe	none	none	22.7826972, 75.9070775	http://swm-api.acceldash.com/uploads/replisters/1681449810149.jpeg
235	8	30	Chandra nagar garden kuan	kuan	government	brickwork	18	6		parapet required	none	none	22.7414315, 75.8950917	http://swm-api.acceldash.com/uploads/replisters/1681449844005.jpeg
236	8	36	Arandiya Gaon	kuan	government	stone	30	3		safe	none	none	22.7950992, 75.9392135	http://swm-api.acceldash.com/uploads/replisters/1681449963586.jpeg
237	8	36	Mayakhedi Ram mandir ke pass	bawdi	government	stone	12	8	6	maintenance and jali required	none	none	22.7770727, 75.945944	http://swm-api.acceldash.com/uploads/replisters/1681450078503.jpeg
238	8	36	Mayakhedi gaon	kuan	government	brickwork	18	3		safe	none	none	22.7770727, 75.945944	http://swm-api.acceldash.com/uploads/replisters/1681450311594.jpeg
239	8	36	Amrit Palace garden	kuan	government	stone	24	5		Covered with jali	none	none	22.7678939, 75.9287705	http://swm-api.acceldash.com/uploads/replisters/1681450475373.jpeg
240	8	37	Nyay nagar garden	kuan	government	rcc	18	5		covered with jali	none	none	22.7466306, 75.9083136	http://swm-api.acceldash.com/uploads/replisters/1681450621868.jpeg
241	8	35	talawali talab ke pass	bawdi	private	rcc	12	9	7.5	Jali required	none	none	22.7996283, 75.9176661	http://swm-api.acceldash.com/uploads/replisters/1681450640137.jpeg
242	9	46	दीपिका मैदान	kuan	government	rcc	30	10	10	जारी लगवाना है ब्लॉक लगवाना है	permanent	residential	22.7335012, 75.8830808	http://swm-api.acceldash.com/uploads/replisters/16814506460374.jpeg
243	9	44	nadiya nagar gali no 45	kuan	government	rcc	20	5	4	1 रिपेयर करना है 2 जाली लगाना है 3 सफाई करवाना है 4 ग्रिन नेट लगानी है	permanent	residential	22.7101788, 75.8265463	http://swm-api.acceldash.com/uploads/replisters/1681450657347.jpeg

244	9	44	nadiya nagar gali no 1	kuan	government	rcc	25	6	6	1 साफ़ई करवाना है 2 हट्ट बढ़वाना है 3 जाली सही करनी है 4 बाउंडरी बनवाना है	religious	22.7099972, 75.8274298	http://swm- api.acceldash.com/uploads/re gisters/16814510871545.jpg
245	9	44	mig word office	kuan	government	rcc	30	6	6	1 जाली लगवाना है 2 साफ़ई करवाना है 3 कवर करवाना है	residential	22.7099972, 75.8274298	http://swm- api.acceldash.com/uploads/re gisters/16814510871545.jpg
246	9	44	jagjivan ram nagar	kuan	government	rcc	29	5	6	1 साफ़ई करवाना है 2 पुताई करवाना है	residential	22.7101767, 75.8365496	http://swm- api.acceldash.com/uploads/re gisters/1681451074804.jpg
247	9	44	chanor nagar sector b	kuan	government	rcc	30	5	5	1 साफ़ साफ़ई 2 जाली लगाना है 3 नेट लगाना है	residential	22.7099972, 75.8274298	http://swm- api.acceldash.com/uploads/re gisters/1681451011249.jpg
248	9	46	3 गुडी	kuan	government	rcc	55	5	5	1 साफ़ साफ़ई करना है 2 जाली लगाना है	religious	22.7301975, 75.8807067	http://swm- api.acceldash.com/uploads/re gisters/1681451247596.jpg
249	9	46	3 गुडी	kuan	government	rcc	55	5	5	1 साफ़ साफ़ई करवाना है 2 जाली लगवाना है 3 कवर करवाना है	religious	22.7301975, 75.8807067	http://swm- api.acceldash.com/uploads/re gisters/1681451300908.jpg
250	9	44	choi khajrani hanuman mandir prishar	kuan	government	rcc	12	4	5	1 साफ़ साफ़ई करवाना है 2 रिपेयर 3 कवर करवाना है	educational	22.7101784, 75.8265554	http://swm- api.acceldash.com/uploads/re gisters/1681451540756.jpg
251	9	45	dev nagar gali no.01	kuan	government	rcc	20	5	5	1) cleaning of well 2) grill work 3) green net coverage 4) other civil maintenance work	none	22.7381364, 75.8811715	http://swm- api.acceldash.com/uploads/re gisters/1681451525221.jpg
252	9	45	panchu kumar ki chai	kuan	government	rcc	18	2.5	18	1) cleaning of well from dewatering 2) grill work. repair 3) green net coverage 4) other civil maintenance work	none	22.7381364, 75.8811715	http://swm- api.acceldash.com/uploads/re gisters/1681451559812.jpg
253	9	45	inside Sanchi Shikhar apartment	kuan	government	rcc	22	5	22	1) cleaning of well 2) grill work 3) green net coverage 4) other civil maintenance work	residential	22.7381364, 75.8811715	http://swm- api.acceldash.com/uploads/re gisters/1681451542512.jpg
254	9	45	A sector MIG kanakeshwari yog kendra	kuan	government	rcc	20	5	20	1) cleaning of well 2) grill work 3) green net coverage 4) other civil maintenance work	commercial	22.7378227, 75.8845777	http://swm- api.acceldash.com/uploads/re gisters/1681451662979.jpg

255	9	45	lala ka bagicha behing Hanuman ji temple	kuan	government	rcc	22	5	0.8	1) cleaning of well 2) grill work 3) green net coverage 4) other civil maintenance work	permanent	residential	22.7378322, 75.6845912	http://swm-api.acceldash.com/uploads/repositories/1681451286128.jpg
256	9	45	lala ka bagicha chota kua	kuan	government	rcc	25	3	2.5	1) cleaning of well with dewatering and desilting 3) green net coverage 4) other civil maintenance work	permanent	religious	22.7378517, 75.8945844	http://swm-api.acceldash.com/uploads/repositories/1681451688401.jpg
257	9	45	lala ka bagicha bada kua	kuan	government	rcc	25	5		1) cleaning of well 2) grill work repair 3) green net coverage 4) boundary wall construction with steel railing 5) other civil maintenance work	none	none	22.7381364, 75.8811715	http://swm-api.acceldash.com/uploads/repositories/1681451876284.jpg
258	9	45	A sector MIG inside Hanuman temple	kuan	government	rcc	22	5		1) cleaning of well 2) grill work 3) green net coverage 4) other civil maintenance work	none	none	22.7378475, 75.8845572	http://swm-api.acceldash.com/uploads/repositories/1681451973239.jpg
259	9	47	Ahilya Mata Colony garden	kuan	government	stone	22	7		Covered with Jaali	none	none	22.7300971, 75.8724698	http://swm-api.acceldash.com/uploads/repositories/1681451973239.jpg
260	9	47	In front of Upadhyay Mess, Dubey ka Bagicha	kuan	government	brickwork	15	3		Cleaning of well and Jaali required	none	none	22.7302766, 75.8720675	http://swm-api.acceldash.com/uploads/repositories/1681451885118.jpg
261	9	47	Near Kushwah cycle shop, Dubey ka Bagicha	kuan	government	stone	11	6	8	cleaning, Jaali and repairing required	permanent	religious	22.7294848, 75.8706415	http://swm-api.acceldash.com/uploads/repositories/1681452047214.jpg
262	9	47	In front of Victoria Urban, Vallabh Nagar	bawdi	government	stone	12	10	10	Unsafe, cleaning and maintenance required	permanent	commercial	22.7271293, 75.8898642	http://swm-api.acceldash.com/uploads/repositories/1681452094714.jpg
263	9	47	Brijeshwar Shiv Mandir, Near Rajkumar bridge	kuan	government	stone	16	7	7	covered with Jaali	none	none	22.7304028, 75.8710882	http://swm-api.acceldash.com/uploads/repositories/1681452238419.jpg
264	9	47	In front of Panchmukhi Hanuman mandir, Scheme no. 91	kuan	government	rcc	18	6		covered with Jaali	none	none	22.7302869, 75.8709129	http://swm-api.acceldash.com/uploads/repositories/1681452156695.jpg
265	9	47	Below Shiv Mandir, Gali no 3, Goma ki fel	kuan	government	brickwork	10	3		covered with slab	none	religious	22.7329175, 75.8763705	http://swm-api.acceldash.com/uploads/repositories/1681452270855.jpg

266	9	47	Near Vijay Asta Chakki, Gali no 3, Goma ki fal	kuan	government	stone	9	3		Cleaning, maintenance required	none	none	22.7329574, 75.8771266	api.acceldash.com/uploads/re gisters/168145250532.jpeg http://swm
267	9	47	Sterling Arcade, 15/3 Race Course road	kuan	private	stone	17	7.5		covered with slab	permanent	commercial	22.7262006, 75.8786614	api.acceldash.com/uploads/re gisters/1681452366081.jpeg http://swm
268	9	47	Shivam Apartment, Chain Singh ka Bagicha	kuan	private	brickwork	6	2		covered with Jaali	none	none	22.7261963, 75.8786386	api.acceldash.com/uploads/re gisters/1681452365738.jpeg http://swm
269	9	47	Near Shiv Mandir, Harijan basti, Palasia	kuan	government	rcc	8.5	2.5		covered with Jaali	none	none	22.7284923, 75.8829785	api.acceldash.com/uploads/re gisters/1681452508274.jpeg http://swm
270	9	47	Near Urvasi Kirana Store, Harijan Basti, Palasia	kuan	government	stone	21	4.5		Jaali and civil work maintenance	none	none	22.725523, 75.8866374	api.acceldash.com/uploads/re gisters/1681452733610.jpeg http://swm
271	9	47	N M tower, 56 dukaan	kuan	private	stone	12	5.5		covered with slab	permanent	commercial	22.7254201, 75.8832877	api.acceldash.com/uploads/re gisters/1681452829675.jpeg http://swm
272	9	47	Chetak vihar, 56 dukaan	kuan	private	stone	15	5		covered with slab	permanent	residential	22.7252401, 75.8834282	api.acceldash.com/uploads/re gisters/1681452839384.jpeg http://swm
273	9	46	पंचम कि फौल बड़े अखाड़े के पास	kuan	government	rcc	420	8	8	बलीन करना है और height बढ़ाना है कलर करना है	temporary	residential	22.7298851, 75.8809796	api.acceldash.com/uploads/re gisters/1681452933065.jpeg http://swm
274	9	46	सिंधी चौक पंचम की फौल	kuan	government	rcc	450	8	8	पूरा रिपेयर कराना है जाली लगनी है कलर कराना है	temporary	residential	22.7309159, 75.879377	api.acceldash.com/uploads/re gisters/1681452955084.jpeg http://swm
275	9	46	पंचम की फौल शितला माला मंदिर के पास	kuan	government	rcc	350	5	8	जाली लगाना है और कलर करना है	temporary	residential	22.7293338, 75.8815747	api.acceldash.com/uploads/re gisters/1681453145863.jpeg http://swm
276	9	46	पंचम की फौल	kuan	government	rcc	350	6	6	पूरा रिपेयर कराना है जाली लगनी है कलर कराना है	temporary	religious	22.7293117, 75.8815766	api.acceldash.com/uploads/re gisters/1681453163888.jpeg http://swm
277	9	46	पंचम की फौल गोपी लोडवाल के घर के पास	kuan	government	rcc	400	8	8	सफाई कराना है जाली लगाना है कलर करना है	temporary	residential	22.7292849, 75.8815784	api.acceldash.com/uploads/re gisters/1681453348457.jpeg http://swm
278	9	46	अनर टेकरी नानी का बड़ा	kuan	government	rcc	200	3	3	1 सॉफ सफाई करने है 2 जाली लगाना है 3 पेंटिंग कराना है	temporary	religious	22.7310342, 75.8815529	api.acceldash.com/uploads/re gisters/1681453366110.jpeg http://swm
279	9	46	अनर टेकरी नाले किनारे	kuan	government	rcc	300	8	8	1 सॉफ सफाई करवाना है 2 जाली लगवाना है 3 पतई करवाना है	temporary	religious	22.7310049, 75.8815346	api.acceldash.com/uploads/re gisters/1681453415349.jpeg http://swm

280	9	45	मौजूदा विडियो गेम के पास	kuan	government	rcc	300	4	4	1 साफ सफाई करवाना है 2 जाली लगवाना है 3 पुताई करवाना है	temporary	religious	22.7317388, 75.8830425	http://swm-api.acceldash.com/uploads/reports/168145343743.jpg
281	9	46	सोमनाथ की जूनि चाल कुशवाह समाज धर्मशाला	kuan	government	rcc	300	5	5	1 साफ सफाई करवाना है 2 पुताई करवाना है	temporary	religious	22.731711, 75.882909	http://swm-api.acceldash.com/uploads/reports/1681453543612.jpg
282	9	46	सोमनाथ की चाल सनी शुक्ला के घर के पास	kuan	government	rcc	350	4	4	1 रिपेयर करना है 2 जाली लगाना है 3 पुताई करना है	temporary	religious	22.7316739, 75.8855982	http://swm-api.acceldash.com/uploads/reports/1681453499618.jpg
283	10	43	Meher apartment 3/3, New Palasia	kuan	private	brickwork	12	2.5	2.5	safe	none	none	22.7283386, 75.8843258	http://swm-api.acceldash.com/uploads/reports/1681453599013.jpg
284	10	43	Dilpasand park, 15/8, New palasia	kuan	private	brickwork	10	3	3	safe in private premises	none	none	22.7283388, 75.883952	http://swm-api.acceldash.com/uploads/reports/1681453667614.jpg
285	10	43	Krishna enclave 36/2 New palasia	kuan	private	brickwork	10	2.7	2.7	safe	none	none	22.7288454, 75.8851484	http://swm-api.acceldash.com/uploads/reports/1681453823247.jpg
286	10	43	Swastik Apartment 39/2 New palasia	kuan	private	brickwork	15	3	3	safe covered by jali	none	none	22.7299113, 75.8850879	http://swm-api.acceldash.com/uploads/reports/1681453961289.jpg
287	10	43	Swastik Apartment 39/2 New palasia	kuan	private	stone	10	2.2	2.2	safe	none	none	22.7297891, 75.8851075	http://swm-api.acceldash.com/uploads/reports/1681454151483.jpg
288	10	43	shastriya naale ke पास 5/2 New palasia Jain diwakar college ke पास	kuan	government	stone	12	5	5	safe	none	none	22.7299017, 75.8850986	http://swm-api.acceldash.com/uploads/reports/1681454266548.jpg
289	10	43	Shree Hari Tiwari 5/8 New palasia	kuan	private	brickwork	12	2.25	2.25	safe	none	none	22.7307786, 75.8835029	http://swm-api.acceldash.com/uploads/reports/1681454143357.jpg
290	10	40	patidar dharmshala	kuan	government	stone	10	2	2	safe and no maintenance required	none	none	22.7296342, 75.8973706	http://swm-api.acceldash.com/uploads/reports/168145439735.jpg
291	10	43	Er Kailash Singh Rathore 13/1-8, New palasia	kuan	private	brickwork	10	2.2	2.2	safe	none	none	22.7291933, 75.8845835	http://swm-api.acceldash.com/uploads/reports/1681454613724.jpg
292	10	40	shri ram mandir mota mandir ke पास	kuan	government	stone	22	1.75	1.75	safe and only green net is required	none	none	22.7324915, 75.9045882	http://swm-api.acceldash.com/uploads/reports/1681454686703.jpg
293	10	40	inside ganeshpuri garden ganeshpuri	kuan	government	rcc	16	5.5	5.5	safe and no maintenance required	none	none	22.7326482, 75.9061063	http://swm-api.acceldash.com/uploads/reports/168145471345.jpg

294	10	40	khajrana mandir campus near new visharam ghar	kuan	government	brickwork	22	5.8		safe and no maintenance required	none	none	22.7290094, 75.9071133	api.acceldash.com/uploads/re gisters/1681454748128.jpeg http://swm-
295	10	40	behind Ganesh ji mandir khajrana temple campus	kuan	Government	rcc	15	2.2		safe and no maintenance required	none	none	22.7314305, 75.9038236	api.acceldash.com/uploads/re gisters/1681454841569.jpeg http://swm-
296	10	40	infront of Ganesh ji mandir khajrana mandir campus	kuan	government	rcc	15	4	8	safe and no maintenance required	none	none	22.7312376, 75.9076554	api.acceldash.com/uploads/re gisters/1681454978214.jpeg http://swm-
297	10	43	Shantinath digamber Jain temple A B road Palasia	kuan	private	stone	11	3		temple premises covered by roof and railing	none	none	22.7296342, 75.8973706	api.acceldash.com/uploads/re gisters/168145519298.jpeg http://swm-
298	10	43	Mata ji ke mandir ke paas, Shrinagar extension	kuan	government	brickwork	15	6		safe covered with parapet and jali	none	none	22.7296342, 75.8973706	api.acceldash.com/uploads/re gisters/1681455191695.jpeg http://swm-
299	10	38	near faizan e madina masjid jalla colony	kuan	government	stone	20	9	9	well has boundary wall and it's top is covered with grating.	none	none	22.7335082, 75.9095053	api.acceldash.com/uploads/re gisters/168145541342.jpeg http://swm-
300	10	38	jia kirane ke paas, Mamta colony khajrana	kuan	private	stone	6	5		रहवासियो से प्राप्त जानकारी अनुसार बावडी के ऊपर मिट्टि किया हुआ है।	permanent	residential	22.7296342, 75.8973706	api.acceldash.com/uploads/re gisters/168145541342.jpeg http://swm-
301	10	39	135 ke samne nalarshah wali road, tanzim nagar, kharana	kuan	private	brickwork				कुं को पूर्व में भर जा चुकी है	none	none	22.7346527, 75.9126098	api.acceldash.com/uploads/re gisters/1681455599281.jpeg http://swm-
302	10	42	vijay kirana store 1/2A Telephone nagar	kuan	private	rcc	15	10		well situated adjacent to road munder repairing and covering work in progress	none	none	22.7232287, 75.9037306	api.acceldash.com/uploads/re gisters/1681455666640.jpeg http://swm-
303	10	42	H.N. 199 Telephone nagar Agrawal house gali no.04 Telephone nagar	kuan	government	brickwork	9	8		situated on road covered with RCC roof	none	none	22.7237316, 75.9036088	api.acceldash.com/uploads/re gisters/1681455718982.jpeg http://swm-
304	10	42	Ajtsingh Rathore 11Manbhavan nagar ke saamne	kuan	government	rcc	15	12		covered with jalli	none	none	22.7215167, 75.9042207	api.acceldash.com/uploads/re gisters/168145574901.jpeg http://swm-
305	10	42	Saveri club Saket nagar	kuan	government	stone	30	14		situated inside saiket club with parapet wall	none	none	22.7214423, 75.9038529	api.acceldash.com/uploads/re gisters/1681455756301.jpeg http://swm-
306	10	42	maata ji mandir ke paas vinoba nagar sankri gali	kuan	government	stone	12	3		well covered with jali and parapet	none	none	22.7206408, 75.8939122	api.acceldash.com/uploads/re gisters/1681455756301.jpeg http://swm-
307	10	42	Ravindra nagar Garden	kuan	government	stone	15	8		safe covered with jali and parapet	none	none	22.7226996, 75.8925482	api.acceldash.com/uploads/re gisters/1681455757477.jpeg http://swm-

308	10	43	H N 123 124 baikunthdham colony	kuan	government	stone	10	4		situated on road covered by roof and parapet wall	none	none	22.7296342, 75.87973706	http://swin-api.acceldash.com/uploads/reports/1681455844716.jpg
309	11	55	RNT road, street no. 01, khandelwal ke pas	kuan	government	brickwork	15	3.8		safe	temporary	residential	22.7096528, 75.8749011	http://swin-api.acceldash.com/uploads/reports/1681455888200.jpg
310	11	55	Kursi mohalla mata mandir ke pas, street no. 08	kuan	government	brickwork	12	5		safe, jali repair & painting work requirement	permanent	religious	22.7102218, 75.875291	http://swin-api.acceldash.com/uploads/reports/1681456124462.jpg
311	11	55	Khazanchi dharmshala 18/1 ushaganj	kuan	government	stone	25	2.4		Unsafe, jali required	permanent	commercial	22.7099134, 75.8768594	http://swin-api.acceldash.com/uploads/reports/1681456124462.jpg
312	11	55	S.p. office Rani sarah	bawdi	government	stone	25	10	10	Safe, Repairing required	none	none	22.7191737, 75.8705777	http://swin-api.acceldash.com/uploads/reports/1681456198608.jpg
313	11	60	Baba deep complex ke pas	bawdi	government	stone	16	3	3	unsafe, jali lagana & repairing work	permanent	commercial	22.7188586, 75.8709976	http://swin-api.acceldash.com/uploads/reports/168145615102.jpg
314	11	60	50 maharani road rej radio ke samne	kuan	government	stone	15	2.1	2.1	safe	none	none	22.7167663, 75.8670012	http://swin-api.acceldash.com/uploads/reports/1681456309116.jpg
315	11	60	Rani pura Kachchi masjid ke pas 20/3	kuan	private	brickwork	20	3	3	Safe	none	none	22.716801, 75.8631326	http://swin-api.acceldash.com/uploads/reports/168145634929.jpg
316	11	60	Rajpura Kachchi masjid ke bayi taraf	kuan	government	brickwork	13	2		Unsafe	permanent	none	22.716801, 75.8631326	http://swin-api.acceldash.com/uploads/reports/1681456372617.jpg
317	11	60	Doulat ganj gali no.03 pakli masjid ke pas	kuan	government	brickwork	15	3	3	Unsafe	temporary	none	22.7153487, 75.8628412	http://swin-api.acceldash.com/uploads/reports/1681456404537.jpg
318	11	60	Urdu maidan doulat ganj	kuan	government	rcc	18	4.3		Safe	none	none	22.7153487, 75.8628412	http://swin-api.acceldash.com/uploads/reports/1681456564074.jpg
319	11	60	North toda Kailash kothi shree ram mandir	kuan	government	brickwork	13	2.5		Safe, jali repairing required	none	none	22.7176666, 75.8607433	http://swin-api.acceldash.com/uploads/reports/168145658955.jpg
320	11	55	Chhoti gwal toli patel lodge ke piche	kuan	government	brickwork	15	2.5		safe, jali repairing	none	none	22.713914, 75.8704949	http://swin-api.acceldash.com/uploads/reports/1681468638911.jpg
321	11	55	Snyogta ganj thana	kuan	government	brickwork	15	2.5		Safe, Jali repairing	temporary	religious	22.7078113, 75.8775359	http://swin-api.acceldash.com/uploads/reports/1681456683791.jpg
322	11	55	P.S.C. Office	kuan	government	brickwork	22	3		Safe	none	none	22.7076808, 75.8789324	http://swin-api.acceldash.com/uploads/reports/1681456803188.jpg

323	11	48	Balaram nagar begiche ke pas	kuan	government	stone	24	4	Safe	none	none	22.715413, 75.8913151	http://swm-api.acceldash.com/uploads/reposters/168145685f0102.jpeg
324	11	48	Priyal apartment	kuan	government	brickwork	16	4	safe	none	none	22.715413, 75.8913151	http://swm-api.acceldash.com/uploads/reposters/1681456900997.jpeg
325	11	48	Pasi mohalla gali no. 01	kuan	government	brickwork	15	3.5	Unsafe, jali repairing.	permanent	religious	22.7156221, 75.8913496	http://swm-api.acceldash.com/uploads/reposters/1681457235870.jpeg
326	11	48	Badi gwaltohi shitala mata mandir ke pas	kuan	government	brickwork	20	3	Unsafe, jali lagana hai	temporary	religious	22.718636, 75.8898427	http://swm-api.acceldash.com/uploads/reposters/1681456983030.jpeg
327	11	48	Devi Indra ekta nagar H.No. 64	kuan	government	brickwork	10	5	Safe, jali repairing	none	none	22.7195936, 75.8904826	http://swm-api.acceldash.com/uploads/reposters/168145714511.jpeg
328	11	49	Goyal nagar shakuntala hospital ke pas shiv mandir	kuan	government	brickwork	22	6	Safe, jali repairing and painting required	none	none	22.7180995, 75.9057197	http://swm-api.acceldash.com/uploads/reposters/1681457411329.jpeg
329	11	49	Goyal nagar ex. jain mandir	kuan	private	brickwork	20	2.1	Safe	none	none	22.7193889, 75.9054685	http://swm-api.acceldash.com/uploads/reposters/168145724197.jpeg
330	11	49	Mahaveer nagar kanadiya road	kuan	government	brickwork	20	3.5	Safe, jali & maintenance work required	permanent	residential	22.717119, 75.9030855	http://swm-api.acceldash.com/uploads/reposters/1681457436157.jpeg
331	11	49	Sai nath colony sansthan	kuan	government	brickwork	22	10	Safe	temporary	residential	22.7188975, 75.9006628	http://swm-api.acceldash.com/uploads/reposters/1681457520136.jpeg
332	11	49	Vandana nagar C-sector Ganesha mandir	kuan	government	stone	30	10	Safe, jali repair required	none	none	22.7177702, 75.9021557	http://swm-api.acceldash.com/uploads/reposters/1681457677777.jpeg
333	11	49	Tilak nagar sai mandir ke samne	kuan	government	brickwork	23	10	safe, jali repair and painting required	temporary	residential	22.7150810, 75.8984207	http://swm-api.acceldash.com/uploads/reposters/168145769072.jpeg
334	11	49	Salasar balaji mandir near post office	kuan	government	brickwork	20	10	Safe	permanent	religious	22.7190362, 75.8956927	http://swm-api.acceldash.com/uploads/reposters/1681457741176.jpeg
335	11	48	Ram mandir badi gwal toli	kuan	government	brickwork	20	5	Unsafe, Side wall settled	none	none	22.7188412, 75.8935146	http://swm-api.acceldash.com/uploads/reposters/1681457741500.jpeg
336	11	60	Champa bag masjid ke pas	kuan	government	brickwork	12	2.5	Unsafe, Munder bana, gaad nikalna, jali lagana	permanent	residential	22.7163345, 75.8661539	http://swm-api.acceldash.com/uploads/reposters/16814577238.jpeg
337	11	60	27 Jawahar marg, hard gear house	kuan	government	brickwork	15	2.5	Unsafe,	permanent	commercial	22.7148295, 75.8658341	http://swm-api.acceldash.com/uploads/reposters/1681457981276.jpeg

338	11	55	Rajjagan travels Patel square	kuan	government	brickwork	12	2.5		Unsafe, dab dalkar band kiya gaya hai	permanent	commercial	22.7155637, 75.8665286	http://swin.apicelldash.com/uploads/reposters/168145846181.jpg
339	11	55	Banjara hotel ke piche chhoti gwal toll	kuan	government	brickwork	15	5.2		Unsafe, slab dal kar band kiya gaya hai	permanent	commercial	22.7143554, 75.8710194	http://swin.apicelldash.com/uploads/reposters/1681458059498.jpg
340	11	55	Ushajani, BIP karyalaya ke samne	kuan	government	brickwork	15	3		Safe	none	none	22.7099713, 75.8794841	http://swin.apicelldash.com/uploads/reposters/1681458207220.jpg
341	11	55	M.Y. Hospital O.P.D. ke andar	kuan	government	brickwork	18	4		Safe	none	none	22.7104984, 75.8800539	http://swin.apicelldash.com/uploads/reposters/1681458306353.jpg
342	11	60	Hathi pala road shree ram mandir	kuan	government	brickwork	12	2.5		Safe	none	none	22.7156912, 75.8660469	http://swin.apicelldash.com/uploads/reposters/1681458259131.jpg
343	11	60	Hathi pala road ramesh rathor ka godaun	kuan	private	brickwork	15	3		Unsafe, jali nhi hai	permanent	commercial	22.7135008, 75.8641215	http://swin.apicelldash.com/uploads/reposters/1681458444762.jpg
344	11	60	gali no 2 pani ki tanki k pass(sahid lab)	kuan	government	brickwork	12	2		repairing and jali required	permanent	residential	22.7159211, 75.8625779	http://swin.apicelldash.com/uploads/reposters/1681458371911.jpg
345	11	49	Vandana nagar Vasundhara complex ke piche	kuan	government	stone	30	10		Safe, jali repairing required	none	none	22.7144948, 75.9004938	http://swin.apicelldash.com/uploads/reposters/1681468871911.jpg
346	11	54	Residency area main road Dargah ke pas	kuan	government	brickwork	30	3		Safe	permanent	religious	22.7050117, 75.8862701	http://swin.apicelldash.com/uploads/reposters/1681458553212.jpg
347	11	54	P.T.S. (Police training sentar)	kuan	government	brickwork	20	5		Safe	none	none	22.7011102, 75.9027001	http://swin.apicelldash.com/uploads/reposters/1681458560095.jpg
348	11	54	P.T.S. ground near H.No. 02	kuan	government	brickwork	26	6	6	Safe, jali repairing required & munder	none	none	22.7083664, 75.8985968	http://swin.apicelldash.com/uploads/reposters/1681458561593.jpg
349	11	54	P.T.S. Helipad ke pas	kuan	government	stone	20	5	4	Safe	none	none	22.6953822, 75.9006037	http://swin.apicelldash.com/uploads/reposters/168145830758.jpg
350	11	48	Palasia square petrol pump left turn	kuan	government	brickwork	15	3		Unsafe	none	none	22.7056745, 75.8848019	http://swin.apicelldash.com/uploads/reposters/1681458756586.jpg
351	11	55	Dhakkan wala kuan Dargah	kuan	government	brickwork	15	3		Safe,	none	none	22.7239432, 75.8869061	http://swin.apicelldash.com/uploads/reposters/1681458815229.jpg
352	11	60	gandhi hall gopeshwar Mahadevi mandir	kuan	government	brickwork	25	2.5		safe	none	none	22.7197816, 75.8656412	http://swin.apicelldash.com/uploads/reposters/1681458872729.jpg

353	11	60	Shree God vidhya mandir	kuan	government	brickwork	15	2.5	2.5	Safe	permanent	religious	22.7131874, 75.8614058	api.acceldash.com/uploads/ce gisters/168145943336.jpeg <a href="http://swin-
api.acceldash.com/uploads/ce
gisters/168145943336.jpeg">http://swin- api.acceldash.com/uploads/ce gisters/168145943336.jpeg
354	12	65	zone 12 ward 6S Sindhu nagar Mata mandir	kuan	government	rcc	25	5	25	slab cutting	none	none	22.7033596, 75.860761	<a href="http://swin-
api.acceldash.com/uploads/ce
gisters/168145910970.jpeg">http://swin- api.acceldash.com/uploads/ce gisters/168145910970.jpeg
355	12	59	Krishna pura chhatri	bawdi	government	brickwork	10	3	3	maintenance required	none	none	22.7188472, 75.8579246	<a href="http://swin-
api.acceldash.com/uploads/ce
gisters/1681459401673.jpeg">http://swin- api.acceldash.com/uploads/ce gisters/1681459401673.jpeg
356	12	59	Krishna pura chhatri	kuan	government	stone	10	2	2	unsafe	none	none	22.7189753, 75.8580053	<a href="http://swin-
api.acceldash.com/uploads/ce
gisters/1681459267135.jpeg">http://swin- api.acceldash.com/uploads/ce gisters/1681459267135.jpeg
357	12	59	Krishna pura chhatri kua	kuan	government	stone	10	2	2	maintenance required	none	none	22.718953, 75.8590216	<a href="http://swin-
api.acceldash.com/uploads/ce
gisters/1681459417370.jpeg">http://swin- api.acceldash.com/uploads/ce gisters/1681459417370.jpeg
358	12	59	harsidih zonal office	kuan	government	rcc	20	5	5	maintenance required	none	none	22.7181019, 75.8578148	<a href="http://swin-
api.acceldash.com/uploads/ce
gisters/1681459488481.jpeg">http://swin- api.acceldash.com/uploads/ce gisters/1681459488481.jpeg
359	12	59	behind registrar office moli tabala	kuan	government	rcc	50	5	5	maintenance required	none	none	22.7123928, 75.8601852	<a href="http://swin-
api.acceldash.com/uploads/ce
gisters/168146592658.jpeg">http://swin- api.acceldash.com/uploads/ce gisters/168146592658.jpeg
360	12	61	surajkund katkatpura bawdi	bawdi	government	stone	20	7	10	unsafe	permanent	religious	22.7079139, 75.8604131	<a href="http://swin-
api.acceldash.com/uploads/ce
gisters/1681459608432.jpeg">http://swin- api.acceldash.com/uploads/ce gisters/1681459608432.jpeg
361	12	61	katkatpura masjid	kuan	government	stone	15	2	2	maintenance required	none	none	22.7099039, 75.8628545	<a href="http://swin-
api.acceldash.com/uploads/ce
gisters/1681459382920.jpeg">http://swin- api.acceldash.com/uploads/ce gisters/1681459382920.jpeg
362	12	61	Lal Mandir Kunawat pura	kuan	government	rcc	15	2	2	maintenance required	permanent	religious	22.7097504, 75.8630088	<a href="http://swin-
api.acceldash.com/uploads/ce
gisters/1681459758511.jpeg">http://swin- api.acceldash.com/uploads/ce gisters/1681459758511.jpeg
363	12	61	Jagga ka bagicha Radha Govind ka bagicha railway line ke paas	bawdi	government	stone	10	5	5	unsafe	none	none	22.7097504, 75.8630088	<a href="http://swin-
api.acceldash.com/uploads/ce
gisters/1681459839881.jpeg">http://swin- api.acceldash.com/uploads/ce gisters/1681459839881.jpeg
364	12	62	vishwanath shiv mandir mural mohalla	kuan	government	brickwork	50	5	5	unsafe	permanent	religious	22.7083664, 75.8643611	<a href="http://swin-
api.acceldash.com/uploads/ce
gisters/1681459109522.jpeg">http://swin- api.acceldash.com/uploads/ce gisters/1681459109522.jpeg
365	12	59	harjan colony below Loha Mandi bridge	kuan	government	brickwork	50	5	5	maintenance required	none	none	22.708295, 75.8671191	<a href="http://swin-
api.acceldash.com/uploads/ce
gisters/1681459244980.jpeg">http://swin- api.acceldash.com/uploads/ce gisters/1681459244980.jpeg
366	12	62	neelkantheshwar mahadev mandir Loha Mandi	kuan	government	stone	50	5	5	maintenance required	none	none	22.7085466, 75.8654364	<a href="http://swin-
api.acceldash.com/uploads/ce
gisters/1681459429851.jpeg">http://swin- api.acceldash.com/uploads/ce gisters/1681459429851.jpeg
367	12	61	katkatpura kabristan	kuan	government	brickwork	50	5	5	unsafe	none	none	22.7069337, 75.8651182	<a href="http://swin-
api.acceldash.com/uploads/ce
gisters/1681460505013.jpeg">http://swin- api.acceldash.com/uploads/ce gisters/1681460505013.jpeg

368	12	61	juni Indore thana	kuan	government	brickwork	50	5	5	none	none	22.7098353, 75.8617571	http://swm-api.acceldash.com/uploads/re-gisters/1681460790130.jpg
369	12	65	behind preetam das sabagrah sadhuwaswani nagar	bawdi	government	rcc	20	10	10	none	none	22.7007286, 75.8653015	http://swm-api.acceldash.com/uploads/re-gisters/1681461027335.jpg
370	12	65	shiv mandir Sindhu palace sadhuwaswani nagar	kuan	government	brickwork	50	5	5	permanent	residential	22.7007286, 75.8653015	http://swm-api.acceldash.com/uploads/re-gisters/1681461054272.jpg
371	12	65	Dr satwani clinic khatiwala tank	kuan	government	rcc	20	2	2	none	none	22.70075, 75.863575	http://swm-api.acceldash.com/uploads/re-gisters/1681461486633.jpg
372	12	66	shiv mandir rajmahal colony	kuan	government	brickwork	50	5	5	none	none	22.698826, 75.857207	http://swm-api.acceldash.com/uploads/re-gisters/1681461778260.jpg
373	12	66	navigrih mandir roopram nagar	kuan	government	rcc	20	2	2	none	religious	22.7001912, 75.8511981	http://swm-api.acceldash.com/uploads/re-gisters/1681461963060.jpg
374	12	66	gurunank colony	kuan	government	brickwork	50	8	8	none	none	22.7001912, 75.8511981	http://swm-api.acceldash.com/uploads/re-gisters/1681462278130.jpg
375	12	66	kerabala maidan	kuan	government	brickwork	50	5	5	none	none	22.7020262, 75.8489546	http://swm-api.acceldash.com/uploads/re-gisters/168146285655.jpg
376	13	77	Ganesh nagar main road कुआं नंबर 4	kuan	government	brickwork	13	12	12	none	none	22.6707233, 75.8697383	http://swm-api.acceldash.com/uploads/re-gisters/1681463213472.jpg
377	13	77	गणेश नगर मेन रोड कुआं नंबर 2	kuan	government	brickwork	13	12	12	none	none	22.6715745, 75.8723954	http://swm-api.acceldash.com/uploads/re-gisters/1681463213068.jpg
378	13	77	साई प्रथम दास स्कूल के पास में छोटा बिलावली टालाब का कुआं पेपर कितनी हागी पली होगी बहुत ही नहीं है इसलिए पिया सुन ली जी तो नना राजा नन राजा नन नन	kuan	government	brickwork	12	11	11	none	none	22.6657833, 75.8749567	http://swm-api.acceldash.com/uploads/re-gisters/1681462762471.jpg
379	13	77	आसाराम आश्रम खुडवा रोड के अंदर का कुआं	kuan	private	brickwork	13	8	8	none	none	22.6666991, 75.8771001	http://swm-api.acceldash.com/uploads/re-gisters/1681462732089.jpg
380	13	78	Amitesh nagar	bawdi	government	stone	15	38	9	permanent	commercial	22.681649, 75.8541034	http://swm-api.acceldash.com/uploads/re-gisters/1681462531832.jpg
381	13	74	shivampuri mataji temple	kuan	government	stone	15	4	4	none	none	22.686875, 75.8616891	http://swm-api.acceldash.com/uploads/re-gisters/1681462816372.jpg

382	13	74	bharampuri Ganesh mandir	kuan	government	rcc	15	4	4	unsafe , covered by RCC slab	none	none	22.686876, 75.8616801	http://swm-api.acceldash.com/uploads/reisters/1681462939310.jpeg
383	13	74	indraperi shiv temple	kuan	government	brickwork	15	10	10	safe	none	none	22.6855989, 75.8652641	http://swm-api.acceldash.com/uploads/reisters/1681462996273.jpeg
384	13	74	nahar bhandara Rajiv Gandhi square	kuan	government	brickwork	15	4	4	safe	none	none	22.6839404, 75.8640273	http://swm-api.acceldash.com/uploads/reisters/16814630014.jpeg
385	13	74	Jai Singh palace	kuan	government	brickwork	15	4	4	safe	none	none	22.6839404, 75.8640273	http://swm-api.acceldash.com/uploads/reisters/16814630014.jpeg
386	13	74	eastern ring road near Rishi ka dhabha	kuan	government	brickwork	15	3	3	safe	none	none	22.6808893, 75.8627555	http://swm-api.acceldash.com/uploads/reisters/168146323738.jpeg
387	13	74	pijyapala Jai Singh nagar	kuan	government	brickwork	15	4	4	safe	none	none	22.6800819, 75.8610722	http://swm-api.acceldash.com/uploads/reisters/1681463280405.jpeg
388	13	74	inside regional park	kuan	government	rcc	15	10	10	unsafe , covered by slab	none	none	22.6806619, 75.8567049	http://swm-api.acceldash.com/uploads/reisters/1681463598267.jpeg
389	13	74	vishnupuri shiv temple	kuan	government	brickwork	15	9	9	unsafe covered by slab	none	none	22.6799781, 75.8610751	http://swm-api.acceldash.com/uploads/reisters/1681463792703.jpeg
390	13	74	antiyapuri colony	kuan	government	brickwork	15	8	8	safe	none	none	22.6900192, 75.8621188	http://swm-api.acceldash.com/uploads/reisters/1681463873914.jpeg
391	13	74	soniya gandhi nagar	kuan	government	brickwork	15	4	4	safe	none	none	22.6710308, 75.8675841	http://swm-api.acceldash.com/uploads/reisters/1681463943773.jpeg
392	13	77	Ganesh Nagar	kuan	private	brickwork	15	8	8	unsafe , covered by slab	none	none	22.6690858, 75.8768148	http://swm-api.acceldash.com/uploads/reisters/16814639864.jpeg
393	13	78	inside choithram square	kuan	government	brickwork	15	10	10	safe	none	none	22.681225, 75.8529323	http://swm-api.acceldash.com/uploads/reisters/1681464141245.jpeg
394	13	78	Lake park colony	bawdi	government	stone	15	6	12	safe	none	none	22.681225, 75.8529323	http://swm-api.acceldash.com/uploads/reisters/1681464172254.jpeg
395	13	78	choithram hospital and research	kuan	private	brickwork	15	8	8	safe	none	none	22.6866152, 75.8543384	http://swm-api.acceldash.com/uploads/reisters/1681464250893.jpeg
396	13	78	choithram school	kuan	private	stone	15	6	12	unsafe , covered by slab	permanent	none	22.6881576, 75.8523857	http://swm-api.acceldash.com/uploads/reisters/1681464300239.jpeg

397	13	78	scheme.103 over-head tank	bawdi	government	stone	15	14	14	safe	none	none	22.6901275, 75.8552888	http://swm-api.acceldash.com/uploads/re gistery/1681464694326.jpeg
398	13	78	nema nagar dharmshala	kuan	private	brickwork	15	6	6	unsafe,sheets to be removed	none	none	22.6817585, 75.8416553	http://swm-api.acceldash.com/uploads/re gistery/1681464656017.jpeg
399	13	78	near Kalia devi temple	kuan	government	brickwork	15	6	6	safe	none	none	22.6809574, 75.8392925	http://swm-api.acceldash.com/uploads/re gistery/1681464962021.jpeg
400	13	78	panwati tukeshwar temple	bawdi	private	stone	15	6	15	unsafe,access to be removed	permanent	none	22.6809574, 75.8392925	http://swm-api.acceldash.com/uploads/re gistery/1681464909020.jpeg
401	13	78	chameeli Devi school	kuan	private	stone	15	12	15	safe	none	none	22.6792764, 75.8595394	http://swm-api.acceldash.com/uploads/re gistery/1681465303032.jpeg
402	13	78	near vinayak restaurant scheme 105	kuan	government	brickwork	15	6	6	safe	none	none	22.6792764, 75.8595394	http://swm-api.acceldash.com/uploads/re gistery/1681465298924.jpeg
403	13	78	Devi ahiya cold storage	kuan	private	brickwork	15	6	6	unsafe,civil work required	none	none	22.6798098, 75.8436948	http://swm-api.acceldash.com/uploads/re gistery/1681465511469.jpeg
404	13	78	infront of basantpuri colony	kuan	government	brickwork	15	8	8	safe	none	none	22.6755483, 75.8472567	http://swm-api.acceldash.com/uploads/re gistery/1681465026327.jpeg
405	13	78	mukteshwar Mahadev temple amitesh nagar	kuan	government	rcc	15	8	8	safe	none	none	22.675483, 75.8472567	http://swm-api.acceldash.com/uploads/re gistery/1681466063350.jpeg
406	13	81	190 प्रिकॉन्को कॉलोनी	kuan	government	rcc	50	30	30	green net ev clining	permanent	residential	22.6671724, 75.8362188	http://swm-api.acceldash.com/uploads/re gistery/1681466404118.jpeg
407	13	81	अन्नापूर्णा मंदिर	kuan	government	rcc	40	17	17	all good	permanent	educational	22.6671724, 75.8362188	http://swm-api.acceldash.com/uploads/re gistery/1681466711341.jpeg
408	13	81	देवेन्द्र नगर शिब के नीचे	kuan	government	rcc	60	30	30	good	permanent	residential	22.6887757, 75.8369914	http://swm-api.acceldash.com/uploads/re gistery/1681466571975.jpeg
409	13	81	26a नमदा नगर	kuan	Government	rcc	50	40	2	green net एवं सफाई की	permanent	residential	22.6828717, 75.8390604	http://swm-api.acceldash.com/uploads/re gistery/16814665613792.jpeg
410	13	81	दारा मंदिर	kuan	government	rcc	50	30	30	good	permanent	religious	22.6828717, 75.8390604	http://swm-api.acceldash.com/uploads/re gistery/1681466809780.jpeg
411	13	77	साई प्रीतमदास स्कूल के पास छोट्टा बिलावली तालाब का क्यूअ	kuan	government	brickwork	13	12	12	no	none	none	22.6699858, 75.8768148	http://swm-api.acceldash.com/uploads/re gistery/1681467230944.jpeg

412	13	81	190 प्रिकॉन्को कॉलोनी	kuan	government	rcc	18	8	8	सफई की जरूरत है	permanen	residential	22.6808054, 75.8266254	api.acceldash.com/uploads/re gisters/168146727202.jpeg http://swm:
413	13	81	अनापूर्णा मंदिर	kuan	government	rcc	18	5	5	good	permanen	educational	22.6808054, 75.8266254	api.acceldash.com/uploads/re gisters/168146727230.jpeg http://swm:
414	13	81	दत्त मंदिर	kuan	government	rcc	16	8	8	all good	permanen	religious	22.6808054, 75.8266254	api.acceldash.com/uploads/re gisters/168146727230.jpeg http://swm:
415	13	81	26/a नर्मदा नगर	kuan	government	rcc	13	10	10	not good	permanen	residential	22.6820885, 75.8354523	api.acceldash.com/uploads/re gisters/168146727230.jpeg http://swm:
416	13	81	dawendar nagar श्रीज के नीचे	kuan	government	rcc	13	10	10	not good	permanen	residential	22.6833117, 75.8363233	api.acceldash.com/uploads/re gisters/168146727230.jpeg http://swm:
417	13	80	द्वारका गार्डन अहिल्सा नगर	kuan	private	rcc	18	5	5	work in progress	permanen	none	22.684319, 75.8401374	api.acceldash.com/uploads/re gisters/1681468219850.jpeg http://swm:
418	13	81	अनापूर्णा मंदिर	kuan	government	rcc	9	2	2	all good	permanen	religious	22.6740223, 75.871718	api.acceldash.com/uploads/re gisters/1681468219850.jpeg http://swm:
419	13	80	तीर सावरकर नगर शिव मंदिर के पास	kuan	government	brickwork	60	1500	80	IMC	none	residential	22.6645695, 75.8245242	api.acceldash.com/uploads/re gisters/1681468219850.jpeg http://swm:
420	13	80	MPEB ऑफिस महिला पॉलिटेक्निक ब्रिज के नीचे	kuan	government	brickwork	45	5	8	IIMC	permanen	none	22.6734031, 75.8325002	api.acceldash.com/uploads/re gisters/168146853320.jpeg http://swm:
421	13	80	veer savarkar nagar	kuan	government	brickwork	15	5	5	unsafe,grill should be installed	none	none	22.6658044, 75.8434208	api.acceldash.com/uploads/re gisters/1681469063405.jpeg http://swm:
422	13	80	retl Mandi near railway track	kuan	government	brickwork	15	6	6	safe	none	none	22.6636962, 75.8234942	api.acceldash.com/uploads/re gisters/1681469195266.jpeg http://swm:
423	13	80	Madhav Vidhya Pith, Ahliya Nagar	kuan	government	brickwork	15	7	7	No Maintenance Required	none	none	22.6732712, 75.8253903	api.acceldash.com/uploads/re gisters/1681469577766.jpeg http://swm:
424	13	80	Ram Mandir, Vaishali Nagar	kuan	government	brickwork	13	3	3	Jail Repair Work Needed.	none	none	22.6732712, 75.8253903	api.acceldash.com/uploads/re gisters/168146981547.jpeg http://swm:
425	13	80	near Rajendra nagar bridge	kuan	government	brickwork	20	10	10	no Maintenance Required	none	none	22.6744782, 75.8318058	api.acceldash.com/uploads/re gisters/168147015837.jpeg http://swm:
426	13	80	Om: Heights	kuan	government	brickwork	15	6	6	Unsafe and Encroachment	permanen	residential	22.6745022, 75.8317692	api.acceldash.com/uploads/re gisters/1681470252148.jpeg http://swm:

427	13	80	Parasar Nagar, Near Shiv Mandir	kuan	government	brickwork	22	8.7	8.7	No Maintenance Required	none	none	22.6732712, 75.82535903	http://swin-api.acceldash.com/uploads/replisters/1681470458019.jpeg
428	13	80	mahila polytechnic collage Rajendra nagar power house	kuan	government	brickwork	14	6	6	no Maintenance Required	none	none	22.6699833, 75.830447	http://swin-api.acceldash.com/uploads/replisters/1681470670162.jpeg
429	13	80	vibyan nagar near kumar garden	kuan	government	brickwork	20	8	8	no Maintenance Required	none	none	22.6729885, 75.8325874	http://swin-api.acceldash.com/uploads/replisters/1681470742569.jpeg
430	13	80	sudarshan nagar	kuan	government	brickwork	20	7	7	no Maintenance Required	none	none	22.6753895, 75.8327361	http://swin-api.acceldash.com/uploads/replisters/1681471392862.jpeg
431	13	80	Ahiya nagar	kuan	government	brickwork	20	8	8	no Maintenance Required	none	none	22.6807355, 75.8328069	http://swin-api.acceldash.com/uploads/replisters/1681471682900.jpeg
432	13	81	Wahaguru clinic Dr. ram nani gali no. 1 Chanakyapuri road narnada nagar	kuan	government	brickwork	20	10	10	no Maintenance Required	none	none	22.6832848, 75.8359964	http://swin-api.acceldash.com/uploads/replisters/1681471883850.jpeg
433	13	81	Dutt mandir umesh nagar anapurna main road	kuan	government	brickwork	22	8	8	no Maintenance Required	none	none	22.6816483, 75.8352293	http://swin-api.acceldash.com/uploads/replisters/1681471829285.jpeg
434	13	80	Rajendra nagar garden	kuan	government	brickwork	20	8	8	no Maintenance Required	none	none	22.6700135, 75.8270128	http://swin-api.acceldash.com/uploads/replisters/1681472119863.jpeg
435	13	81	Dwarka garden	kuan	government	brickwork	20	7	7	Unsafe and Encroachment	permanent	commercial	22.6802597, 75.8346189	http://swin-api.acceldash.com/uploads/replisters/1681472112525.jpeg
436	13	80	Scheme no 97/4 vip paraspar behind hanuman mandir near ryan international school	kuan	government	stone	10.6	4.5	4.5	Maintenance Required	none	none	22.6754205, 75.8209003	http://swin-api.acceldash.com/uploads/replisters/1681472561970.jpeg
437	13	81	Near 109 prikantho colony	kuan	government	brickwork	20	10	10	No Maintenance Required	none	none	22.6839999, 75.8299721	http://swin-api.acceldash.com/uploads/replisters/168147263516.jpeg
438	13	81	Anapurna mandir	kuan	government	brickwork	10	2.5	2.5	No Maintenance Required	none	none	22.6844649, 75.8332594	http://swin-api.acceldash.com/uploads/replisters/1681473671743.jpeg
439	13	81	Anapurna mandir	kuan	government	brickwork	15	7	7	No Maintenance Required	none	none	22.690303, 75.8375674	http://swin-api.acceldash.com/uploads/replisters/1681473819126.jpeg
440	13	81	Devendra nagar new bridge	kuan	government	brickwork	20	10	10	No Maintenance Required	none	none	22.6831058, 75.839673	http://swin-api.acceldash.com/uploads/replisters/1681475881989.jpeg

441	14	84	scheme number 71 hawa Bangla road paschimi ring road opposite futi koti gate	kuan	government	brickwork	50	3	3	no	none	none	22.6938092, 75.8268312	http://swm-api.acceldash.com/uploads/register/1681475810427.jpg
442	14	85	Sai baba nagar Mata Mandir Makaan number 200 ke samne	kuan	government	brickwork	40	5	5	no	none	none	22.6914435, 75.8199545	http://swm-api.acceldash.com/uploads/register/1681477938341.jpg
443	14	85	sector c Aisa beauty parLOUR ma Vaishnav shop Ram Mandir ke pass Prajapat Nagar	kuan	government	brickwork	18	12	12	no	none	none	22.6914435, 75.8199545	http://swm-api.acceldash.com/uploads/register/1681479477951.jpg
444	14	85	shradha puri colony Shiv Mata Mandir Lakshmi kirana general Store ke samne	kuan	government	brickwork	17	6	6	no	none	none	22.6927078, 75.8202053	http://swm-api.acceldash.com/uploads/register/1681479814282.jpg
445	14	85	Aastha place shradha Puri Shiv Mandir ke piche G26 Makaan number ke samne	kuan	government	brickwork	16	7	7	no	none	none	22.6905247, 75.8183449	http://swm-api.acceldash.com/uploads/register/1681480046462.jpg
446	14	82	Shriram Nagar Rishi palace Balaji circle ke samne	kuan	government	brickwork	13	9	9	no	none	none	22.6895514, 75.8161874	http://swm-api.acceldash.com/uploads/register/1681511059922.jpg
447	14	82	shantinath Puri parwahar Nagar hawa Bangla road	kuan	government	brickwork	16	7	7	no	none	none	22.68567, 75.8194393	http://swm-api.acceldash.com/uploads/register/1681532671409.jpg
448	14	79	hari om dhaba ke pass AB road	kuan	government	brickwork	20	5	5	no	none	none	22.6627207, 75.8246067	http://swm-api.acceldash.com/uploads/register/1681533011853.jpg
449	14	79	khedapati Hanuman Mandir ke pass A.B road	kuan	government	brickwork	10	1	1	no	none	none	22.6627207, 75.8246067	http://swm-api.acceldash.com/uploads/register/1681533265201.jpg
450	14	79	Sukh niwas road cate boundary ke pass	kuan	government	brickwork	20	5	5	no	none	none	22.6721253, 75.8036239	http://swm-api.acceldash.com/uploads/register/1681533009016.jpg
451	14	79	Sukh niwas colony samuday bhavan ke piche	kuan	government	stone	11	3	3	no	none	none	22.6711512, 75.8045471	http://swm-api.acceldash.com/uploads/register/168153550259.jpg
452	14	79	Ahir khedi gaon	kuan	government	brickwork	8	3	3	no	none	none	22.6801944, 75.8135882	http://swm-api.acceldash.com/uploads/register/1681533701970.jpg
453	14	79	vidur Nagar	kuan	government	brickwork	20	15	15	no	none	none	22.6819275, 75.8142942	http://swm-api.acceldash.com/uploads/register/1681533827121.jpg
454	15	71	rajit mandir campus ke andar	kuan	government	stone	11	4	4	safe but 1 feet raised boundary is desirable	none	none	22.7055455, 75.8376616	http://swm-api.acceldash.com/uploads/register/1681533971661.jpg

455	15	83	704 sector b scheme 71 ke same mata mandir garden	kuan	government	brickwork	11	2		safe, kua ko slab and tiles lagaakar manoir ke platform me shamil kar la bye tha jise varman me vertcal jali lagaakar logo ki entry restrict kar di gy hai.	permanent	religious	22.7036092, 75.8325901	http://swm-api.acceldash.com/uploads/reposters/16815343426.jpeg
456	15	83	power house ke same scheme 71 sector a	kuan	government	brickwork	15	5		safe, dia 4.5 m	none	none	22.7036443, 75.8326041	http://swm-api.acceldash.com/uploads/reposters/168153461261.jpeg
457	15	83	scheme 71 sector a chandan nagar pani ki tankik pas	kuan	government	brickwork	11	5		safe, jali lagi huyi hai, munder bani hai, safai kama hai dia 4.5m, jali repairing ki avashyakta hai	none	none	22.7031879, 75.8281157	http://swm-api.acceldash.com/uploads/reposters/168153460580.jpeg
458	15	83	scheme 71 sector d maudana azad garden ke pas	kuan	government	brickwork	10	5		safe.	none	none	22.7013295, 75.8270614	http://swm-api.acceldash.com/uploads/reposters/168153457825.jpeg
459	15	83	sales tax garden	kuan	government	brickwork	11	4		safe	none	none	22.69975, 75.8290208	http://swm-api.acceldash.com/uploads/reposters/168153512091.jpeg
460	15	83	rx garden ke pas	kuan	government	brickwork	12	4		safe	none	none	22.6973063, 75.8298125	http://swm-api.acceldash.com/uploads/reposters/1681535329324.jpeg
461	15	71	vishrambagh garden sthit kua	kuan	government	brickwork	18	10		jaali maintenance required	none	none	22.6934773, 75.83356	http://swm-api.acceldash.com/uploads/reposters/1681535446151.jpeg
462	15	71	66 bankcolony ke paas.	kuan	private	brickwork	15	9		jaali lagayi jana hai, kua society dwara maintain kia jata hai	none	none	22.6939402, 75.8367477	http://swm-api.acceldash.com/uploads/reposters/1681535558568.jpeg
463	15	72	8ab parshvath nagar ke paas	kuan	government	brickwork	15	7		safe	none	none	22.6901704, 75.8374875	http://swm-api.acceldash.com/uploads/reposters/1681535662681.jpeg
464	15	73	inside campus of shyam nagar masjid	kuan	government	rcc	22	3		safe no maintenance required yet.	none	none	22.7022998, 75.8390513	http://swm-api.acceldash.com/uploads/reposters/1681535799833.jpeg
465	15	72	kesharbagh crossing ke same anaganwadi ke pas	kuan	government	rcc	15	3		unsafe, dia 2.3m, jaali maintenance required	none	none	22.6870933, 75.843264	http://swm-api.acceldash.com/uploads/reposters/1681535898477.jpeg
466	15	72	kesharbagh road	kuan	private	rcc	15	4		jaali nahi lagi hai,	none	none	22.687912, 75.8436352	http://swm-api.acceldash.com/uploads/reposters/1681536015009.jpeg
467	15	72	siddharth nagar garden kua	kuan	government	brickwork	18	4		dia 3.8m, safe	none	none	22.6897578, 75.844433	http://swm-api.acceldash.com/uploads/reposters/1681536090568.jpeg

468	15	72	lokmany station ke samne jain colony	kuan	government	brickwork	18	13		safe	none	none	22.6912682, 75.8455315	api.acceldash.com/uploads/re gisters/1681536728364.jpeg	http://swm:
469	15	72	moon palace someswar mahadev mandir ke pas	kuan	government	brckwork	15	4		unsafe slab hatakar, boundry banana hai	none	none	22.6944031, 75.8413111	api.acceldash.com/uploads/re gisters/1681536335151.jpeg	http://swm:
470	15	73	ashtang ayurvedic college	kuan	government	brickwork	15	4		jaali lagana hai, boundry hight raise kna hai	none	none	22.6943025, 75.8413649	api.acceldash.com/uploads/re gisters/1681536369282.jpeg	http://swm:
471	15	73	lai bahadur shashtri nagar mata mandir	kuan	government	brickwork	15	2		jaali repairing require	none	none	22.6945055, 75.8478815	api.acceldash.com/uploads/re gisters/1681536409334.jpeg	http://swm:
472	15	73	lalbagh gts ke piche, megar kua	kuan	government	brickwork	20	8		boundrywall tuti jarjar hai, entrance gate toota hai	none	none	22.6970094, 75.844488	api.acceldash.com/uploads/re gisters/1681536563161.jpeg	http://swm:
473	15	72	champa babdi old rto office ke pas kesharbagh road	bawdi	government	stone	15	9	30	jaali lagana h	none	none	22.6988655, 75.8478297	api.acceldash.com/uploads/re gisters/1681536675721.jpeg	http://swm:
474	15	83	vishrambagh babdi	bawdi	government	brickwork	25	9	11	babdi ke charo taraf jaali nai h	none	none	22.6995819, 75.8322153	api.acceldash.com/uploads/re gisters/1681536708040.jpeg	http://swm:
475	15	71	dravid nagar zonal office campus	kuan	government	brickwork	20	10		jaali maintenance	none	none	22.7020935, 75.836488	api.acceldash.com/uploads/re gisters/1681536718437.jpeg	http://swm:
476	15	72	babdi inside laibagh	bawdi	government	stone	15	10	9	broken wire mesh	none	none	22.7028224, 75.8451244	api.acceldash.com/uploads/re gisters/1681536817219.jpeg	http://swm:
477	15	73	vijay nagar garden	kuan	government	brickwork	15	3		dia 2.8m	none	none	22.7040129, 75.8554061	api.acceldash.com/uploads/re gisters/1681536809117.jpeg	http://swm:
478	15	73	infront of 15 ashoka colony	kuan	government	brickwork	15	5		raised boundrywall/parapet required	none	none	22.6946647, 75.8539658	api.acceldash.com/uploads/re gisters/1681536874828.jpeg	http://swm:
479	15	73	poorandas ki bagiya	kuan	government	brickwork	15	2		parapet maintenance required	none	none	22.6931621, 75.8514572	api.acceldash.com/uploads/re gisters/1681537150368.jpeg	http://swm:
480	15	72	lokmany nagar post office ke samne	kuan	government	brickwork	15	16		parapet is cracked, no jaali over well.	none	none	22.6942082, 75.8463607	api.acceldash.com/uploads/re gisters/1681537162586.jpeg	http://swm:
481	15	72	nichli fell	kuan	government	rcc	15	4		safe	none	none	22.6985058, 75.8402553	api.acceldash.com/uploads/re gisters/168153723601.jpeg	http://swm:
482	15	2	70 loha gate gali no 2	kuan	government	brickwork	22	7		jaali repairing required.	permanent	none	22.7088808, 75.8256632	api.acceldash.com/uploads/re gisters/1681537231431.jpeg	http://swm:

483	15	2	nake wala road jn tower le paas footpath par	kuan	government	rcc	18	2	raised parapet banane ki aavashyakta hai	none	none	22.7088714, 75.8256469	http://swin.apnaccedash.com/uploads/revisers/1681537411740.jpeg
484	15	71	ram mandir cloth market hospital ke pas	kuan	government	stone	15	10	raised boundry hai charo taraf. safai ki aavashyakta hai	none	none	22.6452591, 75.8147692	http://swin.apnaccedash.com/uploads/revisers/168153749426.jpeg
485	15	83	scheme 71 sector a industrial area	kuan	government	brickwork	20	5	jaali lagayi jena hai	temporary	commercial	22.7074408, 75.8302252	http://swin.apnaccedash.com/uploads/revisers/1681537513991.jpeg
486	15	83	khushbu apartment	kuan	private	brickwork	15	11.3	shri indore cloth market madhyamvargiy grah nirman sanstha ki bhumi par hai sanstha dwara sandharit hai. sanstha dwara parapet banakar jaali lage di gyi hai	none	none	22.7039077, 75.8255884	http://swin.apnaccedash.com/uploads/revisers/1681537649460.jpeg
487	15	73	guljar masjid	kuan	government	brickwork	15	2	jaali lagakar safe kia gya	none	none	22.6961731, 75.8547541	http://swin.apnaccedash.com/uploads/revisers/1681537685202.jpeg
488	16	3	nagin nagar pani ki tanki ke pass	kuan	government	rcc	23	2.5	steel work green nate repair work	permanent	religious	22.7163792, 75.8234764	http://swin.apnaccedash.com/uploads/revisers/1681537709096.jpeg
489	16	15	bada bhangada gaon	bawdi	government	stone	25	15	jaali se covered karna hai stone judai karna hai	permanent	none	22.756355, 75.7921961	http://swin.apnaccedash.com/uploads/revisers/1681537725307.jpeg
490	16	3	ganga bagichii	kuan	government	brickwork	22	2.8	civil work, green net, steel work	permanent	residential	22.7163792, 75.8234764	http://swin.apnaccedash.com/uploads/revisers/1681538020627.jpeg
491	16	15	kastur Nagar	kuan	government	brickwork	16	7	cleaning nahi he	permanent	residential	22.7470466, 75.7980085	http://swin.apnaccedash.com/uploads/revisers/1681537907350.jpeg
492	16	3	baddi ganga bagichi	bawdi	government	brickwork	75	16	no work	permanent	commercial	22.7128734, 75.8252035	http://swin.apnaccedash.com/uploads/revisers/1681538031627.jpeg
493	16	3	nagin nagar main road	kuan	government	brickwork	65	13.4	civil work green net, steel wrok	permanent	residential	22.7180122, 75.8223532	http://swin.apnaccedash.com/uploads/revisers/1681538073786.jpeg
494	16	3	vijay shree nagar	kuan	government	brickwork	55	12.3	no work	permanent	residential	22.7180819, 75.8223526	http://swin.apnaccedash.com/uploads/revisers/1681538302659.jpeg
495	16	3	bhagwant gardan	kuan	government	brickwork	80	12.4	no work	permanent	residential	22.7218557, 75.821947	http://swin.apnaccedash.com/uploads/revisers/1681538360244.jpeg

496	16	15	airport road	bawdi	private	stone	18	6	8	ok	permanent	residential	22.72893, 75.8047025	api.acceldash.com/uploads/re sisters/1681538695700.jpg
497	16	3	B.S.F parishar	bawdi	government	stone	90	10	90	civil work ,green net	permanent	none	22.7228401, 75.8235958	api.acceldash.com/uploads/re sisters/1681538787708.jpg
498	16	15	airport road chaurasiya Nagar	kuan	private	brickwork	12	4.5		ok he	permanent	residential	22.7296912, 75.8079507	api.acceldash.com/uploads/re sisters/1681538853089.jpg
499	16	15	airport road Shakti Nagar	kuan	government	brickwork	11	2.5	2.5	ok he	none	residential	22.7303005, 75.8082224	api.acceldash.com/uploads/re sisters/1681539046786.jpg
500	16	14	somani nagar	kuan	government	brickwork	50	3.4	50	civil work ,green net steel work	permanent	residential	22.7301756, 75.8233196	api.acceldash.com/uploads/re sisters/1681539393840.jpg
501	16	5	SHIWALAY CHOUK	kuan	government	brickwork	70	10	15	NO	permanent	residential	22.7187463, 75.827559	api.acceldash.com/uploads/re sisters/1681539366357.jpg
502	16	15	tikriya badshah	kuan	private	brickwork	65	10.1	65	steel work,civil work green net	permanent	residential	22.7573805, 75.827793	api.acceldash.com/uploads/re sisters/1681539590134.jpg
503	16	5	shivalay chok raj nagar	kuan	government	brickwork	18	3.9	18	atkraman , steel work	permanent	residential	22.7163792, 75.8234764	api.acceldash.com/uploads/re sisters/1681539859340.jpg
504	16	5	214 raj nagar D sector	kuan	government	brickwork	21	2.9	21	atkraman	permanent	residential	22.7165117, 75.823762	api.acceldash.com/uploads/re sisters/1681540236931.jpg
505	16	5	chandan nagar E sector	kuan	government	brickwork	26	3.1	26	no work	permanent	residential	22.7165117, 75.823762	api.acceldash.com/uploads/re sisters/1681541385671.jpg
506	16	5	chandan nagar E sector	kuan	government	brickwork	25	4.8	25	green net civil work	permanent	residential	22.7165117, 75.823762	api.acceldash.com/uploads/re sisters/1681541841155.jpg
507	16	1	new vaysh nagar	kuan	government	brickwork	28	4.1	28	civil work steel work green net	permanent	residential	22.7165362, 75.8237959	api.acceldash.com/uploads/re sisters/168154210502.jpg
508	16	1	Gandhi place B.S.f wall No pass	kuan	government	brickwork	20	2.3	20	civil work ,green net	permanent	residential	22.7173365, 75.8159901	api.acceldash.com/uploads/re sisters/1681543525613.jpg
509	17	23	Baba ki Kuyaan Lt. Rajesh Joshi Garden	kuan	private	brickwork	20	2		Well should be packed.Usually Garbage thrown in the well.	none	none	22.7486741, 75.8705552	api.acceldash.com/uploads/re sisters/1681543983716.jpg
510	17	23	Mataprasad Tiwari Garden	kuan	government	brickwork	25	6		Well is safe.No maintenance required as it was done 8 months back.	none	none	22.7503988, 75.8709131	api.acceldash.com/uploads/re sisters/1681544267204.jpg

511	17	23	Digambar Jain Mandir Clerk Colony Plot No 410	kuan	private	rcc	20	3	Well is safe enough and in existence from 2017 only.Well Maintained by Mandir Society.	none	none	22.7493159, 75.8712899	http://swm-api.acceldash.com/uploads/reports/1681548522940.jpeg
512	17	23	test address	kuan	government	rcc	10	10	Pardeispura Road No 4 Ram Mandir ke पास Kuan	temporary	residential	37.4220936, -122.083922	http://swm-api.acceldash.com/uploads/reports/1681544968991.jpeg
513	17	23	Ganesh Nagar Pardeispura,inside Shiv Mandir Parisar	kuan	government	brickwork	25	3	Well is safe,Walls not damaged.	none	none	22.7508243, 75.8652845	http://swm-api.acceldash.com/uploads/reports/1681545339832.jpeg
514	17	18	revti hilas	kuan	private	brickwork	30	3	Maintenc required	none	none	22.773078, 75.8425033	http://swm-api.acceldash.com/uploads/reports/1681545822238.jpeg
515	17	19	Akash namkin ke pas Kumedi, Gav	kuan	private	brickwork	40	12	Unsafe	none	none	22.7871824, 75.8573154	http://swm-api.acceldash.com/uploads/reports/1681546799515.jpeg
516	17	19	Kumedi gav	kuan	private	brickwork	35	8	Unsafe	none	none	22.7871824, 75.8573154	http://swm-api.acceldash.com/uploads/reports/1681547182319.jpeg
517	17	18	UJJAIN ROAD BHAWRASLA, RR, Compund, Guru, Ashinwad hotel, Keplice	kuan	private	brickwork	27	8	opan wel mentence. Requard	none	none	22.7832841, 75.8484931	http://swm-api.acceldash.com/uploads/reports/1681547703527.jpeg
518	17	18	pureni revti kalash patel, Manoj, Patel, Ke, Makan, Ke, Piche	kuan	private	stone	23	7	Unsafe, Opan, Well	none	none	22.7978049, 75.8470193	http://swm-api.acceldash.com/uploads/reports/1681548021153.jpeg
519	17	18	Revti, Gav, L.C. T. Colleg, Campus	kuan	private	brickwork	40	12	Unsafe	none	none	22.8020368, 75.838325	http://swm-api.acceldash.com/uploads/reports/1681548173107.jpeg
520	17	18	Bhavani nagar, Kakad, Vidya, Bharti, Scholl ke pas	kuan	private	brickwork	22	12	Unsaf opan, Well	none	none	22.7998316, 75.8467782	http://swm-api.acceldash.com/uploads/reports/1681548554139.jpeg
521	17	20	Khatipura Ram Mandir ke peeche Choudhary Palace	kuan	government	stone	13	2	No maintenance required,Cleaning was done 3 months back,Walls not damaged.	none	none	22.7594196, 75.8609803	http://swm-api.acceldash.com/uploads/reports/1681551507800.jpeg
522	17	18	Bhavani, Nagar, Mahesh, Thakur ke ghar ke, Pice	kuan	private	brickwork	28	7	unsaf opan well	none	none	22.7998316, 75.8467782	http://swm-api.acceldash.com/uploads/reports/1681706247819.jpeg
523	17	23	Clerk Colony Extension Well	kuan	government	brickwork	23	6	Maintenance work was done 8 months back.	none	none	22.7594183, 75.8609864	http://swm-api.acceldash.com/uploads/reports/1681706753182.jpeg

524	17	23	Purana Gauri Nagar Gali No 3, Inside Bholenath Mandir- Parisar	kuan	government	brickwork	25	4	Maintenance work required. Peripheral Walls are damaged up to a depth of 3.5 mtr.	none	none	22.7527034, 75.8632511	http://swm-api.acceldash.com/uploads/reports/16817104291631.jpg
525	17	23	Pardesipura Masjid Gali No 8	kuan	private	brickwork	15	3	Masjid slab is constructed over the well. Walls are also constructed near kuaan. It needs to be demolished.	permanent	religious	22.745664, 75.8698413	http://swm-api.acceldash.com/uploads/reports/1681709121213.jpg
526	17	23	La Gali Farshi Wala Chowk Pardesipura	kuan	government	brickwork	13	2	Slab is constructed over well where traffic passes over this. As water is not available it should be packed.	none	none	22.7455878, 75.866659	http://swm-api.acceldash.com/uploads/reports/1681712211919.jpg
527	17	23	Koli Mohalla, Mahadev Gaun Mandir Gali No 11	kuan	government	brickwork	20	3	Road constructed over the Well traffic passes over the well. Maintenance work must be done. It should be opened	permanent	none	22.7454973, 75.8658974	http://swm-api.acceldash.com/uploads/reports/1681713553725.jpg
528	17	23	Koli Mohalla Dharamshala ke samne Gali No 11 Pardesipura	kuan	government	brickwork	20	4	Road is Constructed over well traffic passes over it which should be demolished. Water is available maintenance work must be done.	permanent	none	22.7456871, 75.865344	http://swm-api.acceldash.com/uploads/reports/1681714826145.jpg
529	17	19	Kumedi, Gav. Ram, Mandir. Ke. Pas	kuan	private	brickwork	50	4	Safe	none	none	22.7801803, 75.8560209	http://swm-api.acceldash.com/uploads/reports/1681717819133.jpg
530	17	19	MR. 10. brige ke., Neche, Bala, Ji, Hanuman, Mandir	bawdi	government	stone	30	9	Safe	none	none	22.7756202, 75.8604761	http://swm-api.acceldash.com/uploads/reports/1681718092455.jpg
531	17	19	MR10. lav, Kush. Chouraha	kuan	private	stone	22	10	Opan. Well dengrous	none	none	22.7890793, 75.84813	http://swm-api.acceldash.com/uploads/reports/1681719286075.jpg
532	17	19	Acha. Confensari के pas. Narwal, Nala	bawdi	government	stone	22	8	Unsafe. Opan. Bawdi	none	none	22.7890793, 75.84813	http://swm-api.acceldash.com/uploads/reports/168171934770.jpg
533	17	19	Ganesh, Dharm, Relvay शहर के pas	kuan	government	brickwork	50	10	open well unsafe	none	none	22.7576837, 75.8513982	http://swm-api.acceldash.com/uploads/reports/1681719369802.jpg

534	17	19	Ganesh, Dhan, Main, Road, 216	kuan	private	brickwork	22	3	kuva ko bhar kar makan ka nirman kar diya. Gava ha. Safe	none	none	22.7631852, 75.8477669	http://swm-api.acceldash.com/uploads/reports/1681724489328.jpg
535	17	19	Ganesh, digam, United, Mission schooli ko samne	kuan	private	brickwork	40	4	kuve ko bharav kar makan ka nirman kar diya gaya ha	none	none	22.7609187, 75.8487159	http://swm-api.acceldash.com/uploads/reports/1681724626247.jpg
536	17	20	Sukhiya Gaon Khamrola House	kuan	government	brickwork	20	2	A water tank for Common use is now placed over slab of the well and it is packed. Condition of well must be checked.	temporary	none	22.7604276, 75.85482	http://swm-api.acceldash.com/uploads/reports/1681725018586.jpeg
537	17	19	bangana brig ke pehele santoch cycle servish ko pas	kuan	government	brickwork	15	4	Safe	none	none	22.7609187, 75.8487159	http://swm-api.acceldash.com/uploads/reports/1681726518837.jpeg
538	17	19	Sanwer road Banfar basti bablu, Panerl ke makan ke age	kuan	government	brickwork	22	5	Safe	none	none	22.7506497, 75.8493854	http://swm-api.acceldash.com/uploads/reports/1681727140897.jpg
539	17	19	Sanwer road, Bhagat shingh, Nagar, banafar basti trath shigh, Banafar, Ke, Piche	kuan	private	brickwork	25	6	Safe	none	none	22.7506497, 75.8493854	http://swm-api.acceldash.com/uploads/reports/1681729035478.jpeg
540	17	19	mukarji, nagar, Ramdat ka bhata badkesvar mahadev bhram	kuan	private	brickwork	22	2	Safe	none	none	22.7655809, 75.8669088	http://swm-api.acceldash.com/uploads/reports/1681729233816.jpg
541	17	19	sanwer, Road, Mukarji, nagar gali, No. 7 Ram dath ka bhata	kuan	private	brickwork	27	2	कच्ची सीं टका है बहुत खतरनाक है	none	none	22.7655809, 75.8669088	http://swm-api.acceldash.com/uploads/reports/1681729811996.jpeg
542	17	19	sanwer road Mukarji nagar gali, No. 1, sadaang bhavan	kuan	private	brickwork	15	6	Covered with R.C. C. Slab safe	none	none	22.7493007, 75.8497136	http://swm-api.acceldash.com/uploads/reports/1681730151414.jpeg
543	17	18	Sanwer, Road, mental, Hospital ke kempus me	kuan	government	brickwork	25	6	Jali se dhaka ha safe	none	none	22.7493007, 75.8497136	http://swm-api.acceldash.com/uploads/reports/1681730576028.jpg
544	17	18	Sanwer road mental hospital administration office ke samne	kuan	government	brickwork	30	5	Jali lagal jali thi hata di gai ha unsafe	none	none	22.7493007, 75.8497136	http://swm-api.acceldash.com/uploads/reports/1681730859961.jpeg
545	17	18	Sanwer road, Bhagat shingh nagar sarswati kucith asram	kuan	government	brickwork	25	5	Mitl malbe se bhar diya gaya ha C. C. Damar kar diya gaya ha	none	none	22.748158, 75.8478309	http://swm-api.acceldash.com/uploads/reports/1681731256852.jpeg

546	17	18	Sanwter road bhagat shing nagar lohar baba vali galli. Bharu baba ka mandir	kuan	private	brickwork	23	5	उक्त स्थान पर कई वर्षों पूर्व खुले कुए पर स्थानीय लोगों द्वारा मलवा मिट्टी से भराव कर पिपलेश्वर महादेव मंदिर का निर्माण कर दिया गया	none	none	22.748168, 75.8478309	http://swm- api.acceldash.com/uploads/re gisters/16817322737.jpg
547	17	18	Sanwter road govind nagar kahrca gali. No. 3. shiv shakti mandirke same	kuan	private	brickwork	18	5	उक्त स्थान पर कुछ वर्षों पूर्व भराव कर मलके मकान का निर्माण कर दिया गया है	none	none	22.7492038, 75.847394	http://swm- api.acceldash.com/uploads/re gisters/1681732154910.jpg
548	17	18	Sanwter road bhagat shingh nagar. सिवारी complex parisar	kuan	private	brickwork	32	6	उक्त स्थान पर कुए पर मुंडेर का निर्माण होकर लोहे की जाली से ढका है किंतु कुआं दस रहा है जो कि खतरनाक है	none	none	22.7492038, 75.847394	http://swm- api.acceldash.com/uploads/re gisters/1681732287811.jpg
549	17	18	Sanwter road maruti nagar sha vas kush asram parisar ma	kuan	government	brickwork	15	4	उक्त स्थान पर कुए पर 3 फीट ऊंचाई की मुंडेर का निर्माण होकर लोहे की जाली नहीं लगी है एवं कुआं में मिट्टी और मलबे का भराव कर दिया गया है	none	none	22.7495306, 75.8496468	http://swm- api.acceldash.com/uploads/re gisters/16817322958227.jpg
550	17	18	Bhavani nagar. Mata ji. Mandir. parisar	kuan	government	brickwork	32	8	उक्त कुए पर वर्षों पूर्व लोहे की जाली लगाई गई थी जो कि अब जगह जगह से क्षतिग्रस्त हो गई है कुवे का मेंटेनेंस आवश्यक है	none	none	22.7732618, 75.8423345	http://swm- api.acceldash.com/uploads/re gisters/1681733366518.jpg
551	17	18	Bhawrasla Gav Shiv. Mandir	kuan	private	brickwork	15	2	उक्त स्थान पर निर्मित कुवे पर स्थानीय सर्वसीयो द्वारा मलवा मिट्टी डालकर असुरीसी छत डालकर नगर निगाा सीमा में आने के पहले दिनांक 5.7. 2024 शिव मंदिर का निर्माण कर दिया गया है	none	none	22.779378, 75.8450262	http://swm- api.acceldash.com/uploads/re gisters/1681733669924.jpg

559	17	18	Ujain road narwal monti baba ashram parisar	bawdi	private	stone	42	5	5	Safe	none	none	22.7826506, 75.8486423	http://swin.apicelldash.com/uploads/reposters/1681793422459.jpeg
560	17	18	Ujain road kaka Shree Petrol Pump ke Piche Garam.	kuan	private	brickwork	30	8	8	Safe	none	none	22.7874405, 75.8457372	http://swin.apicelldash.com/uploads/reposters/1681793714971.jpeg
561	18	53	Revdi shakmbari. Parisar Azad nagar Mansuri kirana ke paas wali gali me	kuan	government	brickwork	16	7	7	not required	none	none	22.6928912, 75.8862689	http://swin.apicelldash.com/uploads/reposters/1681793910838.jpeg
562	18	53	Near Fatima Masjid madine nagar gali no. 4	kuan	private	brickwork	14	4.5	4.5	not required	none	none	22.693391, 75.8854004	http://swin.apicelldash.com/uploads/reposters/1681794307367.jpeg
563	18	53	Azad Nagar Chatni Gali Soheli Kirana ke Pass	kuan	government	brickwork	13	2.4	2.4	well boundary and well structural steel (lohe ki jali) is required.	none	none	22.6920581, 75.8873432	http://swin.apicelldash.com/uploads/reposters/1681794402525.jpeg
564	18	53	AZAD NAGAR NURI NAGAR MUKTIDHAM KE PICHE	kuan	government	brickwork	11	2.7	2.7	cleaning required	none	none	22.6928992, 75.8899022	http://swin.apicelldash.com/uploads/reposters/1681794896828.jpeg
565	18	53	AZAD NAGAR NEAR ALFALAH MADARSA RAJAK PATEL HOUSE	kuan	private	brickwork	18	3.5	3.5	no required	none	none	22.6928992, 75.8899022	http://swin.apicelldash.com/uploads/reposters/1681795237645.jpeg
566	18	53	AZAD NAGAR NURI NAGAR MEDAN KE PASS	kuan	government	brickwork	14	5.8	5.8	well boundary and well structural steel (lohe ki jali) required.	none	none	22.6958323, 75.8891301	http://swin.apicelldash.com/uploads/reposters/1681795106299.jpeg
567	18	53	AZAD NAGAR TANVEER DUDH DAIRY WATER PUMP URDU SCHOOL KE PASS	kuan	government	brickwork	14	8	8	well boundary and structural steel (lohe ki jali) required	none	none	22.696669, 75.8909196	http://swin.apicelldash.com/uploads/reposters/1681801412015.jpeg
568	18	53	NEAR MOHAMMADI MASJID AZAD NAGAR13	kuan	government	brickwork	13	3.3	3.3	not required	none	none	22.6970747, 75.8858144	http://swin.apicelldash.com/uploads/reposters/1681802654318.jpeg
569	18	53	AZAD NAGAR BACK SIDE OF URDU SCHOOL	kuan	government	brickwork	16	6.6	6.6	well boundary and structural steel (lohe ki jali) is required...	permanen:	residential	22.6971063, 75.8958222	http://swin.apicelldash.com/uploads/reposters/1681802772944.jpeg
570	18	53	AZAD NAGAR MUSLIM KABRISTAN	kuan	government	brickwork	12	4.3	4.3	not required	none	none	22.6971063, 75.8858222	http://swin.apicelldash.com/uploads/reposters/1681803080454.jpeg
571	19	50	गौरी बुद्धेश्वर गंगा माता मंदिर पिपलियागा गांव	kuan	government	brickwork	13	4	4	safe	none	none	22.7008321, 75.9092076	http://swin.apicelldash.com/uploads/reposters/1681803423643.jpeg
572	19	50	श्री खेड़माती हनुमान मन्दिर पिपलियागा गांव	kuan	government	brickwork	18	7	7	iron jali required on top for safety and maintenance	none	none	22.7348561, 75.9591135	http://swin.apicelldash.com/uploads/reposters/1681805421240.jpeg

573	19	41	shw temple kanadia road near bangali square	kuan	government	rcc	15	5	5	safe	none	none	22.7357267, 75.939124	http://swm- acceldash.com/uploads/re gistrs/168180720927.jpg
574	19	50	वैभवा नगर उद्यान सेक्टर सी उद्यान के पास	kuan	government	brickwork	17	8	8	safe	none	none	22.7189857, 75.9195622	<a href="http://swm-
acceldash.com/uploads/re
gistrs/1681807579923.jpg">http://swm- acceldash.com/uploads/re gistrs/1681807579923.jpg
575	19	41	shree ram temple near subh labh avenue	kuan	private	rcc	16	4	4	iron jali required	none	none	22.7348561, 75.9591125	<a href="http://swm-
acceldash.com/uploads/re
gistrs/168180401832.jpg">http://swm- acceldash.com/uploads/re gistrs/168180401832.jpg
576	19	41	हनुमान मंदिर कनाडिया रोड 12 संचार नगर के पास	kuan	government	brickwork	16	8	8	safe	none	none	22.7240256, 75.9161001	<a href="http://swm-
acceldash.com/uploads/re
gistrs/1681895569119.jpg">http://swm- acceldash.com/uploads/re gistrs/1681895569119.jpg
577	19	41	ख समीर चिटनिश उद्यान आलोक नगर 15	kuan	government	brickwork	18	9	9	safe	none	none	22.7240256, 75.9161001	<a href="http://swm-
acceldash.com/uploads/re
gistrs/1681961876100.jpg">http://swm- acceldash.com/uploads/re gistrs/1681961876100.jpg
578	19	76	करुणा सागर कनाडिया रोड	kuan	government	brickwork	17	7	7	unsafe, maintenance required,	none	none	22.7281753, 75.9313298	<a href="http://swm-
acceldash.com/uploads/re
gistrs/168205934248.jpg">http://swm- acceldash.com/uploads/re gistrs/168205934248.jpg
579	19	76	khasra 357 शीला सिंह ईट का भट्ट	bawdi	government	stone	9	8	12	maintenance required	none	none	22.7348561, 75.9591125	<a href="http://swm-
acceldash.com/uploads/re
gistrs/1682057135983.jpg">http://swm- acceldash.com/uploads/re gistrs/1682057135983.jpg
580	19	76	खसरा 194 कनाडिया सचिन पिता नरेश	bawdi	private	brickwork	10	15	25	maintenance required	none	none	22.7348561, 75.9591125	<a href="http://swm-
acceldash.com/uploads/re
gistrs/1683098963575.jpg">http://swm- acceldash.com/uploads/re gistrs/1683098963575.jpg
581	19	75	कर्बला मैदान ,to road	kuan	government	brickwork	15	6	8	ok	none	none	22.6667685, 75.9141535	<a href="http://swm-
acceldash.com/uploads/re
gistrs/1682059910315.jpg">http://swm- acceldash.com/uploads/re gistrs/1682059910315.jpg
582	19	75	NEAR RTO PALDA RE 2 ROAD	kuan	government	brickwork	20	7	7	maintenance required	none	none	22.6754272, 75.9089517	<a href="http://swm-
acceldash.com/uploads/re
gistrs/1682140877705.jpg">http://swm- acceldash.com/uploads/re gistrs/1682140877705.jpg
583	19	75	near PMAY PROJECT RTO ROAD MADAN LAL KUMAWAT	kuan	private	brickwork	25	6	6	iron jali required	none	none	22.6727164, 75.9063429	<a href="http://swm-
acceldash.com/uploads/re
gistrs/1682142707816.jpg">http://swm- acceldash.com/uploads/re gistrs/1682142707816.jpg
584	19	75	खसरा क्रमांक 228 पालदा विनय कुमार	kuan	private	brickwork	18	6	6	iron jali required	none	none	22.6791107, 75.8947474	<a href="http://swm-
acceldash.com/uploads/re
gistrs/1682142707816.jpg">http://swm- acceldash.com/uploads/re gistrs/1682142707816.jpg
585	19	75	near tejaji chowk	kuan	government	brickwork	17	6	6	maintenance required	none	none	22.6807506, 75.89487	<a href="http://swm-
acceldash.com/uploads/re
gistrs/168214259763.jpg">http://swm- acceldash.com/uploads/re gistrs/168214259763.jpg
586	19	75	khasra 74/1 पालदा हिममत नगर औपन परिया	kuan	private	brickwork	15	4	4	maintenance required	none	none	22.6814209, 75.8901558	<a href="http://swm-
acceldash.com/uploads/re
gistrs/1682333215148.jpg">http://swm- acceldash.com/uploads/re gistrs/1682333215148.jpg
587	19	75	हिममत नगर भट्टे के पारा	kuan	government	brickwork	15	4	4	unsafe	none	none	22.6804885, 75.8905355	<a href="http://swm-
acceldash.com/uploads/re
gistrs/1682333721005.jpg">http://swm- acceldash.com/uploads/re gistrs/1682333721005.jpg

588	19	75	मुक्ता प्रजापति हिममत नगर	kuan	private	brickwork	15	4	4	4	none	none	22.6802406, 75.889149	api.acceldash.com/uploads/re-gisters/1682335734811.jpg
589	19	75	कन्हैया लाल कश्यप हिममत नगर	kuan	private	brickwork	18	6	6	6	none	none	22.6803249, 75.8888515	api.acceldash.com/uploads/re-gisters/168275050756.jpg
590	19	75	राधा स्वामी सरसंग कॅम्पस	kuan	private	brickwork	18	6	6	6	ok	none	22.6801134, 75.8886695	api.acceldash.com/uploads/re-gisters/1682580230221.jpg
591	19	75	babulal dhakad खसरा 264/3	kuan	private	stone	15	5	5	5	none	none	22.6753892, 75.8967052	api.acceldash.com/uploads/re-gisters/1682745470392.jpg
592	19	75	खसरा 292 मुड्डला नायला मंसूर पिता सरार	kuan	private	stone	13	7	7	7	none	none	22.6694736, 75.9126734	api.acceldash.com/uploads/re-gisters/1682745783052.jpg
593	19	75	st arnold school campus 1	kuan	private	brickwork	20	9	9	9	ok	none	22.6836911, 75.8877559	api.acceldash.com/uploads/re-gisters/168274577333.jpg
594	19	75	st arnold school well no 02	kuan	private	brickwork	20	10	10	10	none	none	22.684198, 75.8866212	api.acceldash.com/uploads/re-gisters/16825470347.jpg
595	19	75	st arnold school well no 03	kuan	private	brickwork	17	7	7	7	ok	none	22.6845396, 75.8866227	api.acceldash.com/uploads/re-gisters/1682088080988.jpg

Annexure-2



कार्यालय, नगर पालिक निगम, इन्दौर
जलयंत्रालय एवं ड्रेनेज विभाग

क्रमांक - 1137 / 23-24 / इन्दौर

दिनांक 19.7.23

प्रति,

श्री एस.एन. द्विवेदी
क्षेत्रीय अधिकारी
क्षेत्रीय कार्यालय म.प्र. प्रदुषण नियंत्रण बोर्ड
स्कीम नं. 78-सी, पार्ट-2 अरण्य नगर इन्दौर

विषय :- माननीय राष्ट्रीय हरित अधिकरण, सेन्ट्रल झोन, भोपाल में प्रचलित प्रकरण क्र. 306/2023 (प्रियान्शु गुप्ता विरुद्ध म.प्र. शासन) में दिनांक 20.04.2023 को पारित आदेश के अनुपालन बाबद्।

संदर्भ :- 1. आपका पत्र क्र. 2471/क्षे.का.ई/2023, इन्दौर, दिनांक 18.07.2023
2. आपका पत्र क्र. 1431/क्षे.का.ई/2023, इन्दौर, दिनांक 17.07.2023

उपरोक्त विषयांतर्गत संदर्भित पत्र के क्रम में लेख है कि, संदर्भित पत्र क्र. 02 के बिन्दु क्र. 01 में उल्लेखित अनुसार बॉवडी को भरने के संबंध में आदेश की प्रति चाही गई थी, तदक्रम में लेख है कि, बॉवडी क्षतिग्रस्त हो जाने से भविष्य में कोई जनहानि ना हो के दृष्टिगत जिला प्रशासन के निर्णय एवं वरिष्ठ अधिकारियों के निर्देशानुसार बॉवडी भरने का कार्य किया गया। भविष्य में ऐसी दुर्घटना ना हो के दृष्टिगत निगम द्वारा कुओं/बॉवडी को संरक्षित करने हेतु संलग्न आदेश जारी किया गया है।

अतः चाही गई जानकारी अग्रिम कार्यवाही हेतु प्रेषित।

(अपर आयुक्त महोदय द्वारा अनुमोदित)


अधीक्षण यंत्री

जलयंत्रालय एवं ड्रेनेज
नगर पालिक निगम, इन्दौर

कार्यालय, नगर पालिक निगम, इंदौर

क्रमांक 1364.../2023

इंदौर, दिनांक 31.03.2023

आदेश

झोन क्रमांक 18 अंतर्गत दिनांक 30.03.2023 को स्नेह नगर के पास पटेल नगर में वेंलेश्वर महादेव झूलेलाल मंदिर स्थित वावड़ी के अचानक धंसने की घटित घटना को दृष्टिगत रखते हुए समस्त झोनल अधिकारियों, भवन अधिकारियों एवं भवन निरीक्षकों को आदेशित किया जाता है कि, आपके झोन क्षेत्रान्तर्गत स्थित ऐसे समस्त कुएं व वावड़ियां जो खुले हुए हैं व जिनके खुले रहने से किसी भी समय कोई अप्रिय घटना घटित होने की संभावना है तथा ऐसे समस्त कुएं व वावड़ियां जिन पर अतिक्रमण कर अवैध निर्माण कर लिया गया है को सूचीबद्ध कर, विस्तृत एवं समुचित सर्वे कराते हुए अतिक्रमण कुएं व वावड़ियों को निर्धारित प्रक्रिया का नियमानुसार पालन करते हुए अतिक्रमण मुक्त कराया जाना सुनिश्चित करें।

उपरोक्त निर्देशित कार्यवाही अभियान के रूप में पूर्ण कराते हुए पालन प्रतिवेदन संबंधित अपर आयुक्त को उपलब्ध कराते हुए अधोहस्ताक्षरी को अवगत कराना सुनिश्चित करें। ताकि दिनांक 30.03.2023 को घटित घटना की भविष्य में पुनरावृत्ति न हों।

आदेश का तत्काल प्रभाव से पालन किया जावे।

7847 7855 03

पृ. क्रमांक/2022

आयुक्त
नगर पालिक निगम, इंदौर
इंदौर, दिनांक 31.03.2023

प्रतिलिपि :-

1. निजी सहायक महापौर की ओर मान. महापौर जी को अवगत कराने हेतु प्रेषित।
2. अपर आयुक्त (समस्त) नगर पालिक निगम, इंदौर।
3. कार्यपालन यंत्री (भवन अनुज्ञा-मुख्यालय), नगर पालिक निगम, इंदौर की ओर संपूर्ण कार्यवाही स्वयं के नियंत्रण, निर्देशन में निर्धारित समयावधि में कराया जाना सुनिश्चित करें।
4. कार्यपालन यंत्री (समस्त), नगर पालिक निगम, इंदौर।
5. सचिव, नगर पालिक निगम, इंदौर।
6. उपायुक्त (रिमुक्कल), नगर पालिक निगम, इंदौर।
7. झोनल अधिकारी, झोन क्रमांक 01 से 19 तक, नगर पालिक निगम, इंदौर की ओर पालनार्थ।
8. भवन अधिकारी, झोन क्रमांक 01 से 19 तक, नगर पालिक निगम, इंदौर की ओर पालनार्थ।
9. भवन निरीक्षक, झोन क्रमांक 01 से 19 तक, नगर पालिक निगम, इंदौर की ओर पालनार्थ।

आयुक्त
नगर पालिक निगम, इंदौर

Annexure-3

कार्यालय नगर पालिक निगम, इंदौर

बंद कुए बावड़ी की सूची

प्रपत्र (अ)

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Ba-wadi	Depth (in meters)	Width/Diameter (in meters)	Useful or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-location	Remarks
1	2	6	Test	Kuan	government	rcc	10	10	testing the software	Close	residential	22.7725866, 75.8951093	उक्त कुए पर स्टेव डालकर पूरे में सड़क निर्माण की गयी थी। वर्तमान में आवारागमन हो रहा था। जनगणिका की दरिगाह से उक्त कुए की स्टेव को हटाकर भराव करके पूर्ण रूप से बंद किया गया है ताकि भविष्य में कोई दुर्घटना न हो।
2	2	69	8, pipil bajar	kuan	private	stone	12	2.5	unsafe	Close	commercial	22.7191395, 75.8511407	उक्त कुए पर स्टेव डालकर पूरे में सड़क निर्माण की गयी थी। वर्तमान में आवारागमन हो रहा था। जनगणिका की दरिगाह से उक्त कुए की स्टेव को हटाकर भराव करके पूर्ण रूप से बंद किया गया है ताकि भविष्य में कोई दुर्घटना न हो।
3	2	69	narsingh tower, narsingh bajar chouraha	kuan	government	stone	10	2	unsafe	Close	commercial	22.7156106, 75.8466528	उक्त कुए पर स्टेव डालकर पूरे में सड़क निर्माण की गयी थी। वर्तमान में आवारागमन हो रहा था। जनगणिका की दरिगाह से उक्त कुए की स्टेव को हटाकर भराव करके पूर्ण रूप से बंद किया गया है ताकि भविष्य में कोई दुर्घटना न हो।
4	3	56	bumpy dumpy school ke samne	kuan	government	stone	25	7	at present above slab is damaged by govt authority	Close	none	22.7277743, 75.8645929	उक्त कुए पर स्टेव डालकर पूरे में सड़क निर्माण की गयी थी। वर्तमान में आवारागमन हो रहा था। जनगणिका की दरिगाह से उक्त कुए की स्टेव को हटाकर भराव करके पूर्ण रूप से बंद किया गया है ताकि भविष्य में कोई दुर्घटना न हो।
5	11	55	Dhakkan wala kuan Darigaah	kuan	government	brickwork	15	3	Unsafe,	close	none	22.7239432, 75.8868061	उक्त कुए पर स्टेव डालकर पूरे में सड़क निर्माण की गयी थी। वर्तमान में आवारागमन हो रहा था। जनगणिका की दरिगाह से उक्त कुए की स्टेव को हटाकर भराव करके पूर्ण रूप से बंद किया गया है ताकि भविष्य में कोई दुर्घटना न हो।

S.No.	Zone	Ward	Address	Type	Category	Types of Construct ion of Kuan/Ba well	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Enhancement Category	Geo-location	Remarks
6	17	23	La Gali Farshi Wala Chawk Pardespura	kuan	government	brickwork	13	2	Slab is constructed over well where traffic passes over this.As water is not available it should be packed.	Close	none	22.7455878, 75.866659	उक्त कुए पर स्लैब डालकर पूर्व में राउक निर्माण की गयी थी। वर्तमान में आसपास ही रहा था। जनशान की दृष्टिगत से उक्त कुए की स्लैब को हटाकर भराव करके पूर्ण रूप से बंद किया गया है ताकि भविष्य में कोई दुर्घटना न हो।
7	17	23	Koli Mohalla, Mahadev Gauri Mandir Gali No 11	kuan	government	brickwork	20	3	Road constructed over the Well traffic passes over the well.Maintenance work must be done.It should be opened	close	none	22.7454973, 75.8656974	उक्त कुए पर स्लैब डालकर पूर्व में राउक निर्माण की गयी थी। वर्तमान में आसपास ही रहा था। जनशान की दृष्टिगत से उक्त कुए की स्लैब को हटाकर भराव करके पूर्ण रूप से बंद किया गया है ताकि भविष्य में कोई दुर्घटना न हो।
8	17	19	Ganesh, Dhan. Main. Road. 216	kuan	private	brickwork	22	3	Kuva को bhar kar makan ka nirman kar diya Gaya ha. Sale	Close	none	22.7631852, 75.8477665	kuva को bhar kar makan ka nirman kar diya. Gaya ha. Sale
9	17	19	Ganesh. dgam. United. Mission school के samne	kuan	private	brickwork	40	4	kuve को bharav kar makan ka nirman kar diya gaya ha	close	none	22.7609187, 75.8487159	kuve को bharav kar makan ka nirman kar diya gaya ha
10	17	18	Sanwer road bhugat shing nagar lohar baba vali gali. Bharu baba ka mandir	kuan	private	brickwork	23	5	उक्त स्थान पर कई वर्षों पूर्व खुले कुए पर सैन्यीय लोगों द्वारा मलबा सिंटी से भराव कर विपरीत में महादेव मंदिर का निर्माण कर दिया गया	close	none	22.748168, 75.8478309	उक्त स्थान पर कई वर्षों पूर्व खुले कुए पर सैन्यीय लोगों द्वारा मलबा सिंटी से भराव कर विपरीत में महादेव मंदिर का निर्माण कर दिया गया

S.No.	Zone Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi well	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Engrovement Category	Geo-Location	Remarks
11	17	Sanwer road gowind nagar kahirca gali, No. 3, shiv shakti mandirke samne	kuan	private	brickwork	18	5	उक्त स्थान पर कुछ वर्षों पूर्व भटव कर पूर्व भराव कर पक्क मकान का निर्माण कर दिया गया है	Close	none	22.7492038, 75.847394	उक्त स्थान पर कुछ वर्षों पूर्व भटव कर पक्के मकान का निर्माण कर दिया गया है
12	17	Bhavastla gav Shiv. Mandir	kuan	private	brickwork	16	2	उक्त स्थान पर निर्मित कुवे पर स्थानीय रवातसीयो द्वारा भराव मिट्टी डालकर आखरीसी छत डालकर नगर निगम सीमा में आने के पहले दिनांक 5.7.2014 शिव मंदिर का निर्माण कर दिया गया है	close	none	22.779378, 75.8450252	उक्त स्थान पर निर्मित कुवे पर स्थानीय रवातसीयो द्वारा भराव मिट्टी डालकर आखरीसी छत डालकर नगर निगम सीमा में आने के पहले दिनांक 5.7.2014 शिव मंदिर का निर्माण कर दिया गया है
13	17	ujain road/Bhavastla chouraha sulab complex के age से गाँव के खुद margin par left sinde	bawdi	government	stone	16	3	उक्त स्थान पर ग्रामीण रवातसी द्वारा भराव मिट्टी से ढाबड़ी को भरकर शिव मंदिर का निर्माण कर शोड लगा दिया गया है उक्त कार्य नगर निगम की सीमा में आने से पहले किया गया है	close	none	22.7915904, 75.8458923	उक्त स्थान पर ग्रामीण रवातसी द्वारा भराव मिट्टी से ढाबड़ी को भरकर शिव मंदिर का निर्माण कर शोड लगा दिया गया है उक्त कार्य नगर निगम की सीमा में आने से पहले किया गया है
14	17	Garam सरदारी shree ram carbar mandir parisar	kuan	private	brickwork	16	5	उक्त स्थान पर ग्रामीण वासियों द्वारा लोकिर भवन गांव ग्राम वासियों द्वारा मिट्टी भराव का भराव कर श्री राम मंदिर का निर्माण कर दिया गया है क्योंकि नगर निगम की सीमा में आने के पूर्व निर्मित है	close	none	22.792926, 75.8380614	उक्त स्थान पर ग्रामीण वासियों द्वारा लोकिर भवन गांव ग्राम वासियों द्वारा मिट्टी भराव का भराव कर श्री राम मंदिर का निर्माण कर दिया गया है क्योंकि नगर निगम की सीमा में आने के पूर्व निर्मित है



अधीक्षण यंत्री

जाल युंत्रालय एवं ड्रेनेज
इन्दीर नगर पालिक निगम

56

Annexure-4

कार्यालय नगर पालिक निगम, इंदौर
संधारण कार्य किये गये कुए / बावड़ी की सूची

प्रपत्र (ब)

S.No	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe-of Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-Location
1	1	9	Near GDC police campus V/P Route	kuan	government	stone	20	4	Inside clean and Covered by jaali. surrounding cleaning required my health department	No	none	22.7296364, 75.8456869
2	1	9	Kamla nehru nagar near h no. 37B	bawdi	government	stone	20	5	covered with jaali, safai required	No	none	22.7383913, 75.8453201
3	1	9	32/54 Khasgi ka Bageecha	kuan	government	brickwork	8	5	Garder Jaali Damaged Munder required on road level safai required one column removed by removal team civil work required	No	residential	22.7402905, 75.8465269
4	1	9	vrindavan garden	kuan	government	brickwork	15	4	safai required rest ok	No	none	22.7372594, 75.8481268
5	1	9	Gadrakhedi Khatu Shyam Mandir Footpath	kuan	government	brickwork	10	2	civil work in progress after removal	No	none	22.7398079, 75.849325
6	1	9	15th Battalion	kuan	government	brickwork	10	3	jaali required safai required	No	none	22.7348162, 75.8466703

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-Location
7	1	9	Behind Girls School Open Area	kuan	government	rcc	12	3	jaali repair munder required safai required	No	none	22.7348162, 75.8466703
8	1	7	Behind Sharda Kanya School	kuan	government	brickwork	12	4	jaali repair safai required munder new required	No	none	22.7216065, 75.8412604
9	1	7	Near Fire Station VIP route	kuan	government	brickwork	25	3	munder required and safai Wall must be removed at time of munder construction	No	none	22.7268495, 75.8421951
10	1	7	Ram Krishna Mission School Campus	kuan	private	brickwork	12	3	covered with slab and parapret wall	No	none	22.7263351, 75.8400834
11	1	4	Panchwati Colony	kuan	government	brickwork	20	6	jaali ok net ok safai required	No	none	22.7266394, 75.8332513
12	1	4	Shivdham Mandir Kanyakubj Garden	kuan	government	brickwork	12	2	covered i near shiv pratima	No	religious	22.7276044, 75.8283348
13	1	4	Nemi Nath Villa Sadhna Nagar	kuan	private	stone	18	5	parapret height must be increased, jaali ok	No	none	22.7279425, 75.8296826
14	1	7	Shramik Colony Kandipur Shetleshwar Mahadev Mandir Hanuman Mandir Hukumchand Pehlwan Subhash Marg	kuan	private	stone	15	3	jaali ok r et ok wall height may be increased	No	none	22.723466, 75.8270937
15	1	7	Hanuman Mandir VeerGadi	kuan	government	brickwork	15	4	jaali ok	No	none	22.7241248, 75.8444968
16	1	7	Hanuman Mandir Campus	bawdi	government	stone	18	5	Civil work required jaali ok safai	No	none	22.7252682, 75.8442845

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-Location
17	1	16	Chota Bangarda Petrol Pump	kuan	government	brickwork	18	6	jaali ok	No	none	22.7446792, 75.8147272
18	1	16	Hanuman Mandir Garcen Vyankatesh Vihar	kuan	government	brickwork	15	4	jaali ok	No	none	22.7462337, 75.8172601
19	1	16	Vandana Nagar	kuan	government	brickwork	12	7	jaali ok water dirty	No	none	22.7366589, 75.8242163
20	1	8	tatya ki bawdi laal hospital	bawdi	government	stone	15	10	covered with grill and shed minor cracks in wall	No	none	22.722933, 75.8451934
21	1	7	Hathile Hanuman Mandir Campus	kuan	government	brickwork	12	1.5	jaali covered parapret ok safai required	No	none	22.7271603, 75.8486202
22	1	7	A-15 Quarter VIP Route	kuan	government	brickwork	20	2	uncovered jaali required	No	none	22.7262799, 75.8434538
23	1	7	A-17 Vip Route Quarter	kuan	government	brickwork	12	4	jaali ok safai required	No	none	22.7265693, 75.8430641
24	1	7	Mahadev Mandir Hari Parvat Gaurav nagar ke peche	kuan	government	brickwork	12	1.5	jaali nhi hai parapret wall required	No	none	22.7223601, 75.8394489
25	1	7	Kadabeen Lal Mandir ke पास	kuan	government	stone	12	2	Covered	No	none	22.7204505, 75.8424164
26	2	6	सुमनचंद नगर में उद्यान	kuan	government	brickwork	18	9	required maintenance work :-cleaning work ,green net , colour l	No	none	22.7213658, 75.8347229
27	2	6	hukumchand colony sarkari school kua	bawdi	government	brickwork	10	3	not required	No	religious	22.7264163, 75.8322122

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-Location
28	2	6	panchkuiya shree Ram mandir in front of goushala	kuan	government	brickwork	15	3	cleaning, steel work repair required	No	none	22.7198011, 75.8329347
29	2	6	panchkuiya khedapati mandir kua	kuan	government	brickwork	15	2.5	not required	No	none	22.7178983, 75.8322359
30	2	6	hansdas math bawdi piliyakhal	bawdi	private	stone	20	4	maintenance work required..	No	none	22.721643, 75.8354197
31	2	69	1/11 mahesh nagar	kuan	private	stone	12	2.5	safe	No	none	22.7165081, 75.8429887
32	2	6	sitarer park kua	kuan	private	brickwork	15	5	steel work repair and cleaning work..	No	educational	22.7198854, 75.8398103
33	2	69	Old rajmohalla sabji mandi	kuan	government	stone	15	6	Maintenance required	No	none	22.7143891, 75.8446685
34	2	69	saranga sarees , govardhan chok , MT cloth market15	kuan	government	stone	15	2	safe	No	none	22.7172191, 75.8479205
35	2	69	Govardhan nath mandir, yashwant road	kuan	private	stone	25	2.5	Safe	No	none	22.71805, 75.84813
36	2	69	Govardhan nath mandir, yashwant road	kuan	private	stone	12	2	Safe	No	none	22.7182197, 75.8473947
37	2	70	indreshwer mahadev mandir adrsh indira nagar	kuan	government	brickwork	12	4	maintenance required	No	none	22.711844, 75.8328775

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (In meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-Location
38	2	70	190 loknayak nagar	kuan	government	brickwork	15	4	maintenance required	No	none	22.7131021, 75.8336038
39	2	70	jila hospital campus	kuan	government	brickwork	15	4	no	No	none	22.7131021, 75.8336038
40	2	69	tulsidas ram mandir, khajuri bajar mg road	kuan	private	stone	15	1.5	Maintenance required	No	none	22.7193956, 75.8496813
41	2	67	baake bihari mandir, chhattisgarh	kuan	government	stone	12	2	Maintenance required	No	none	22.7166676, 75.8407965
42	2	67	vyankatesh mandir, chhattisgarh	kuan	private	stone	10	2	Maintenance required	No	none	22.711664, 75.851031
43	2	67	shree agni akhada hanuman mandir(ramjhiri), chhattisgarh	kuan	private	brickwork	9	2	Safe	No	none	22.7093413, 75.851413
44	2	67	na yo ki bagichi, jairampur pool ke pass, chhattisgarh	kuan	private	brickwork	9	2	Safe	No	none	22.7097021, 75.8519324
45	2	67	shree rameshwar ma-nadev mandir, chhattisgarh	kuan	private	brickwork	15	1.5	safe	No	none	22.7095776, 75.8495548
46	2	67	ramdwar, chhattisgarh	kuan	private	brickwork	12	2	safe	No	none	22.7088961, 75.8478514
47	2	67	maruti mandir, bara bhai	kuan	private	brickwork	10	2	safe	No	none	22.7066811, 75.84705

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-Location
48	2	67	shaligram ka bagicha, arjunpura lal bagh k samne	kuan	government	brickwork	15	5	safe	No	none	22.7055947, 75.8463143
49	2	69	bhakt prahelad nagar udhyan	kuan	government	brickwork	12	2	safe	No	none	22.7066851, 75.8469672
50	2	67	trishala apartment, biyabani	kuan	private	brickwork	12	2.5	safe	No	none	22.7118378, 75.8459574
51	2	6	Nehru nagar road no.08 jairam kol ke makan ke samne	kuan	government	stone	20	5	safe	No	none	22.7352684, 75.8850771
52	3	56	kachi mohalla jyoti cinema ke samne	kuan	government	stone	45	15	disilting and dewatering	No	none	22.724753, 75.8619285
53	3	57	District court	kuan	government	stone	20	3	Desilting and dewatering of well and changing old damage jali	No	none	22.7197004, 75.8648656
54	3	57	gopeshwar mahadev mandir gandhi hall	kuan	private	stone	15	3	disilting	No	none	22.7250524, 75.8664923
55	3	56	hanuman mandir ke paas	kuan	government	stone	22	5	Desilting & dewatering of well	No	none	22.7197844, 75.8659774
56	3	56	Central Jail Shiv mandir ke paas	kuan	government	stone	15	5	Desilting & dewatering of well	No	none	22.7277743, 75.8645929
57	3	57	narayan bag bawdi	bawdi	government	rcc	20	12	dewatering and disilting and painting	No	none	22.7271017, 75.8642257

62

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-Location
58	3	56	Kacchi mohalla Lal kuan	kuan	government	stone	15	4	Desilting and dewatering required	No	none	22.7223907, 75.8629203
59	3	57	Heera bawdi cologround	bawdi	government	stone	20	15	Desilting and dewatering required	No	none	22.731293, 75.8573256
60	3	58	sadar bazar shiv mandir ke samne	kuan	private	stone	10	3	cleaning and new jali	No	none	22.7273744, 75.8519862
61	3	56	Rajkumar mandir Sheelnath camp well	kuan	private	stone	18	4	Desilting and dewatering required	No	none	22.7313971, 75.8571681
62	3	56	Rejkumar Mandir Sheelnath camp bawdi	bawdi	private	stone	6	3	Jali required	No	none	22.7363715, 75.8655594
63	3	57	Rambag near 15 no.govt.school	kuan	government	stone	15	4	Desilting and dewatering required	No	none	22.7319081, 75.8604761
64	4	13	mataji ka bagicha scheme no. 51	kuan	government	brickwork	20	5	not required	No	none	22.7415203, 75.8358099
65	4	13	sector-c well	kuan	government	brickwork	20	12	not required	No	none	22.7370524, 75.8389573
66	4	13	laxmipuri near ram mandir	kuan	government	brickwork	18	5	not required	No	none	22.7344869, 75.8425877
67	4	10	Kabristan banganga	kuan	government	rcc	50	10	kachara	No	none	22.7363417, 75.8494347
68	4	13	laxmibai anaj mandir pwrtsar	kuan	government	brickwork	20	2	needs to be covered	No	none	22.7330733, 75.837161

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-Location
69	4	13	laxmanpura infront of laturbagh tigriya badshah road	kuan	government	brickwork	20	5	not required	No	none	22.7260437, 75.8441975
70	4	10	baou parag kabhatta	kuan	private	rcc	50	12	kachara	No	commercial	22.7463583, 75.8496783
71	4	10	brajlal wyam shala	kuan	government	rcc	50	12	pani	No	commercial	22.7374052, 75.8496677
72	4	11	rafeli community,aanga nwali & shani mandir campus	kuan	government	brickwork	18	2	not required	No	none	22.7454188, 75.8608392
73	4	11	marindra jain mithai shop 484 bhagirathpura	kuan	private	brickwork	15	2	not required	No	none	22.7463296, 75.8600484
74	4	11	mohan bagdi steel railing works infront of sachin paan near tejaji mandir	kuan	private	brickwork	18	4	covered jali maintenance required	No	none	22.7467718, 75.862137
75	4	12	govind col.gully no.2	kuan	government	brickwork	18	5.5	wire mesh reqd.	No	none	22.7415858, 75.847134
76	4	12	savniva Seth mandir.govind col.	kuan	government	brickwork	21	4.5	wall rep.plstr.reqd.	No	none	22.741357, 75.8454211
77	4	17	kushvah shree ngr.	kuan	private	brickwork	21	4.5	wall rep.reqd.	No	none	22.7471358, 75.8403867
78	4	17	kushvah ngr.near purv parshad house	kuan	private	brickwork	18	6	wall rep.reqd.	No	none	22.7484732, 75.8427526

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geolocation
79	4	12	maharana pratap ngr.tanki/goshala mndir	bawdi	government	stone	15	4.5	steel jali reqd.	No	none	22.747256, 75.8488563
80	4	12	baneshvr mahadev mndir ujjain Indore road	bawdi	government	stone	7.5	9	wire mesh reqd.	No	none	22.7457154, 75.8493438
81	4	17	vijayvargiya ngr.Ram mndir	kuan	government	brickwork	24	3	prpt wall rising reqd.	No	none	22.7527624, 75.8412303
82	4	11	chargiri kua mndir	kuan	private	brickwork	15	2	inside temple premise	No	religious	22.747501, 75.863744
83	4	17	prjapaty dharmshala,dashr ath bagh shiv mndir	kuan	private	brickwork	18	4.5	wire mesh reqd.& steel jali reqd.	No	none	22.7500033, 75.8369
84	4	12	rajaram ngr gully no.2	kuan	government	brickwork	15	6	wire mesh reqd.	No	none	22.7462017, 75.84087
85	5	22	M 35/A veena nagar main road trilokesvar mndir	kuan	government	brickwork	22	5	covered with jali and parapet walk (sate)	No	none	22.7588318, 75.8689601
86	5	21	492 shyam nagar main,	kuan	government	brickwork	24	5	coverd with jali and parapet wall(sate)	No	none	22.7591032, 75.8694146
87	5	21	59 sundar nagar Ext. ke samne	kuan	government	brickwork	20	5	covered with jali and parapet wall(sate)	No	none	22.7594703, 75.867991
88	5	22	love kush E sectar bandan gardn	kuan	government	brickwork	17	7	jali repairiy equired	No	religious	22.7508573, 75.8693542
89	5	22	sukhiya C sectar hanuman mndir HDFC bank	kuan	government	brickwork	10	6	covered with jali and parapet wall (sate)	No	none	22.7604813, 75.8725913

65

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-location
90	5	22	Ravidas nagar main road	kuan	government	brickwork	15	4	covered with jali and parapet wall (sate)	No	none	22.7613239, 75.8717996
91	5	22	murli vala sweet ke samne sukhliya main road	kuan	government	brickwork	16	6	covered with jali and parapet wall (sate)	No	none	22.7617025, 75.875863
92	5	28	megdud gardan music fauten ke pass	kuan	government	brickwork	13	7	jali repairs or parapet repairing required	No	none	22.7545284, 75.8792254
93	5	28	megdud gardan ke andar	kuan	government	stone	13	7	covered with jali and parapet wall (sate)	No	none	22.7502856, 75.8841774
94	5	28	kelash ka bhatta bajrang mandir	kuan	government	stone	12	5	jali repairs or parapet repairing required	No	none	22.7479836, 75.885204
95	5	28	mall samaj ki basti bhamori sarkari school	kuan	government	brickwork	12	3	covered with jali and parapet wall (sate)	No	none	22.7476304, 75.8849731
96	5	28	shiv sakti nagar gaytri mandie	kuan	government	brickwork	12	3	jali required	No	religious	22.7474140, 75.8834631
97	5	28	shiv sakti nagar shiv mandir bagicha	kuan	government	brickwork	15	7	covered with jali and parapet wall (sate)	No	religious	22.7474140, 75.8884632
98	5	22	AM sectar sukhiya pipleshvar mahadev mandir	kuan	government	brickwork	14	6	covered with jali and parapet wall (sate)	No	religious	22.7553899, 75.8758185
99	6	25	pakki chei main road	kuan	government	rcc	50	15.2	safe and covered	No	religious	22.7421303, 75.6674768

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Entrenchment Category	Geo Location
100	6	24	pipal ki chal	kuan	government	stone	32.5	15.6	safe and covered	No	none	22.7415839, 75.8053061
101	6	26	nehru nagar road no 08 near Mahadev temple	kuan	government	stone	20	5	Safe (slab removed on 04.04.2023)	No	none	22.7352684, 75.8850771
102	6	26	Nehru nagar Road no 04 near temple	kuan	government	stone	20	5	Safe	No	none	22.735214, 75.882502
103	6	25	Nehru nagar Road no 04	kuan	government	rcc	20	5	Safe	No	none	22.735244, 75.882502
104	6	26	Nehru nagar inside lalapura temple campus	kuan	government	brickwork	20	5	Safe	No	none	22.735406, 75.8799538
105	6	25	Patnipura main road basti	kuan	government	stone	20	4	Safe	No	none	22.7365263, 75.878784
106	6	25	Janita Quarter Main road inside Garden	kuan	private	brickwork	15	4	Safe	No	none	22.7365263, 75.878784
107	6	25	Nanda nagar post office Garden	kuan	government	brickwork	20	5	Safe	No	none	22.7439918, 75.8769985
108	6	25	Nanda nagar Road no 13 govt. school ke saamne shiv mandir	kuan	government	brickwork	15	4	safe. cleaning required	No	none	22.7427383, 75.8794755
109	6	27	Nanda nagar, Chandan chowk garden	kuan	government	brickwork	20	4	Safe	No	none	22.7163468, 75.8780751

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Enrichment Category	Geo-Location
110	5	24	parshad office ke peeche	kuan	government	brickwork	35	5	safe maintenance required	No	none	22.7427163, 75.8664296
111	6	24	Shyama Charan Shukla nagar	kuan	government	brickwork	35	12	safe And covered.	No	none	22.7383005, 75.8656725
112	7	29	AD Mand oi Garden Scheme No. 74 C	kuan	government	brickwork	12	4	No Maintenance Required	No	none	22.7575019, 75.8864446
113	7	29	Panchmukhi Hanuman Mandir	kuan	government	brickwork	20	4	No Maintenance Required	No	none	22.7557273, 75.8946665
114	7	32	Near Nari Masand	kuan	government	brickwork	10	4	No Maintenance Required	No	none	22.7593096, 75.897611
115	7	34	Bawdi Balaji Hanuman Mandir Scheme no 78	bawdi	government	brickwork	15	7	Jali Damaged, Jali Maintenance Required	No	none	22.7650481, 75.887236
116	7	29	Zone -08 Campus Vijay Nagar Square	kuan	government	brickwork	15	6	No Maintenance Required	No	none	22.7528769, 75.8955122
117	8	35	Lasudiya Mori Gaon, Behind 55 infinitus	kuan	private	rcc	30	20	located in farm	No	none	22.7886516, 75.9297612
118	8	37	Tulsi nagar Maa Saraswati mandir ke pass	kuan	government	brickwork	24	4.5	Covered with jali	No	religious	22.752979, 75.9173989
119	8	37	Tulsi Nagar main road	kuan	government	rcc	30	5	Covered with jali	No	none	22.752979, 75.9173989
120	8	37	Behind Deep palace Palm green	kuan	government	rcc	21	4	covered with jali	No	none	22.752979, 75.9173989

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Require Maintenance and Civil Work	Encroachment Category	Geo-Location
121	8	30	Behind shreemaya hotel, malviya nagar gali no 02	kuan	government	rcc	24	5	Covered with jali	No	none	22.7494107, 75.8952609
122	8	30	Behind ginger hotel Ayodhyapuri colony	kuan	government	rcc	24	6	Covered with jali	No	none	22.7381007, 75.8956181
123	8	37	Swarn bag colony Scheme 94	kuan	government	rcc	30	6	Covered with jali	No	none	22.7381007, 75.8956181
124	8	35	Lasudiya Mori Gaon anganwadi ke samne	kuan	government	brickwork	30	4	safe	No	none	22.7826972, 75.9170775
125	8	30	Chandra nagar garden kuan	kuan	government	brickwork	18	6	parapet required	No	none	22.7414215, 75.895097
126	8	36	A-andiya Gaon	kuan	government	stone	30	3	safe	No	none	22.7950992, 75.9392135
127	8	36	Mayakhedi Gaon	kuan	government	brickwork	18	3	safe	No	none	22.7770221, 75.665944
128	8	35	Amit Palace garden	kuan	government	stone	24	5	Covered with jali	No	none	22.7678939, 75.9287705
129	8	37	Niyay nagar garden	kuan	government	rcc	18	5	covered with jali	No	none	22.7466306, 75.9083136
130	9	46	दीपिका मेदान	kuan	government	rcc	30	10	जाती लगवाना है ब्लॉक लगवाना है	No	residential	22.7335012, 75.8890808

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Obsear Maintenance Required Details	Maintenance Bill/ Civil Work	Ins. No./ Bill Category	Cell No./ Mobile
131	9	44	nadiva nagar gali no 1	kuan	government	rcc	25	6	1 सफाई करवाना है 2 हड्डत बढ़वाना है 3 जाली सही करनी है 4 बाउंडरी बनवाना है	No	religious	22.7099972, 75.8274298
132	9	44	mig word office	kuan	government	rcc	30	6	1 जाली लगवाना है 2 सफाई करवाना है 3 कलर करवाना है	No	residential	22.7099972, 75.8274298
133	9	44	jagjivan ram nagar	kuan	government	rcc	29	5	1 सफाई करवाना है 2 मुताई करवाना है	No	residential	22.7101767, 75.8265496
134	9	44	chendr nagar sector b	kuan	government	rcc	30	5	1 साफ सफाई 2 जाली लगाना है 3 नेट लगाना है	No	residential	22.7099972, 75.8274298
135	9	46	3 कुआँ	kuan	government	rcc	55	5	1 साफ सफाई करना है 2 जाली लगाना है	NO	religious	22.7301975, 75.8807067
136	9	46	3 कुआँ	kuan	government	rcc	55	5	1 साफ सफाई करवाना है 2 जाली लगवाना है 3 कलर करवाना है	NO	religious	22.7301975, 75.8807067
137	9	44	choti khajrani hanuman mandir arishar	kuan	government	rcc	12	4	1 साफ सफाई करवाना है 2 रिपेयर 3 कलर करवाना है	NO	educational	22.7101784, 75.8265554
138	9	45	dev nagar gali no.01	kuan	government	rcc	20	5	1) cleaning of well 2) grill work 3) green net coverage 4) other civil maintenance work	NO	none	22.7381364, 75.8811715

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Require Maintenance and Civil Work	Electrification Category	Coordinates (Lat/Long)
139	9	45	panchu Kumar ki chal	kuan	government	rcc	18	2.5	1) cleaning of well from dewatering 2) grill work. repair 3) green net coverage 4) other civil maintenance work	NO	none	22.7381364, 75.8811715
140	9	45	lala ka bagicha chota kua	kuan	government	rcc	25	3	1) cleaning of well with dewatering and desilting 3) green net coverage 4) other civil maintenance work	NO	religious	22.7378517, 75.8845844
141	9	47	Ahilya Mata Colony garden	kuan	government	stone	22	7	Covered with Jaali	NO	none	22.7300971, 75.8724698
142	9	47	In front of Upadhyay Mess, Dubey ka Bagicha	kuan	government	brickwork	15	3	Cleaning of well and -all required	NO	none	22.7302766, 75.8720675
143	9	47	Brijeshwar Shiv Mandir, Near Rajkumar bridge	kuan	government	stone	16	7	covered with Jaali	NO	none	22.7304028, 75.8710882
144	9	47	In front of Panchmukhi Hanuman mandir, Scheme no. 91	kuan	government	rcc	18	6	covered with Jaali	NO	none	22.7302869, 75.8709129
145	9	47	Shivam Apartment, Chain Singh ka Bagicha	kuan	private	brickwork	6	2	covered with Jaali	NO	none	22.7261964, 75.8786386
146	9	47	Near Shiv Mandir, Harijan basti, Palasia	kuan	government	rcc	8.5	2.5	covered with jaali	NO	none	22.7284923, 75.8829796

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (In meters)	Width/Diameter (In meters)	Units or Maintenance Required Details	Requires Maintenance and Civil Work	Encumbrance Category	Assessment (2017-18)
147	9	47	Near Urvasi Kirana Store, Harijan Basti, Palasia	kuan	government	stone	21	4.5	Jaali and civil work maintenance	NO	none	22.7293523, 75.8866674
148	9	46	पंचम को फेल शिला माता मंदिर के पास	kuan	government	rcc	350	6	जाली लगाना है और कलर सफाई कराना है	NO	residential	22.7293338, 75.8815747
149	9	46	पंचम को फेल गोपी लोडबाल के घर के पास	kuan	government	rcc	400	8	सफाई कराना है जाली लगाना है कलर कराना है	No	residential	22.7292819, 75.8815784
150	10	43	Meher apartment 3/3, New Palasia	kuan	private	brickwork	12	2.5	safe	No	none	22.7293386, 75.8843758
151	10	43	Dipasad park, 15/8, New palasia	kuan	private	brickwork	10	3	safe in private premises	No	none	22.7293388, 75.881957
152	10	43	Krishna enclave 36/2 New palasia	kuan	private	brickwork	10	2.7	safe	No	none	22.7288454, 75.8851484
153	10	43	Swastik Apartment 39/2 New palasia	kuan	private	brickwork	15	3	safe covered by jali	No	none	22.7299113, 75.8850879
154	10	43	Swastik Apartment 39/2 New palasia	kuan	private	stone	10	2.2	safe	NO	none	22.7297891, 75.8851075
155	10	43	shashkiva naale ke paas 5/2 New palasia Jain diwakar college ke paas	kuan	government	stone	12	5	safe	No	none	22.7799017, 75.8850986
156	10	43	Shree Hari Tiwari 9/8 New palasia	kuan	private	brickwork	12	2.25	safe	NO	none	22.7307786, 75.8835029

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Units of Maintenance Required Details	Required Maintenance and Civil Work	Emendament Category	Geo-Location
157	10	40	patidar dharmshala	kuan	government	stone	10	2	safe and no maintenance required	NO	none	22.7296342, 75.8973706
158	10	43	Er Kailash Singh Rathore 13/1-8, New palasia	kuan	private	brickwork	10	2.2	safe	No	none	22.7291933, 75.8845836
159	10	40	shri ram mandir moza mandir ke paas	kuan	government	stone	22	1.75	safe and only green net is required	No	none	22.7324916, 75.9045882
160	10	40	insidee ganeshpuri garden ganeshpuri	kuan	government	rcc	16	5.5	safe and no maintenance required	No	none	22.7326482, 75.9061063
161	10	40	khairana mandir campus near new visharam ghar	kuan	government	brickwork	22	5.8	safe and no maintenance required	No	none	22.7290094, 75.9071135
162	10	40	behind Ganesh ji mandir khajrana temple campus	kuan	government	rcc	15	2.2	safe and no maintenance required	No	none	22.7314305, 75.9098236
163	10	40	infront of Ganesh ji mandir khajrana mandir campus	kuan	government	rcc	15	4	safe and no maintenance required	No	none	22.7312376, 75.9076554
164	10	43	Shantinath digamber jain temple A B road Palasia	kuan	private	stone	11	3	temple premises covered by roof and railing	No	none	22.7296342, 75.8973706
165	10	43	Mata ji ke mandir ke paas, Shrinagar extension	kuan	government	brickwork	15	6	safe covered with parapet and jali	NO	none	22.7296342, 75.8973706
166	10	38	near faizan e madina masjid jalla colony	kuan	government	stone	20	9	well has boundary wall and it's top is covered with grating	NO	none	22.7335082, 75.9095053

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-Location
167	10	42	vijay kirana store 1/2A Telephone nagar	kuan	private	rcc	15	10	well situated adjacent to road munder repairing and covering work in progress	NO	none	22.723287, 75.9037306
168	10	42	Ajitsingh Rathore 11Mambhavan nagar ke saamne	kuan	government	rcc	15	12	covered with jalli	NO	none	22.7215167, 75.9042207
169	10	42	Saket club Saket nagar	kuan	government	stone	30	14	situated inside saket club with parapet wall	NO	none	22.7214423, 75.9038529
170	10	42	maata ji mandir ke pas vinoba nagar sankri gali	kuan	government	stone	12	3	well covered with jalli and parapet	NO	none	22.7206408, 75.8939122
171	10	42	Ravindra nagar Garden	kuan	government	stone	15	8	safe covered with jalli and parapet	NO	none	22.7226996, 75.8925482
172	10	43	H N 123 124 baikunthdham colony	kuan	government	stone	10	4	situated on road covered by roof and parapet wall	NO	none	22.7295342, 75.8973706
173	11	55	RNT roed, street no. 01, khandetwal ke pas	kuan	government	brickwork	15	3.8	safe	NO	residential	22.7036528, 75.8740011
174	11	55	Kursi mohalla mata mandir ke pas, street no. 08	kuan	government	brickwork	12	5	safe, jalli repair & painting work requirement	NO	religious	22.7102218, 75.875291
175	11	55	Khazanchi dhamshala 18/1 ushagenj	kuan	government	stone	25	2.4	Unsafe, jalli required	NO	commercial	22.7099134, 75.8768594
176	11	55	S.p. office Rani sarah	bawdi	government	stone	25	10	Safe, Repairing required	NO	none	22.7191737, 75.8705777

S.No.	Zone Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe of Malnourance Required Details	Required Maintenance and Civil Work	Expenditure Category	Geographical
177	11 60	50 maharani road raj radio ke samne	kuan	government	stone	15	2.1	safe	NO	none	22.7167663, 75.8570012
178	11 60	Rani pura Kachchi masjid ke pas 20/3	kuan	private	brickwork	20	3	Safe	NO	none	22.716801, 75.8631325
179	11 60	Urdu maidan doulat ganj	kuan	government	rcc	18	4.3	Safe	NO	none	22.7153487, 75.8523412
180	11 60	North toda Kailash kothi shree ram mandir	kuan	government	brickwork	13	2.5	Safe, Jali repairing required	NO	none	22.7176565, 75.8607433
181	11 55	Chhoti gwal toll Patel lodge ke piche	kuan	government	brickwork	15	2.5	safe, jali repairing	NO	none	22.713914, 75.8704949
182	11 55	P.S.C. Office	kuan	government	brickwork	22	3	Safe	NO	none	22.7076808, 75.8789324
183	11 48	Priyal apartment	kuan	government	brickwork	16	4	safe	NO	none	22.715413, 75.8913151
184	11 48	Devi Indra ekta nagar H.No. 64	kuan	government	brickwork	10	5	Safe, jali repairing	NO	none	22.7195936, 75.8904826
185	11 49	Goyal nagar shakuntala hospital ke pas shiv mancir	kuan	government	brickwork	22	6	Safe, jali repairing and painting required	NO	none	22.7180995, 75.9057197
186	11 49	Goyal nagar ex. jain mandir	kuan	private	brickwork	20	2.1	Safe	NO	none	22.7193889, 75.9054685
187	11 49	Sai nath colony sanshan	kuan	government	brickwork	22	10	Safe	NO	residential	22.7188975, 75.900628

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Entrenchment Category	Geo Location
188	11	49	Vandana nagar C-sector Ganesh mandir	kuan	government	stone	30	10	Safe, jali repair required	NO	none	22.7177702, 75.9021557
189	11	49	Salasar balaji mandir near post office	kuan	government	brickwork	20	10	Safe	NO	religious	22.7190362, 75.8956927
190	11	48	Ram mandir badi gwal toli	kuan	government	brickwork	20	5	Unsafe, Side wall settled	NO	none	22.7188412, 75.8935146
191	11	55	Usharani, BJP karyalaya ke samne	kuan	government	brickwork	15	3	Safe	NO	none	22.7099713, 75.8794841
192	11	55	M.Y. Hospital O.P.D. ke andar	kuan	government	brickwork	18	4	Safe	NO	none	22.7104984, 75.8800639
193	11	49	Vandana nagar Vasundhara complex ke pichhe	kuan	government	stone	30	10	Safe, jali repairing required	NO	none	22.7144948, 75.9004938
194	11	54	Residency area main road Dargah ke pas	kuan	government	brickwork	30	3	Safe	NO	religious	22.7050117, 75.8862701
195	11	54	P.T.S. (Police training sentar)	kuan	government	brickwork	20	5	Safe	NO	none	22.7011027, 75.9027001
196	11	54	P.T.S. ground near H.No. 02	kuan	government	brickwork	26	6	Safe, jali repairing required & munder	NO	none	22.7083664, 75.8985968
197	11	54	P.T.S. Helpad ke pas	kuan	government	stone	20	5	Safe	NO	none	22.6953822, 75.9006937
198	11	60	gandhi hall Bopeshwar Mahadevi mandir	kuan	government	brickwork	25	2.5	safe	no	none	22.7197816, 75.8656412

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Environment Category	Est. Location
199	11	60	Shree God vidhya mandir	kuan	government	brickwork	15	2.5	Safe	no	religious	22.7131974, 75.8614958
200	12	65	zone 12 ward 65 Sindhu nagar Mata mandir	kuan	government	rcc	25	5	slab cutting	no	none	22.7033596, 75.860761
201	12	59	Krishna pura chhatra kua	kuan	government	stone	10	2	maintenance required	no	none	22.718953, 75.87590216
202	12	59	harsiddhi zonal office	kuan	government	rcc	20	5	maintenance required	no	none	22.7181619, 75.8578118
203	12	59	behind registrar office moti tabala	kuan	government	rcc	50	5	maintenance required	no	none	22.7123923, 75.8601852
204	12	59	harjan colony below Loha Mandi bridge	kuan	government	brickwork	50	5	maintenance required	no	none	22.708295, 75.8671191
205	12	62	neelkantheshwar mahadev mandir Loha Mandi	kuan	government	stone	50	3	maintenance required	no	none	22.7085366, 75.8654364
206	12	61	kakhpura kabristan	kuan	government	brickwork	50	5	unsafe	no	none	22.7069337, 75.8651132
207	12	61	juni incore thana	kuan	government	brickwork	50	5	maintenance required	no	none	22.7003353, 75.8617571
208	12	65	behind preetam das sabhgrah sadhwaswani naga-	bawdi	government	rcc	20	10	maintenance required	no	none	22.7007286, 75.8653015

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bandi	Depth (in meters)	Width/Diameter (in meters)	State of Maintenance Required Details	Requiring Maintenance and Civil Work	Establishment Category	Geo-Location
209	12	65	shiv mandir Sindhu palace sachuwaswani nagar	kuan	government	brickwork	50	5	unsafe	no	residential	22.7007286, 75.8657015
210	12	65	Dr satwani clinic khatiwala tank	kuan	government	rcc	20	2	maintenance required	no	none	22.70075, 75.863575
211	12	66	shiv mandir rajmahal colony	kuan	government	brickwork	50	5	maintenance required	no	none	22.698926, 75.857207
212	12	66	navgrih mandir roopram nagar	kuan	government	rcc	20	2	unsafe	no	religious	22.7001912, 75.8511981
213	12	66	gurunank colony	kuan	government	brickwork	50	8	maintenance required	no	none	22.7001912, 75.8511981
214	12	66	kerabala maidan	kuan	government	brickwork	50	5	maintenance required	no	none	22.7020252, 75.8489546
215	13	77	Ganesh nagar main road कुआँ नगर 4	kuan	government	brickwork	13	12	no	no	none	22.6707233, 75.8697383
216	13	77	गणेश नगर मेन रोड कुआँ नंबर 2	kuan	government	brickwork	13	12	no	no	none	22.6715745, 75.8723934

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (In meters)	Width/Diameter (In meters)	Unsafe or Maintenance-Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-Location
217	13	77	साई प्रथम दास स्कूल के पास में छोटा बिलावली तालाब का कुआँ पेपर कितनी होगी पत्नी होगी बहुत ही नहीं है इसलिए पिपा सुन लो जी तो तना तना तन तना तना तन तन	kuan	government	brickwork	12	11	no	no	none	22.6657833, 75.8749567
218	13	77	आसाराम आश्रम खंडवा रोड के अंदर का कुआँ	kuan	private	brickwork	13	8	no	no	none	22.6656991, 75.8771001
219	13	78	Amitesh nagar	bawdi	government	stone	15	38	no required	no	commercial	22.681649, 75.8541034
220	13	74	shivapuri mateji temple	kuan	government	stone	15	4	safe	no	none	22.686876, 75.8616891
221	13	74	indrapuri shiv temple	kuan	government	brickwork	15	10	safe	no	none	22.6855989, 75.8652641
222	13	74	nehari bhendara Rajiv Gandhi square	kuan	government	brickwork	15	4	safe	no	none	22.6839404, 75.8640273
223	13	74	Jai Singh palace	kuan	government	brickwork	15	4	safe	no	none	22.6839404, 75.8640273
224	13	74	eastern ring road near Rishi ka dhabha	kuan	government	brickwork	15	3	safe	no	none	22.6808893, 75.8627555
225	13	74	pipiyapala Jai Singh nagar	kuan	government	brickwork	15	4	safe	no	none	22.6808819, 75.8610722

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of (kuan/Bawdi)	Depth (in meters)	Width/Diameter (in meters)	Unsafe Maintenance Required Details	Requires Maintenance and Civil Work	Environment Category	Spd. Serial
226	13	74	inside regional park	kuan	government	rec	15	10	unsafe, covered by slab	no	none	22.6806619, 75.9567049
227	13	74	vishnupuri shiv temple	kuan	government	brickwork	15	9	unsafe covered by slab	no	none	22.6799781, 75.8610751
228	13	74	ahilyapuri colony	kuan	government	brickwork	15	8	safe	no	none	22.6900192, 75.8621188
229	13	74	soniya gandhi nagar	kuan	government	brickwork	15	4	safe	no	none	22.6710306, 75.8675841
230	13	78	inside choithram square	kuan	government	brickwork	15	10	safe	no	none	22.681225, 75.8529323
231	13	78	lake park colony	bawdi	government	stone	15	6	safe	no	none	22.681225, 75.8529323
232	13	78	choithram hospital and research	kuan	private	brickwork	15	8	safe	no	none	22.6866152, 75.8543384
233	13	78	scheme.103 over head tank	bawdi	government	stone	15	14	safe	no	none	22.6901279, 75.8552888
234	13	78	nema nagar dharmshala	kuan	private	brickwork	15	6	unsafe,sheets to be removed	no	none	22.6817585, 75.8416553
235	13	78	near kaila devi temple	kuan	government	brickwork	15	6	safe	no	none	22.6809574, 75.8392925
236	13	78	chameli Devi school	kuan	private	stone	15	12	safe	no	none	22.6792764, 75.8395394

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Esserment Category	Geo. Station
237	13	78	near vinayak restaurant scheme 103	kuan	government	brickwork	15	6	safe	no	none	22.6792764, 75.8395394
238	13	78	infront of basantipuri colony	kuan	government	brickwork	15	8	safe	no	none	22.6755483, 75.8472567
239	13	78	mu,teshwar Mahadev temple amitash nagar	kuan	government	rcc	15	8	safe	no	none	22.6755483, 75.8472567
240	13	81	190 पिकॉको कॉलोनी	kuan	government	rcc	50	30	green net ev clining	no	residential	22.6871724, 75.8362188
241	13	81	अन्नपूर्णा मंदिर	kuan	government	rcc	40	17	all good	no	educational	22.6871724, 75.8362188
242	13	81	देवेंद्र नगर ब्रिज के नीचे	kuan	government	rcc	60	30	good	no	residential	22.6887757, 75.8369914
243	13	81	26a मर्मदा नगर	kuan	government	rcc	50	40	green net एवं सफाई की	no	residential	22.6828717, 75.8390604
244	13	81	दात मंदिर	kuan	government	rcc	50	30	good	no	religious	22.6828717, 75.8390604
245	13	77	साई प्रोतमदास स्कूल के पास छोटा बिलावली तालाब का कूआ	kuan	government	brickwork	13	12	no	no	none	22.6699858, 75.8798148
246	13	81	190 पिकॉको कॉलोनी	kuan	government	rcc	18	8	सफाई की जरूरत है	no	residential	22.6808054, 75.8266254
247	13	81	अन्नपूर्णा मंदिर	kuan	government	rcc	18	5	good	no	educational	22.6808054, 75.8266254

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (In meters)	Width/Diameter (In meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Phone No./G.P. Location
248	13	81	दत्त मंदिर	kuan	government	rcc	16	8	all good	no	religious	22.6808054, 75.8266254
249	13	81	26/a नर्मदा नगर	kuan	government	rcc	13	10	not good	no	residential	22.6820885, 75.8354523
250	13	81	davendar nagar ब्रीज के नीचे	kuan	government	rcc	13	10	not good	no	residential	22.6833117, 75.8363233
251	13	80	द्वारका गार्डन अहिल्या नगर	kuan	private	rcc	18	5	work in progress	no	none	22.684319, 75.8401374
252	13	81	अन्नपूर्णा मंदिर	kuan	government	rcc	9	2	all good	no	religious	22.6740223, 75.871718
253	13	80	MPER ऑफिस महिला पॉलिटेक्निक ब्रिज के नीचे	kuan	government	brickwork	45	5	IIMC	no	none	22.6734031, 75.8325002
254	13	80	reti Mandi near railway track	kuan	government	brickwork	15	6	safe	no	none	22.6539982, 75.8234047
255	13	80	Madhav Vidhya Pith, Ahiliya Nagar	kuan	government	brickwork	15	7	No Maintenance Required	no	none	22.6732712, 75.8253003
256	13	80	Ram Mandir, Vaishali Nagar	kuan	government	brickwork	13	3	Just Repair Work Needed.	no	none	22.6732712, 75.8253003
257	13	80	near Rejendra nagar bridge	kuan	government	brickwork	20	10	no Maintenance Required	no	none	22.6734287, 75.8313058
258	13	80	Om Heights	kuan	government	brickwork	15	6	Unsafe and Encroachment	no	residential	22.6745022, 75.8317502

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawaf	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Requires Maintenance and Civil Work	House Number/Category	Coordinates
259	13	80	Parasar Nagar, Near Shiv Mandir	kuan	government	brickwork	22	8.7	No Maintenance Required	no	none	22.6737712, 75.8253903
260	13	80	mahila polytechnic collage Rajendra nagar power house	kuan	government	brickwork	14	6	no Maintenance Required	no	none	22.6699333, 75.830447
261	13	80	vigyan nagar near kumar garden	kuan	government	brickwork	20	8	no Maintenance Required	no	none	22.6729885, 75.8325874
262	13	80	sudarshan nagar	kuan	government	brickwork	20	7	no Maintenance Required	no	none	22.6753895, 75.8327361
263	13	80	Ahilya nagar	kuan	government	brickwork	20	8	no Maintenance Required	no	none	22.6807365, 75.8328069
264	13	81	Waheguru clinic Dr. ram nani gali no. 1 Chanakyapuri road narmada nagar	kuan	government	brickwork	20	10	no Maintenance Required	no	none	22.6832848, 75.8359964
265	13	81	Dutt mandir umesh nagar annapurna main road	kuan	government	brickwork	22	8	no Maintenance Required	no	none	22.6816483, 75.8352293
266	13	80	Rajendra nagar garden	kuan	government	brickwork	20	8	no Maintenance Required	no	none	22.6700135, 75.8270128
267	13	81	Dwarka garden	kuan	government	brickwork	20	7	Unsafe and Encroachment	no	commercial	22.6802597, 75.8346169

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Update or Maintenance Required Details	Required Maintenance and Civil Work	Enviro-Friend Category	Cost/Estimation
268	13	80	Scheme no 97/4 vip paraspar behind hanuman mandir near ryan international school	kuan	government	stone	10.6	4.5	Maintenance Required	no	none	22.6754205, 75.8209003
269	13	81	Near 109 prikanko colony	kuan	government	brickwork	20	10	No Maintenance Required	no	none	22.683999, 75.8299721
270	13	81	Anapurna mandir	kuan	government	brickwork	10	2.5	No Maintenance Required	no	none	22.6844649, 75.8332594
271	13	81	Anapurna mandir	kuan	government	brickwork	15	7	No Maintenance Required	no	none	22.690303, 75.8375674
272	13	81	Devendra nagar new bridge	kuan	government	brickwork	20	10	No Maintenance Required	no	none	22.6831068, 75.839673
273	14	84	scheme number 71 hawa Bangla road paschimi ring road opposite full koti gate	kuan	government	brickwork	50	3	no	no	none	22.6938092, 75.8268312
274	14	85	Sai baba nagar Mata Mandir Makan number 200 ke samne	kuan	government	brickwork	40	5	no	no	none	22.6914435, 75.8199545
275	14	85	shradha puri colony Shiv Mata Mandir Lakshmi kiran general Store ke samne	kuan	government	brickwork	17	6	no	no	none	22.6927078, 75.8202053

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawal	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Coordinates
276	14	85	Aastha place shradha Puri Shiv Mandir ke piche 626 M'akan number ke samne	kuan	government	brickwork	16	7	no	no	none	22.6905247, 75.8183449
277	14	82	Shriram Nagar Rishi palace Balaji circle ke samne	kuan	government	brickwork	13	9	no	no	none	22.6895514, 75.8141674
278	14	82	shantinath Puri parivahan Nagar hawa Bangla road	kuar	government	brickwork	16	7	no	no	none	22.68557, 75.8194393
279	14	79	hari om dhaba ke pass AB road	kuan	government	brickwork	20	5	no	no	none	22.6627287, 75.8246057
280	14	79	khedapatti Hanuman Mandir ke pass A,B road	kuan	government	brickwork	10	1	no	no	none	22.6627207, 75.8246067
281	14	79	Sukh nivas colony samuday bhavan ke piche	kuan	government	stone	11	3	no	no	none	22.671512, 75.8045471
282	14	79	Ahira khedi gaon	kuan	government	brickwork	8	3	no	no	none	22.6801944, 75.8135882
283	14	79	vidur Nagar	kuan	government	brickwork	20	15	no	no	none	22.6811275, 75.8122942
284	15	71	ranjit mandir campus ke andar	kuan	government	stone	11	4	safe but 1 feet raised boundary is desirable	no	none	22.7052455, 75.8376616

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-Location
285	15	83	704 sector b scheme 71 ke samne mata mandir garden	kuan	government	brickwork	11	2	safe, kua ko slab and tiles lagaakar mandir ke platform me shami kar lia gya tha jise varman me vertical jali lagaakar logo ki entry restrict kar di gyi hai.	no	religious	22.7036092, 75.8325901
286	15	83	power house ke samne scheme 71 sector a	kuan	government	brickwork	15	5	safe. dia 4.5 m	no	none	22.7036443, 75.8326041
287	15	83	scheme 71 sector d maujana azad garden ke pas	kuan	government	brickwork	10	5	safe.	no	none	22.7013295, 75.8270614
288	15	83	sales tax garden	kuan	government	brickwork	11	4	safe	no	none	22.69979, 75.8290208
289	15	83	rx garden ke pas	kuan	government	brickwork	12	4	safe	no	none	22.6973063, 75.8298125
290	15	71	vishrambagh garden sthit kua	kuan	government	brickwork	18	10	jaali maintenance required	no	none	22.6934773, 75.83356
291	15	72	8ab parshvath nagar ke paas	kuan	government	brickwork	15	7	safe	no	none	22.6901704, 75.8374875
292	15	73	Inside campus of shvam nagar masjid	kuan	government	rcc	22	3	safe no maintenance required yet.	no	none	22.7022998, 75.8390513
293	15	72	kesharbagh crossing ke samne anaganwadi ke pas	kuan	government	rcc	15	3	unsafe. dia 2.3m jaali maintenance required	no	none	22.6870933, 75.843264

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of (kuan/Bawdi)	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geolocation
294	15	72	siddharth nagar garden kua	kuan	government	brickwork	18	4	dia 3.8m , safe	no	none	22.6897578, 75.8444433
295	15	72	lokmany station ke samne jain colony	kuan	government	brickwork	18	13	safe	no	none	22.6912682, 75.8455315
296	15	72	moon palace someshwar mahadev mandir ke pas	kuan	government	brickwork	15	4	unsafe. slab hatakar, boundry banana hai	no	none	22.6944931, 75.841311
297	15	73	lal bahadur shastri nagar mata mandir	kuan	government	brickwork	15	2	jaali repairing require	no	none	22.6945055, 75.8478815
298	15	72	champa baddi old rto office ke pas kesharbagh road	bawdi	government	stone	15	9	jaali lagana h	no	none	22.6988655, 75.843297
299	15	83	vishrambagh baddi	bawdi	government	brickwork	25	9	babdi ke charo taraf jaali nahi h	no	none	22.6995819, 75.8322153
300	15	71	dravid nagar zonal office campus	kuan	government	brickwork	20	10	jaali maintenance	no	none	22.7020935, 75.836488
301	15	72	baddi inside labagh	bawdi	government	stone	15	10	broken wire mesh	no	none	22.7028224, 75.8451244
302	15	73	vijay nagar garden	kuan	government	brickwork	15	3	dia 2.8m	no	none	22.7040129, 75.8554061
303	15	73	infront of 15 ashoka colony	kuan	government	brickwork	15	6	boundrywall/parapet required	no	none	22.6946647, 75.8539658
304	15	72	nichli fell	kuan	government	rcc	15	4	safe	no	none	22.6985058, 75.8402553

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Estimated Category	Geo. Location
305	15	2	70 lona gate gali no 2	kuan	government	brickwork	22	7	jaali repairing required.	no	none	22.7088808, 75.8256432
306	15	83	khushbu apartment	kuan	private	brickwork	15	11.3	shri indore cloth marketket machyamvarg'y grah nirman sanstha ki bhumji par hai sanstha dwara sandharit hai.sanstha dwara parapat banakar jaali laga di gyi hai	no	none	22.7039077, 75.8255884
307	15	73	guljar masjid	kuan	government	brickwork	15	2	jaali lagaakar safe kia Gya	no	none	22.6961731, 75.8547541
308	16	3	negin nagar pani ki tanki ke pass	kuan	government	rcc	23	2.9	steel work green nate repair work	no	religious	22.7163792, 75.8231764
309	16	15	kastur Nagar	kuan	government	brickwork	16	7	cleaning nahi he	no	residential	22.7470466, 75.7980085
310	16	3	vijay shree nagar	kuan	government	brickwork	55	12.3	no work	no	residential	22.7180819, 75.8223326
311	16	3	bhagwant gardan	kuan	government	brickwork	80	12.4	no work	no	residential	22.7218557, 75.821947
312	15	15	airport road	bawdi	private	stone	18	6	ok	no	residential	22.72893, 75.8047025
313	15	3	B.S.F.parishar	bawdi	government	stone	90	10	civil work , green net	no	none	22.7228401, 75.8235958

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Sawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-Location
314	16	15	airport road chaurasiya Nagar	kuan	private	brickwork	12	4.5	ok he	no	residential	22.7296912, 75.8079507
315	16	15	airport road Shakti Nagar	kuan	government	brickwork	11	2.5	ok he	no	residential	22.7303005, 75.8082224
316	16	5	SHIWALAY CHOUK	kuan	government	brickwork	70	10	NO	no	residential	22.7187463, 75.827559
317	16	5	shivalay chok raj nagar	kuan	government	brickwork	18	3.9	atikraman , steel work	no	residential	22.7163792, 75.8234764
318	16	5	214 raj nagar D sector	kuan	government	brickwork	21	2.9	atikraman	no	residential	22.7165117, 75.823762
319	16	5	chandan nagar E sector	kuan	government	brickwork	26	3.1	no work	no	residential	22.7155117, 75.823762
320	16	5	chandan nagar E sector	kuan	government	brickwork	25	4.8	green net civil work	no	residential	22.7165117, 75.823762
321	16	1	new vaysh nagar	kuan	government	brickwork	28	4.1	civil work-steel work green net	no	residential	22.7165362, 75.8237959
322	16	1	Gandhi place B.S.f wall ke pass	kuan	government	brickwork	20	2.3	civil work, green net	no	residential	22.7173365, 75.8159901
323	17	23	Mataprasad Tiwari Garden	kuan	government	brickwork	25	6	Well is safe.No maintenance required as it was done 8 months back.	no	none	22.7503988, 75.8709131

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-location
324	17	23	Digambar Jain Mandir, Clerk Colony Plot No 410	kuan	private	rcc	20	3	Well is safe enough and in existence from 2017 only. Well Maintained by Mandir Society.	no	none	22.7493159, 75.8712899
325	17	23	Ganesh Nagar Pardesipura, Inside Shiv Mandir Parisar	kuan	government	brickwork	25	3	Well is safe. Walls not damaged.	no	none	22.7508243, 75.8662845
326	17	18	revti hlias	kuan	private	brickwork	30	3	Maintence required	no	none	22.773078, 75.8425033
327	17	18	UJJAIN ROAD BHAWRASLA. RR. Compund. Guru. Ashirvad hotel. Keptice	kuan	private	brickwork	27	8	open well mentence. Requard	no	none	22.7832841, 75.8484931
328	17	20	Khatipura Ram Mandir ke peeche Choudhary Palace	kuan	government	stone	13	2	No maintenance required. Cleaning was done 3 months back. Walls not damaged.	no	none	22.7594196, 75.8609803
329	17	23	Clerk Colony Extension Well	kuan	government	brickwork	23	5	Maintenance work was done 8 months back	no	none	22.7594183, 75.8609864
330	17	23	Purana Gauri Nagar Gali No 3, Inside Bhollerath Mandir Parisar	kuan	government	brickwork	25	4	Maintenance work required. Periphoral Walls are damaged up to a depth of 3.5 mt.	no	none	22.7527634, 75.8652511
331	17	19	Kumedi. Gav. Ram. Mandir. Ke. Pas	kuan	private	brickwork	50	4	Safe	no	none	22.7801803, 75.8502099

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Inspection/ Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-coordinates
332	17	19	MR. 10. brige ke... Nechu. Bala. Ji. Hanuman. Mandir	bawdi	government	stone	30	9	Safe	no	none	22.7756202, 75.8504761
333	17	19	bangana breg ke pehele santoch cycle servish ke pas	kuan	government	brickwork	15	4	Safe	no	none	22.7609187, 75.8487159
334	17	19	Sanwer road. Banfar basti bablu. Paneri ke makan ke age	kuan	government	brickwork	22	5	Safe	no	none	22.7506497, 75.8493854
335	17	19	Sanwer road. Bhagat shingh. Nagar. banafar basti tirath shingh. Banafar. Ke. Piche	kuan	private	brickwork	25	6	Safe	no	none	22.7506497, 75.8493854
336	17	19	mukarji. nagar. Ramdat ka bhata badkesvar mahadev bham	kuan	private	brickwork	22	2	Safe	no	none	22.7655309, 75.8665088
337	17	18	Sanwer. Road. mental. Hospital ke kempus me	kuan	government	brickwork	25	6	jali se dhaka ha safe	no	none	22.7493007, 75.8497136
338	17	18	Sanwer road mental hospital adminestration office ke samne	kuan	government	brickwork	30	5	Jali lagar jai thi hata di ga ha unse	no	none	22.7493007, 75.8497136
339	17	18	Sanwer road bhagat shingh nagar. तिबारी complex panisar	kuan	private	brickwork	32	6	उक्त स्थान पर कुए पर मंडर का निर्माण होकर लौहे की जाली से ढका है किंतु कुआं दस रहा है जो कि खतरनाक है	no	none	22.7492038, 75.847394

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-Location
340	17	18	Garam barderijash, Engineering parisar Ujjain road.	kuan	private	brickwork	25	6	Safe	no	none	22.7959972, 75.8437695
341	17	18	Arvind Hospital campus	kuan	private	brickwork	35	10	Safe	no	none	22.7957003, 75.8470204
342	17	18	Ujjain road harwal moni baba ashram parisar	bawdi	private	stone	42	5	Safe	no	none	22.7826506, 75.8488423
343	17	18	Ujjain road kaka.Shree.Petroli.Pump.Ke.Piche Garam. Revti shakmbhari. Parisar	kuan	private	brickwork	30	8	Safe	no	none	22.7874405, 75.8497372
344	18	53	Azad nagar Mansuri kirana ke paas wali gali me	kuan	government	brickwork	16	7	not required	no	none	22.5928912, 75.8862689
345	18	53	AZAD NAGAR NURI NAGAR MUKTIDHAM KE PICHE	kuan	government	brickwork	11	2.7	cleaning required	no	none	22.6928992, 75.889922
346	18	53	AZAD NAGAR NEAR ALFALAH MADARSA RAJAK PATEL HOUSE NEAR	kuan	private	brickwork	18	3.5	no required	no	none	22.6928992, 75.889922
347	18	53	MOHAMMADI MASJID AZAD NAGAR13	kuan	government	brickwork	13	3.3	not required	no	none	22.6970747, 75.8858144
348	18	53	AZAD NAGAR MUSLIM KABRISTAN	kuan	government	brickwork	12	4.3	not required	no	none	22.6971063, 75.8958222

S.No.	Zone Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-Location
349	19	50 गौरी घुडखर गंगा माता मंदिर पिपलियाना गांव	kuan	government	brickwork	13	4	safe	no	none	22.7068321, 75.9092076
350	19	41 shiv temple kanadia road near bangali square	kuan	government	rcc	15	5	safe	no	none	22.7357267, 75.939124
351	19	50 देवव नगर उद्यान सेक्टर सी उद्यान के पास	kuan	government	brickwork	17	8	safe	no	none	22.7180857, 75.9195622
352	19	41 shree ram temple near subh labh avenue	kuan	private	rcc	16	4	iron jali required	no	none	22.7348561, 75.9591125
353	19	41 हनुमान मंदिर कनाडिया रोड 12 संचार नगर के पास	kuan	government	brickwork	16	8	safe	no	none	22.7240256, 75.9161001
354	19	41 स्व समीर विद्वानिध उद्यान आजीक नगर 15	kuan	government	brickwork	18	9	safe	no	none	22.7240256, 75.9161001
355	19	75 कर्बला मैदान ,no road	kuan	government	brickwork	15	6	ok	no	none	22.66667685, 75.9141535
356	19	75 खसरा क्रमांक 228 पालदा विनय कुमार	kuan	private	brickwork	18	6	iron jali required	no	none	22.6791107, 75.8947474
357	19	75 near tejaji chowk	kuan	government	brickwork	17	6	maintenance required	no	none	22.6807506, 75.89487
358	19	75 कन्हैया ताल कश्यप हिमाल नगर	kuan	private	brickwork	18	6	maintenance and iron jali required	no	none	22.6803249, 75.8888515
359	19	75 राधा स्वामी सतसंग कैपस	kuan	private	brickwork	18	6	ok	no	none	22.6801134, 75.8886695

94

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-Location
360	19	75	st arnold school campus 1	kuan	private	brickwork	20	9	ok	no	none	22.6836911, 75.8877539
361	19	75	st arnold school well no 03	kuan	private	brickwork	17	7	ok	no	none	22.6845396, 75.8866227


अधीक्षण यंत्री
जल यंत्रालय एवं ड्रेनेज
इन्दौर नगर पालिक निगम

Annexure-5

कार्यालय नगर पालिक निगम, इंदौर
संधारण कार्य किये जाने वाले कुए / बावड़ी की सूची

प्रपत्र (स)

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Length (in meters)	Update on Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-Location
1	1	9	Near Post Office Kila maidan VIP Route	kuan	government	brickwork	10	2		jali and cleaning required presently filled with malwa only 1m available depth	Yes	none	22.7268723, 75.8460579
2	1	9	Goreswar Mahadev Mandir Campus Khaagi Bagecha	kuan	government	stone	12	4	4	open jali not there, major cracks in wall parapet wall damaged safai required	Yes	none	22.7401845, 75.8439477
3	1	9	Sangum Nagar GTS Campus	bawdi	government	stone	15	10	10	Not Covered Safai Required Secured by Fencing	Yes	none	22.7401845, 75.8439477
4	1	9	Hemu Colony Naale ke paas	kuan	government	stone	15	5		Open, Safai Not Required Munder Damaged Wall Damaged, One side House Wall with Kiwe ki wall	Yes	residential	22.7398932, 75.8430421
5	1	9	Laal kuwa Vrandavan Colony	kuan	government	stone	14	5		Jali Damaged Need Repair, Munder wall height increase saatal required	Yes	none	22.7402905, 75.8465289
6	1	9	MKV School ke paas Kumharkhadi	kuan	government	brickwork	8	3		jali required, temporary material se dhaka hai roac level par hai, wall required	Yes	none	22.7389348, 75.8479605
7	1	9	H No 14 Kumhar khadi Naale ke paas	kuan	private	brickwork	10	2		Jali open Munder required	Yes	none	22.7379574, 75.847933
8	1	9	147 Kumharkhadi	kuan	private	brickwork	12	2		Fashti se covered hai munder required	Yes	none	22.7263534, 75.8466557
9	1	9	government school kila maidan	bawdi	government	stone	15	6	6	one side wall collapsed covered by profile sheet. need civil work	Yes	none	22.7306818, 75.8458348

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Length (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-Location
10	1	9	behind gutkeshwar Temple	kuan	government	brickwork	10	3		wall collapsed need civil work temporary covered with profile sheet	Yes	none	22.7283238, 75.8465222
11	1	7	55 Mahaveerbag ke Samne	kuan	government	brickwork	12	4		jaali repair munder height and safai required	Yes	none	22.7231928, 75.838449
12	1	4	Rapto Police line Campus	kuan	government	brickwork	10	2		jaali nhi hai, open hai 4 ft par hi sab malwa pada hai	Yes	none	22.7265834, 75.8331293
13	1	4	Rapto Campus	bawdi	government	stone	20	8		jaali required safai required	Yes	religious	22.7263835, 75.8342729
14	1	4	Honey Apartment 2 E Sachna Nagar	kuan	private	brickwork	10	2		jaali repair munder required	Yes	none	22.7245805, 75.8270401
15	1	4	Manpasand Colony Peopal Tree Gali No 2	kuan	government	brickwork	15	5		Covered with Road	Yes	none	22.7245805, 75.8270401
16	1	7	Shankargiri Ashram Kancilpura	kuan	private	stone	15	3	3	No Jaali open munder damage	Yes	none	22.723466, 75.8270937
17	1	7	Shankargiri Ashram	kuan	private	stone	15	4		covered with jaali	Yes	none	22.7237712, 75.8415419
18	1	7	Ram Bagichi Kandilpura	kuan	government	brickwork	12	3		Jaali repair Munder required	Yes	none	22.7260649, 75.8417508
19	1	7	Nigam Jinsi Workshop	bawdi	government	stone	20	5		jaali nhi hai safai required	Yes	none	22.7241248, 75.8444968
20	1	7	Arjun Paltan	bawdi	government	stone	20	7	15	stone wall cracks jaali repair munder height required jarjar	Yes	none	22.7228608, 75.8442627
21	1	7	Dalal Bag Ground VIP Route	kuan	private	stone	22	4	4	Jaali nhi hai munder damage safai required	Yes	none	22.7259483, 75.8388894
22	1	16	Kasam Ki Bawdi Chota Bangarwa	bawdi	government	stone	15	6	16	open wall jarjar malwa mitti no water stone work collapse of staircase area	Yes	none	22.7245776, 75.8462504

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuany/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Length (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-Location
23	1	16	Ram Mandir Chota Bangarda	kuan	private	stone	12	5	5	jaali nahi secured by Fencing malwa mitti no water safai required munder required	Yes	none	22.7245776, 75.8462504
24	1	16	Isha Corridor	kuan	private	brickwork	12	6		No jaali munder damaged below road level	Yes	none	22.7446792, 75.8147222
25	1	16	Smruti Nagar Shiv Mandir Garden	kuan	government	brickwork	15	5		collapsed one year ago civil work-in progress secured by Fencing	Yes	none	22.7446792, 75.8147222
26	1	7	Neelkanth Colony ke peeche	bawdi	government	stone	14	4	5	Jaali not there safai required munder damaged	Yes	none	22.7257923, 75.8470795
27	1	7	Kali masjid Jinsi	kuan	government	brickwork	12	2		covered with slab and steel cover	Yes	religious	22.7229693, 75.8467695
28	1	8	Safed Masjid Jins St.	kuan	government	brickwork	12	2		covered with slab and steel cover	Yes	religious	22.7229693, 75.8467695
29	1	8	Mahant Complex Malharganj	kuan	private	brickwork	12	2		covered with slab and steel cover and used for parking	Yes	residential	22.7203136, 75.8474518
30	1	8	hari heights North yashwant ganj	kuan	private	brickwork	12	2		covered with slab and used for parking	Yes	residential	22.7197294, 75.8474884
31	1	8	Masjid Chhipa Bakhal	kuan	government	brickwork	12	2		covered with slab and steel cover	Yes	religious	22.7204331, 75.8490658
32	1	8	Choti Masjid Junarisala	kuan	government	brickwork	10	1.5		as per member prevent covered with slab nearby waju area not able to view as said by the ones present	Yes	religious	22.7234844, 75.8504198
33	1	8	Badi Masjid Junarisala	kuan	government	brickwork	10	2		covered with slab and steel cover	Yes	religious	22.7242455, 75.8500933
34	1	7	Dhola Kuwa	kuan	government	stone	20	5		malwa safai required jaali repair munder height required	Yes	none	22.7242601, 75.8501069

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Length (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Environment Category	Geo-Location
35	1	7	gokul ganj rear shiv temple	kuan	government	brickwork	20	2		covered with grill cleaning required	Yes	none	22.7244124, 75.8474293
36	1	16	scheme no 155	kuan	government	brickwork	18	8		brickwork and grill required	Yes	none	22.7479664, 75.8365374
37	1	4	infront of radam tower vip route	kuan	government	brickwork	5	2		filled with material not covered	Yes	none	22.7740419, 75.87804
38	2	5	बिवासा कॉलोनी उद्यान	kuan	government	brickwork	12	4		maintenance required (cleaning, colour, sign board, ornamental kund, green net, etc)	Yes	none	22.7221189, 75.8319413
39	2	69	18/2 new mahesh nagar	kuan	private	stone	9	2.5		Maintenance required	Yes	none	22.7162318, 75.8365267
40	2	69	44, old rajrohalla	kuan	private	stone	12	2		Unsafe	Yes	none	22.7162994, 75.8448617
41	2	69	south yashwant gorj near naveen chitra talkies	kuan	private	stone	15	2.5		Unsafe	Yes	none	22.71805, 75.84813
42	2	69	maheshwari panchayat trust gorakund	bawdi	private	stone	10	20	8	unsafe	Yes	commercial	22.71919, 75.895233
43	2	67	6/1 ramkrishna mandir, chhattribagh	kuan	private	stone	10	3.5		Safe	Yes	none	22.7124356, 75.9494237
44	2	67	99, chhattribagh (maharshi gadichi dharmshala)	kuan	private	stone	12	7.5		Safe	Yes	none	22.7090487, 75.8481198
45	2	67	59/1 kirti apartment, chhattribagh	kuan	private	stone	9	2		Maintenance required	Yes	residential	22.7107128, 75.8497303
46	2	67	narsing mandir, sai mandir ke pass chhattribagh	kuan	private	brickwork	12	2		unsafe	Yes	religious	22.7101716, 75.8495847

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Length (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-Location
47	2	67	lakshmi vyankatesh mandir, rajput bagichi ke pass chhatrabagh	kuan	private	brickwork	9	1		unsafe	Yes	none	22.7085338, 75.8496075
48	2	69	parasrampuriya school sonuth rajmohalla	kuan	private	stone	20	3	4	unsafe	Yes	educational	22.714734, 75.8443355
49	2	67	छोटीबाग हनुमान चौक हनुमान मंदिर हनुमति	kuan	private	stone	10	1.5		unsafe	Yes	religious	22.7095705, 75.8484757
50	3	56	kachi mohalla near hajari center	kuan	government	stone	12	3		dewatering disliting and new jaali	Yes	none	22.7250524, 75.8664923
51	3	57	shram ayukt karyalay ke pass	kuan	government	stone	18	3		dewatering disliting and new jaali fitting	Yes	none	22.7250524, 75.8664923
52	3	56	Srinath Niketan,Snehharag anj Gali no.3	kuan	private	stone	25	4		4 no of flats are constructed above well	Yes	residential	22.7277743, 75.8645929
53	3	57	Lochi mohalla shiv mandir ke pass	kuan	government	stone	15	3		Desliting and dewatering required	Yes	none	22.7204717, 75.8624957
54	3	57	35, Mewati mohalla	kuan	private	stone	10	3		Verandah constructed on well by cement concrete slab. Slab dismantle and cover with jaali	Yes	residential	22.7204717, 75.8624957
55	3	57	Mewati mohalla masjid	kuan	private	stone	7	3		Slab and wall constructed	Yes	religious	22.7229578, 75.8639263
56	3	56	Inside Ganesh Mandol	kuan	private	stone	18	4		Slab Constructed on well	Yes	none	22.7223531, 75.863253
57	3	57	Jail road shiv mandir	bawdi	private	stone	15	4	5	Temple construction on well	Yes	religious	22.7263553, 75.8627287
58	3	58	Sadar bazar main road Bhoot bawdi	bawdi	government	stone	20	20	20	Desliting and dewatering required	Yes	none	22.7392686, 75.855873

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Length (in meters)	Ursafe or Maintenance Required Details	Required Maintenance and Civil Work	Enrichment Category	Geo-Location
59	3	58	sadar bazar masjid	kuan	private	stone	10	3		slab work on well	Yes	religious	22.7301685, 75.8492194
60	3	58	Bakshibag Bawdi	bawdi	government	stone	20	15	30	Desilting and dewatering required and Jali required	Yes	none	22.7271229, 75.8512519
61	3	56	rajumar mandi near compost	kuan	government	stone	25	12		dewatering desilting and jaali	Yes	none	22.7342184, 75.8659225
62	3	57	DRP line shiv mandir ke pas	kuan	government	stone	25	7		new construction work with jaali and cleaning required	Yes	none	22.7316416, 75.8615654
63	3	57	DRP line near boen gym	kuan	government	stone	15	3		new construction like RCC work and jaali and cleaning required	Yes	none	22.7316416, 75.8615654
64	3	57	Mahar Ashram Bawdi	bawdi	government	stone	20	15	15	desilting and dewatering required	Yes	none	22.7246991, 75.8532138
65	4	10	natveshwar mahadev Mandir	kuan	government	rcc	70	4	70	naveshwar mahadev mandir free ganj	Yes	none	22.7360653, 75.8493219
66	4	10	akhada banganga main road	kuan	government	rcc	50	10	50	shukha	Yes	none	22.7386715, 75.8496689
67	4	13	laxmi bai anaj mandi campus near nr5 road	kuan	government	brickwork	12	4		needs to be covered & partially filled with garbage restoration required	Yes	none	22.7394739, 75.8371997
68	4	10	laxmi bai nagar bheru baba mandeal	kuan	government	rcc	70	7	70	shukha	Yes	none	22.7403348, 75.8503321
69	4	10	choti kumar khadi anganwadi	kuan	government	rcc	40	5	40	shukha	Yes	residential	22.7435949, 75.8519666
70	4	10	banganga kund Jim ke pass	kuan	government	rcc	50	20	50	shukha	Yes	residential	22.74419, 75.8488103
71	4	10	hajri sentar uljen naka	kuan	government	rcc	45	20	45	kachar bhara he	Yes	residential	22.7455637, 75.8461584

S.No.	Zone /Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Length (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Coordinates
72	4	kush aasram Mahesh Yadav nagar	kuan	government	rcc	45	7	45	kachara	Yes	residential	22.7452938, 75.8503088
73	4	bawdi basti bhagirathpura	bawdi	government	stone	20	12		needs to be covered , raising wall height , cleaning & restoration work	Yes	none	22.7454188, 75.8603392
74	4	kashyap house behind hanuman mandir main road bhagirath pura	kuan	private	brickwork	18	4		not required	Yes	none	22.7470773, 75.8631252
75	4	khatic samaj dharmshala inside premise	kuan	private	brickwork	18	3		unsafe/slab needs to be dismantled & fixed by steel jaali	Yes	commercial	22.7491593, 75.8619285
76	4	new Ram ngr. shiv mandir.	kuan	government	brickwork	18	6		prpt wall reqd. & steel jali reqd.	Yes	none	22.7566651, 75.8337436
77	4	bhagirathpura near mamaji ka bhata	kuan	private	brickwork	15	2		to be covered steel jali	Yes	none	22.74923, 75.8586605
78	5	E71 love kush and sabri g sector	kuan	government	brickwork	16	7	7	covered with jali and parapet wall (sate)	Yes	none	22.7606334, 75.8721477
79	5	lulaa babo ka mandir hira nagar poonli thana	kuan	government	brickwork	6	2	2	covered with jali and parapet wall (sate)	Yes	none	22.7591818, 75.8728333
80	5	ma sarab nagar ma sarab mandir sukhliya	kuan	government	brickwork	17	4	4	covered with Rcc slab in mandir campus	Yes	religious	22.7590365, 75.8748033
81	5	325 c m second sukhliya	kuan	government	brickwork	13	6	6	jali Or parapet wall required	Yes	none	22.7653774, 75.8761578
82	5	megdud garden ke andar mandir ke Pass	kuan	government	stone	13	6	5	covered with jali and parapet wall (sate)	yes	none	22.7510551, 75.8889505
83	5	megdud Nagar gali no. 9 r ageshwar mhiadev mandir	kuan	government	brickwork	14	5	5	covered with R C C. slab in mandir campus	Yes	religious	22.7510551, 75.8889505

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Length (in meters)	Unsafer Maintenance Required Details	Required Maintenance and Civil Work	Spotlights Category	Geo-Location
84	5	28	n-egdut Nagar gali no. 2 sifla mata mandir	kuan	government	brickwork	15	6	6	covered with R.C.C. slab in mandir campus,	Yes	religious	22.7509279, 75.8831975
85	5	28	Medium Nagar gali no. 12	kuan	government	brickwork	15	4	4	covered with jali and parapet wall (sate)	Yes	none	22.75056634, 75.8829851
86	5	28	badi bhamori sindhi ka kuwa	kuan	government	brickwork	12	4	4	covered with R.C.C. slab in mandir campus	Yes	religious	22.7476304, 75.8849731
87	5	22	hira nagar basti punm hardiya ke piche	kuan	government	brickwork	9	3	3	covered with R.C.C. slab in mandir campus	Yes	none	22.7587327, 75.868919
88	5	24	Kulkarni bhatta nayi basti	kuan	government	brickwork	25.5	10		totally unsafe and need to construct wall for and steel work for cover.	Yes	none	22.7416536, 75.8635336
89	6	25	Janta Quarter Inside Motibaba Garden	kuan	government	stone	10	4	4	Safe	Yes	none	22.741033, 75.8767367
90	6	25	Nanda nagar Jhanda chowk garden	kuan	government	brickwork	20	5	5	Slab covered over well which is situated in front of shiv mandir inside Jhanda chowk garden.	Yes	religious	22.7427808, 75.879527
91	6	25	Nanda nagar behind gurudwara	kuan	government	brickwork	12	5	5	Safe , maintenance required	YES	none	22.7406392, 75.881615
92	6	25	Nanda nagar road no 08 vijayeshwar mandir	kuan	government	brickwork	20	5	5	Covered with slab, inside temple campus open area	Yes	religious	22.740686, 75.881432
93	6	25	Nanda nagar road no 08 vijayeshwar mandir	kuan	government	brickwork	20	5	5	Covered with slab, inside temple campus open area	Yes	religious	22.740686, 75.881432
94	6	25	Nanda nagar, Road no 09, shiv mandir	kuan	government	brickwork	30	5	5	Covered by slab, situated inside temple activities area	Yes	religious	22.744134, 75.8792991
95	6	27	Nanda nagar siflamata mandir Garden	kuan	government	brickwork	15	4	4	Half covered with slab ,Maintenance required	YES	religious	22.7447752, 75.8808941

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Length (in meters)	Uses or Maintenance Required Details	Required Maintenance and Civil Work	Settlement Category	Geo-Location
96	6	27	Geeta bawdi hanuman mandir bajrang nagar	bawdi	government	stone	30	10	10	Very Unsafe, Bawdi is covered with slab and paver blocks are sinking also the place is used for activities and functions. Maintenance required urgently.	YES	religious	22.7481443, 75.883145
97	5	24	shivshakti nagar Kulkarni bhatta	kuan	government	brickwork	35	10		Totally unsafe uncovered civil work requirement.	YES	none	22.739209, 75.864407
98	5	24	Mali mohalla	kuan	government	brickwork	10	5		unsafe need to be covered and civil work requirement.	YES	residential	22.7424810, 75.8653682
99	7	29	Neelkantheshwar Mahadev Mandir Behind Jain Mandir Vijay nagar	kuan	government	brickwork	14	4	4	Unsafe, RCC Slab. Room Constructed on kuan	Yes	residential	22.765045, 75.8873412
100	7	29	Vijayeshwari Mata Mandir, Vijay Nagar	kuan	government	brickwork	15	4	4	Unsafe, Room Constructed On Kuan	Yes	residential	22.7544389, 75.8911285
101	7	29	Bhawen, Vijay Manglik Nagar	kuan	government	brickwork	15	4	4	Unsafe, RCC Slab	Yes	commercial	22.750934, 75.8947683
102	8	35	Panchwati main kuwa	kuan	government	brickwork	24	6.5		damaged parapet and jali required	Yes	none	22.7937912, 75.9028474
103	8	35	Panchwati mandir garden ke samne	kuan	government	rtc	20	9		Jali required	YES	none	22.7943106, 75.9048032
104	8	35	Talawali gaon near dream city	kuan	government	stone	18	5	6	Jali required	YES	none	22.7990906, 75.9117993
105	8	35	hamuman mandir Govt school	kuan	government	brickwork	15	6		Jali required	YES	educational	22.7990906, 75.9117993
106	8	35	bhagat Singh market AB road	kuan	private	brickwork	15	3		parapet and jali required	YES	none	22.7858891, 75.9073307

S.No.	Zone/Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Length (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Enroachment Category	Geo-Location
107	8	Mayakheji Ram mandir ke pass	bawdi	government	stone	12	8	6	maintenance and jali required	YES	none	22.770777, 75.945944
108	8	talawali talab ke pass	bawdi	private	rcc	12	9	7.5	Jali required	YES	none	22.7996283, 75.9176861
109	9	nadiya nagar gali no 4,5	kuan	government	rcc	20	5	4	1 रिपेयर करना है 2 खासी लगाना है 3 सफाई करवाना है 4 ड्रिन नेट लगाना है	YES	residential	22.7101788, 75.8265463
110	9	inside Sandhi Shikhar apartment	kuan	government	rcc	22	5		1) cleaning of well 2) grill work 3) green net coverage 4) other civil maintenance work	YES	residential	22.7381354, 75.8811715
111	9	A sector MIG kankest-wari yog kendra	kuan	government	rcc	20	5		1) cleaning of well 2) grill work 3) green net coverage 4) other civil maintenance work	YES	commercial	22.7378327, 75.6845777
112	9	lala ka bagicha behing-hanuman ji temple	kuan	government	rcc	22	5	0.8	1) cleaning of well 2) grill work 3) green net coverage 4) other civil maintenance work	YES	residential	22.7378327, 75.6845912
113	9	lala ke bagicha baba kua	kuan	government	rcc	25	5		1) cleaning of well 2) grill work repair 3) green net coverage 4) boundary wall construction with steel railing 5) other civil maintenance work	YES	none	22.7381364, 75.8811715
114	9	A sector MIG inside Hanuman temple	kuan	government	rcc	22	5		1) cleaning of well 2) grill work 3) green net coverage 4) other civil maintenance work	YES	none	22.7376475, 75.8845972

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (In meters)	Width/Diameter (In meters)	Length (In meters)	Unsafe or Maintenance Required Details	Required (Mechanics and Civil) Work	Encroachment Category	Geo-Location
115	9	47	Near Kushwah cycle shop, Dubey ka Bagicha	kuan	government	stone	11	6	8	cleaning, Jaali and repairing required	YES	religious	22.7294848, 75.870645
116	9	47	In front of Victoria Urban, Vallabh Nagar	bawdi	government	stone	12	10	10	Unsafe, cleaning and maintenance required	YES	commercial	22.7271293, 75.8698642
117	9	47	Below Shv Mandir, Gali no 3, Goma ki fel	kuan	government	brickwork	10	3		covered with slab	YES	religious	22.7329175, 75.8763705
118	9	47	Near Vijay Aata Chakki, Gali no 3, Goma ki fel	kuan	government	stone	9	3		Cleaning, maintenance required	YES	none	22.7329574, 75.8771266
119	9	47	Sterling Arcade, 15/3 Race Course road	kuan	private	stone	17	7.5		covered with slab	YES	commercial	22.7252006, 75.8786614
120	9	47	NM tower, 56 dukaan	kuan	private	stone	12	5.5		covered with slab	YES	commercial	22.7254201, 75.8832867
121	9	47	Chetak vihar, 56 dukaan	kuan	private	stone	15	5		covered with slab	YES	residential	22.7252401, 75.8834282
122	9	46	पंचम कि फैल बड़े अखाड़े के पास	kuan	government	rcc	420	8	8	स्लीन करना है और height बढ़ाना है कलर करना है	Yes	residential	22.7298951, 75.8809796
123	9	46	सिंधी चौक पंचम की फ़ैल	kuan	government	rcc	450	8	8	पूरा रिपेयर करना है जाली लगनी है कलर करना है	Yes	residential	22.7309159, 75.879177
124	9	46	पंचम की फ़ैल	kuan	government	rcc	550	6	6	पूरा रिपेयर करना है जाली लगनी है कलर करना है	Yes	religious	22.7293117, 75.8815766
125	9	46	अमर टेकरी नानी का बड़ा	kuan	government	rcc	200	3	3	1 साफ़ सजाई करने है 2 जाली लगाना है 3 पेंटिंग करना है	YES	religious	22.7310542, 75.8815529
126	9	46	अमर टेकरी नाले किनारे	kuan	government	rcc	300	3	8	1 साफ़ सजाई करवाना है 2 जाली लगवाना है 3 पुरताई करवाना है	YES	religious	22.7310649, 75.8815306

S.No.	Zone/Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Length (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Engagement Category	Geo-location	
127	9	46	मोनु वीडियो गेम के पास	kuan	government	rcc	300	4	4	1 साफ सफाई करवाना है 2 जाली लगवाना है 3 पुताई करवाना है	YES	religious	22.7317388, 75.8830425
128	9	46	सामनाथ की जुनि चाल कुयवाड़े सनाज धर्मशाळा	kuan	government	rcc	300	5	5	1 साफ सफाई 2 पुताई करवाना है	YES	religious	22.731711, 75.887709
129	9	46	सोमनाथ की चाल सनी शुकवा के घर के पास	kuan	government	rcc	350	4	4	1 रिपेयर करना है 2 जाली लगाना है 3 पुताई करना है	YES	religious	22.7316739, 75.8855982
130	10	38	Jija kirane ke पास Marmta colony khajrana	kuan	private	stone	6	5	5	रहवासियों से प्राप्त जानकारी अनुसार बावड़ी के ऊपर निर्माण किया हुआ है।	Yes	residential	22.7296342, 75.8973706
131	10	39	135 ke samne naharshah wali road, tanzim nagar, khajrana	kuan	private	brickwork				कुएँ को पूर्व में भरा जा चुका है	YES	none	22.7346527, 75.9126098
132	10	42	Telephone nagar Agrawal house gali no.04 Telephone nagar	kuan	government	brickwork	9	8	8	situated on road covered with RCC roof	YES	none	22.7237316, 75.9036088
133	11	60	Baba deep complex ke पास	bawdi	government	stone	16	3	3	unsafe, jali lagana & repairing work	YES	commercial	22.7188586, 75.8709975
134	11	60	Raipura Kachchi masjid ke bayi taraf	kuan	government	brickwork	13	2	2	Unsafe	YES	none	22.716801, 75.8631325
135	11	60	Doulat ganj gali no.03 pekki masjid ke पास	kuan	government	brickwork	15	3	3	Unsafe	YES	none	22.7153487, 75.8528412
136	11	55	Snyogita ganj thana	kuan	government	brickwork	15	2.5	2.5	Safe, jali repairing	YES	religious	22.7078113, 75.8775359
137	11	48	Balaram nagar Bagiche ke पास	kuan	government	stone	24	4	4	Safe	YES	none	22.715413, 75.8913151

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Length (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-Location
138	11	48	Pasi mohalla gail no. 01	kuan	government	brickwork	15	3.5		Unsafe, jali repairing	YES	religious	22.7156221, 75.8913496
139	11	48	Badi gwalitoli shila mata mandir ke pas	kuan	government	brickwork	20	3		Unsafe, jali lagana hai	YES	religious	22.7186316, 75.8898427
140	11	49	Mahaveer nagar kanoalya road	kuan	government	brickwork	20	3.5		Safe, jali & maintenance work required	YES	residential	22.717119, 75.9030855
141	11	49	Tilak nagar sai mandir ke samne	kuan	government	brickwork	23	10		safe, jali repair and painting required	YES	residential	22.7150819, 75.8984207
142	11	60	Champa bag masjid ke pas	kuan	government	brickwork	12	2.5		Unsafe, Munder bnane, gaad nikalhai, jali lagana	YES	residential	22.7164345, 75.8661539
143	11	60	27 Jawahar marg, hard gair house	kuan	government	brickwork	15	2.5		Unsafe,	YES	commercial	22.7148395, 75.8658341
144	11	55	Raigagan travels patel square	kuan	government	brickwork	12	2.5		Unsafe, slab dalakar band kiya gya hai	YES	commercial	22.7155637, 75.8665285
145	11	55	Banjara Hotel ke piche chhoti gwal toll	kuan	government	brickwork	15	5.2		Unsafe, slab dal kar band kiya gya hai	YES	commercial	22.7143554, 75.8710194
146	11	60	Hathi pala road shree ram mandir	kuan	government	brickwork	12	2.5		Safe	YES	none	22.7156912, 75.8666059
147	11	60	Hathi pa a road remesh rathor ka godaun	kuan	private	brickwork	15	3		Unsafe, jali nhi hai	YES	commercial	22.7135008, 75.8641215
148	11	60	gokiro 2 pani ki tanki k pas (sahid lala)	kuan	government	brickwork	12	2		repairing and jali required	YES	residential	22.7159211, 75.8625779
149	11	48	Palasia square petrol pump left turn	kuan	government	brickwork	15	3		Unsafe	YES	none	22.7056745, 75.8848019
150	12	59	Krishna pura chhatri	bawdi	government	brickwork	10	3	3	maintenance required	yes	none	22.7188472, 75.8579246

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Radius (in meters)	Length (in meters)	Unsafe of Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geo-Location
151	12	59	Krishna pura chhatri	kuan	government	stone	10	2	2	unsafe	yes	none	22.7183753, 75.8580053
152	12	61	surajkund katkatpura bawdi	bawdi	government	stone	20	7	10	unsafe	yes	religious	22.7079139, 75.8604131
153	12	61	katkatpura masjid	kuan	government	stone	15	2	2	maintenance required	YES	none	22.7099039, 75.8628545
154	12	61	Lal Mandir Kumawat pura	kuan	government	rcc	15	2	2	maintenance required	YES	religious	21.7097504, 75.8630038
155	12	61	Jagde ka bagicha Radha Govind ka bagicha railway line ke paas	bawdi	government	stone	10	5	5	unsafe	yes	none	22.7097504, 75.8630038
156	12	62	vishwarath shiv mandir-murali mohalla	kuan	government	brickwork	50	5	5	unsafe	YES	religious	22.708364, 75.8643611
157	13	74	bharanpuri Ganesh mandir	kuan	government	rcc	15	4	4	unsafe ,covered by RCC slab	YES	none	22.686876, 75.8616891
158	13	77	Ganesh Nagar	kuan	private	brickwork	15	8	8	unsafe ,covered by slab	YES	none	22.6699898, 75.8768148
159	13	78	choitram school	kuan	private	stone	15	6	12	unsafe , covered by slab	yes	none	22.6881576, 75.8523857
160	13	78	parwati tukeshwar temple	bawdi	private	stone	15	6	15	unsafe,access to be removed	yes	none	22.6809574, 75.8392929
161	13	78	Devi bhilya colic storage	kuan	private	brickwork	15	6	6	unsafe ,civil work required	yes	none	22.6796008, 75.8436848
162	13	80	वीर सावरकर मंदिर शिव मंदिर के पास	kuan	government	brickwork	60	1500	80	IMC	yes	residential	22.6645695, 75.8245242

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Length (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Chit Work	Encroachment Category	Geo-Location
163	13	80	veer savarkar nagar	kuan	government	brickwork	15	5	5	unsafe grill should be installed	yes	none	22.6658014, 75.8234208
164	14	85	sector c Aisa beauty parlour ma Vaishnav shop Ram Mandir ke pass Prajapat Nagar	kuan	government	brickwork	18	12	12	no	yes	none	22.6914435, 75.8199545
165	14	79	Sukh nivas road gate boundary ke pass	kuan	government	brickwork	20	5	5	no	yes	none	22.6721253, 75.8036239
166	15	83	scheme 71 sector a chandan nagar pani ki tanki k pass	kuan	government	brickwork	11	5		safe. jaali lagi huyi hai. munder bani hai. safai karna hai dia 4.5m. jali repairing ki aavashyakta hai	yes	none	22.7031879, 75.8281157
167	15	71	66 bankcolony ke pass.	kuan	private	brickwork	15	9		jaali lagayi jana hai. kua society dwara maintain kia jata hai	yes	none	22.6938402, 75.8367477
168	15	72	kesharbagh road	kuan	private	rcc	15	4		jaali nahi lagi hai.	yes	none	22.687917, 75.8436352
169	15	73	ashtang ayurvedic college	kuan	government	brickwork	15	4		jaali lagana hai. boundry hight raise krna hai	yes	none	22.6949025, 75.8413549
170	15	73	lalbagh gts ke piche, magar kua	kuan	government	brickwork	20	8		boundrywall tuti jarjar hai, entrance gate toota hai	yes	none	22.6970094, 75.8444818
171	15	73	poorandas ki bagiya	kuan	government	brickwork	15	2		parapet maintenance required	yes	none	22.6931621, 75.8514572
172	15	72	lokmany nagar post office ke samne	kuan	government	brickwork	15	16		parapet is cracked, no jaali over well.	yes	none	22.6547082, 75.8463807
173	15	2	nake wala road jp tower le paas footpath par	kuan	government	rcc	18	2		raised parapet banane ki avashyakta hai	yes	none	22.7088714, 75.8256469

S No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Length (in meters)	Details of Maintenance Required	Required Maintenance and Civil Work	Encroachment Category	Coordinates
174	15	71	ram mandir cloth market hospital ke pas	kuan	government	stone	15	10	10	raised boundary hai charo taraf. safai ki avashyakta hai	yes	none	22.6452591, 75.8147692
175	15	83	scheme 71 sector a industrial area	kuan	government	brickwork	20	5		jali lagayi jana hai	yes	commercial	22.7074408, 75.8302252
176	16	15	bada bhangada gaon	bawdi	government	stone	25	15	20	jali se covered karna hai stone judai karna hai	yes	none	22.756355, 75.7921961
177	16	3	ganga bagichhi	kuan	government	brickwork	22	2.8	22	civil work, green net, steel work	yes	residential	22.7163797, 75.8234764
178	16	3	baddi ganga bagichi	bawdi	government	brickwork	75	16	75	no work	yes	commercial	22.7128734, 75.8252035
179	16	3	nagin nagar main road	kuan	government	brickwork	65	13.4	65	civil work green net, steel work	yes	residential	22.7180122, 75.8223532
180	16	14	somani nagar	kuan	government	brickwork	50	3.4	50	civil work, green net steel work	yes	residential	22.7301756, 75.8233196
181	16	15	tkriya baoshah	kuan	private	brickwork	65	10.1	65	steel work, civil work green nete	yes	residential	22.7573805, 75.827793
182	17	23	Baba ki Kuyaan Lt. Rajesh Joshi Garden	kuan	private	brickwork	20	2		Well should be packed. Usually Garbage thrown in the well.	yes	none	22.7486741, 75.8705552
183	17	23	test address	kuan	government	rec	10	10	10	Pardesipura Road No 4 Ram Mandir ke पास Kuan	yes	residential	37.4220936, 122.083922
184	17	19	Akash namkir, ke pas kumedi, Gav	kuan	private	brickwork	40	12		Unsafe	yes	none	22.7871824, 75.8573154
185	17	19	Kumedi gav	kuan	private	brickwork	35	8		Unsafe	yes	none	22.7871824, 75.8573154

S.No.	Zone	Ward	Address	Type	Category	Type of Construction of Kuan/Bawdi	Depth (in meters)	Width/Diameter (in meters)	Length (in meters)	Unsafe or Maintenance Required Details	Required Maintenance and Civil Work	Encroachment Category	Geotification
186	17	18	purani revti kalash patel, Manoj. Patel. Ke. Makan. Ke. Piche	kuan	private	stone	23	7		Unsafe, Open Well	yes	none	22.7978049, 75.8470193
187	17	18	Revti, Gay. L.C. I. Colleg. Campus	kuan	private	brickwork	40	12		Unsafe	yes	none	22.8020368, 75.838325
188	17	18	Bhavani nagar. Kakad, Vidya. Bhardi, School ke pas.	kuan	private	brickwork	22	12		Unsafe open Well	yes	none	22.7998319, 75.8467782
189	17	18	Bhavani, Nagar. Mahesh, Thakur ke ghar ke Piche	kuan	private	brickwork	28	7		unsaf open well	yes	none	22.7998316, 75.8467792
190	17	23	Pardesipura Masjid Gali No 8	kuan	private	brickwork	15	3		Masjid slab is constructed over the well. Walls are also constructed near kuan. It needs to be demolished.	yes	religiouis	22.745664, 75.8698413
191	17	23	Koli Mohalla Dharashala ke samne Gali No 11 Pardesipura	kuan	government	brickwork	20	4		Road is Constructed over well traffic passes over it which should be demolished. Water is available maintenance work must be done.	yes	none	22.7456871, 75.863344
192	17	19	MR10. lav. Kush. Chouraha	kuan	private	stone	22	10		Open Well dengrcus	yes	none	22.7890793, 75.84813
193	17	19	Asha. Confensnati ke pas. Narwal. Nala	bawdi	government	stone	22	8	8	Unsafe, Open, Bawdi	yes	none	22.7576837, 75.8513982
194	17	19	Ganesh. Dham. Relvey रीटन के pas	kuan	government	brickwork	50	10		open well unsafe	yes	none	22.7604275, 75.85482
195	17	20	Sukhiya Gaon Khamrola House	kuan	government	brickwork	20	2		A water tank for Common use is now placed over slab of the well and it is packed. Condition of well must be checked.	yes	none	

(Signature)
अधीक्षक यंत्रणी



जल यंत्रालय एन डी नं०
N.A. नगर पालिक निकास

Annexure-6

Annexure-6


Photographs taken during inspection on dated 15/07/2023




Meeting of Committee Members at ADM Office, Indore on dated 15/07/2023



Baoli/ Stepwell at Sapna Sangeeta Main Road, Opposite Capital Tower building



Well (Large Dia Well) at Agrawal Nagar, Sitlamata Mandir, Indore




Well (Large Dia Well) at Vishnupuri Shiv Mandir, Indore



Baoli at Amitesh Nagar, Udhm Singh Chouraha, Indore




Well (Large Dia Well) at Mukteshwar Mahadev Mandir, Amitesh Nagar, Indore




Baoli at Government Higher Secondary School Campus, Kila Maidan, Indore



Dhakkanwala Kuwan, Dhakkanwala Squire, Indore



Filled up well at Snehlata ganj Square, Near Jail, Indore



Filled up site of well/ baoli at Beleshwar Mahadev Mandir, Patel Nagar, Indore