


SHIVALIK BUILDTech  
Pvt Ltd  
Pavement - V  
Gutter - Field  
Damage - V-Shape  
Drain  
971256 - 971276


For Shivalik Buildtech Pvt Ltd.  
Authorised Signatory




SHIVVIK SALES/TRADE  
Mr. Vikas  
961980 - 971030  
Earthwork

For Shivvik  
Authorized  
Signation






For Shivalik Buildtech Pvt. Ltd.  
Authorised Signatory





For Shivalik Buildtech Pvt. Ltd.  
Authorised Signatory

SHIVALIK BUILDTECH  
PVT LTD  
PACKAGE - V  
97+455 to 97+484  
Damage: Retaining  
Wall





Shivalik Buildtech Pvt. Ltd.  
Authorised  
Signatory





SHIVAK BUILDTECH  
PVT LTD  
PRAKASH - V GUMMA - TELANGANA  
97490-97510  
Damage : DBM, BC  
(RHS)





SHIVAJI BUILDTECH  
Pvt Ltd  
PUNE - V. GUMASTHA  
974560 - 974610  
Dams - V-Shape  
Drain


For Shivaji Buildtech Pvt. Ltd.  
Authorized Signatory





Shivalik Buildtech Pvt. Ltd.  
Authorized Signatory












Shivalik Buildtech Pvt. Ltd.  
Authorized Signatory


SHIVALIK BUILTECH PVT. LTD.  
P. K. RAJE-V, SUMMA - FEZIZ  
103+367  
Damage to - Concrete R/W  
Apron






SHIVALIK BUILDTECH PVT. LTD.  
PACKAGE-V, SUMMA-BEER  
103+026 to 103+041  
Damage:- Retaining Wall/  
Modified Time  
Beam/  
Shoulder

For Shivalik Buildtech Pvt. Ltd.  
Authorised Signatory





For Shivalik Buildtech Pvt. Ltd.  
Authorised  
Signatory





SHIVALIK BUILDTECH Pvt. Ltd.  
 PACKAGE - V, SUMMA - FEEDIZ  
 102+460 to 102+750  
 Damage: Earthenwork  
 DBM/BC/  
 Shoulder  
 V-Shape Drain

For Shivalik Buildtech Pvt. Ltd.  
 Authorised  
 Signatory



Shivalik Buildtech Pvt. Ltd.  
Authorised  
Sales Office

SHIVALIK BUILDTECH PVT. LTD.  
PACKAGE - V, SUMMA - FEEDER  
102+460 to 102+750  
Damage: Ear/Airwork  
DSm/Bcl  
Shoulder  
V-shape Drain




For Shivalik Buidtech Pvt. Ltd.  
Authorised Signatory

SHIVALIK BUIDTECH PVT. LTD.  
PACHWADE-V, SUMMA-FEED  
102+126 to 102+260  
Damage: Retaining Wall  
Dism/BC  
Shoulder N.  
Snake Drain  
Modified Time Depth




SHIVALIK BUILDTECH PVT. LTD.  
PASSAGE-V, SUMMA-REDE  
1011860 to 1011925  
Damage: Breast Wall






SHIVALIK BUILDTECH PVT. LTD.  
10270000 to 10271000  
Drawing: Earthwork / CSG  
Shoulder / N-Shoulder  
Shape Open








SHIVALIK OVERTECH PVT. LTD.  
Summa - FEED  
101+722 - 101+742


SHIVALIK OVERTECH PVT. LTD.  
Package - V, SUMMA - FEED  
101+722 - 101+742  
Damage: Modified Thrust Beam





SHIVALIK BUILDTech Pvt. Ltd.  
PACKAGE - V, GUMMA - FEEDS  
101+850 - 102+000  
Damage: DBM/BC  
CRSB/MMM Shoulder  
V-Shape Dr  
Earthwork
















SHIVALIK DIVITECH PVT. LTD.  
PACKAGE-V, SUMMA-FEDIZ  
10+580-101+600  
Damage: DBM/BC  
(RHS)











For Sh  
Authorised  
Signatory  
SHIVAJI RAVITECH Pvt Ltd


SHIVAJI RAVITECH Pvt Ltd  
Package - V, Gunna - Fez  
161+560 - 101+580  
Damage: Modified  
Time Beam








SHIVRUK CONTRACTS Pvt Ltd  
Phase V, Gumbha - ECDC  
101+L100 to 101+46  
Damage? Modified Time Beam

Authorized Signatory  
SHIVRUK CONTRACTS PVT. LTD.









Shivalik Buildtech Pvt. Ltd.  
Autonomous  
Institution

SHIVALIK BUILDTTECH PVT. LTD  
PACKAGE-V, SUMMA-FEDIZ  
10H156  
Culvert  
Return Water  
Damage:

Columbus

