

1251

**BEFORE THE HON'BLE NATIONAL GREEN TRIBUNAL
PRINCIPAL BENCH, NEW DELHI
O.A. NO.311 OF 2022**

IN THE MATTER OF:

Dr. Jeet Singh Yadav

...Applicant

Versus

Govt. of NCT Delhi & Others

...Respondents

N.D.O.H.: 16.02.2026

**CONVENIENCE COMPILATION FILED ON BEHALF OF
THE RESPONDENT NO. 3 /DDA**

INDEX

S. No.	Particulars	Page No.
1.	Overview of Khasra No. 373/1 of Village Mundka.	1-6
2.	Overview of Khasra No. 178/1 of Village Mundka.	7-11
3.	Overview of Khasra No. 163/1 of Village Mundka.	12-15
4.	Overview of Khasra No. 142 of Village Mundka.	16-21
5.	Copies of relevant videos in a pendrive.	22

RESPONDENT No.3/DDA

THROUGH

**DEEKSHA L. KAKAR
COUNSEL FOR DDA**

B-6/58, LGF, SAFDARJUNG ENCLAVE
NEW DELHI – 110029.

Ph. 9313119255 | deeksha.kakar@scladi.com

Enrol.No.D/1154/2008

Place: New Delhi

Dated: 13.02.2026

BRIEF OVERVIEW OF WATER BODY AT KHASRA NO 373/1 OF VILLAGE MUNDKA**OVERVIEW:-**

S. no	Description	Details
1	Location (Geo-coordinates)	28.677344"N 77.025229"E
2	Dimensions as per revenue Records: Length	71.34Gatha(179.06 mtrs) 82.89 Gatha(208.05 mtrs) 52.51Gatha(131.80 mtrs)
4	Area as per revenue	15-18(Bigha-biswa)(13403 in sqm)

BRIEF OVERVIEW OF WATER BODY AT KHASRA NO 373/1 OF VILLAGE MUNDKA

OVERVIEW:-

S. no	Description	Details
1	As per existing site condition The area for Takiya Talab	
2	Dimensions as per site condition: a) Length(Total W/B within boundary wall) b) Length(water filled)	134.19 mtrs, 230.5 mtrs ,176.11 mtrs 134.19 mtrs, 52.71 mtrs, 101.86 mtrs, 112.74mtrs
3	Area-Total within boundary wall Area-Water filled Area-Park area including Temple & Post office	13397sqm(approx.) 8622.44sqm(approx.) 4774.57sqm(approx.)
4	Area as per existing talab area within boundry wall	(13397 in sqm)

WATER BODY AT KHASRA NO 373/1 OF VILLAGE MUNDKA

DETAILS OF WORKS:-


SURROUNDING PATH:-A wide path with walkway and green area surrounding all sides of the water body is proposed by IIT which is yet to be constructed as the estimate is under scrutiny.

RESTORATION AND PROTECTION MEASURES:- Water body is receiving constant inflow of drain water from multiple sources and storm water through rain. The water body is already in raw shape. General desilting, boundary wall repair works will taken up in 1st phase of rejuvenation, further as per consultancy with IITDelhi .Water body is proposed for beautification and protection of water body including building walkway, fountains ,areators , STP installation for water filtration have been taken up in the estimate, which is under scrutiny phase .Work will takeup after completion of codal formalities.

WATER BODY AT KHASRA NO 373/1 OF VILLAGE MUNDKA

CURRENT STATUS OF WATER BODY:-

GPS photographs and videos of water body are provided below. showing the current condition of water body:-




<https://drive.google.com/file/d/1IiN99hiW610rITzFz9POjaNq1h5vzqr/view?usp=drivesdk>

WATER BODY AT KHASRA NO 373/1 OF VILLAGE MUNDKA

CURRENT STATUS OF WATER BODY:-

GPS photographs and videos of water body are provided below, showing the current condition of water body:-



<https://drive.google.com/file/d/13oD9dlsrVHtwD42VdkJuAnYilxxwd/view?usp=drivesdk>

**Overview of Khasra No. 373/1 of Village Mundka
Aerial/ Drone Video-graphy**

1. <https://drive.google.com/file/d/1IiN99hiW610rffTzFz9PQiaNq1h5yzqr/view?usp=drivesdk>
2. https://drive.google.com/file/d/13oD9dlsnVHtwD42VdkJuAnYjlxxwd_V/view?usp=drivesdk

WATER BODY AT KHASRA NO 178/1 OF VILLAGE MUNDKA**OVERVIEW:-**

S. no	Description	Details
1	Location (Geo-coordinates)	28.677736"N 77.033213"E
2	Dimensions as per revenue records	42.04 Gatha (105.5 mtr), 8.66 Gatha (21.73 mtr), 52.00 Gatha(130.52 mtr)
4	Area in sqm	1640 sqm.
5	Area as per revenue records	01-19

WATER BODY AT KHASRA NO 178/1 OF VILLAGE MUNDKA

DETAILS OF WORKS:-

BOUNDARY WALL:- The pond area is a part of the park and vacant land which is surrounded by the densely populated area it is very necessary to construct Boundary wall as per site conditions.

SURROUNDING PATH:-A wide path with walkway with Green hedges surrounding all sides of the water body is to be proposed by IIT.

RESTORATION AND PROTECTION MEASURES:- Water body is receiving only storm water through rain. ~~The water body is already in raw shape having a well maintained park in half of the area. General~~ excavation, boundary wall works will under progress in 1st phase of rejuvenation, Further as per awaited report of consultant IIT Delhi may includes beautification and protection aspects of water body may include building walkway, painting wall, green portion development ,slope management etc. The proposal of rejuvenation of water body from IIT Delhi is still awaited.

WATER BODY AT KHASRA NO 178/1 OF VILLAGE MUNDKA

CURRENT STATUS OF WATER BODY:-

GPS photographs and videos of water body are provided below. showing the current condition of water body land:-



[https://drive.google.com/file/d/1DSzqoTP9jiGUBPm5pxepEjFO3z1eoSQf/view?](https://drive.google.com/file/d/1DSzqoTP9jiGUBPm5pxepEjFO3z1eoSQf/view?usp=drive_dk)
[https://drive.google.com/file/d/1DSzqoTP9jiGUBPm5pxepEjFO3z1eoSQf/view?](https://drive.google.com/file/d/1DSzqoTP9jiGUBPm5pxepEjFO3z1eoSQf/view?usp=drive_dk)

WATER BODY AT KHASRA NO 178/1 OF VILLAGE MUNDKA

CURRENT STATUS OF WATER BODY:-

GPS photographs and videos of water body are provided below, showing the current condition of water body land:-



[https://drive.google.com/file/d/1uaCCLJEdWgG1jLTImOHwSQdyhSzxJdm/view?](https://drive.google.com/file/d/1uaCCLJEdWgG1jLTImOHwSQdyhSzxJdm/view?usp=sharing)

Overview of khasra No. 178/1 of village Mundka Aerial/ Drone Video-graphy

1. <https://drive.google.com/file/d/1DSzqoTP9iiGUBPm5pxepFfFQ3z1eoSOf/view?usp=drivesdk>
2. <https://drive.google.com/file/d/1uaCLLJEdWgG1jLTInQHwSQdyhSzxJdm/view?usp=drivesdk>

**OVERVIEW OF WATER BODY OF KHASRA NO 163/1 OF VILLAGE
MUNDKA
OVERVIEW:-**

S. no	Description	Details
1	Location (Geo-coordinates)	28.681013"N 77.008802"E
2	Length	26.67Gatha (66.94mtr.)
3	Width	24.00 Gatha(60.24 mtr.)
4	Area in sqm	4046.4 sqm.
5	Area as per revenue	04-16

WATER BODY AT KHASRA NO 163/1 OF VILLAGE MUNDKA

DETAILS OF WORKS:-

RESTORATION AND PROTECTION MEASURES:- Water body is receiving only storm water through rain. The water body is already in Developed shape having a well maintained park, walkway and water body with pitching.

WATER BODY AT KHASRA NO 163/1 OF VILLAGE MUNDKA

CURRENT STATUS OF WATER BODY:-

GPS photographs and videos of water body are provided below. showing the current condition of water body:-



<https://drive.google.com/file/d/1hXDADLISSlu2dHKll7QobOHmBY3LVv6l/view?>

**Overview of khasra No. 163/1 of village Mundka Aerial/
Drone Video-graphy**

1. <https://drive.google.com/file/d/1hXDADLlSSlu2dHKIh7QobOHmBY3LVv6l/view?usp=drivesdk>

WATER BODY AT KHASRA NO 142 OF VILLAGE MUNDKAOVERVIEW:-

S. no	Description	Details
1	Location (Geo-coordinates)	28°41'27"N 77°01'08"E
2	Length	24 Gatha(60.40 mtr.)
3	Width	17.00 Gatha(42.70 mtr.)
4	Area in sqm	2579.97 sqm.
5	Area as per revenue	03bigha-01biswa

WATER BODY AT KHASRA NO 142 OF VILLAGE MUNDKA

DETAILS OF WORKS:-

BOUNDARY WALL:- The construction of peripheral boundary is under progress. Boundary wall has been constructed at two adjacent sides. However, due to higher water level the boundary wall could not be constructed at third site yet.


SURROUNDING PATH:-A 3M wide path surrounding three sides of the water body is proposed to be constructed. The construction work is under progress. However, difficulties are being faced due to high water level.

RESTORATION AND PROTECTION MEASURES:- Water body is receiving only single source of seasonal inflow of storm water through rain only. The water body is already in developed shape. General cleaning, repair and maintenance works are under progress for restoration, beautification and protection of water body as per Hon'ble court of NGT guidelines.

WATER BODY AT KHASRA NO 142 OF VILLAGE MUNDKA

CURRENT STATUS OF WATER BODY:-

GPS photographs and videos of water body are provided below, showing the current condition of water body:-



WATER BODY AT KHASRA NO 142 OF VILLAGE MUNDKA**CURRENT STATUS OF WATER BODY:-**



GPS photographs and videos of water body are provided below. showing the current condition of water body:-



WATER BODY AT KHASRA NO 142 OF VILLAGE MUNDKA

CURRENT STATUS OF WATER BODY:-

GPS photographs and videos of water body are provided below. showing the current condition of water body:-



**Overview of khasra No. 142 of village Mundka Aerial/
Drone Video-graphy**

1. https://drive.google.com/file/d/1f5t70Fnpwh2LO_5pQw_G_CHSdL9Z1KB0/view?usp=drivesdk
2. https://drive.google.com/file/d/1fghiROUkYIh8uJCGzEi_jmxbj2WeMxGiR/view?usp=drivesdk

1273

22

Copies of relevant videos in a pendrive.

