

Dated:-July15, 2020

JOINT INSPECTION REPORT IN VIEW OF ORDER OF NGT IN I.A. NO. 12/2020/EZ

Joint inspection report in view of order of NGT in I.A.No 12/2020/EZ

In reference of NGT order dated 23.6.2020, joint inspection has been carried out on 15.07.2020 by committee formed by NGT. Q-complex under question has been inspected. It is being constructed on the banks of mansinghi pond & having covered area 7105.16 sq.m including ground & first floor. The seating capacity to accumulate the pilgrims is 2920 no. and for their use toilet facility is provided. For disposal of sewage separate septic tank with soak pit has been constructed and effluent is being disposed off in drains. It has no relevance with pond.

Environment point of view number of large windows has been provided and there is sufficient aeration & ventilation. From environment side there is no problem.


For supply of water ,under ground water tank will be constructed and will be filled up by supplying water through boring & corporation water.

In routine , q-complex is not being used . it is used in special festival & in shrawan months for controlling the crowd & to facilitate the pilgrims. The passing strength of pilgrims is around 30000-40000 per day in peak season.

On the overall , the water of pond is safe and not being polluted due to construction of Q-complex. The overflow from Holy shiv Ganga comes to this pond and from here goes to Jalsar pond in case of overflow.

Also it to inform you that SSIEAA is not existing now.


(Ravindra Prasad)
Regional Officer


(Toufic Aslam)
Scientist 'B' (CPCB)


(Shailendra Kumar Lal)
D.D.C. Deoghar