

Important submission OA.065/2024 (CZ) Joint Inspection CBWTF SATNA

From : adnrtripathi71@gmail.com
Subject : Important submission OA.065/2024 (CZ) Joint Inspection
CBWTF SATNA

Fri, May 03, 2024 04:59 PM

📎 1 attachment

To : Registrar NGT, CZB, Bhopal <ngtczbbho-mp@gov.in>

Cc : ms msoffice <ms-mppcb@mp.gov.in>, chairman
chairmanoffice <chairman-mppcb@mp.gov.in>, ms
mpseiaa <ms.mpseiaa@gmail.com>, MS, CPCB
<mccb.cpcb@nic.in>, Ms Leena Nandan <secy-
moef@nic.in>, Raghvendra Kumar Singh
<ps1.cm@mp.gov.in>, bamra gulsan
<bamra.gulsan@mp.gov.in>, dm satna
<dmsatna@nic.in>, Public Grievance <publicgrievance-
ngt@gov.in>, Chairman CPCB <ccb.cpcb@nic.in>

Respected Sir,

As per Honorable NGT,CZ order to conduct joint inspection of CBWTF of Indo water management and pollution control corporation, satna on dated 29.04.2024 for the serious violation of BMW rule-16 by this facility of storing Hazardous medical waste for months which have to disposed off in 48 hours, Our representative was also there.

We observed and raised some points before officers present there, but no basic documents were evaluated as this plant is running without environment clearance, this plant was closed for one year(12-07-2021 to11-07-2022) for violating BMW Rules, but He had managed to get CTO without following SOP dated 07.07.2021 issued by the ministry for identification and handling of violation cases under EIA notification 2006.

We only inspected waste areas and there was no Incident Panchnama but officers had taken our sign on one page which contained only the name of participants, there was a huge quantity of untreated waste stored, we were restricted to take photos during inspection.

I have attached a PDF file for your reference which contains images of untreated waste storage by this facility for the months , Director of this plant was well aware of this inspection so he tried very hard to misguide the team he just covered the untreated waste with a plastic sheet and replaced waste polythene to new one, and some whitewash of storage area just before the inspection ,These images were taken just before and after the inspection.

Regards

Rajeev Nayan Tripathi
07000091663

 **CBWTF SATNA Waste OA 0652024cz.pdf**
2 MB

Biomedical Waste Storage for the months against the BMW rule-16 by Indo water management and pollution control corporation, Satna

All the images are original and with GPS coordinates

1. 1 February 2024 – page no. 2-4 (**OA.065/2024 (CZ) registered** on the basis of these photos)
2. 24 April 2024 -page no. 5-7 (Just **before** Joint Inspection of this plant(29.04.2024) by the order of Honourable NGT,CZ
3. 05 may 2024 –page no. 8-11 (just **after** the joint inspection)



 **GPS Map**
Camera Lite

GV75+G7W, Barkhera Bais, Pateri, Madhya Pradesh 485001, India

Latitude
24.51386929°

Longitude
80.85831755°

Local 11:45:16 PM
GMT 06:15:16 PM

Altitude 299 meters
Thursday, 01.02.2024



GV75+G7W, Barkhera Bais, Pateri, Madhya Pradesh 485001, India

Latitude

24.51385458°

Local 11:45:33 PM


GMT 06:15:33 PM

Longitude

80.85832393°

Altitude 299 meters

Thursday, 01.02.2024







GV75+G7W, Barkhera Bais, Pateri, Madhya Pradesh 485001, India

Latitude
24.51383189°

Local 09:44:39 PM
GMT 04:14:39 PM

Longitude
80.85833437°

Altitude 299 meters
Wednesday, 24.04.2024





GV75+G7W, Barkhera Bais, Pateri, Madhya Pradesh 485001, India

Latitude
24.51383758°

Longitude
80.85834696°

Local 11:01:17 PM
GMT 05:31:17 PM

Altitude 299 meters
Thursday, 02.05.2024





GV75+G7W, Barkhera Bais, Pateri, Madhya Pradesh 485001, India

Latitude
24.51375418°

Longitude
80.85832427°

Local 10:59:43 PM
GMT 05:29:43 PM

Altitude 299 meters
Thursday, 02.05.2024

