

**BEFORE THE HON'BLE NATIONAL GREEN TRIBUNAL,
SOUTHERN ZONE AT CHENNAI**

O. A. No. 22 of 2025

IN THE MATTER OF

Vadthyavath Munya and others

... Applicants

AND

The District Collector and
Others


... Respondents

REPORT OF THE IRRIGATION DEPARTMENT - R2

S.No.	Date	Description	Pg.No.
1	19.03.2026	Report of the 2 nd Respondent - The Irrigation Department	1
2	27.03.2025	ANNEXURE - I Joint Inspection Report	2
3	11.06.2020	ANNEXURE - II Amendment to Additional Guidelines for Processing Mining Projects by the SEIA & SEAC, Telagana	3
4	-	ANNEXURE - III New Record of Rights with translated copy	4
5	-	ANNEXURE - IV Cadastral and other Maps	6

Place: Chennai


Date: 19.03.2026



H. YASMEEN ALI

Counsel for the 2nd Respondent

1. As per ground inspection the Tank Thirupathi Cheruvu having Geo Id: 786110167258 and UID: 70831900601401.
2. Accordingly during joint inspection with Irrigation and Revenue Department officers concern, Lease area Demarcated with respect to the tank.
3. The tank Situated in Survey number 69, the offset distance of the quarry lease area is measured and marked on the location sketch map as per the Geo coordinates.
4. The Location sketch duly superimposed on village map.
5. As per site inspection, it is observed that the tank fed by runoff water from the higher contours through the feeder channel into the tank and surplus weir is also existing.
6. As per village map the Pedda cheruvu is situated in survey number 69, in new Record of Rights(ROR) of chedurvally village the tank extent of 34Ac-12Guntas mentioned as shikam Talab.
7. The tank area which is demarcated in the village map double line in Chedurvally (v), Veldanda (m), Nagarkurnool (dist). The feeder channel which is coming from the upstream catchment area which is clearly demarcated in the village map.
8. Runoff water from upstream catchment area is being feed to tank by feeder channel.
9. During the flow, the tank surplus over the existing weir, the head of water over the weir is temporarily causes afflux on the rear side of the water contours.


Executive Engineer,
Irrigation Division No.6,
Kalwakurthy.

2/10
12/03

11/10
11/03

Date of Inspection: 27.03.2025


Sub: I & CAD – Dept – Joint Inspection of Thirupathi Cheruvu (Pedda Cheruvu as per village map) situated in Chedurvally (Vg), Veldanda (M), Nagarkurnool Dist –Regarding NGT application No.22 of 2025(S2)- Report submitted-Reg.

- Ref: 1. Collectorate – Nagarkurnool vide Lr No. D1/355/2025, Dt:12.03.2025.
2. Notice Received from the Registrar, National Green Tribunal Sitting at Chennai, Date:24.02.2025 Received on 03.03.2025.
3. F.No.4/TSPCB/EC/SEIAA/General/2015, Dt:11.06.2020.
4. Lr.No. DEE/ISD4/KLKY/337, Dt:20.03.2025.


With reference to the subject cited above, we have jointly inspected the site on dt: 27.03.2025 situated at Chedurvally village, Veldanda Mandal, Nagarkurnool District.

During the inspection, the following observations were made:


1. As per ground inspection the Tank Thirupathi cheruvu having Geo Id: 786110167258 and UID: 70831900601401.
2. Accordingly during joint inspection, Lease area Demarcated with respect to the tank.
3. The Tank Situated in Survey number 69, the offset distance of the quarry lease area is measured and marked on the location sketch map is enclosed (Map-1).
4. The Location sketch duly superimposed on village map is also enclosed (Map-2).
5. After conducting the field survey it is seen that the tank fed by water from the higher contours through the feeder channel into the tank and surplus weir is also existing.
6. As per village map the Peddacheruvu is situated in survey number 69, in new Record of Rights(ROR) of chedurvally village the tank extent of 34Ac-12Guntas mentioned as shikam Talab.



Assistant Executive Engineer
Irrigation Section, Veldanda



Mandal Surveyor,
Veldanda



Deputy Executive Engineer,
Irrg Sub-Division-4, Kalwakurthy



Tahsildar,
Veldanda



State Level Environment Impact Assessment Authority (SEIAA)

**Telangana State
Government of India**

**Ministry of Environment, Forests & Climate Change
A-3, Industrial Estate, Sanathnagar, Hyderabad- 500 018.**

F.No.4/TSPCB/EC/SEIAA/General/2015-

Dt:11.06.2020.

**AMENDMENT TO ADDITIONAL GUIDELINES FOR PROCESSING
MINING PROJECTS BY THE SEIAA & SEAC, TELANGANA**

During the meeting held on 11.06.2020, after due deliberations the following amendments to the additional guidelines are decided for considering mining projects by SEIAA, Telangana:

- The minimum distance (aerial distance - as crow flies) from the boundary of mine lease area should be as follows:
- Nearest human habitation : 200 mts.
 - Nearest water body : 50 mts.
 - Reserve Forest : 50 mts.

[Signature]
11/6/2020
MEMBER
SEAC, TS.

[Signature]
11/6/2020
MEMBER
SEAC, TS.

[Signature]
CHAIRMAN
SEAC, TS.

[Signature]
MEMBER SECRETARY
SEIAA, TS. 11.06.2020.

[Signature]
MEMBER
SEIAA, TS.

[Signature]
15/6/2020
CHAIRMAN
SEIAA, TS.

Chedurvally Village Pahani Details Report generated as on 31/12/25

S.No	Passbook No	Khata No	Pattadar Name	Father's / Husband's Name	Aadhaar no / CIN No / Passport no	Gender	Caste Category	Survey no / Sub-division no	Base Survey no	Land Type (Agriculture / Notional / Non-Agriculture)	Total Extent	Land Nature	Land Classification	Land Enjoyment	Mutation reason	Digital Signed	Signed by	Signed date	Non ds reason	
3579		20000101	Government Lands	Government Lands				69	69	Agriculture	34.1200	G Land / Government Land / Government	G Land/ Government land/ Sarkari		Pattadar					

[Signature]
NAIB TAHSILDAR
VELDANDA MANDAL

1వ 5వ మూనా
(2,3 వ మూలక పాఠశాల)
సామూహిక రికార్డు నిమూనా

గ్రామం - వెంకటపల్లె

మహిళా శిక్షణ కేంద్రం

తరగతి


మంథలం పేరు

శిక్షణా గాఢీ నమూనా

1	2	3	4	5	6	7	యొదానీలు, అక్షరాల వర్ణ వివరాలు							14
							8	9	10	11	12	13		
56	3-00 1-00					జి క్యూల రాము తమ్మ	రాము తమ్మ	1-00						
	1-00					అలవేల ఎం. దాకయ్య	అలవేల	1-00						
	1-00					వెలియ ఎం. కృష్ణయ్య జి.కె.ల శంకరయ్య/కె.కె.ల	ఫణియ శంకరయ్య	1-00 3-00						
69	34-12					ప్రకాశ్ ఆలక్	ప్రకాశ్ ఆలక్	34-12						
70	15-23		9-27			తరుళ్ల సోమయ్య 90 రామయ్య	సోమయ్య	3-00						
						పుష్పయ్య	పుష్పయ్య	12-23						
						పాపయ్య దాదీరు	పాపయ్య దాదీరు 90లక్ష్మణ							
71	2-29		2-35			కొక్క వాల్మీకి వర్మ } 40 రెడియా సూర్య } సోమయాజీ లక్ష్మణన్ }	వాల్మీకి వర్మ } రెడియా సూర్య } సోమయాజీ లక్ష్మణన్ }	2-29						
						పాపయ్య పాపయ్య	పాపయ్య	2-29						

తుర్క ప్రతి
నాయకుల తహశీల్దార్
కొండ మండలం

6
LOCATION SKETCH SY. NO. 76. OF CHEDURVALLI VILLAGE
VELDANDA MANDAL, NAGAR, KURNOOL DIST.



Seenu
Mandal Surveyor
VELDANDA.

జిల్లా
ఆఫ్ వేల్దాండా

మాజీ వ్యవస్థాపక కమిషనరు.

Dy. Executive Engineer
Irrigation Sub Division-4,
Kalwakurthy.

Attested
TAHSILDAR
VELDANDA MANDAL.

గి.డి.కా. కార్య.

LOCATION SKETCH SY. NO. 76. OF CHEDURVALLI VILLAGE VELDANDA MANDAL, NAGAR KURNOOL DIST.



INDEX


EXISTING BUND	*****
FTL LIMIT LINE	=====
BUFFER ZONE 30 M	=====
APPLICANTS LAND	=====
SY. NO. LINE	=====

GEO COORDINATES FOR APPLICANT BOUNDARY

POINTS	LATITUDE (N)	LONGITUDE (E)
A	16°43'34.0165"N	78°36'25.8292"E
B	16°43'40.7065"N	78°36'25.5540"E
C	16°43'40.4283"N	78°36'30.8536"E
D	16°43'35.5801"N	78°36'31.6300"E
E	16°43'31.2722"N	78°36'30.9804"E

GEO COORDINATES FOR SY NO. 69 BOUNDARY

POINTS	LATITUDE (N)	LONGITUDE (E)
S1	16°43'20.49"N	78°36'39.12"E
S2	16°43'29.49"N	78°36'32.46"E
S3	16°43'40.62"N	78°36'37.47"E
S4	16°43'39.84"N	78°36'42.90"E
S5	16°43'37.01"N	78°36'45.16"E
S6	16°43'36.64"N	78°36'47.88"E




Seenu
Mandal Surveyor
VELDANDA

Jesudh
AEE Veldanda

|| Attested ||

[Signature]
TAHSILDAR
VELDANDA MANDAL

C. neseel
Dy. Executive Engineer
Irrigation Sub Division-4,
Kalwakurthy.



100 m
300 ft



Seena

**Mandal Surveyor
VELDANDA**

High Resolution Data(1m) -21FEB2018

Lat: 16.73 N | Lon: 78.61 E



Jeeva
AEE Veldanda

|| Attested ||

[Signature]

**TAHSILDAR
VELDANDA MANDAL**

[Signature]

**Dy.Executive Engineer
Irrigation Sub Division-4,
Kalwakurthy.**

LOCATION SKETCH SY. NO. 76 OF CHEDURVALLI VILLAGE,
VELDANDA MANDAL, NAGAR KURNOOL DIST.



GEO CORDINATES FOR APPLICANT BOUNDARY

POINTS	LATITUDE (N)	LONGITUDE (E)
A	16°43'34.0165"N	78°36'25.8292"E
B	16°43'40.7065"N	78°36'25.5540"E
C	16°43'40.4283"N	78°36'30.8536"E
D	16°43'35.5801"N	78°36'31.6300"E
E	16°43'31.2722"N	78°36'30.9804"E

GEO CORDINATES FOR SY. NO. 69 BOUNDARY

POINTS	LATITUDE (N)	LONGITUDE (E)
S1	16°43'20.49"N	78°36'39.12"E
S2	16°43'29.49"N	78°36'32.46"E
S3	16°43'40.62"N	78°36'37.47"E
S4	16°43'39.84"N	78°36'42.90"E
S5	16°43'37.01"N	78°36'45.16"E
S6	16°43'36.64"N	78°36'47.88"E

Jeyaraj
A.E. Veldanda

Mandal Surveyor
Sri Jayaraj

S. Srinivas
Dy. Executive Engineer
Irrigation Sub Division-4,
Kalwakurthy.

|| Attested ||
[Signature]
TAHSILDAR
VELDANDA MANDAL