

**BEFORE THE HON'BLE NATIONAL GREEN TRIBUNAL,
PRINCIPAL BENCH, NEW DELHI**

Original Application No. 533/2022

In the matter of:

Ajay Kumar

...Applicant

Versus

Govt. of NCT of Delhi

...Respondents

NDOH:- 23.12.2023

INDEX

S. No.	Contents	Page No.
1	Action Taken Report in compliance to order dated 09.05.2022.	1-3
2	<u>Annexure-1(Colly)</u> Copy of the joint inspection report dated 09.11.2022 along with photographs.	4-15

Filed by:

New Delhi:

Dated: 7th.12.2022



Delhi Pollution Control Committee

**BEFORE THE HON'BLE NATIONAL GREEN TRIBUNAL,
PRINCIPAL BENCH, NEW DELHI**
Original Application No. 533/2022

In the matter of:

Ajay KumarApplicant

Versus

Govt. of NCT of Delhi ...Respondents

**ACTION TAKEN REPORT ON BEHALF OF DELHI POLLUTON
CONTROL COMMITTEE IN COMPLAINCE TO THE ORDER
DATED 02.09.2022.**

IT IS MOST RESPECTFULLY SHOWETH:

1. That this Hon'ble Tribunal took up the above referred matter on 02.09.2022 and was pleased to direct the DPCC and Deputy Commissioner (North West), Delhito take action about 4 factories making thin plastic carry bags from the basement to top at DSIIDC, Bawana, Delhi. In the original application received from this Hon`ble Tribunal addresses of the unit is mentioned as N-132, N-134,N-135 and N-136, sector-1, Bawana Industrial Area, Delhi-110039.
2. That the area falls under the jurisdiction of Deputy Commissioner (North), hence in place of Deputy Commissioner (North West), Deputy Commissioner (North)officials were called.
3. That a joint inspection of the site was carried out on 09.11.2022by the representative of DPCC official and Revenue Department official. During the inspection it was observed that:

1. M/s HK Industries N-132 Sec-1, DSIIDC Bawana Industrial Area.


- Unit found in operation and engaged in activity of the Manufacturing of carry bags and plastic packaging material.
- Thickness of Carry bag which was found being manufacturing during inspection is 84 microns and of packaging material is 105 microns.
- As per record unit has obtained registration under PWM Rules, 2016.
- Unit is running with valid CTO (13.09.2032) for the activity of “manufacturing of carry bags and plastic packing material”
- No Violation Observed with respect to consent and PWM Rules.

2. **M/s HK Industries N-134, Sec-1, DSIIDC Bawana Industrial Area.**

- Unit found in operation and engaged in the activity of Plastic Packaging material.
- Thickness of Plastic packing material which was found being manufacturing during inspection is 79 microns.
- As per record unit has obtained registration under PWM Rules, 2016.
- Unit is running with valid CTO (29.07.2029) for the activity of “manufacturing of plastic packing material”
- No Violation Observed with respect to consent and PWM Rules.

3. **M/s HK Industries N-135 ,Sec-1, DSIIDC Bawana Industrial Area.**

- Unit found in operation and engaged in the activity of Plastic Packaging material.
- Thickness of Plastic packing material which was found being manufacturing during inspection is 86 microns.
- As per record unit has obtained registration under PWM Rules, 2016.
- Unit is running with valid CTO (29.07.2029) for the activity of “manufacturing of plastic packing material”
- No Violation Observed with respect to consent and PWM Rules.





4. **M/s HK Industries N-136, Sec-1, DSIIDC Bawana Industrial Area.**

- Unit found in operation and engaged in the activity of Reprocessing of plastic waste/ PVC without Washing.
- Channelization with hood and duct provided for process emission.
- As observed unit is using rejects of Plastic bags and other packaging material/ scrap for manufacturing of plastic Granules.
- Unit has applied for CTO on 07.10.2022 for the activity of “Reprocessing of waste Plastic from plastic scrap without washing”
- No Violation Observed with respect to consent and PWM Rules.

Copy of the joint inspection report dated 09.11.2022 alongwith photographs are enclosed herewith as **ANNEXURE-1 (Colly)**.

4. The present status report may kindly be taken on record.


(Mohd. Arif)
Sr. Environmental Engineer



DELHI POLLUTION CONTROL COMMITTEE
 DEPARTMENT OF ENVIRONMENT (GOVT. OF NCT OF DELHI)
 4th & 5th FLOOR ISBT BUILDING KASHMERE GATE DELHI-6
 visit us at : <http://dpcc.delhigovt.nic.in>

Inspection Report

Annexure-1 (Colly) 4

1. Name & Address of the Unit : M/s H.K. Industries
 N-132 Sector-1 DSIIDC
 Barwana Industrial Area
 Delhi -110039
2. Owner/ Partner's Name & Contact Details(Phone & E-mail) : Sh. Vinay Aggarwal
 9899189884
3. Date of Inspection : 09/11/2022
4. Name & Designation of the Persons contacted at the industry : Sh. Vinay Aggarwal
5. Kind of Industry : Manufacturing of Carry bags and Plastic Packing Material.
6. Product & Capacity : As per demand
7. Main Raw Materials : LLDPE Plastic Granules (Fagsh)
8. Water Polluting : Yes/No ETP Installed : Yes/No/NA
9. Air Pollution : Yes/No ECS Installed : Yes/No/NA
10. Details of Stack Height (Furnace/Boilers/Others) : (Above G.L.)..... (Above R.L.).....
11. Type of Fuel Used : Electricity
12. A. Source of Water Supply : DJB/NDMC/DSIIDC/Borewell/Tankers/Others
- B. Effluent Discharge : (a) Domestic/ Trade Effluent
 (b) Unit connected to Conveyance System: Yes/No
 (c) Discharging into... Sewer
13. Status of Consent {If Any} : CTO (Green) upto 13/09/2032
14. D.G. Set(s) {if Any} : No. Capacity.....KVA. Acoustic: Yes/No
 Stack Height.....(Above G.L.).....(Above RL)
15. Plot Area : ≈ 150 sq.m
16. Labour : 5
17. Machinery : Tubing Machine - 07
 Cutting Machine - 04

- 18. Detail of Power Connection : 60026683437
- 19. Whether Unit found in Operation : ✓ Yes/No
- 20. Status of Registration under Plastic Waste Management Rules, 2016 : As per Record
- 21. Whether Generating Hazardous Waste : Yes/No ✓
- 22. Details about Hazardous Waste :
 - (a) Status of Authorization {if any} :
 - (b) Display Board Provided : Yes/No
 - (c) Whether Hazardous Waste is stored in Leak proof container : Yes/No
 - (d) Whether container marked with specified label : Yes/No
 - (e) Whether container stored kept in an isolated area : Yes/No
 - (f) Whether Hazardous Waste is being stored on-pucca floor & in covered area : Yes/No
 - (g) Whether date on which storage began indicated on each container : Yes/No
 - (h) Whether daily record of Hazardous Waste maintained in Form-3 : Yes/No
 - (i) Category of Hazardous Waste as per the Schedules I,II and III of these rules :
 - (j) Authorized mode of disposal or recycling or utilization or co-processing etc. :
 - (k) Quantity (Ton/Annum) :

N/A

Remarks (if Any)

- Unit found in operation and engaged in the activity of the manufacturing of carry bag and plastic packing material.
- Thickness of carry bag which was found being manufactured during inspection is 84 microns and of packaging material is 105 microns.
- No violation observed w.r.t Consent & PWM rules

Manish Aggarwal
9/11/22


S/m-9
9/11/2022
(Manish K Gula)
Naib Tehsildar

Signatures, Name & Designation of inspecting officials.
09/11/2022


6



GPS Map Camera




New Delhi, Delhi, India
151, Pocket N, Sector 1, Bawana, New Delhi,
Delhi 110039, India
Lat 28.786192°
Long 77.046602°
09/11/22 11:55 AM GMT +05:30



GPS Map Camera




New Delhi, Delhi, India
143, DSIIIC Industrial Area, Pocket N, Sector
1, Bawana, New Delhi, Delhi 110039, India
Lat 28.786125°
Long 77.046558°
09/11/22 11:42 AM GMT +05:30



GPS Map Camera



New Delhi, Delhi, India
143, DSIIIC Industrial Area, Pocket N, Sector 1,
Bawana, New Delhi, Delhi 110039, India
Lat 28.786125°
Long 77.046558°
09/11/22 11:42 AM GMT +05:30




GPS Map Camera



New Delhi, Delhi, India
142, Pocket N, Sector 1, Bawana, New Delhi,
Delhi 110039, India
Lat 28.786069°
Long 77.046527°
09/11/22 11:43 AM GMT +05:30

Photographs of M/s HK Industries N-132 Sector 1 DSIIIC Bawana Industrial Area Delhi – 110039 Dated 09.11.2022



DELHI POLLUTION CONTROL COMMITTEE
 DEPARTMENT OF ENVIRONMENT (GOVT. OF NCT OF DELHI)
 4th & 5th FLOOR ISBT BUILDING KASHMERE GATE DELHI-6
 visit us at : <http://dpec.delhigovt.nic.in>

7

Inspection Report

1. Name & Address of the Unit : M/s H.K. Industries
 N-134 Sector-1 DSIIDC
 Bawana Industrial
 Area Delhi
2. Owner/ Partner's Name & Contact Details(Phone & E-mail) : Sh. Vinay Aggarwal (owner)
3. Date of Inspection : 09/11/2022
4. Name & Designation of the Persons contacted at the industry : Sh. Vinay Aggarwal
5. Kind of Industry : Manufacturing of Plastic
 Packing material
6. Product & Capacity : As per demand
7. Main Raw Materials : LLDPE Plastic Granules
8. Water Polluting : Yes/No ETP Installed : Yes/No / NA
9. Air Pollution : Yes/No ECS Installed : Yes/No / NA
10. Details of Stack Height (Furnace/Boilers/Others) : (Above G.L.)..... (Above R.L.).....
11. Type of Fuel Used : Electricity
12. A. Source of Water Supply : DJB/NDMC/DSIIDC/Borewell/Tankers/Others
- B. Effluent Discharge : (a) Domestic/ Trade Effluent
 (b) Unit connected to Conveyance System: Yes/No
 (c) Discharging into: Sewer
13. Status of Consent {If Any} : CTO (Green) upto 29/07/2029
14. D.G. Set(s) {if Any} : No...Capacity.....KVA. Acoustic: Yes/No
 Stack Height.....(Above G.L.).....(Above RL)
15. Plot Area : $\approx 1500 \text{ sq. m}$
16. Labour : 6
17. Machinery : Tubing Machine - 01
 Punching Machine - 02
 Cutting Machine - 03

8

- 18. Detail of Power Connection : As per Record
- 19. Whether Unit found in Operation : Yes/No
- 20. Status of Registration under Plastic Waste Management Rules, 2016 : As per Record
- 21. Whether Generating Hazardous Waste : Yes/ No
- 22. Details about Hazardous Waste :
 - (a) Status of Authorization {if any} :
 - (b) Display Board Provided : Yes/No
 - (c) Whether Hazardous Waste is stored in Leak proof container : Yes/No
 - (d) Whether container marked with specified label : Yes/No
 - (e) Whether container stored kept in an isolated area : Yes/No
 - (f) Whether Hazardous Waste is being stored on pucca floor & in covered area : Yes/No
 - (g) Whether date on which storage began indicated on each container : Yes/No
 - (h) Whether daily record of Hazardous Waste maintained in Form-3 : Yes/No
 - (i) Category of Hazardous Waste as per the Schedules I, II and III of these rules :
 - (j) Authorized mode of disposal or recycling or utilization or co-processing etc. :
 - (k) Quantity (Ton/Annum) :

NIA

Remarks (if Any)

- Unit found in operation and engaged in the activity of Plastic Packing material.
- Thickness of Plastic packing material which was found being manufactured during inspection is 79 microns.
- No violation observed w.r.t Consent-2 PWM rules


S.M. E.
(Manish Kumar Gubie)
Naib Tehsildar

Vinay Aggarwal
9/11/22

Ajay Malik
Ajay Malik
JEE
Signatures, Name & Designation of inspecting officials. 09/11/2022

9


N - 134
SECTOR -
DSI IDC
BAWANA



GPS Map Camera



New Delhi, Delhi, India
143, DSIIDC Industrial Area, Pocket N, Sector
1, Bawana, New Delhi, Delhi 110039, India
Lat 28.786173°
Long 77.046592°
09/11/22 12:05 PM GMT +05:30




GPS Map Camera



New Delhi, Delhi, India
140, Pocket N, Sector 1, Bawana, New
Delhi, Delhi 110039, India
Lat 28.785916°
Long 77.046674°
09/11/22 12:06 PM GMT +05:30

Photographs of M/s HK Industries N-134 Sector 1 DSIIDC Bawana Industrial Area Delhi – 110039 Dated 09.11.2022



DELHI POLLUTION CONTROL COMMITTEE
 DEPARTMENT OF ENVIRONMENT (GOVT. OF NCT OF DELHI)
 4th & 5th FLOOR ISBT BUILDING KASHMERE GATE DELHI-6
 visit us at : <http://dpcc.delhigovt.nic.in>

10

Inspection Report

1. Name & Address of the Unit : M/s H.K Industries
 N-135 Sector -1 DS II DC
 Bawana Industrial
 Area Delhi - 110039
2. Owner/ Partner's Name & Contact Details(Phone & E-mail) : Sh. Vinay Aggarwal (owner)
3. Date of Inspection : 09/11/2022
4. Name & Designation of the Persons contacted at the industry : Sh. Vinay Aggarwal
5. Kind of Industry : Manufacturing of Plastic Packing material
6. Product & Capacity : As per demand
7. Main Raw Materials : LLDPE Plastic Granules
8. Water Polluting : Yes/No No ETP Installed : Yes/No NA
9. Air Pollution : Yes/No No ECS Installed : Yes/No NA
10. Details of Stack Height (Furnace/Boilers/Others) : (Above G.L.)..... (Above R.L.).....
11. Type of Fuel Used : Electricity
12. A. Source of Water Supply : DJB/NDMC/DSIIDC/Borewell/Tankers/Others
- B. Effluent Discharge : (a) Domestic/ Trade Effluent
 (b) Unit connected to Conveyance System: Yes/No
 (c) Discharging into Sewer
13. Status of Consent {If Any} : CTO (Green) upto 29/07/2029
14. D.G. Set(s) {if Any} : No.....Capacity.....KVA. Acoustic: Yes/No
 Stack Height.....(Above G.L.).....(Above RL)
15. Plot Area : ≈ 150 sqm
16. Labour : 5
17. Machinery : Tubing Machine - 05

- 18. Detail of Power Connection : As per Record
- 19. Whether Unit found in Operation : Yes/No
- 20. Status of Registration under Plastic Waste Management Rules, 2016 : As per Record
- 21. Whether Generating Hazardous Waste : Yes/No
- 22. Details about Hazardous Waste :
 - (a) Status of Authorization {if any} :
 - (b) Display Board Provided : Yes/No
 - (c) Whether Hazardous Waste is stored in Leak proof container : Yes/No
 - (d) Whether container marked with specified label : Yes/No
 - (e) Whether container stored kept in an isolated area : Yes/No
 - (f) Whether Hazardous Waste is being stored on pucca floor & in covered area : Yes/No
 - (g) Whether date on which storage began indicated on each container : Yes/No
 - (h) Whether daily record of Hazardous Waste maintained in Form-3 : Yes/No
 - (i) Category of Hazardous Waste as per the Schedules I,II and III of these rules :
 - (j) Authorized mode of disposal or recycling or utilization or co-processing etc. :
 - (k) Quantity (Ton/Annum) :

N/A

Remarks (if Any)

- Unit found in operation and engaged in the activity of Plastic Packing material.
- Thickness of plastic packing material which was found being manufactured during inspection is 86 microns.
- No violation observed wrt Consent and PWM rules.

9/11/22

(Manish Kumar Gulie)
Naib Tehsildar


Manish Aggarwal
9/11/22

Manish
Manish
JEE

Signatures, Name & Designation of inspecting officials.


09/11/2022

12



New Delhi, Delhi, India
 136, Pocket N, Sector 1, Bawana, New
 Delhi, Delhi 110039, India
 Lat 28.785715°
 Long 77.04663°
 09/11/22 12:09 PM GMT +05:30

Google



New Delhi, Delhi, India
 136, Pocket N, Sector 1, Bawana, New
 Delhi, Delhi 110039, India
 Lat 28.785767°
 Long 77.046669°
 09/11/22 12:06 PM GMT +05:30

Google

Photographs of M/s HK Industries N-135 Sector 1 DSIIDC Bawana Industrial Area Delhi – 110039 Dated 09.11.2022

Inspection Report

(13)

1. Name & Address of the Unit : M/s H.K Industries
 N-136 Sector-1 DSIIDC
 Bawana Industrial Area
 Delhi-110039
2. Owner/ Partner's Name & Contact Details(Phone & E-mail) : Sh. Vinay Aggarwal (owner)
3. Date of Inspection : 09/11/2022
4. Name & Designation of the Persons contacted at the industry : Sh. Vinay Aggarwal
5. Kind of Industry : Reprocessing of Waste Plastic/PVC without washing
6. Product & Capacity : As per demand
7. Main Raw Materials : Plastic Scrap
8. Water Polluting : Yes/No No ETP Installed : Yes/No/NA NA
9. Air Pollution : Yes/No Yes ECS Installed : Yes/No Yes
10. Details of Stack Height (Furnace/Boilers/Others) : (Above G.L.)..... (Above R.L.) Adequate
11. Type of Fuel Used : Electricity
12. A. Source of Water Supply : DJB/NDMC/DSIIDC/Borewell/Tankers/Others
- B. Effluent Discharge : (a) Domestic/ Trade Effluent Domestic
 (b) Unit connected to Conveyance System: Yes/No Yes
 (c) Discharging into Sewer
13. Status of Consent {If Any} : CTO (Orange) Applied - 07/10/2022
14. D.G. Set(s) {if Any} : No. Capacity.....KVA. Acoustic: Yes/No
 Stack Height.....(Above G.L.).....(Above RL)
15. Plot Area : = 150 sqm
16. Labour : 7
17. Machinery : Extruder - 01
 Cutter - 01

- 18. Detail of Power Connection : As per Record
- 19. Whether Unit found in Operation : Yes/No
- 20. Status of Registration under Plastic Waste Management Rules, 2016 : As per Record
- 21. Whether Generating Hazardous Waste : Yes/No
- 22. Details about Hazardous Waste :
 - (a) Status of Authorization {if any} :
 - (b) Display Board Provided : Yes/No
 - (c) Whether Hazardous Waste is stored in Leak proof container : Yes/No
 - (d) Whether container marked with specified label : Yes/No
 - (e) Whether container stored kept in an isolated area : Yes/No
 - (f) Whether Hazardous Waste is being stored on pucca floor & in covered area : Yes/No
 - (g) Whether date on which storage began indicated on each container : Yes/No
 - (h) Whether daily record of Hazardous Waste maintained in Form-3 : Yes/No
 - (i) Category of Hazardous Waste as per the Schedules I, II and III of these rules :
 - (j) Authorized mode of disposal or recycling or utilization or co-processing etc. :
 - (k) Quantity (Ton/Annum) :

N/A





Remarks (if Any)

- Unit found in operation and engaged in the activity of Reprocessing of Plastic Waste / PVC without Washing.
- Channelization with hood and duct provided for process emission.
- As observed unit is using rejects of Plastic bags and other packaging material as raw material / Scrap for manufacturing of Plastic Granules.
- No violation observed w/o Consent of PWM rules

Ministry Approval

SPM-4
9/11/2022
(Manish Kumar Gula)
Naib Tehsildar

Manish Kumar Gula
Signatures, Name & Designation of inspecting officials. 09/11/2022



Photographs of M/s HK Industries N-136 Sector 1 DSIIDC Bawana Industrial Area Delhi – 110039 Dated 09.11.2022