

**BEFORE THE HON'BLE NATIONAL GREEN TRIBUNAL,  
PRINCIPAL BENCH, NEW DELHI**

Original Application No. 581/2023

In the matter of:

**Tribunal on its Motion**

**INDEX**

S. No.	Contents	Page No.
1	Action taken report on behalf of Delhi Pollution Control Committee (DPCC) with respect to the order dated 07.11.2023.	1-2
2	<u>Annexure-1</u> (70/17) Copy of the inspection report dated 02.02.2024 alongwith geotagged photographs.	3-21
3	<u>Annexure-2</u> Copy of the letter dated 07.03.2024 addressed to MCD and DDA.	22

Filed by:

New Delhi:

Dated: 12.03.2023



Delhi Pollution Control Committee

**BEFORE THE HON'BLE NATIONAL GREEN TRIBUNAL,  
PRINCIPAL BENCH, NEW DELHI**

Original Application No. 581/2023

In the matter of:

**Tribunal on its Motion**

**ACTION TAKEN REPORT ON BEHALF OF DELHI POLLUTION  
CONTROL COMMITTEE IN COMPLIANCE TO THE ORDER  
DATED 07.11.2023.**

IT IS MOST RESPECTFULLY SHOWETH:

1. That this Hon'ble Tribunal took up the above referred matter on 07.11.2023 on the basis of the letter dated 24.06.2023 raising the grievance that in Khasra No. 1706, Village Aya Nagar, New Delhi, there is a Johar (pond) which is being filled with garbage, dumping material and raw material and it is losing its identity as a pond. This Hon'ble Tribunal pleased to direct that site may be inspected by DPCC, ascertain the correct position and if required, take appropriate remediation action.
2. That, in compliance to the order, an inspection of the site was carried out on 02.02.2024 by the DPCC officials. During the inspection, it was observed that:
  - Plastic waste such as bottles and polythene were found floating in the pond. Garbage was also found dumped in the pond. It seems the local people who are living nearby the pond, are dumping their waste in the pond illegally.

*bu*

- There is a park which is maintained by MCD just adjacent to the pond wherein cow dungs and garbage were observed. The local enquiry revealed that some people washing their cows/cattle in the park and discharged all the waste water into the pond.
- The local enquiry informed that that there is no sewerage system in the locality. Also, it is observed that there is an open drain beside the pond from which the sewage is directly discharged into the pond.
- Lots of Garbage was also found dumped at the entrance of the park which may ultimately falls into the pond.
- There is no Malba, Construction and demolition waste was observed near the pond. Local people informed that around 1 year ago MCD had got the work done to maintain the park and got installed the railing surrounding the pond.

Copy of the inspection report alongwith photographs taken during the inspection on 02.02.2024 are enclosed herewith as **ANNEXURE-1(Colly)**.

3. That, in view of the observations of the inspection, DPCC has issued directions to MCD and DDA to look into the matter and direct the concerned officers to take further necessary action. Copy of the letter dated 07.03.2024 addressed to MCD and DDA is enclosed herewith as **ANNEXURE -2**.
4. The present action taken report may kindly be taken on record.




(B.M.S. Reddy)


Sr. Environmental Engineer

Inspection report in compliance of Hon'ble NGT order dated 07.11.2023 in original application No-581/2023.

DPCC officials visited the site mentioned in the order i.e. Johar(Pond) in Khasra No-1706, Village Aya Nagar, New Delhi on 02.02.2024. And following are the observations during the inspection:

1. Plastic waste such as bottles and polythene was found floating in the pond. Garbage was also found dumped in the pond. It seems the local people who are living neaby pond are dumping this waste in the pond illegally.
2. There is a park which is maintained by SDMC just adjacent to the pond wherein cow dungs and garbage were observed and the local enquiry revealed that some people washing their cows/cattle in the park and discharged all the waste water into the pond.
3. From the enquiry gathered from local people it is found that there is no sewerage system in the locality. Also it is observed that there is a open drain beside the pond from which the sewage is directly discharged into the pond.
4. Lots of Garbage was also found dumped at the entrance of the park which may ultimately falls into the pond as told by the locals living there.
5. There is no Malba, Constuction and demolition waste was observed near the pond. Local people informed that around 1 year ago SDMC had got the work done to maintain the park and got installed the railing surrounding the pond.

  
2.2.2024  
AMZAD KHAN(JEE,DPCC)

  
Abhishek Meena(Trainee, DPCC)



GPS Map  
Camera Lite


F4GJ+P9Q, Aya Nagar, New Delhi, Delhi 110047, India

Latitude  
28.476675°

Longitude  
77.13094°

Local 05:02:12 PM  
GMT 11:32:12 AM

Altitude 274 meters  
Friday, 02.02.2024



GPS Map  
Camera Lite

F4GJ+P9Q, Aya Nagar, New Delhi, Delhi 110047, India

Latitude  
28.476518333333335°

Longitude  
77.13107°

Local 05:03:16 PM  
GMT 11:33:16 AM

Altitude 272 meters  
Friday, 02.02.2024



GPS Map  
Camera Lite


F4GJ+P9Q, Aya Nagar, New Delhi, Delhi 110047, India

Latitude  
28.476675°

Longitude  
77.13094°

Local 05:02:29 PM  
GMT 11:32:29 AM

Altitude 274 meters  
Friday, 02.02.2024



GPS Map  
Camera Lite

F4GJ+P9Q, Aya Nagar, New Delhi, Delhi 110047, India

Latitude  
28.476513333333333°

Longitude  
77.13106833333333°

Local 05:03:21 PM  
GMT 11:33:21 AM

Altitude 272 meters  
Friday, 02.02.2024



 **GPS Map**  
**Camera Lite**

F4GJ+CGP, Baba Mohalla, Aya Nagar, New Delhi, Delhi 110047, India

Latitude  
28.47645°

Longitude  
77.13112166666666°

Local 05:03:37 PM  
GMT 11:33:37 AM

Altitude 272 meters  
Friday, 02.02.2024



GPS Map  
Camera Lite

F4GJ+CGP, Baba Mohalla, Aya Nagar, New Delhi, Delhi 110047, India

Latitude  
28.47642°

Longitude  
77.13110166666667°

Local 05:03:59 PM  
GMT 11:33:59 AM

Altitude 272 meters  
Friday, 02.02.2024



GPS Map  
Camera Lite


119, Baba Mohalla, Aya Nagar, New Delhi, Delhi 110047, India

Latitude  
28.475695000000005°

Longitude  
77.13068833333334°

Local 05:44:19 PM  
GMT 12:14:19 PM

Altitude 271 meters  
Friday, 02.02.2024



GPS Map  
Camera Lite

F4GJ+J4F, Aya Nagar, New Delhi, Delhi 110047, India

Latitude  
28.47656833333333°

Longitude  
77.13033°

Local 05:44:56 PM  
GMT 12:14:56 PM

Altitude 274 meters  
Friday, 02.02.2024



GPS Map  
Camera Lite


F4GJ+83W Gurjar Samrat Mihir Bhoj Kul Park Aya Nagar, Aya Nagar,  
New Delhi, Delhi 110047, India

Latitude  
28.47663°

Longitude  
77.13055166666666°

Local 05:45:24 PM  
GMT 12:15:24 PM

Altitude 274 meters  
Friday, 02.02.2024



GPS Map  
Camera Lite

F4GJ+P9Q, Aya Nagar, New Delhi, Delhi 110047, India

Latitude  
28.476743333333335°

Longitude  
77.130885°

Local 05:46:14 PM  
GMT 12:16:14 PM

Altitude 274 meters  
Friday, 02.02.2024



GPS Map  
Camera Lite

F4GJ+P9Q, Aya Nagar, New Delhi, Delhi 110047, India

Latitude  
28.476726666666664°

Longitude  
77.13089°

Local 05:46:18 PM  
GMT 12:16:18 PM

Altitude 274 meters  
Friday, 02.02.2024



GPS Map  
Camera Lite


F4GJ+P9Q, Aya Nagar, New Delhi, Delhi 110047, India

Latitude  
28.47670666666667°

Longitude  
77.13090166666666°

Local 05:46:28 PM  
GMT 12:16:28 PM

Altitude 274 meters  
Friday, 02.02.2024



GPS Map  
Camera Lite


F4GJ+CGP, Baba Mohalla, Aya Nagar, New Delhi, Delhi 110047, India

Latitude  
28.476441666666666°

Longitude  
77.13113166666668°

Local 05:47:35 PM  
GMT 12:17:35 PM

Altitude 272 meters  
Friday, 02.02.2024



GPS Map  
Camera Lite

119, Baba Mohalla, Aya Nagar, New Delhi, Delhi 110047, India

Latitude  
28.475638333333336°

Longitude  
77.130665°

Local 05:50:23 PM  
GMT 12:20:23 PM

Altitude 271 meters  
Friday, 02.02.2024



GPS Map  
Camera Lite

119, Baba Mohalla, Aya Nagar, New Delhi, Delhi 110047, India

Latitude  
28.475606666666668°

Longitude  
77.130546666666667°

Local 05:50:40 PM  
GMT 12:20:40 PM

Altitude 271 meters  
Friday, 02.02.2024



GPS Map  
Camera Lite

F4CM+Q5W, Adarsh Enclave, Aya Nagar, New Delhi, Delhi 110047, India

Latitude  
28.475620000000003°

Longitude  
77.13045666666667°

Local 05:51:04 PM  
GMT 12:21:04 PM

Altitude 271 meters  
Friday, 02.02.2024




Adarsh Enclave Mod, Sunday Market Rd, Aya Nagar, New Delhi, Delhi  
110047, India

Latitude  
28.475560000000005°

Longitude  
77.130023333333334°

Local 05:53:35 PM  
GMT 12:23:35 PM

Altitude 271 meters  
Friday, 02.02.2024



GPS Map  
Camera Lite


Adarsh Enclave Mod, Sunday Market Rd, Aya Nagar, New Delhi, Delhi  
110047, India

Latitude  
28.475560000000005°

Longitude  
77.13002333333334°

Local 05:53:40 PM  
GMT 12:23:40 PM

Altitude 271 meters  
Friday, 02.02.2024



**DELHI POLLUTION CONTROL COMMITTEE**  
**DEPARTMENT OF ENVIRONMENT**  
 (GOVT. OF NCT OF DELHI)  
 2<sup>nd</sup> FLOOR, C-BLOCK, VIKAS BHAWAN-II, UPPER  
 BELA ROAD, CIVIL LINES DELHI-54  
 ( visit us at website : <http://dpcc.delhigovt.nic.in/> )



DPCC/CMC-II(10)(10)(92)/Leg.08/ 92-94

Date: 09/03/2024.

To,

- 1, **The Commissioner,**  
Municipal Corporation of Delhi,  
4<sup>th</sup> Floor, Dr. S.P.M. Civic Centre,  
Minto Road,  
New Delhi-110002.
- 2, **The Vice-Chairman,**  
Delhi Development Authority,  
Vikas Sadan, INA,  
New Delhi - 110023.

*Annexure-2*

**Sub.: Hon'ble NGT order dated 07.11.2023 in OA No. 581/2023 "Tribunal on its motion" regarding garbage, dumping material and raw material in Khasra No. 1706, Village Aya Nagar, New Delhi, Johar (pond).**

Sir,

This has reference to the order dated 07.11.2023 passed by Hon'ble NGT in OA No. 581/2023 "Tribunal on its motion" regarding garbage, dumping material and raw material in Khasra No. 1706, Village Aya Nagar, New Delhi, Johar (pond). Consequent to the order passed by the Hon'ble Tribunal, an inspection of the site was conducted by the officials of DPCC on 02.02.2024 and the observations in this regard are as under:-

1. Plastic waste such as bottles and polythene were found floating in the pond. Garbage was also found dumped in the pond.
2. There is a park which is maintained by SDMC adjacent to the pond wherein dumps of cow dungs and garbage were observed and the local enquiry revealed that some people washing their cows/cattle in the park and discharged all the waste water into the pond.
3. From the enquiry gathered from local people it is found that there is no sewerage system in the locality. Also it is observed that there is an open drain beside the pond from which the sewage is directly discharged into the pond.
4. Lots of Garbage was also found dumped at the entrance of the park which may ultimately falls into the pond as per the information gathered during inspection.
5. There is no Malba, Construction and demolition waste was observed near the pond.

In view of the above observations, you are requested to look into the matter and direct the concerned officers to take further necessary action and provide the Action Taken Report within 10 days to enable this office to apprise the same before the Hon'ble NGT. Copy of the order of Hon'ble NGT is also enclosed herewith for your ready reference.

*BMS*

(Dr. BMS Reddy)  
SEE, CMC-II

Copy to:

Master File.