

7765

**BEFORE THE NATIONAL GREEN TRIBUNAL
PRINCIPAL BENCH NEW DELHI**

**OA NO. 667/2018 (MAHENDRA SINGH VERSUS STATE
OF HARYANA AND ORS.) WITH OA NO. 679/2018
(TEJPAL VERSUS STATE OF HARYANA AND ORS.),
IN OA NO. 599/2019 (BISHAMBER SINGH VERSUS
STATE OF HARYANA AND ORS.)**

The next date of hearing is fixed on dated 01.02.2024.

AS PER HON'BLE NGT ORDER DATED 23.11.2023

Date: - 30.01.2024

Place: - Mahendragarh (Haryana)

Hon'ble NGT passed the following directions in Order dated 23.11.2023 in OA No. 667/2018 (Mahendra Singh Versus State of Haryana and Ors.) with OA No. 679/2018 (Tejpal Versus State of Haryana and Ors.), in OA No. 599/2019 (Bishamber Singh Versus State of Haryana and Ors.): -

"9. Since, new stone crusher units have been impleaded today, therefore the Counsel for the HSPCB is directed to examine the compliance of newly impleaded stone crusher units in terms of the direction of the Tribunal contained in the previous order. He is also directed to examine the date of setting up of all the respondent crusher units, the date of closure, if any and the violation of environmental norms for the past period by the concerned units. Some of the applicants have taken the plea that though they had set up the unit but they never operated it. This plea of such applicant be also examined by the HSPCB on the basis of the available record and on the basis of the spot inspection. In view of this, Counsel for the HSPCB is directed to file further report disclosing the relevant details in the updated chart about each of the unit. Let the same be filed within a period of eight weeks by email at judicial-ngt@gov.in preferably in the form of searchable PDF/ OCR Support PDF and not in the form of Image PDF.

10. Since, a large number of IAs have been filed, therefore, we also direct the Counsel for the applicants to tabulate the information in the chart form in respect of each applicant they are representing and by giving details of the applicants, the date of setting up of the unit by the applicant, the position of CTE/CTO and also the compliance status along with the geo-coordinates of the units. Let the same be filed within four weeks.

11. We have also heard learned Counsel for all the applicants present today in respect of their other prayers in the IAs which are mainly relating to recall of the order dated 18.01.2023. Learned Counsel for the applicants have advanced following arguments in support of their plea to recall the order dated 18.01.2023:-

- i. The carrying capacity of the area concerned needs to be reexamined by the Tribunal.
- ii. The units have now developed green belt, therefore, their current compliance status needs consideration.
- iii. Some of the units had never started operation, therefore, they cannot be treated to be defaulter for the past period.
- iv. The units are complying with the environmental norms, therefore, they are not liable to pay EC.
- v. The calculation of interim compensation be done on the basis of the default period and not uniformly."

Updated Action Taken Report of District Mahendragarh in compliance of Hon'ble National Green Tribunal, Principal Bench, New Delhi order dated 23.11.2023 in the matter of OA No. 667/2018 with OA No. 679/2018 and in OA No. 599/2019.

The Action Taken Report in compliance with the above directions, passed by Hon'ble National Green Tribunal, New Delhi, is as under: -

1. In compliance of Order dated 20.09.2023 & 23.11.2023. Status of 133 Nos. stone crushing units located in District Mahendragarh are summarized as below:

A.	Units found Complying as per provision of notification dated 11.05.2016	80
B.	Units found non-complying as per provision of notification dated 11.05.2016	53
	(i). Recommended for closure action to Head Office.	02
	(ii). Units closed by Board & CTE/CTO revoked by Board	26
	(iii). Units found dismantled	11
	(iv). Closed of its own	14

2. The requisite updated information of 133 stone crushing units in tabular form regarding the date of setting up of all the respondent crusher units (CTE and First CTO granted details), inter-se-distance, latest CTO status with validity, status of compliance in respect of the pollution norms as per Notification 11.05.2016, operational status, the date of closure if any and the violation of all the environmental norms for the past period by concerned units, as per record/information available in the office is attached as **Annexure-1**.
3. An amount of Rs. 1,40,00,000/- has been deposited by 07 Nos. of stone crusher of Rs. 20.00 lacs each as interim environmental compensation in the account of HSPCB, Panchkula. Also, HSPCB has imposed environmental compensation amount of Rs. 65,81,250/- against 09 Nos. of stone crushing units for the various violation of environmental norms.

It is, therefore, prayed that the above action taken report alongwith information in tabulate form in compliance with the directions issued by this Hon'ble Tribunal vide order dated 23.11.2023, may kindly be considered, please.

Dated: - 30.01.2024


Regional Officer
HSPCB, Mahendragarh

7768

Sr No.	Respondent No. (IA No.)	Name and address of the unit Latitude Longitude	Date of establishment/setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (Date of First CTO Granted)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Wetting & Cleaning of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Operational Status	Date of Closure, if any	Violation of environmental norms for past period, if any	Environment Compensation Status	Action Taken	Remarks
1	12 (94-95 of 2023)	SHREE BALAJI GRIT UDYOG M.No. 23, Kila No. 9 (8-0), 2 min South (4-0), 8/2 min West (6-0), 13/1 min West (2-0), 12/1 (2-0), 12/2 (6-0) Total 28 Kanal 0 Marla at Village-Gangutana, Tehsil-Nangal, Chaudhary, Distt-Mohindergarh 27.877648 76.061147	313129217MAHCT E4665005 dated 16.11.17	11.07.2018	Granted from 01/04/2021 - 31/03/2024	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
2	13 (96-97 of 2023)	SHREE RAM STONE CRUSHER, M.No. 62, Kila No. 3 (7-12), 2/3 (1-17), 2/1 (1-12), 2/4 (2-16) and 2/2 (0-11) Total 14 Kanal 8 Marla at Village-Dholera, Tehsil-Nangal Chaudhary, Distt-Mohindergarh 27.92501 76.06026	313129218MAHCT E5190323 dated 27.03.18	23.12.2021	Granted from 29/11/2021 - 31/03/2026	35 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
3	14 (98-99 of 2023)	Shree Balaji Stone Crusher, M.No./Kila No 62/9(4-0), 7/2 (2-3)& 8(6-18), Village-Dholera, Tehsil-Nangal Choudhary, Distt-Mohindergarh 27.92264 76.06054	402-405 dated 21.06.04	07.11.2007	Granted from 01/04/2022 - 31/03/2027	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
4	15 (106-107 of 2023)	ASHA STONE CRUSHING CO, Khwat No. 110, Khatoni No. 128, Mustil & Kila No. 62 / / 5/2(6-16), 6 Min west (5-18), 343/1 min west (0-14) total 13 Kanal 8 Marla VILLAGE DHULEDA NARNAUL MAHENDERGARH 27.922662 76.064052	HSPCB/DHR/2017/2146 dated 03.10.17	10.04.2018	Granted from 01/04/2023 - 31/03/2028	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
5	16 (119 of 2023)	GANESH STONE CRUSHER Khwat No. 75, Khatoni No. 81, M.No. 8, Kila No. 23 (8-0) At Village-Khatoli Ahir, Tehsil-Nangal Chaudhary, Distt-Mohindergarh 27.966494 76.083972	313129217MAHCT E4690378 dated 08.12.17	18.07.2018	Granted from 14/04/2023 - 31/03/2028	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	Interim EC deposited of Rs. 20.0 Lakhs by the unit.	NA	Unit is complying presently
6	17 (121-122 of 2023)	SHRI RAM STONE CRUSHER PLANT 2, Khewat No. 23, Khatoni NO. 25, M/Kila No. 46/21 (8-0), 22(8-16), 48/1(7-7) & 2(2-11) total 26 Kanal 14 Marla at Village Panchnota, Nangal Chaudhary, Distt-Mohindergarh 27.903847 76.017596	313129220MAHCT E8036401 dated 26.08.2020	14.10.2020	Granted from 14/10/2020 - 31/03/2024	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
7	18 (123-124 of 2023)	Baba Kheta Nath Stone Crusher, Kila No. 109/2/1, 9/1, 98/22/2, 8 kanal 16 marla 98/22// 5 kanal 0 marla total 13 kanal 16 marla Vill.-Zerpur, M/garh 28.324268 76.087004	1786 dated 12.05.06	28.12.2007	Granted from 26/12/2022 - 31/03/2027	55 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently

8	19 (271-272 of 2023)	SATYAM STONE CRUSHER UNIT II MUSTKIL NO 57 KILLA NO. 12/2/1 & 19/2, VILLAGE BEGOPUR TEHSIL NARNUAL 27.92374 76.05472	2817715MAHCTE2 104566 dated 13.07.15	18.05.2016	Granted from 01/10/2021 to 31/03/2026	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
9	20 (273-274 of 2023)	Siddhi Vinayak Stone Crusher VIII-Dholera, Narnaul, Distt-Mohindergarh Khewat No. 361, Khatoni No. 400, M.No. 51, Kila No. 19/2 (6-12) & Khewat No. 365, Khatoni No. 409, M. No. 51, Kila No. 22 (1-15) total measuring 8 K 7 M MAHENDRAGARH 27.924129 76.0606	2817715MAHCTE1 895585 dated 14.04.15	13.07.2015	Granted from 01/10/2021 to 30/09/2026	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
10	21 (275-276 of 2023)	Mahalaxmi Stone Crusher, Khewat No. 197, Khatoni No. 231, Kila No. 50/16/2, 6/15, Vill-Dholera, Nangal Chaudhary, Mohindergarh 27.924626 76.05945	490 dated 03.08.06	30.03.2013	Granted from 01/04/2022 - 31/03/2027	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
11	22 (277-278 of 2023)	Rajokari Stone Cr. (Kontech Crushing Co.,) Khewat no. 16, khatoni no. 46 & 48, rakba 140 kanal & 16 Marla, khasra no. 7/21 (8-0), 22 (7-1) & 8/25/2 (5-12) Vill-Bakhrija, Narnaul, Distt-Mohindergarh 27.920515 76.054241	1357-60 dated 28.04.06	22.01.2007	Granted from 01/04/2022 - 31/03/2027	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
12	23 (279-280 of 2023)	JAI BHARAT STONE CRUSHER Khewat No. 107, Khatoni No. 121, M.No. 53, Kila No. 23 Min East (4-0) & 24 (8-0) Total 12 Kanal 0 Marla at Village-Begopur, Nangal Chaudhary, Distt-Mohindergarh 27.925918 76.051751	313129218MAHCTE5334249 dated 30.05.18	10.01.2020	Granted from 22/04/2021 - 31/03/2025	55 feet	Not provided adequate arrangement	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Not provided adequate sprinklers	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	Closure order issued vide order No. 538 dated 21.09.2020	85 days	Imposed EC of Rs. 5,31,250/- Vide order dated 17.02.2023 and the same was deposited by the unit.	NA	Unit is complying presently
13	24 (281-282 of 2023)	Nirvaan Infrastructure At Khewat No. 143, Khatoni No. 170, M.No. 13, Kila NO. 17(8-0), 18(8-0), 19(5-14) & 24/1 (2-0) (Total 23K-14M), Vill-Lutafpur, Terhsil-Narnaul Distt Mohindergarh 28.04342 76.05209	2817716MAHCTE3 227197 dated 03.08.16	09.12.2016	Granted from 01/04/2023 - 31/03/2028	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
14	25 (283-284 of 2023)	Sheranwall Stone Crusher, Khewat No. 25, Khatoni No. 54, total 45 kanal 9 marla Vill-Bakhrija, Narnaul, Distt. Mohindergarh 27.92022 76.053868	1666 dated 16.12.05	30.05.2012	Granted from 01/04/2023 - 31/03/2028	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
15	26 (285-286 of 2023)	Shree Shyam Stone Crusher, Khewat No. 237, Khatoni No. 269, Kila No. 51 / / 13, (8-0), 17/3/3 (3-16), 18(8-0), 19/1 (0-2)Vill-Dholera, Nangal Chaudhary, Distt-Mohindergarh 27.9243 76.061297	1088-91 dated 05.10.05	01.06.2011	Granted from 01/04/2022 - 31/03/2027	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently

16	27 (287-288 of 2023)	Satyam Stone Crusher, Khewat no. 182, khatoni no. 209, kila no. 57/12/2, 13/2, 18,19/1, 19/2 (19 kanal) Vill-Begopur, Narnaul, Distt-Mohindergarh 27.92374 76.05472	2408-11 dated 16.01.06	30.03.2012	Granted from 01/04/2022 - 31/03/2027	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
17	28 (320-321 of 2023)	SHRI RADHEY MINES PRIVATE LIMITED, Khewat No. 10, Khatoni NO. 13, M.No. 8, Kila No. 23 (2-0), 24 Min South (2-18) & M.No. 13, Kila No. 4/1 (7-2) total 12 Kanal 0 Marla at Village-Gangutana, tehsil-Nangal Chaudhary, Distt-Mohindergarh 27.86639 76.04743	313129219MAHCT E7012328 dated 12.12.19	25.07.2020	Granted from 25/07/2020 - 31/03/2024	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
18	29 (393-394 of 2023)	SHRI RAM STONE CRUSHER, Khewat No. 11, Khatoni NO. 11, M.No. 49, Kila No. 3 (7-11) & 4 (7-11) total 15 Kanal 02 Marla at VIII-Panchnota, Nangal Chaudhary Distt-Mohindergarh 27.904775 76.017043	313129218MAHCT E6117016 dated 26.12.18	30.07.2019	Granted from 30/07/2019 - 31/03/2024	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
19	30 (694-695 of 2023)	Haryana stone crusher Kila NO. 25//19,20, Vill: garhi distt. Mahendergarh 28.434106 76.111652	1262-64 dated 01.06.11	29.03.2014	Granted from 31/10/2022 - 31/03/2027	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
20	31 (696-697 of 2023)	Shree Baba Jairamdass Grit Udyog, Khewat No. 5, Khatoni No. 15, Kila No. 35, total 206 kanal 4 marla Vill-Garhi, Distt-Mohindergarh 28.434167 76.111252	1377-80 dated 01.05.06	07.11.2007	Granted from 01/08/2022 - 31/03/2027	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
21	32 (713 of 2023)	Karan Stone Cr., Khasra no. 109/12 (7-8), 19/(7-16) Vill-Zerpur, Mohindergarh 28.319049 76.087335	400 dated 21.07.06	04.06.2012	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Unit found dismantled from the site	Unit found dismantled from the site
22	33 (718 of 2023)	Shiv Sunder Grit Udyog, Kila No. 71/6, Vill-Lutafpur, Narnaul, Mohindergarh 28.042011 76.07308	2423 dated 09.12.96	30.03.2007	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection
23	324 of 2023	Lakshmi Stone Crusher, Khasra No. 268, Kila No. 70/1, Khatoni No. 322 to 324 (25 Kanal 14 marla) Kultajpur Road, Lutufpur, Narnaul, Distt-Mohindergarh	1416 dated 08.03.94	22.01.2007	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection
24	325 of 2023	Laxmi Stone Crusher Khewat No. 190, Khatoni No. 256, M.No. 44, Kila No 14/2 (3-4), 15/2(3-19), 16/2(2-0), 17/1(3-0) at Village Kultajpur, Narnaul District-Mohindergarh 28.04574 76.05937	313129217MAHCT E3878565 dated 02.03.17	22.11.2017	Granted from 01/04/2022 - 31/03/2027	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently

25	326 of 2023	Bajrang Stone Crusher Khewat No. 362, Khatoni No. 403, M.No. 50, Kila No. 24/1 (1-16) & 24/2 (6-12) Total 8 Kanal 08 Marla at Village Dholera, Nangal Chaudhary District Mohindergarh 27.92463 76.05933	313129217MAHCT E3563202 dated 28.03.17	14.12.2017	Granted from 01/04/2022 - 31/03/2027	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
26	327 of 2023	Bajrang Stone Crusher, Khewat No. 121, Khatoni No. 148, Khasra No. 53 total 260 kanal 15 marla Vill.-Faizabad, Narnaul 28.108867 76.111231	183 dated 25.05.2000	16.10.2001	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	Closure order issued vide order No. I/129410/2022 dated 16.08.2022	NA	NA	Closed by Board	Closed by Board
27	328 of 2023	M J ENTERPRISES, Khewat No. 6, Khatoni No. 6, M.No. 41, Kila No. 24 (6-3), 25/1 (1-14), 16/2 (0-8), 17 (1-13), Village-Kultajpur, Tehsil-Narnaul, District-Mohindergarh 28.04607 76.04958	HSPCB/DHR/2017/1937 dated 12.09.17	01.05.2018	Granted from 01/04/2023 - 31/03/2028	85 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
28	329 of 2023	Balaji Stone Crushing Company Khasra No. 44//6(7-8), 7 (8-0) 15/1 (1-13) Vill Garhi, PO-Khudana, Distt-Mohindergarh 28.433475 76.111387	101-07 dated 20.10.02	01.03.2005	Granted from 01/04/2023 - 31/03/2028	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
29	330 of 2023	Mahashiv Stone Crusher (DDR Stone) Khewat No. 9, Khatoni No. 21 & 22, Kila No. 19//25, 8-0, 31//5, 8-0, 30//1, 3-0 Vill-Jainpur, Narnaul, Distt-M/garh 27.90693 76.08658	HSPCB/TAC(B)2006/546 dated 11.08.06	30.03.2012	Granted from 01/04/2023 - 31/03/2028	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
30	331 of 2023	Banshi Stone Crusher, Rect/Kila No. 95//2, 3min east 8 min east total measuring 21 Kanal 18 marla Vill-Bayal, Narnaul, Distt-Mohindergarh 27.84928 75.97549	4050 dated 08.03.10	30.03.2012	Granted from 01/10/2020 - 31/03/2025	-	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	Interim EC deposited of Rs. 20.0 Lakhs by the unit.	NA	Unit is complying presently
31	332 of 2023	Maman Grit Udyog, Khasra no. 182/209 Vill- Begopur, Tehsil- Narnaul, Mohindergarh 27.923481 76.055496	938-41 dated 16.03.06	03.12.2008	Granted from 01/10/2020 - 31/03/2024	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
32	333 of 2023	Pooja Stone Crusher, Kila no. 53/9, 10, khewat no. 2, khatoni no. 6 Vill-Garhi, Mohindergarh 28.430789 76.111599	921-24 dated 16.03.06	31.03.2008	Granted from 01/04/2022 - 31/03/2027	85 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
33	334 of 2023	Bhagwati Grit Udyog, Khewat No. 110/13/8, 13/3 14-17, 18/1, 18/2 Vill-Zerpur, Mohindergarh 28.318371 76.091941	1621 dated 22.02.02	30.03.2007	Granted from 01/04/2022 - 31/03/2027	65 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently

34	335 of 2023	Parkash Stone Crusher, Khewat no. 173, 178, khatoni no. 198, 203 and Kila no. 57/7-8, 13/1, 14/1/1, Vill-Begopur, Narnaul 27.92508 76.0553	838-41 dated 05.08.05	11.12.2007	Granted from 01/04/2022 - 31/03/2027	35 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
35	336 of 2023	BHAWANI GRIT UDYOG Khewat No. 58, Khatoni No. 62, M.No. 8, Kila No. 17/1(7-11), 18/1 min East (4-09) Total 12 Kanal 0 Marla At Village-Khatoli Ahir, Tehsil-nangal Chaudhary, Distt-Mohindergarh 27.967061 76.083448	313129218MAHCT E5012062 dated 16.02.18	27.01.2019	Granted from 01/04/2023 - 31/03/2028	65 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	Interim EC deposited of Rs. 20.0 Lakhs by the unit.	NA	Unit is complying presently
36	337 of 2023	Rohit Stone Crusher Company, Khewat no. 16, Khatoni no. 46,48, Kila no. 8/15, 16 (16 kanal 12 Marla) Vill. Bakhrija, Narnaul, Distt. Mohindergarh 27.921571 76.053801	542 dated 08.02.06	08.12.2015	Granted from 01/04/2022 - 31/03/2027	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
37	338 of 2023	Sheetla stone Crusher, Khewat no. 16, khatoni no. 46, 48 kila no. 8/15, 16) 16 kanal 12 marla Vill. Bakhrija, Narnaul, Distt. Mohindergarh 27.921098 76.052743	538-40 dated 09.02.06	30.03.2012	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	Closure order issued vide order No. 444-447 dated 03.09.2020	NA	NA	Closed by Board	Closed by Board
38	339 of 2023	Dev Shri Krishna Stone Crusher, Khewat No. 31, Khatoni No. 34, M.No. 98, Kila No. 20/3 & 21 (8-16) Khewat No. 68, Khatoni No. 83, M.No. 98, K.No. 15/2 & 16(13-6), Khewat No. 70, Khatoni No. 85, M.No. 99, Kila No. 24/2 & 25 (12-0) Total 32 Kanal 12 Marla Vill-Zerpur, Distt-Mohindergarh 28.321515 76.086305	704 dated 18.08.04	21.08.2013	Granted from 06/02/2023 - 31/03/2027	55 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	Closure order issued vide order No. 1/129404/2022 dated 16.08.2022	173 days	Imposed EC of Rs. 10,81,250/- Vide order dated 28.11.2022 and the same was deposited by the unit.	NA	Unit is complying presently
39	340 of 2023	Shiv Grit Udyog, Khasra no. 44, kila no. 24, (4-6), 2597-8) total 11 kanal 14 marla Village-Garhi, Tehsil & District-Mohindergarh 28.43308 76.11048	1299 dated 11.11.2005	28.12.2007	Granted from 01/04/2019 - 31/03/2024	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
40	341 of 2023	SHIV SHAKTI STONE CRUSHER UNIT II, Khewat No. No. 250, Khatoni No. 277, M.No. 52, Kila No. 24 min East (7-8) & 25 min West (0-12) Total 8 Kanal 0 Marla at Village-Begopur, Nangal Chaudhary, Distt-Mohinergarh 27.927192 76.055183	313129218MAHCT E4986616 dated 01.03.18	02.10.2019	Granted from 02/10/2019 - 31/03/2024	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
41	342 of 2023	Shivalya Stone Crusher, Kila no. 57/9/2, 10/1, 10/2, 12/1 & 13/1 Vill-Begopur, Narnaul, Distt-Mohindergarh 27.92445 76.053755	1893 dated 11.02.05	30.03.2012	Granted from 01/04/2022 - 31/03/2027	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently

42	343 of 2023	Shivalik Stone Crusher Co., Khewat no. 19, Khatoni no. 22, kila no. 13/3, 4/2, (4-11), (0-18) Vill-Gangutana, Nangal Chaudhary, Narnaul 27.8838 76.065491	1593 dated 01.12.05	01.10.2012	Granted from 01/04/2022 - 31/03/2027	55 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently	
43	344 of 2023	Jai Shree Shyam Stone Crusher (Formerly Shivam Stone Crusher), Khewat no. 8, khatoni no. 10, kila n. 109/6/2/1(2-11)/15 (9-16), 16 (8-0) Vill-zerpur, Mohindergarh 28.324268 76.087004	1533 dated 28.12.04	04.06.2012	Granted from 30/08/2022 - 31/03/2027	85 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Not Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Not operational	Closure order issued vide order No. 53807995CO N001-005 dated 02.01.2024	NA	NA	NA	Closed by Board	Closed by Board
44	345 of 2023	SHREE BALAJI GRIT UDYOG M.No. 56, Kila No. 13/3 (5-2), 18(2-4), 13/1 (2-15) & 13/2 (2 Marla 4 sarsai) Total 10 Kanal 3 Marla 4 Sarsai at Village-Begopur, Tehsil- Nangal Chaudhary, Distt- Mohindergarh 27.924686 76.051271	313129217MAHCT E4639993 dated 16.11.17	01.03.2018	Granted from 01/04/2024 - 31/03/2028	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently	
45	346 of 2023	DHARAM GRIT UDYOG M.No. 56, Kila No. 7/1 (7-8), 7/3 & 8/1/2 (4 -12) & 7/2, 7/4, 8/1/1 (6 marla 5 sarsai) Total 12 Kanal 6 Marla 5 Sarsai at Village-Begopur, Nangal Chaudhary, Distt- Mohindergarh 27.934717 76.047124	313129217MAHCT E4639961 dated 16.11.17	16.08.2019	Granted from 01/04/2024 - 31/03/2029	35 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently	
46	347 of 2023	SHREE GANPATI STONE CRUSHER, Kh. No 66, Khatoni No 70, M.No. 7, Kila No 10/2 min West-South (2-10) & M.No. 8 Kila No 6(8-0), 7 min East-South (2-0) Total 12 K.10 M. at Vill-Khatoli Ahir, Nangal Chaudhary, Distt- Mohindergarh 27.967285 76.82697	313129218MAHCT E5150531 dated 13.03.18	15.08.2018	Granted from 01/04/2023 - 31/03/2028	65 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently	
47	348 of 2023	Shree Ganpati Stone Crusher, Khewat No. 12, Khatoni No. 41, Mustkil & Kila No. 8/2/2 (4-8) & 8/3/1 (5-4) Vill. Bakhrija, P.O Dholera, Narnaul Distt-Mohindergarh 27.923007 76.051278	2817715MAHCTE1 380035 dated 21.01.15	08.10.2015	CTO Revoked	-	-	-	-	-	-	-	-	Not operational	Closure order issued vide order No. 534 dated 21.09.2020	NA	NA	NA	Closed by Board	Closed by Board
48	349 of 2023	HINDUSTHAN STONE CRUSHER, M.No. 11, Kila No. 9/2(4-0), 12/1(4-0), 12/2(3-11) & 13/1(3-11) Total 15 Kanal 02 Marla at Vill-Khatoli Ahir, Nangal Chaudhary, Distt- Mohindergarh 27.965012 76.081801	313129218MAHCT E5366474 dated 30.05.18	05.02.2019	Granted from 01/04/2023 - 31/03/2028	95 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently	
49	350 of 2023	SHREE NARAYAN STONE CRUSHER, Khewat No. 18, Khatoni NO. 20, M.No. / Kila No. 24//24 Min East (6-0) & 27//4 Min North (6-0) total 12 Kanal 0 Marla AT Vill-Khatoli Ahir, Nangal Chaudhary Distt- Mohindergarh 27.961276 76.082149	313129218MAHCT E5495746 dated 08.08.18	21.12.2018	Granted from 06/06/2022 - 31/03/2027	110 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently	

50	351 of 2023	Ishwar Stone Crushing Co., Khwat No. 24, Khatoni No. 53, Kila No. 7/11/1(2-19, 11/2(4-5), 12, VIII. Bakhrija, Narnaul 27.92149 76.05438	2404 dated 13.01.06	30.03.2012	Granted from 01/04/2022 - 31/03/2027	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
51	352 of 2023	Jai Durga Maa Stone Crusher, Kila no. 44/4, 5,8, 7, 8 khawat no. 87, khatoni no. 156 Vill Garhi, Mohindergarh 28.435302 76.11175	946 dated 16.03.06	11.12.2007	Granted from 01/04/2022 - 31/03/2027	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
52	353 of 2023	SHREE OM INFRASTRUCTURE COMPANY, Khewat No. 46, Khatoni NO. 48, M.No. 23, Kila No. 21/1 Min East (2-18), 22/1/1 (4-16), 22/2/1 (1-0) & 23/1 (4-8) total 13 Kanal 02 Marla at Village Berundla, Nangal Chaudhary, Distt-Mohindergarh 27.955593 76.079958	313129218MAHCT E5487561 dated 08.08.18	27.12.2018	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	Closure order issued vide order No. 43457229CO NCO001-005 dated 05.09.2023	NA	NA	Closed by Board	Closed by Board
53	354 of 2023	Jai Hanuman Stone Crusher Company Kila No. 19/16(7-11), 20/11(2-8), 20(2-17) Vill-Jainpur, Tehsil-Narnaul, DisttMohindergarh 27.90704 76.087315	2817714MAHCTE1 145776 dated 28.08.14	30.01.2015	Granted from 01/10/2020 - 31/03/2025	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
54	355 of 2023	JAI HIND STONE CRUSHER Khewat No. 173, Khatoni No. 202, M.No. 16, Kila No. 19 (5-12), 20/1 (0-4), 21 (0-5) & 22 (5-19) Total 12 Kanal 0 Marla at Village Lutafpur, Narnaul, DistrictMohindergarh 28.04404 76.06146	313129217MAHCT E3825519 dated 09.02.17	11.09.2017	Granted from 07/07/2021 - 31/03/2026	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
55	356 of 2023	Shree Shyam Stone Crusher Khewat No. 177, Khatoni No. 243, M.No. 43, Kila No. 9 (5-2) & 12 (3-18) at Vill-Kultajpur, Tehsil-Narnaul Distt Mohindergarh 28.045538 76.049318	2817715MAHCTE2 203311 dated 26.08.15	31.03.2016	Granted from 01/04/2023 - 31/03/2028	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
56	357 of 2023	Jai Stone Crusher Co., Khewat no. 16, Khatoni no. 46- 48, Kita no. 35, Tadadi rakba 145 kanal 9 marla Vill- Bakhrija, Narnaul, Mohindergarh 27.922913 76.052799	159 dated 22.06.08	30.03.2012	Granted from 01/10/2020 - 31/03/2024	32 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
57	358 of 2023	Karota Stone Grinding, Khewat no. 32, khatoni no. 64, kila no. 12//20 (9-0), khewat no. 33, Khatoni no. 65, kila no. 13//16(6-12) Vill Karota, Narnaul, Distt-Mohindergarh 27.98377 76.087415	217-220 dated 28.07.2000	16.05.2008	Closed by Board	-	-	-	-	-	-	-	-	Not operational	Closure order issued vide order No. I/129648/202 2 dated 17.08.2022	174 days	Imposed EC of Rs. 10,87,500/- Vide order dated 28.11.2022 and the same was not deposited by the unit till date.	Closed by Board	Closed by Board

58	359 of 2023	SHREE SHYAM BABA STONE CRUSHER M.No. 11, Kila No. 20/2 min East (2-0), 19/2 min West (2-0), 21/1/1 min East (1-11), 22 min West(2-11) & 21/1/2(1-16) Total 9 Kanal 18 Marla at Vill-Khatoli Ahir, Nangal Chaudhary, Distt-Mohindergarh 27.965519 76.082729	313129218MAHCT E4895016 dated 30.01.18	08.05.2018	Granted from 01/04/2022 - 31/03/2027	120 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently	
59	360 of 2023	Krishna Stone Crusher Khewat No. 365, Khatoni No. 409 (51/22) 2/19, 410 (51/23/2),1/18, 411 (51/23/1) 2/5, 412(51/23/2) 413 (51/23/2) at Vill-Dholera, Narnaul, Distt-Mohinergarh 27.923114 76.06058	2817715MAHCTE1 661941 dated 26.02.15	13.07.2015	Granted from 01/04/2022 - 31/03/2027	40 feet	Not provided adequate arrangement	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Not provided adequate sprinklers	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently	
60	361 of 2023	VINAYAK CONSTRUCTION COMPANY Khewat No. 173, Khatoni No. 202, M.No. 16, Kila No. 20/1/2 (3-19) & 21/1 (4-1) VillLutafpur, Narnaul, District-Mohindergarh 28.04617 76.512	313129217MAHCT E4606128 dated 18.10.17	17.10.2022	Granted from 17/10/2022 - 31/03/2027	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently	
61	362 of 2023	ARIHANT STONE CRUSHER Khewat No. 235, Khatoni No. 262, M.No. 57, Kila No. 2/2 (8-0) Total 8 Kanal 0 Marla at Village-Begopur, tehsil-Nangal Chaudhary, Distt-Mohindergarh 27.925265 76.054075	313129217MAHCT E4728375 dated 14.12.17	21.12.2018	Granted from 01/04/2023 - 31/03/2028	35 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently	
62	363 of 2023	Yaduvanshi Stone Crusher, Khewat No. 98//10 (8-0), 98/11 (7-11), 99/6 (8-0), 15/1 (3-16) Vill-Zerpur, Distt-Mohindergarh 28.322281 76.086118	1476-80 dated 30.01.02	10.01.2008	CTO Revoked	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	CTO Revoked	CTO Revoked	
63	364 of 2023	Bajrang Bali Stone Crusher, Khasra No. 98//17/2/2, 24, 109//4/1, 3/2, 18/3/2 Vill-Zerpur, Narnaul, Mohindergarh 28.320332 76.088689	76 dated 26.04.04	03.04.2015	Granted from 01/10/2020 - 30/09/2024	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Not Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Not operational	Recommendation for Closure sent to Head Office	NA	NA	NA	Recommendation for Closure sent to Head Office	Recommendation for Closure sent to Head Office
64	365 of 2023	DEV SHRI KRISHNA STONE CRUSHER Khewat No. 234, Khatoni No. 261, M.No. 52, Kila No. 19 (8-0) & 18 min East (4-0) at Village-Begopur, Tehsil-Nangal Chaudhary, Distt-Mohindergarh 27.92704 76.054796	313129217MAHCT E4690444 dated 16.12.17	03.01.2018	Granted from CTO 01/04/2022 - 31/03/2027	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently	
65	365 of 2023	JAI BABA SHYAM STONE CRUSHER M.No. 51, Kila No. 16/2/2/2 (1-1) & 25/3 (5-19), M.No. 52 Kila NO. 21/1/1(5-0) Total 12 Kanal 0 Marla at Village-Dholera, Tehsil-Nangal Chaudhary, District-Mohindergarh 27.923793 76.062579	313129217MAHCT E4584396 dated 16.10.17	21.12.2018	Granted from 01/04/2023 - 31/03/2028	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently	

66	365 of 2023	JAI SHREE SHYAM STONE CRUSHER M.No. 51, Kila No. 23/3 (1-10), 24(7-11), 16/2/2/1(0-6), 17/2/2(0-10), 17/3/2(0-3), 25/1(1- 18) & 25/2 (0-2) Total 12 Kanal 0 Marla at VIII-Dholera, Distt- Mohindergarh 27.92381 76.062573	313129217MAHCT E4599566 dated 16.10.17	10.04.2018	Granted from 01/04/2023 - 31/03/2028	28 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
67	365 of 2023	SHREE GANESH STONE CRUSHER, Khewat No. 73, Khatoni No. 80, M.No. 52, Kila No. 20/1 Min North (4-15), 11/1 Min South (0-12), 11/2 Min South (2-15) at Village-Begopur, Tehsil-Nangal Chaudhary, Distt- Mohindergarh 27.924256 76.05244	313129218MAHCT E5140113 dated 01.03.18	22.12.2018	Granted from 01/04/2023 - 31/03/2028	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
68	366 of 2023	HARE KRISHNA STONE CRUSHER Khewat No. 14, Khatoni No. 43, M.No. 3, Kila No. 24/1(7-0), M.No. 8, Kila No. 4/1/1 (1- 19) at Village-Bakhrja, Tehsil-Nangal Chaudhary, District- Mohindergarh 27.921093 76.053368	313129217MAHCT E4587895 dated 17.10.17	07.05.2018	CTO Revoked	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	CTO Revoked	CTO Revoked
69	367 of 2023	SHRI HARI STONE CRUSHER Khewat No. 157, Khatoni No. 185, M.No. 16, Kila No. 9/3(2-0), 11/3 (2- 01), 12 (8-0) at Village-Lutafpur, Tehsil- Narnaul, District- Mohindergarh 28.02096 76.07285	313129217MAHCT E4620500 dated 08.12.17	23.05.2018	Granted from 01/04/2023 - 31/03/2028	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
70	368 of 2023	Maa Durga St. Cr. (Dalal Construction Co.), Kila no. 110-1/2 (6-0), 2/(2-0), 2(8-0) Vill-zerpur, Mohindergarh 28.324268 76.087004	245 dated 01.06.04	30.03.2007	Granted from 01/04/2022 - 31/03/2027	120 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
71	369 of 2023	Shree Ram Stone Crusher, Khewat no. 13, khatoni no. 26, kila no. 19//6 (4-5), 7 (1-8), 14(1-4), 15/1 (5-0) total land (11 kanal 17 Marla) VIII- Jainpur, Narnaul, Distt. Mohindergarh 27.9084 76.08638	812 dated 04.08.05	11.12.2007	Granted from 01/10/2020 - 31/03/2025	35 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
72	370 of 2023	Jai Hanuman Stone Crusher, Kila no. 110//11(6-11) 110//19(7-16), 110//20(8-0) Vill-zerpur Mandola, Mohindergarh 28.318989 76.090193	764 dated 31.10.04	29.11.2007	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection
73	371 of 2023	Jai Hind Stone Crusher, Kila no. 50 (25 kanal 3 marla) VPO- Jainpur, Narnaul, Distt. Mohindergarh 27.9084 76.08688	249-252 dated 09.01.06	30.03.2012	Granted from 01/04/2022 - 31/03/2027	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	30 days	Imposed EC of Rs. 1,87,500/- Vide order dated 09.05.2023 and the same was deposited by the unit.	NA	Unit is complying presently

74	372 of 2023	Jai Shree Krishna Stone Crusher, Khewat No. 11, Khatoni No. 25, Musti & Kila No. 16/23 (1-0), 19/3(7-14) total 16 Kanal 14 marla Vill-Jainpur, Narnaul, Mohindergarh 27.90939 76.085038	950 dated 16.03.06	30.03.2012	Granted from 01/04/2023 - 31/03/2028	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
75	373 of 2023	Shree Shyam Grit Udyog, Khasra No. 24, Kila No. 16 & 17, total 16 Kanal, Vill.-Garhi, Mohindergarh 28.434559 76.11131	1294 dated 21.12.01	26.07.2004	Granted from 01/04/2022 - 31/03/2027	55 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
76	374 of 2023	JC STONE CRUSHER Khewat No. 63, Khatoni No. 67, M.No. 8, Kila No. 14 min East (6-0) & 15 Min West(6-0) total 12 Kanal 0 Marla at Vill-Khatoli Ahir, Nangal Chaudhary, Distt-Mohindergarh 27.967701 76.08445	313129218MAHCT E5334707 dated 09.06.18	03.02.2022	Granted from 03/02/2022 - 31/03/2026	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
77	375 of 2023	JAI DURGA STONE CRUSHER, Khewat No. 5, Khatoni NO. 5, M.No. 56, Kila No. 14 (8-0) total 8 Kanal 0 Marla at Village Begopur, Nangal Chaudhary, Distt-Mohindergarh 27.92233 76.0523	313129220MAHCT E7943886 dated 31.07.2020	11.12.2021	Granted from 11/12/2021 - 31/03/2026	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
78	376 of 2023	SHREE GANESH STONE CRUSHER, M.No. 7, Kila NO. 1/1 Min West (4-06-1), 1/2 Min West (0-13-8) & 10 min West (5-0) 10 Kanal 0 Marla at Vill-Bakhrja, Nangal Chaudhary, Distt-Mohindergarh 27.922937 76.052345	313129218MAHCT E5279024 dated 04.05.18	20.08.2019	Granted from 01/04/2020 - 31/03/2025	28 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
79	378 of 2023	Om Grit Crusher, Khewat no. 15, Khatoni no. 45, kila no. 7/7/8 (4-8) & 9 (9-13) total 14 Kanal 1 Marla Vill.-Bakhrja, Narnaul 27.92201 76.05493	NOC/2005/TAC/256 dated 16.03.06	30.03.2007	Granted from 01/04/2021 - 31/03/2026	35 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
80	379 of 2023	JMD Stone Crushing Company Part I Khewat No. 5, Khatoni No. 5, Kila NO. 16//20, 21 Min Vill-Jainpur, Narnaul, Distt-Mohindergarh 27.90999 76.08419	2817715MAHCTE1590529 dated 03.02.15	07.11.2015	CTO Revoked	-	-	-	-	-	-	-	-	Not operational	NA	NA	Interim EC deposited of Rs. 20.0 Lakhs by the unit.	CTO Revoked	CTO Revoked
81	380 of 2023	JMD Stone Crushing Company Part II Khewat No. 5, Khatoni No. 5, Kila NO. 16//21 Min, 19//1 VillJainpur, Narnaul Distt-Mohindergarh 27.90999 76.08419	2817715MAHCTE1590698 dated 04.02.15	18.05.2016	Granted from 01/04/2021 - 31/03/2026	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Not operational	Closure order issued vide order No. 37935226CO NCO001-005 dated 11.09.2023	NA	Interim EC deposited of Rs. 20.0 Lakhs by the unit.	Closed by Board	Closed by Board
82	381 of 2023	Raj Stone Crusher, Khewat no. 178, hatoni no. 203, kila no. 56/15 & 57 //1 (14 kanal 8 marla) Vill.-Begopur, Narnaul, Distt. Mohindergarh 27.92513 76.052206	1100 dated 06.10.05	30.03.2012	Granted from 01/04/2022 - 31/03/2027	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently

83	382 of 2023	Jayoti Stone Crusher, Khewat no. 7, Khatoni no. 36, kila no. 8/5/ 2(3-3), 6/1(3-3) & 7 (7-11) Vill-Bakhrija, Narnaul, Distt-Mohindergarh 27.92248 76.052805	937 dated 16.03.06	25.07.2012	Granted from 01/04/2022 - 31/03/2027	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
84	383 of 2023	SHIKOHPUR STONE CRUSHER COMPANY, Khewat No. 288, Khatoni No. 319, M.No. 62, Kila No. 7/1/2 (6-10), 15/1(1-10) at Village-Dholera, tehsil-Nangal Chaudhary, Distt-Mohindergarh 27.922239 76.062123	HSPCB/DHR/ 2017/1525 dated 17.08.17	07.05.2018	Granted from 01/04/2023 - 31/03/2028	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
85	384 of 2023	Shiv Stone Crusher Khewat No. 362, Khatoni No. 402, M. No. 50, Kila No. 17 At Vill-Dholera, Nangal Chaudhary, Narnaul, Distt-Mohindergarh 27.923905 76.058892	2817715MAHCTE2 292703 dated 29.12.15	11.08.2016	Granted from 01/04/2022 - 31/03/2027	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
86	385 of 2023	Mahadev Stone Crusher Khewat No. 190, Khatoni No. 256, M.No.44, Kila No. 6/4 (4-04), 7/1(3-8), 14/2/1(0-4), 15/1(0-5) Total 8 kanal 01 Marla at Village-Kultajpur, Narnaul District-Mohindergarh 27.04327 76.06049	313129217MAHCT E4608948 dated 26.10.17	22.11.2021	Granted from 22/11/2021 - 31/03/2026	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
87	386 of 2023	SHREE KRISHNA STONE CRUSHING MILLS, Kila No. 98(20/1), 19,18(2/2), 23(2/1) VILLAGE ZERPUR, DISTRICT-MOHINDERGARH 28.31723 76.09197	HSPCB/2004/282 dated 08.06.2004	16.02.2018	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	Closure order issued vide order No. I/129435/2022 dated 16.08.2022	173 days	Imposed EC of Rs. 10,81,250/- Vide order dated 28.11.2022 and the same was not deposited by the unit till date.	Closed by Board	Closed by Board
88	387 of 2023	New Haryana Stone Crusher, Khasra no. 57//8, 9/1, 13/1, Vill-Begopur, Narnaul, Distt-Mohindergarh 27.92504 76.054303	799 dated 03.08.05	30.03.2012	Granted from 01/04/2022 - 31/03/2027	35 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
89	388 of 2023	Yaduvanshi Grit Udyog, Khewat No. 98, Khatoni No. 165, Kila No. 8, total 58 kanal 15 Marla Vill-Garhi, Mohindergarh 28.434648 76.113061	917 dated 16.03.06	30.03.2007	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection
90	389 of 2023	Nihal Stone crusher, Kila no. 56//6, 15 Min (15 kanal 11 Marla) Vill-Begopur, Narnaul, Distt-Mohindergarh 27.921825 76.052831	1096 dated 05.10.05	21.08.2013	Granted from 01/04/2022 - 31/03/2027	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
91	390 of 2023	Jai Bajrang Bali Stone Crusher, Khasra no. 23/1/2, 10 Vill-Gangutana, Narnaul 27.8796 76.060307	414 dated 25.07.06	06.01.2009	Granted from 01/04/2022 - 31/03/2027	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently

92	391 of 2023	DEV STONE CRUSHER, M. No. 53, Kila No. 16/1(4-8), 16/2(34) & M.No. 52, Kila No. 20/2(1-12) Total 9 Kanal 4 Marla at Village-Begopur, Nangal Chaudhary, Distt-Mohinergarh 27.926883 76.052708	313129218MAHCT E4998498 dated 15.02.18	08.01.2019	Granted from 01/04/2023 - 31/03/2028	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
93	391-392 of 2023	DEVA STONE CRUSHER, Khewat No. 6, Khatoni NO. 6, M.No. / Kila No. 7//22/1 (7-04) & 22//2/2/1 (4-16) total 12 Kanal 0 Marla at Vill-Berundla, Nangal Chaudhary Distt-Mohindergarh 27.95301 76.0788	313129218MAHCT E5590990 dated 16.08.18	04.06.2022	Granted from 04/06/2022 - 31/03/2027	-	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
94	395 of 2023	NEW SIDDHI VINAYAK STONE CRUSHER, Khewat No. 37, Khatoni No. 41, M.No. 25, Kila No. 17 (8-0), 24(2-16) & 25 min West (1-4) Total 12 Kanal 0 Marla, Vill-Khatoli Ahir, Nangal Chaudhary, Distt-Mohindergarh 27.960682 76.080892	313129218MAHCT E5285231 dated 04.05.18	15.08.2018	Granted from 01/04/2023 - 31/03/2028	85 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
95	396 of 2023	SHREE VINAYAK STONE CRUSHER Khewat No. 8, Khata No. 8, M.No. 42, Kila No. 19/2(5-6), 20/1 (4-12), 21/2 (4-11) 22/1 (4-11) At Village-Kultajpur, Tehsil-Narnaul, District-Mohindergarh 28.04605 76.051	313129217REWCT E4616727 dated 26.10.17	05.10.2021	Granted from 01/04/2022 - 31/03/2025	65 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	Interim EC deposited of Rs. 20.0 Lakhs by the unit.	NA	Unit is complying presently
96	436 of 2023	LAXMI VISHNU STONE CRUSHING COMPANY, Khewat No. 10, Khatoni NO. 22, Kila No. 31//5(8-0) & 30//1(1-10), At Village-Jainpur, Tehsil-Nangal Chaudhary, District-Mohindergarh 27.909284 76.092529	HSPCB/DHR/2017/2142 dated 03.10.2017	10.08.2018	Granted from 01/04/2023 - 31/03/2028	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	30 days	Imposed EC of Rs. 1,87,500/- Vide order dated 09.05.2023 and the same was deposited by the unit. Also, Interim EC deposited of Rs. 20.0 Lakhs.	NA	Unit is complying presently
97	438 of 2023	Shree Shyam Stone Crusher, KHEWAT NO. 36, KHATONI NO. 88, M.NO. 43, KILA NO. 16/2 (6-0) & 17(6-0), AT VILLAGE-GARHI, DISTRICT-MOHINDERGARH 28.43491 76.1137	HSPCB/DHR/2017/2093 dated 26.09.17	11.07.2018	Granted from 01/04/2023 - 31/03/2028	150 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	NA	NA	NA	NA	Unit is complying presently
98	674 of 2023	Baba Jethu Ji Stone Crusher, Khasra/ kila no. 18/19, Vill. Gangutana, Mohindergarh 27.87897 76.05966	527 dated 11.08.06	21.08.2013	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection
99	739 of 2023	RAO STONE CRUSHER, Khewat No. 5, Khatoni NO. 5, M.No. / Kila No. 23//10/2 min West South(0-2), 23//11 Min West South (2-6), & 24//15 Min East South(7-9) total 9 Kanal 17 Marla at Vill-Khatoli Ahir, Nangal Chaudhary, Distt-Mohindergarh 27.9622 76.082992	313129218MAHCT E5495862 dated 27.07.18	17.02.2020	Granted from 01/04/2022 - 31/03/2027	100 feet	Not provided adequate arrangement	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Not provided adequate sprinklers	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Not operational	Recommendation for Closure sent to Head Office	NA	NA	Recommendation for Closure sent to Head Office	Recommendation for Closure sent to Head Office

100	Baba Jamna Giri Stone Crusher Khewat No. 121, Khatoni No. 190, M.No. 49, Kila No. 18 at Vill-Garhi, DisttMohindergarh 28.432052 76.111387	2817716MAHCTE3 140134 dated 04.07.16	09.11.2016	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Unit found dismantled from the site	Unit found dismantled from the site
101	Balaji Stone Crusher Khewat No. 23, Khatoni No. 57, M.No. 49, Kila No. 17(8-0) at Vill-Garhi, Distt-Mohindergarh 28.433475 76.111387	2817716MAHCTE3 138720 dated 04.07.16	29.11.2016	CTO Revoked	-	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	CTO Revoked	CTO Revoked
102	Bhagwati Stone crusher, Kita no. 45/8/2/2, 9/1, 10/1, Vill. Mandiana, Distt-Mohindergarh 28.08837 76.078608	1443 dated 10.12.2004	30.03.2013	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	Closure order issued vide order No. I/129407/2022 dated 16.08.2022	174 days	Imposed EC of Rs. 10,87,500/- Vide order dated 28.11.2022 and the same was not deposited by the unit till date.	Closed by Board	Closed by Board
103	Bharat Stone Crusher, Khasra/ kila no. 44/14/1, 15/2/1 Vill-Garhi, Mohindergarh 28.432936 76.111341	434 dated 26.07.06	11.12.2007	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	Closure order issued vide order No. 43457064CO NCO001 dated 04.09.2023	NA	NA	Closed by Board	Closed by Board
104	Chhawri Stone Crusher, Khewat No. 9, Khatoni NO. 38, M.No. 8, Kila No. 7/2 & 8/1 at Vill-Bakhrija, Narnaul, Distt-Mohindergarh 27.922181 76.051442	2817716MAHCTE3 174900 dated 04.07.16	23.07.2017	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	Closure order issued vide order No. 549-52 dated 22.09.2020	81 days	Imposed EC of Rs. 5,06,250/- Vide order dated 28.11.2022 and the same was not deposited by the unit till date.	Closed by Board and Prosecution case filed in Special Environment Court, Faridabad	Closed by Board and Prosecution case filed in Special Environment Court, Faridabad
105	Deepak Construction Co., Khasra No. 211, Vill Raghunathpura, Distt. Mohindergarh 28.07425 76.07761	Not available in the record dated Not available in the record	19.07.2004	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	Closure order issued vide order No. 619-621 dt. 19-05-2014	NA	NA	Closed by Board and Prosecution case filed in Special Environment Court, Faridabad	Closed by Board and Prosecution case filed in Special Environment Court, Faridabad
106	Godara Stone Crusher Rect/Kila Nos. 14, 15, 6 total 17 Kanal 6 Marla Vill-Garhi, Distt-Mohindergarh 28.431036 76.103964	1225-27 dated 11.05.11	06.05.2015	Granted from 28/04/2022 - 31/03/2027	-	-	-	-	-	-	-	-	-	Not operational	Closure order issued vide order No. 44278365CO NCO001-005 dated 19.09.2023	NA	NA	Closed by Board	Closed by Board
107	Hydel Construction Pvt. Ltd & Mobile Drill Master (Joint Venture) -HMJV Khewat No. 171, Khatoni No. 232 & 235, Mustil No. 43/1/1 (6-16), 44/4(7-11) 5 (7-11), 7/2 total 26 kanal Village-Kultajpur, Narnaul Distt-Mohindergarh 28.048477 76.064263	1259 dated 01.06.11	21.08.2013	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection
108	Jai Hanuman Stone Crusher Khewat No. 23, Khatoni NO. 56, Kila No. 49//6/2(8-0) at Village Garhi, DistrictMohindergarh 28.43046 76.10057	313129217MAHCT E4150302 dated 10.08.17	26.12.2017	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Unit found dismantled from the site	Unit found dismantled from the site

109	Jai Maa Kamakhaya Industries (Superb Star Promoters Private Limited), Khewat No. 20, Khatoni No. 22, Kila No. 30/3 (5-16) & 4(3-16) Vill-Gangutana, Nangal Chaudhary Distt-Mohindergarh 27.87607 76.058621	2817715MAHCTE1 590358 dated 02.02.15	22.09.2015	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	Closure order issued vide order No. I/129649/2022 dated 17.08.2022	NA	NA	Closed by Board	Closed by Board
110	Jai Mata Di Stone Crusher (Formerly Jagdamba Stone Crusher), Khewat no. 16, khatoni no. 48, kila no. 7/19,20 Vill. Bakhrija, Narnaul Distt-Mohindergarh 27.90999 76.08419	929 dated 01.03.06	21.08.2013	CTO Revoked	-	-	-	-	-	-	-	-	Not operational	Closure order issued vide order No. 440-443 dated 03.09.2020	NA	NA	Closed by Board	Closed by Board
111	K S Y BUILDCON, Khewat No. 50, Khatoni NO. 72, M.No. 9, Kila No. 15/2/2 (2-17), 16/2 Min West (5-14) & 17/1 (0-9) total 9 Kanal 0 Marla at Village Khatoli Jat, Nangal Chaudhary, Distt-Mohindergarh 27.97287 76.08708	313129218MAHCT E5063571 dated 13.03.18	20.03.2020	CTE Revoked	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	CTE Revoked and Prosecution case filed in Special Environment Court, Faridabad	CTE Revoked and Prosecution case filed in Special Environment Court, Faridabad
112	Karni Maa Stone Crusher, Khewat No. 144, Khatoni No. 217, M.No.71, Kila No. 3(6-9) & 8(1-11) at Village Garhi, Distt-Mohindergarh 28.42997 76.099361	2817716MAHCTE3 138772 dated 04.07.16	29.11.2016	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection
113	Keshav Stone Crusher Formerly Yograj Infrastructure, Plant-III, Kila no. / Khasra no. 23//11,20, Vill. Gangutana, Narnaul 27.88029 76.06203	4059 dated 08.03.10	02.04.2014	CTO Revoked	50 feet	Not provided adequate arrangement	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Not provided adequate sprinklers	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Not operational	NA	NA	NA	CTO Revoked	CTO Revoked
114	Krishna Arjun Buildtech Pvt. Ltd., Khewat No. 14, Khatoni No. 43, 44, Mustil & Kila No. 14 / / 11/2(3-15), 19(2-10), 22(2-18), 12(5-4), 13/2(3-1) Vill-Bakhrija, Narnaul, Distt-Mohindergarh 27.9193 76.054323	1265 dated 01.06.11	30.03.2012	CTO Revoked	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	CTO Revoked	CTO Revoked
115	KSY Grit Udyog, Khewat no. 182, khatoni no. 209, 57//14-1(0-17), 15/1(4-5), 15/2(1-5), Total 6 kanal 7 Marla & 57//14/2(3-2), 57//7(5-18) total 9 kanal 0 marla Vill.- Begopur, Narnaul 27.9247 76.056188	1601 dated 06.12.05	30.03.2012	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Unit found dismantled from the site	Unit found dismantled from the site
116	Maa Durga Stone Crusher, Khasra No. 11/1/2(3-8), 11//2 (7-11) Vill-Khatoli Ahir, Distt-Mohindergarh 27.96628 76.08047	1423 dated 04.03.2004	21.08.2013	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Unit found dismantled from the site	Unit found dismantled from the site
117	Maa Sherawali Stone Crushing Co Khewat No. 163, Khatoni No. 228, Kila no. 24/23, 25/3,4, 58/2/2,3,18/4/2 Vill Zerpur, Distt-Mohindergarh 28.318989 76.090193	2817715MAHCTE2 300599 dated 28.10.15	25.01.2016	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection

118	Mungipa Stone Crusher, Khewat No. 18, Khatoni No. 20, Kila No. 12/2, 110/3, 18/3/9 village Zerpur, Mohindergarh 28.318993 76.090963	4264 dated 31.03.13	04.05.2015	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Unit found dismantled from the site	Unit found dismantled from the site
119	Pooja Milling And Crushing Unit Mustil No-23, Kila No.16, Village-Gangutana, Nangal Choudhary, Distt.Mohindergarh 27.8776 76.06146	2817714MAHCTE1 350984 dated 10.11.14	07.10.2015	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Unit found dismantled from the site	Unit found dismantled from the site
120	Rathi Stone Crusher Co., Khasra no./ kila no. 30//18 Vill- Gangutana, Mohindergarh 27.8748 76.05732	614 dated 30.08.07	30.03.2012	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection
121	Sadashiv Stone Crusher, Kila no. 76/5, 70/21, 77/1,2 khewat no. 6, khatoni no. 18 VIII-Garhi Khudana, Distt-Mohindergarh 28.426171 76.102493	802-06 dated 02.03.06	21.10.2008	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	Closure order issued vide order No. 542 dated 21.09.2020	NA	NA	Closed by Board and Prosecution case filed in Special Environment Court, Faridabad	Closed by Board and Prosecution case filed in Special Environment Court, Faridabad
122	Shivam Stone Crushing Company, Khewat No. 19, Khatoni No. 21, Mustil & Kila No. 30//8/1(9-18), 9/1(0-17) Village Gangutana Tehsil Narnaul District Mohindergarh 27.875812 76.05754	2817715MAHCTE2 320784 dated 28.10.15	16.02.2018	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Unit found dismantled from the site	Unit found dismantled from the site
123	Shree Balaji Stone Crusher, Kila no. 19/2, 9, 10, 11/1, khewat no. 4,5,6 Village Jainpur, Narnaul Distt.- Mohindergarh 27.90913 76.08468	1123 dated 09.11.06	30.03.2013	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	Closure order issued vide order No. 4115 dated 19.05.2017	NA	NA	Closed by Board	Closed by Board
124	Shree Ganesh Stone Crusher, Khasra no. / kila no. 18/21 (7-4) & 23/1 (1-4) Vill- Gangutana, Narnaul, Distt. Mohindergarh 27.8794 76.05966	239 dated 29.06.06	21.08.2013	CTO Revoked	-	-	-	-	-	-	-	-	-	Not operational	Closure order issued vide order No. 37935123CO NCO001-004 dated 18.08.2023	NA	NA	Closed by Board	Closed by Board
125	Shree Shyam Stone Crusher, Khewat no. 19, khatoni no. 21, kila no. 109/14/2, 17 (2-0) (7-9) Vill.-Zerpur Madola, Mohindergarh 28.318989 76.090193	925 dated 16.03.06	05.12.2006	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Unit found dismantled from the site	Unit found dismantled from the site
126	SHRI VINAYAK STONE CRUSHER, Khewat No. 10, Khatoni No. 10, M.No. 28, Kila No. 1 (8-0) & 10 min North (4-0) Total 12 Kanal 0 Marla at VIII-Berunda, Tehsil-Nangal Chaudhary, Distt-Mohindergarh 27.954878 76.080504	313129218MAHCT E5183051 dated 26.03.18	28.12.2018	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	Closure order issued vide order No. 288-91 dated 22.06.2020	133 days	Imposed EC of Rs. 8,31,250/- Vide order dated 20.12.2022 and the same was not deposited by the unit till date.	Closed by Board and Prosecution case filed in Special Environment Court, Faridabad	Closed by Board and Prosecution case filed in Special Environment Court, Faridabad
127	SURYA STONE CRUSHER Khewat No. 23, Khatoni No. 56, M.No. 50, Kila No. 10/2/2(7-6), 11/1(7-01), 9/3/2(0-14), 12/1/1(0-8) Total 15 Kanal 09 Marla at Village-Garhi, District-Mohindergarh 28.42871 76.09925	313129217MAHCT E4702342 dated 08.12.17	14.05.2018	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Unit found dismantled from the site	Unit found dismantled from the site

128	T & R Milling and Crushing Unit Mustil No. 23, Kila No. 3, Vill Gangutana, Narnaul Mohindergarh 27.877857 76.059546	2817714MAHCTE9 25833 dated 09.06.14	03.04.2015	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection
129	T & R STONE CRUSHER, Mustil No. 23, Kila No. 2, VILLAGE-GANGUTANA, NAGAL CHODHARY, NARNUAL, Mohindergarh 27.877857 76.059546	2817714MAHCTE9 32804 dated 09.06.14	03.11.2015	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection
130	Universal Stone Crusher, Khewat No. 16, Khatoni No. 29, Kila No. 19//4(2-16), 6(4-5), 7(8-0), 14(8-0), 15/1(5-0), 17(7-11) Vill-Jainpur, Distt-Mohindergarh 27.90875 76.08591	1295 dated 11.11.05	01.10.2012	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection
131	Vinayak Stone Crusher, Khasra no. 82 Min (24-0) VPO- Jainpur, Narnaul, Distt-Mohindergarh 27.9099 76.09248	679-82 dated 14.08.04	06.11.2007	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Unit found dismantled from the site	Unit found dismantled from the site
132	Vishal Stone Crusher, Khewat no. 13, khatoni no. 26, Kila no. 19//14, min (4-5) & 17(7-11) Vill.-Jainpur, Narnaul, Distt. Mohindergarh 27.907128 76.086277	1291 dated 11.11.05	30.03.2013	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection
133	Yog Milling And Crushing Unit Mustil no.-23,Kila no.-15,Village-Gangutana, Nangal Choudhary, Narnaul Mahendragarh 27.8779 76.06146	2817714MAHCTE9 33153 dated 09.06.14	07.10.2015	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	NA	NA	NA	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection