

<b>INDEX</b>		
<b>Sr. No.</b>	<b>Particulars</b>	<b>Page No.</b>
1.	Report in matter of OA NO. 607/2018 (VINOD KUMAR JANGRA VERSUS STATE OF HARYANA AND ORS.)	1
2.	Annexure-1	5

**12492**

**BEFORE THE NATIONAL GREEN TRIBUNAL**

**PRINCIPAL BENCH NEW DELHI**

**OA NO. 607/2018 (VINOD KUMAR JANGRA VERSUS**

**STATE OF HARYANA AND ORS.)**

**AS PER HON'BLE NGT ORDER DATED 23.11.2023**

**Hon'ble NGT passed the following directions in order dated 23.11.2023 in OA NO. 607/2018 (Vinod Kumar Jangra Versus State of Haryana And Ors.): -**

"9. Since, new stone crusher units have been impleaded today, therefore the Counsel for the HSPCB is directed to examine the compliance of newly impleaded stone crusher units in terms of the direction of the Tribunal contained in the previous order. He is also directed to examine the date of setting up of all the respondent crusher units, the date of closure, if any and the violation of environmental norms for the past period by the concerned units. Some of the applicants have taken the plea that though they had set up the unit but they never operated it. This plea of such applicant be also examined by the HSPCB on the basis of the available record and on the basis of the spot inspection. In view of this, Counsel for the HSPCB is directed to file further report disclosing the relevant details in the updated chart about each of the unit. Let the same be filed within a period of eight weeks by email at [judicial-ngt@gov.in](mailto:judicial-ngt@gov.in) preferably in the form of searchable PDF/ OCR Support PDF and not in the form of Image PDF.

10. Since, a large number of IAs have been filed, therefore, we also direct the Counsel for the applicants to tabulate the information in the chart form in respect of each applicant they are representing and by giving details of the applicants, the date of setting up of the unit by the applicant, the position of CTE/CTO and also the compliance status along with the geo-coordinates of the units. Let the same be filed within four weeks.

11. We have also heard learned Counsel for all the applicants present today in respect of their other prayers in the IAs which are mainly relating to recall of the order dated 18.01.2023. Learned Counsel for the applicants have advanced following arguments in support of their plea to recall the order dated 18.01.2023:-

i. The carrying capacity of the area concerned needs to be reexamined by the Tribunal.



ii. The units have now developed green belt, therefore, their current compliance status needs consideration.

iii. Some of the units had never started operation, therefore, they cannot be treated to be defaulter for the past period.

iv. The units are complying with the environmental norms, therefore, they are not liable to pay EC.

v. The calculation of interim compensation be done on the basis of the default period and not uniformly."

**Action Taken Report dated 30.01.2024 in compliance with Hon'ble National Green Tribunal, Principal Bench, New Delhi order dated 23.11.2023 in the matter of OA NO. 607/2018 (Vinod Kumar Jangra Versus State of Haryana and Ors).**

The stone crushers are located in the district of Charkhi Dadri, Haryana in the various villages of 02 Nos. of Tehsil namely (i) Charkhi Dadri (ii) Bhadra and mainly in five major cluster in District Charkhi Dadri. There are total 343 Nos. stone crushing units in district Charkhi Dadri as per order of Hon'ble NGT since 2013. The Action Taken Report in compliance with the above directions, passed by Hon'ble National Green Tribunal, New Delhi, is as under:-

1. In compliance of Order dated 23.11.2023, the status of stone crushing units located in District Charkhi Dadri are summarized as below:

A.	Units found Complying as per provision of notification dated 11.05.2016	233
B.	Units found non-complying as per provision of notification dated 11.05.2016	110
	(i). Recommended for closure action to Head Office	04
	(ii). Units closed by Board	27
	(iii). Units found dismantled	70
	(iv). Plant & Machinery not installed	9

	and CTE expired	
--	-----------------	--

2. The requisite information of 343 stone crushing units in tabular form regarding detail of IAs filed by individual stone crusher, name and address of the unit & GPS Coordinate, CTE details, date of establishment/ setting up of the Stone Crusher (Grant of CTE), date of first operation after establishment (First CTO Granted to Stone Crusher), latest CTO status with validity, Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher ), status of compliance in respect of the pollution norms as per notification dated 11.05.2016, Operational Status, Production capacity as per latest CTO and as per on site conditions, Violation of environmental norms in past period, if any, Environment Compensation Status for the past violation & compliance status of stone crusher units as per notification dated 11.05.2016 is attached as **Annexure R-1**.
3. The Environment Compensation imposed on the stone crushing units before order 23.11.2023 was Rs. 4,31,78,500/- on 60 number of stone crushing units. Further for the past violation the recommendation for levy of Environment Compensation of Rs. 1,89,38,000/- for 33 number of stone crushing units has been sent recently to Head Office.

It is humbly prayed that the above Action Taken Report may be considered please.

Dated : 30.01.2024

  
**Regional Officer**  
**HSPCB, Charkhi Dadri**

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/ Dust containment system/ .	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/ separate energy meter/ logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
1	8	Shree Balaji Stone Crusher, Village Kaliyana, Charkhi Dadri, Latitude : 28.570603 , Longitude : 76.264	Granted vide No. 3329046 dated 30.08.2016	30.08.2016	8/1/2018	17.02.21-31.03.25	100 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 740 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 325 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 156 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2500 MTD	NA	NA	NA	NA	Unit is complying presently
2	9	Rao Stone Crusher Co., Village Kaliyana, Charkhi Dadri, Latitude : 28.55752 , Longitude : 76.201481	Granted vide No. 3313572 dated 03.08.2016	03.08.2016	12.07.2017	08/01/2024 - 31/03/2028	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 220 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 315 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	700 MTD	Issued vide letter No. 4089 dated 13.03.2020 & No. HSPCB/0500 04/61/2020-Publicity Cell HSPCB 07.12.2021	27 days (18.01.2020 to 13.02.2020 )	Imposed EC of Rs. 168750 Vide order dated 16.08.2023 and deposited Rs. 168750	NA	Unit is complying presently
3	10	Zamidar Stone Crusher Village Kaliyana, Charkhi Dadri , Latitude : 28.573868 , Longitude : 76.207194	Granted vide No. 3195809 dated 27.06.2016	27.06.2016	29.07.2018	01.04.23-31.03.28	65 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 185 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 270 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 155 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	450 MTD	NA	NA	NA	NA	Unit is complying presently
4	11	New Baba Sita Nath Stone Crusher, Village Kaliyana, Charkhi Dadri , Latitude : 28.57026 , Longitude : 76.20651	Granted vide No. 2313498 dated 10.10.2015	10.10.2015	18.03.2016	09/01/2024 - 31/03/2028	100 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 287 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 386 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 156 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	600 MTD	Issued vide No. 1/36829/2021 dated 26.04.2021	18.01.2020 to 13.02.2020 ( 13.5 Days) as there was ban from 6:00PM to 6:00 AM as per EPCA direction	Imposed EC of Rs. 81375/- Vide order dated 25.11.2022 and deposited Rs. 81375/-	NA	Unit is complying presently
5	12	Pardhan Stone Crusher Village Kaliyana, Charkhi Dadri , Latitude : 28.5731267 , Longitude : 76.20173	Granted vide No. 5082 dated 05.11.2017	05.11.2017	21.08.2018	28.10.21-31.03.26	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 205 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 250 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1950 MTD	issued vide letter No. 4123 dated 13.02.2020 & vide letter No. HSPCB-050004/6/2021 - Publicity Cell HSPCB dated 31.08.2021	92 days ( 23.03.2019 to 13.02.2020 Grap period (22 days) - close its own (61+153 days)	Imposed EC of Rs. 575000 Vide order dated 09.02.2021 and deposited Rs. 575000 on dated 17.02.2021	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
6	13	New Bharat Stone Crushing Company, VPO PICHOPA KALAN, Charkhi Dadri , Latitude : 28.552265 , Longitude : 76.082644	Granted vide No. 5082751 dated 23.02.2018	23.02.2018	22.01.2019	01.04.23-31.03.28	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 225 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1200 MTD	NA	NA	NA	NA	Unit is complying presently
7	14	Abhishek Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.56432 , Longitude : 76.18638	Granted vide no. 487 dated 02.08.2006	02.08.2006	30.03.2007	01.04.21-31.03.26	35 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 240 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 360 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 130 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	400 MTD	NA	NA	NA	NA	Unit is complying presently
8	15	Bhagwati Stone Crusher, Vill, Kheri Battar, Charkhi Dadri , Latitude : 28.5645 , Longitude : 76.18822	Granted vide No. 351 dated 17.07.2006	17.07.2006	31.03.08	30.01.21-31.03.25	62 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 325 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 370 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1800 MTD	Issued vide No. 4093 dated 13.02.2020	17.01.2020 to 16.02.2020 (15.5 Days) as there was ban for 06:00 PM to 06:00AM as per EPCA directions	Imposed EC of Rs. 96875 Vide order dated 25.11.2022 and deposited Rs. 96875	NA	Unit is complying presently
9	16	Pokhar Stone Crusher, Vill, Kheri Battar, Charkhi Dadri , Latitude : 28.56368 , Longitude : 76.18484	Granted vide letter No. 116 dated 16.06.2006	16.06.2006	30.03.2007	01.04.21-31.03.26	38 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 350 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 315 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1800 MTD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
10	17	QEM Processing Pvt Ltd., Pichopa Kalan, Charkhi Dadri, Latitude : 28.551736 , Longitude : 76.085414	Granted vide No. 3732442 dated 30.01.2017	30.01.2017	28/07/2019	01/04/2024 - 31/03/2029	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 380 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 337 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 145 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2600 MTD	NA	NA	NA	NA	Unit is complying presently
11	18	Vijay Stone Crusher, Village Pichopa kalan, Charkhi Dadri, , Latitude : 28.54935 , Longitude : 76.09084	Granted vide No. 2059 dated 29.09.2008	29.09.2008	23.03.2012	01.04.21- 31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 290 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 145 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1500 MTD	NA	NA	NA	NA	Unit is complying presently
12	19	Sohna Aggregate Solutions Vill Pichopa Kalan Charkhi Dadri , Latitude : 28.551836 , Longitude : 76.079544	Granted vide No. 5509105 dated 17.07.2018	17.07.2018	24.10.2019	30.01.2024 to 31.03.2026	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 240 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 261 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1250 MTD	NA	NA	NA	NA	Unit is complying presently
13	20	Soorya Stone Crusher Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.551836 , Longitude : 76.084153	granted vide No. 4793845 dated 20/12/2017	20/12/2017	9/8/2018	01/04/2024 - 31/03/2029	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1400 MTD	Issued vide No. 4197 dated 14.02.2020	19.01.2020 to 19.02.2020 ( 15 Days) as there was ban for 6:00 PM to 6:00 AM as per EPCA Direction	Imposed EC of Rs. 100000 Vide order dated 25.11.2022 and deposited Rs. 100000	NA	Unit is complying presently
14	21	Saraswati Stone Crusher, Vill Kheri Battar, Charkhi Dadri , Latitude : 28.568261 , Longitude : 76.184435	Granted vide No.107 DATED 16.06.2006	16.06.2006	31.03.2008	01.04.21- 31.03.26	58 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 310 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 280 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 138 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2000 MTD	NA	NA	NA	NA	Unit is complying presently




Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/ Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/ separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
15	22	Triupati Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.84816 , Longitude : 76.54641	Granted vide letter No. 556 dated 01.02.2006	01.02.2006	23.03.2012	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	NA	NA	NA	NA	Dismantled
16	23	R.B.S Stone Crusher Village Kaliyana, Charkhi Dadri , Latitude : 28.57092 , Longitude : 76.20239	Granted vide No. 2943 dated 22.09.11	22.09.11	15.03.2014	30.01.2024 to 30.03.2028	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 260 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 325 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 90 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	700 MTD	Issued vide No. 4411 dated 27.07.2020	25.02.2018 to 07.03.2020 = 742-89.5 (GRAP period)=65 2.5 days	Imposed EC of Rs. 153125 Vide order dated 25.11.2022 and deposited Rs. 153125 on dated 26.05.2023	NA	Unit is complying presently
17	24	Royal Stone Crusher Village Kaliyana Distt Charkhi Dadri , Latitude : 28.5522 , Longitude : 76.1972	Granted vide No. 3454 dated 27.09.2017	27.09.2017	28/05/2022	09/01/2024 - 31/03/2028	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 340 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 325 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 107 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	750 MTD	NA	NA	NA	NA	Unit is complying presently
18	25	Shree Luxmi Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.56728 , Longitude : 76.1842	Granted vide no. 296 dated 01.02.2008	01.02.2008	30.03.2013	08/01/2024 - 31/03/2028	27 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	850 MTD	NA	NA	NA	NA	Unit is complying presently

# 12500

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
19	26	Pal stone Crusher Vill. Atela Kalan Charkhi Dadri , Latitude : 28.57497 , Longitude : 76.09651	granted vide no. 495 dated 3.08.06	03.08.06	31.03.08	01.04.21-31.03.26	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 300 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 320 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2400 MTD	NA	NA	NA	NA	Unit is complying presently
20	27	Pardhan Stone Crusher Village Pichopa Kala Charkhi Dadri , Latitude : 28.554161 , Longitude : 76.089974	Granted vide No. 3391185 dated 27.09.2016	27.09.2016	4/12/2017	Not having valid CTO & dismantled	40 feet	Unit was found dismantled at the time of inspection	Unit was found dismantled at the time of inspection	Unit was found dismantled at the time of inspection	Unit was found dismantled at the time of inspection	Unit was found dismantled at the time of inspection	Unit was found dismantled at the time of inspection	Unit was found dismantled at the time of inspection	Unit was found dismantled at the time of inspection	Non-operational	NA	NA	NA	NA	NA	Dismantled
21	28	Maman Stone Crusher, VPO Kheri Battar, Charkhi Dadri , Latitude : 28.56447 , Longitude : 76.18577	Granted vide No. 1524 dated 08.02.2006	08.02.2006	30.03.2007	24/01/2024 - 31/03/2028	38 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 285 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	450 MTD	NA	NA	NA	NA	Unit is complying presently
22	29	Partap Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.56948 , Longitude : 76.18424	Granted vide No. 517 dated 08.03.2006	08.03.2006	31.03.2008	01.04.21-31.03.26	92 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 318 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 310 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 201 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1700 MTD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
23	30	Millan Stone Cusher, Village Kaliyana, Charkhi Dadri , Latitude : 28.575207 , Longitude : 76.205681	Granted vide No. 5062480 dated 05.03.2018	05.03.2018	01.07.2019	08/01/2024 - 31/03/2028	42 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 250 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	750 MTD	Issued vide letter No. 4133 dated 13.02.2020	150 Days (01.07.2019 to 18.12.2019 Grap Period 45 + 33 Days)	Imposed EC of Rs. 937500 Vide order dated 08.06.2020 and deposited Rs. 937500 on dated 09.11.2020	NA	Unit is complying presently
24	31	Mahadev grit Udyog, Pichopa Kalan, Charkhi Dadri , Latitude : 28.553237 , Longitude : 76.086766	Granted vide No. 5006 dated 17.11.2017	17.11.2017	02.07.2018	17/01/2024 - 31/03/2028	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 290 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 264 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1075 MTD	NA	NA	NA	NA	Unit is complying presently
25	32	J M and Company, Vill-Pichopa Kalan, Charkhi Dadri , Latitude : 28.552187 , Longitude : 76.083212	Granted vide No. 4651564 dated 22.11.2017	22.11.2017	01.07.2018	01.04.23- 31.03.28	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 220 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 160 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	400 MTD	NA	NA	Na	NA	Unit is complying presently
26	33	Ajanta Stone Crusher, Vill. Atela Kalan, Charkhi Dadri , Latitude : 28.5771 , Longitude : 76.10196	Granted vide No. 1749 dated 25.09.1991	25.09.1991	29.01.2009	Not having valid CTO & Closed by Board	40 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	70 MTD	Closure order issued vide no. 986 dated 17.07.2013	NA	NA	Unit has been closed by the Board	Unit has been closed by the Board
27	34	Shree Nanak Stone Crusher, VPO Kheri Battar, Charkhi Dadri , Latitude : 28.56557 , Longitude : 76.18495	Granted vide No. 286 dated 22.05.2008	22.05.2008	30.03.2013	08/01/2024 - 31/03/2028	15 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 410 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 365 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 160 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	900 MTD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
28	35	Shree Balaji Stone Crusher, Village Bilawal, Charkhi Dadri , Latitude : 28.57579 , Longitude : 76.09317	Granted vide No. 3384200 dated 29.10.2016	29.10.2016	19.01.2017	01.04.21-31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 305 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 380 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 128 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1400 MTD	NA	NA	NA	NA	Unit is complying presently
29	36	Shivji Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.5325832 , Longitude : 76.0756637	Granted vide No. 3442090 dated 26/10/2016	10/26/2016	9/22/2017	17/01/2024 - 31/03/2028	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 260 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 160 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	750 MTD	Issued vide No. 4814 dated 06.05.2020	NA	NA	NA	Unit is complying presently
30	37	Shiv Stone Crusher, Vill. Atela Kalan, Charkhi Dadri , Latitude : 28.57457 , Longitude : 76.09589	Granted vide No. 1581 dated 29.12.2003	29.12.2003	31.03.2008	27.04.20-31.03.25	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 280 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 285 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2400 MTD	NA	NA	NA	NA	Unit is complying presently
31	38	Shiv Stone Crushing Co., Village Pichopa kalan, Charkhi Dadri , Latitude : 28.55091 , Longitude : 76.08968	Granted vide No. 102 dated 16.06.2006	16.06.2006	31.03.2008	01.06.20-31.03.25	60 feet	Unit was found dismantled at the time of inspection	Unit was found dismantled at the time of inspection	Unit was found dismantled at the time of inspection	Unit was found dismantled at the time of inspection	Unit was found dismantled at the time of inspection	Unit was found dismantled at the time of inspection	Unit was found dismantled at the time of inspection	Unit was found dismantled at the time of inspection	Unit was found dismantled at the time of inspection	NA	NA	NA	NA	SCN for closure and revocation of consent to operate issued to unit vide letter no. 1133-34 Dated 07.11.2023. The unit have dismantled plant and machinery from the site.	Unit was found dismantled at the time of inspection
32	39	Satayvir Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.55032 , Longitude : 76.09043	Granted vide No. 2054 dated 29.09.2008	29.09.2008	23.03.2012	01.04.21-31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 290 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 378 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1200MTD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
33	40	QEM Processing Pvt Ltd. Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.554354 , Longitude : 76.184195	Granted vide No. 3377279 dated 29.11.2016	29.11.2016	07.02.2017	01.04.21-31.03.26	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 480 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 380 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 260 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2700 MTD	NA	NA	NA	NA	Unit is complying presently
34	41	Rakesh Malik Stone Crusher Vill-Pichopa Kalan, Charkhi Dadri. Latitude : 28.551639, Longitude : 76.08365	Granted vide No. 4698862 dated 22.11.2017	22.11.2017	26.07.2018	10/01/2024 - 31/03/2028	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 350 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 210 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 130 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1300 MTD	NA	NA	NA	NA	Unit is complying presently
35	42	Mahashay Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.554097 , Longitude : 76.082666	Granted vide No. 5127779 dated 24/02/2018	2/24/2018	7/10/2019	30.01.2024 - 31.03.2028	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 172 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	800 MTD	NA	NA	NA	NA	Unit is complying presently
36	43	Omara Mines and Crushers, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.55111 , Longitude : 76.08887	Granted vide No. 3145014 dated 09.06.2016	09.06.2016	14.06.2017	Valid upto 31.03.27 & revocation in process	60 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	450MTD	Issued vide No. 1/170150/2023 dated 29.07.2023	03.05.2023 to 29.08.2023 =119 Days	Recommended levy of EC of Rs. 743750 Vide letter no. 1531 dated 25.01.2024	Unit has been closed by the Board	Unit has been closed by the Board
37	44	Swastik Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.603337 , Longitude : 76.139204	Granted vide No. 5047883 dated 08.02.2018	08.02.2018	26.04.2019	01/04/2022 - 31/03/2027	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 385 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 115 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1000 MTD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
38	45	Krishna Stone Crusher, Vill. Pichopa Kalan, Charkhi Dadri , Latitude : 28.54935 , Longitude : 76.08884	Granted vide No. 2334 dated 03.03.2008	03.03.2008	19.03.2009	29.06.21-31.06.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 295 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 191 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1000 MTD	NA	NA	NA	NA	Unit is complying presently
39	46	Jai Ambey stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.56807 , Longitude : 76.183519	Granted vide No. 401-03 dated 04.09.2007	04.09.2007	03.05.2015	23.01.23-31.03.27	26 feet	Unit has not provided Covered sheds over machinery	Unit has not provided proper & adequate size wind breaking wall & telescopic chute as per norms	Unit has provided roads for vehicular movement within the premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 320 Plants and plantation plan obtained from DFO vide letter dated 14.01.2021 & same is also verified by DFO	Not provided sufficient number of water sprinklers	Not provided Interlocking system of water sprinkler with stone crusher machine and not maintained logbook for water & energy consumption	No vehicle reported during inspection	Non-Operational	400 MTD	Issued vide No. 1/11534/2020 dated 11.12.2020	31.01.2022 to 26.05.2022	Imposed EC of Rs. 318750 Vide order dated 29.04.22 and deposited Rs. 318750 on dated 10.05.2022	SCN for closure and revocation of consent to operate issued to unit vide letter No. 1034-35 Dated 31.10.23. The unit is lying closed of its own due to repair and has submitted under taking that unit will start operation after verification of provisions of notification. The same has also been verified by the field officer.	Unit is complying presently
40	47	Shiv Stone Crusher, Village Asewari, Charkhi Dadri , Latitude : 28.55377 , Longitude : 76.14362	Granted vide No. 1969 dated 23.01.2008	23.01.2008	19.03.2009	01.04.23-31.03.28	500 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 500 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 280 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 250 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	600 MTD	NA	NA	NA	NA	Unit is complying presently
41	48	Neelam Stone Crusher Vill Pichopa Kalan, Charkhi Dadri , Latitude : 28.551722 , Longitude : 76.084058	Granted vide No. 5096084 dated 24.02.2018	24.02.2018	26.07.2018	01.04.23-31.03.28	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 400 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 175 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2500 MTD	NA	NA	NA	NA	Unit is complying presently
42	49	Mahaluxmi Mines and Stone Crusher VPO Pichopa Kalan, Charkhi Dadri , Latitude : 28.539506 , Longitude : 76.08865	Granted vide No. 4652018 dated 02/11/2017	11/2/2017	4/30/2018	01.04.23-31.03.28	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 450 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 193 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1200 MTD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/ Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
43	50	Maha Luxmi Stone Crusher, Village Bilawal, Charkhi Dadri , Latitude : 28.57592 , Longitude : 76.09377	Granted vide No. 1267 dated 20.04.2006	20.04.2006	31.03.2013	01.04.21-31.03.26	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 440 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2400 MTD	NA	NA	NA	NA	Unit is complying presently
44	51	Krishna Stone Crusher-1, Vill. Kheri Battar Charkhi Dadri , Latitude : 28.5654866 , Longitude : 76.184395	Granted vide No. 942 dated 16.03.2006	16.03.2006	11.01.2013	01.04.21-31.03.26	32 feet	Unit has provided two shed with water sprinkler for dust suppression	Provided Wind breaking wall of about 16 feet height & 408 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 357 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 157 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1700 MTD	NA	NA	NA	NA	Unit is complying presently
45	52	Jai Balaji Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.551772 , Longitude : 76.0873	Granted vide No. 3738538 dated 18.01.2017	18.01.2017	13.01.2018	12/01/2024 - 31/03/2028	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 350 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 203 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	850 MTD	NA	NA	NA	NA	Unit is complying presently
46	53	Dharampal Stone Crusher, pichopa Kalan, Charkhi Dadri , Latitude : 28.54263 , Longitude : 76.09261	Granted vide No. 1163 dated 20.01.2004	20.01.2004	30.03.2007	01.04.21-31.03.26	170 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 265 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 333 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1500 MTD	NA	NA	NA	NA	Unit is complying presently
47	54	Dada shakti Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.551809 , Longitude : 76.081648	Granted vide 5061524 dated 09.02.2018	09.02.2018	23.11.2019	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Dismantled	NA	Issued vide No. 1/62843/821 dated 06.09.2021	183 Days (18.03.2021 to 17.09.2021 )	Imposed EC of Rs. 1150000 Vide order dated 25.11.2022 and deposited Rs. 1150000 on dated 27.12.2022	NA	Dismantled

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/Logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
48	55	Chetna Stone Crusher, Village Atela Kalan, Charkhi Dadri , Latitude : 28.57575 , Longitude : 76.0959	Granted vide No. 489 dated 22.04.2009	22.04.2009	9/27/2015	01.04.21-31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 290 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 421 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1100MTD	NA	NA	NA	NA	Unit is complying presently
49	56	Balaji Stone Crusher, Village Birhi Kalan, Charkhi Dadri , Latitude : 28.614862 , Longitude : 76.141384	Granted vide No. 3165675 dated 02/06/2016	6/2/2016	18.01.2017	01.04.21-31.03.26	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 260 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 660 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1500 MTD	NA	NA	NA	NA	Unit is complying presently
50	57	Shree Ganesh Crusher Udyog, Village Kheri Battar, Charkhi Dadri , Latitude : 28.543 , Longitude : 76.1428	Granted vide no. 215 dated 28.06.2006	28.06.2006	30.03.2007	Latest CTO granted vide No. 9283110 revoked vide order No. HSPCB-050004/737/2021 dated 04.04.2022	27 feet	Not provided proper covered sheds on all machinery	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 315 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 42 Water sprinklers for dust suppression & same are not sufficient as per norms	Interlocking system of water sprinkler system with stone crusher machine provided and not maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-Operational	1700 MTD	Closure case recommended to HO	NA	NA	Recommended for closure to HO vide letter no. 1325 Dated 05.12.2023 & same is under process	Recommended for closure to HO vide letter no. 1325 Dated 05.12.2023 & same is under process
51	58	Shiv Bhole Stone Crushing Co., Kaliyana, Charkhi Dadri , Latitude : 28.533825 , Longitude : 76.18432	Found operated without CTE, after prosecution obtained CTO on 11.01.2013	Found operated without CTE, after prosecution obtained CTO on 11.01.2013	11.01.2013	10.09.20-31.03.25	300 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 350 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 325 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 160 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2600 MTD	NA	NA	NA	NA	Unit is complying presently
52	59	Shree Ganesh Stone Crusher Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.5703 , Longitude : 76.1867	Granted vide 2023 dated 28.01.2008	28.01.2008	22.10.2018	Not having valid CTO & dismantled	-	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	NA	Issued vide No. 3129 dated 31.10.2019	16.01.2023 to 20.05.2023 =125 Days	Recommended levy of EC of Rs. 781250 Vide letter no. 1529 dated 25.01.2024	NA	Dismantled
53	60	Shree Laxmi Stone Crusher, Pichopa Kalan, Charkhi Dadri , Latitude : 28.547055 , Longitude : 76.089785	Granted vide No. 5193969 dated 22.08.2018	22.08.2018	22.11.2019	Valid upto 31.03.24 & revocation in process	90 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	1000 MTD	Issued vide No. 1/163105 dated 11.05.2023	16.01.2023 to 16.05.2023 =121 Days	Recommended levy of EC of Rs. 756250 Vide letter no. 1528 dated 25.01.2024	Unit has been closed by the Board	Unit has been closed by the Board

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
54	61	Sangwan Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.5697 , Longitude : 76.18614	Granted vide No. 828 dated 20.06.2008	20.06.2008	20.05.2009	01.04.21-31.03.26	56 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 340 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 130 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1700 MTD	NA	NA	NA	NA	Unit is complying presently
55	62	Om Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.570125 , Longitude : 76.183246	Granted vide No. 127 dated 16.06.2006	16.06.2006	31.03.2008	01.04.23-31.03.28	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 225 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-operational	NA	NA	NA	NA	NA	Unit is complying presently
56	63	Khatu Shyam Stone Crusher, Village Pichopa Kala Charkhi Dadri , Latitude : 28.53472 , Longitude : 76.083056	Granted vide No. 5042477 dated 09/02/2018	2/9/2018	04.07.2019	01.07.19-31.03.24	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 310 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 170 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1000 MTD	NA	NA	NA	NA	Unit is complying presently
57	64	Jai Durga Stone Crusher, Vill. Kheri Battar, Ch.Dadri , Latitude : 28.56876 , Longitude : 76.18543	Granted vide No. 360 dated 17.07.2006	17.07.2006	21.05.2009	01.04.21-31.03.26	48 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 260 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 340 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 188 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1000 MTD	NA	NA	NA	NA	Unit is complying presently
58	65	Bed Stone Crusher Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.551698 , Longitude : 76.087951	Granted vide No. 3279536 dated 17.08.2016	17.08.2016	20.05.2018	Valid upto 31.03.27 & revocation in process	80 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	350 MTD	Issued vide NO. 1/170152/2023 dated 01.08.2023	03.05.2023 to 29.08.2023 =119 Days	Imposed EC of Rs. 743750/- Vide order dated 27.12.2023 and deposited Rs. 743750/- on dated 08.01.2024.	Unit has been closed by the Board	Unit has been closed by the Board

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
59	66	Balaji Stone Crusher, VPO Kaliyana, Charkhi Dadri , Latitude : 28.57309 , Longitude : 76.20328	Granted vide No. 3094512 dated 21.04.2016	21.04.2016	07.01.2018	30.01.2024 - 31.03.2028	36 feet	Unit has provided shed with water sprinkler for dust suppression	Provided Wind breaking wall of about 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 450 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 80 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1100 MTD	Issued vide letter No. 4085 dated 13.02.2020 & vide No. 1/163095/2023 Dated 11.05.2023	247 days ( 26.03.2019 to 13.02.2020 (78 Days)) & 124 days (16.01.2023 to 20.05.2023 )	Imposed EC of Rs. 1543750 & 775000 Vide order dated 08.07.2020 & 20.06.2023 respectively and deposited Rs. 771900 & 775000 on dated 14.02.2020 & 20.06.2023 (Submitted 50%) & Submitted	NA	Unit is complying presently
60	67	Asawari Stone Crushing Co., Vill-Asawari Tehsil & Charkhi Dadri , Latitude : 28.553868 , Longitude : 76.142276	Granted vide No. 5728618 dated 10.11.2018	10.11.2018	2/8/2020	05.02.20- 31.03.24	100 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 500 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 535 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	300TPH	NA	NA	NA	NA	Unit is complying presently
61	68	Jai Shree Ram Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.554398 , Longitude : 76.187539	Granted vide No. 5151260 dated 10.08.2018	10.08.2018	12.05.2020	12/05/2020 - 31/03/2025	102 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 205 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1500 MTD	Issued vide No. 1/163268/2023 dated 12.05.2023	16.01.2023 to 25.05.2023 =129 days	Imposed EC of Rs. 806250 Vide order dated 20.06.2023 and deposited Rs. 806250 on dated 20.06.2023	NA	Unit is complying presently
62	69	Jai Shree Ganesh Stone Crusher Vill-Kheri Battar, Charkhi Dadri , Latitude : 28.57034 , Longitude : 76.18692	Granted vide No. 2361847 dated 20.11.2015	20.11.2015	25.04.2016	08/01/2024 - 31/03/2028	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 348 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 360 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 72 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	750 MTD	NA	NA	NA	NA	Unit is complying presently




Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
63	70	Jai Baba Sita Nath Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.57041 , Longitude : 76.18556	Granted vide NO. 12449 DATED 17.03.2009	17.03.2009	30.03.2013	16.03.21-31.03.25	56 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 380 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 370 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 138 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1700 MTD	NA	NA	NA	NA	Unit is complying presently
64	71	Jagdish Pahal Stone Crusher Village Birhi Kalan Charkhi Dadri , Latitude : 28.607937 , Longitude : 76.138801	Granted vide No. 3174496 dated 08.06.2016	08.06.2016	09.01.2017	13.01.21-31.03.26	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 330 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 138 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	200 MTD	Issued vide No. 4101 dated 13.02.2020,	25.03.2019 to 16.02.2020 = 329-45-34.5 (GRAP period) = 249.5 days	Imposed EC of Rs. 1559375 Vide order dated 17.06.2020 and deposited Rs. 1559375 on dated 03.11.2020	NA	Unit is complying presently
65	72	Jai Bajrangbali Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.56708 , Longitude : 76.1849	Granted vide No. 1650 dated 27.12.2005	27.12.2005	30.03.2007	01.04.21-31.03.26	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 350 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 408 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1700 MTD	NA	NA	NA	NA	Unit is complying presently
66	73	Vishal Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.55785 , Longitude : 76.18547	Granted vide No. 9610 dated 29.01.2009	29.01.2009	30.03.2013	01/04/2024 - 31/03/2029	42 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 305 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 305 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1100 MTD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ interlocking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
67	74	Gohana Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.5593 , Longitude : 76.18896	Granted vide No. 3065349 dated 12.04.2016	12.04.2016	1/27/2018	08/01/2024 - 31/03/2028	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 185 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1100 MTD	Issued vide NO. 4654 dated 13.03.2020	NA	NA	NA	Unit is complying presently
68	75	Suryawansi Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.55385 , Longitude : 76.18701	Granted vide No. 3040915 dated 06/04/2016	4/6/2016	10/13/2017	19/01/2024 - 31/03/2028	105 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 250 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 360 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	850 MTD	NA	NA	NA	NA	Unit is complying presently
69	76	Silver Stone Crusher Village Kheri Battar Charkhi Dadri , Latitude : 28.557664 , Longitude : 76.189411	Granted vide No. 7640420 dated 01.06.2020	01.06.2020	19.05.2016	14/07/2020 - 31/03/2025	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 280 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 90 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1800 MTD	NA	NA	NA	NA	Unit is complying presently
70	77	Shri Shyam Stone Crusher Village Kaliyana Charkhi Dadri , Latitude : 28.533912 , Longitude : 76.179481	Granted vide No. 3130263 dated 02.06.2016	02.06.2016	26.07.2018	09/01/2024 - 31/03/2028	35 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 225 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 325 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 128 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1200 MTD	Issued vide No. 4145 dated 13.02.2020	NA	NA	NA	Unit is complying presently
71	78	Shree Maha Luxmi Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.568555 , Longitude : 76.184065	Granted vide No. 1093 dated 05.10.2005	05.10.2005	31.03.2008	01.04.21- 31.03.26	84 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 410 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 385 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2250 MTD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
72	79	Durga Stone Crusher Mills, Village Kaliyana, Charkhi Dadri , Latitude : 28.57244 , Longitude : 76.20219	Granted vide No. 499 dated 03.08.2006	03.08.2006	29.01.2009	25.10.21-31.03.26	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 278 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 296 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 196 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	750MTD	Issued vide no. 4385 dated 26.02.2020	261.5 days (23.03.2019 to 07.03.2020 Grap preid &Covid 19 (45+44.5D ays)	Imposed EC of Rs. 156000/- Vide order dated 28.11.2022 and deposited	NA	Unit is complying presently
73	80	Diamond Stone Crusher Village Kheri Battar, Charkhi Dadri , Latitude : 28.55559 , Longitude : 76.18394	Granted vide No. 2347938 dated 04.11.2015	04.11.2015	5/4/2016	28.10.21-31.03.26	54 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 245 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2000 MTD	Issued vide No. HSPCB-050004/530/2021 - PUBLICITY CELL-HSPCB Dated 30.09.2021	NA	NA	NA	Unit is complying presently
74	81	Bijender Singh Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.56848 , Longitude : 76.18196	Granted vide No. 577 dated 17.08.2006	17.08.2006	30.03.2007	24/01/2024 - 31/03/2028	95 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 270 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 340 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1000 MTD	Issued vide No. 1/163112 dated 11.05.2023	122 days ( 16.01.2023 to 18.05.2023 )	Imposed EC of Rs. 762500 Vide order dated 20.06.2023 and deposited Rs. 762500 on dated 20.06.2023	NA	Unit is complying presently
75	82	Anand Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.568192 , Longitude : 76.18293	Granted vide No. 168 dated 22.06.2006	22.06.2006	29.01.2009	08/01/2024 - 31/03/2028	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 255 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	850 MTD	NA	NA	NA	NA	Unit is complying presently




Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
76	83	Dada Syonand Maharaj Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.551608 , Longitude : 76.085955	Granted vide No. 3399560 dated 27.09.2016	27.09.2016	19.12.2017	12/01/2024 - 31/03/2028	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 300 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 180 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 99 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	900 MTD	NA	NA	NA	NA	Unit is complying presently
77	84	Hari Om Stone Crusher Pichopa Kalan , Charkhi Dadri , Latitude : 28.542551 , Longitude : 76.088542	Granted vide No. 5109170 dated 19.03.2018	19.03.2018	02.10.2019	06.05.21- 31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 180 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2000 MTD	NA	NA	NA	NA	Unit is complying presently
78	85	Sheoran Stone Crusher, Village Atela Kalan, Charkhi Dadri , Latitude : 28.57571 , Longitude : 76.09494	Granted vide No. 412 dated 20.04.2012	20.04.2012	21.01.2013	01.04.21- 31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 185 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1500 MTD	Issued vide No. 3004 dated 16.10.2019	NA	NA	NA	Unit is complying presently
79	86	MDN Stone Crusher Vill- Pichopa Kalan, Charkhi Dadri , Latitude : 28.553348 , Longitude : 76.082677	Granted vide No. 3546 dated 09.10.2017	09.10.2017	10.02.2018	01.04.22- 31.03.27	60 feet	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	NA	Unit found dismantled at the time of inspection	NA	NA	NA	Unit found dismantled at the time of inspection
80	87	Shyam Stones Vill- Pichopa Kalan, Charkhi Dadri , Latitude : 28.539039 , Longitude : 76.08998	Granted vide no. 5036881 dated 06.02.2018	06.02.2018	02.10.2019	06.05.21- 31.03.26	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 245 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 151 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 140 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2000 MTD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
81	88	Caps Tradelink Pvt. Ltd., Kheri Battar, Charkhi Dadri , Latitude : 28.556542 , Longitude : 76.184849	Granted vide No. 5131535 dated 26.03.2018	26.03.2018	7/11/2019	01/04/2024 - 31/03/2029	18 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 235 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1000 MTD	NA	NA	NA	NA	Unit is complying presently
82	89	Maha Singh Stone Crusher Village Kheri Battar Charkhi Dadri , Latitude : 28.56967 , Longitude : 76.18204	Granted vide NO. 563 dated 15.09.2005	15.09.2005	30.03.2007	31.10.21- 31.03.26	120 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 90 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1500 MTD	Issued vide No. 4623 dated 12.03.2020	NA	NA	NA	Unit is complying presently
83	90	Baniwal Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.565271 , Longitude : 76.184592	Granted vide NO. 219 dated 28.06.2006	28.06.2006	31.03.2008	Valid upto 31.03.26 & revocation in process	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	NA	Issued vide No. 4097 dated 13.02.2020	251.5 Days( 23.03.2019 to 16.02.2020 Gap Period (79.5 Days))	Imposed EC of Rs. 1575000 Vide order dated 22.01.2021 and deposited Rs. 1575000 on dated 05.04.2021	The unit was closed by board & found dismantled	The unit was closed by board & found dismantled
84	-	Alpha Stone Crusher Vill-Kaliyana, Charkhi Dadri , Latitude : 28.57206 , Longitude : 76.210626	Granted vide No. 3449582 dated 25.11.2016	25.11.2016	22.08.2018	01/04/2024 - 31/03/2029	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 320 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	800 MTD	Issued vide No. 4649 dated 13.03.2020 vide no. 1/62864/2021 dated 02.09.2021	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
85	-	Amarnath Stone Crusher Vill-Kheri Battar, Distt. Charkhi Dadri , Latitude : 28.553422 , Longitude : 76.184178	Granted vide NO. 2912737 dated 17.03.2016	17.03.2016	27.03.2017	09/01/2024 - 31/03/2028	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 205 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	750 MTD	Issued vide NO. 179 dated 24.01.2019	NA	NA	NA	Unit is complying presently
86	-	Anup Stone Crusher-1, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.56838 , Longitude : 76.17488	Granted vide No. 5562345 dated 13.08.2018	13.08.2018	04.06.2019	01.04.20-31.03.25	100 feet	Unit has not provided proper covered shed over machinery	Provided Wind breaking wall of about 16 feet height & Length not as per norms and not provided telescopic chute	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 500 Plants and plantation plan obtained from DFO & same is also verified by DFO	Unit has not provided sufficient number of water sprinklers.	Not provided Interlocking system of water sprinkler with stone crusher machine and not maintained logbook for water & energy consumption	No vehicle reported during inspection	Non-Operational	2500 MTD	NA	NA	NA	SCN for closure and revocation of consent to operate issued to unit vide letter No. 1030-31 Dated 31.10.23. The unit is lying closed of its own due to repair and has submitted under taking that unit will start operation after verification of provisions of notification. The same has also been verified by the field officer.	Unit is complying presently
87	-	Baba Ramdass Stone Crusher Village Kaliyana, Charkhi Dadri , Latitude : 28.573058 , Longitude : 76.20666	Granted vide 2356155 dated 28.10.2016	28.10.2016	29.07.2018	18.01.22-31.03.26	102 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 225 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 250 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	450MTD	Issued vide No. 4149 dated 13.02.2020	16.12.2020 to 07.01.2021	Imposed EC of Rs. 131250/- and unit has deposited.	NA	Unit is complying presently
88	-	Bhavishay Stone Crusher Village Kaliyana, Charkhi Dadri , Latitude : 28.57524 , Longitude : 76.196693	Granted vide No. 3230019 dated 28.06.2016	28.06.2016	21.08.2018	01.04.23-31.03.28	110 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 480 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 180 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	400 MTD	Issued vide No. 4125 dated 13.02.2020	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/ Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ interlocking system/ separate energy meter/ logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
89	-	Choudhary Construction Company, Village Kalayana, Charkhi Dadri , Latitude : 28.57103 , Longitude : 76.20591	Granted vide No. 2294898 dated 27.09.2015	27.09.2015	31.03.2016	08/01/2024 - 31/03/2028	105 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 215 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 87 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1000 MTD	Issued vide No. 7180 - 82 dated 19.01.2018	NA	NA	NA	Unit is complying presently
90	-	Choudhary Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.55989 , Longitude : 76.18926	Granted vide No. 17.01.2006 dated 17.01.2006	17.01.2006	13.03.2013	22.03.21- 31.03.25	110 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 310 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 98 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2500MTD	issued vide No. 2239-42 dated 03.10.2008	NA	NA	NA	Unit is complying presently
91	-	Classic Mobile Stone Crusher Village Kheri Battar Charkhi Dadri , Latitude : 28.56034 , Longitude : 76.18539	Granted vide No. 3136525 dated 19.05.2016	19.05.2016	22.08.2017	08/01/2024 - 31/03/2028	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 280 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 306 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 140 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1250MTD	Issued vide No. 4113 dated 13.02.2020	334 Days ( 20.03.2019 to 16.02.2020 Gap Period (79.5Days))	Imposed EC of Rs. 1590625 Vide order dated 17.06.20 and deposited Rs. 795313 (Submitted 50%)	NA	Unit is complying presently

# 12516

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ interlocking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
92	-	Dada Dhola Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.55251 , Longitude : 76.18755	Granted Vide No. 3901 Dated 12.09.2011	12.09.2011	21.03.2014	01.04.21-31.03.26	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 205 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 150 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2000 MTD	NA	NA	NA	NA	Unit is complying presently
93	-	Dada Ram Prasad Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.58227 , Longitude : 76.182708	Granted vide No. 9587 dated 29.01.2009	29.01.2009	30.03.2013	10.09.20-31.03.25	110 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 390 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 285 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2500 MTD	NA	NA	NA	NA	Unit is complying presently
94	-	Dada Stone Crusher, Village Kheri Battar, Tehsil Charkhi Dadri , Latitude : 28.552229 , Longitude : 76.183488	Granted vide No. 391 dated 20.04.2012	20.04.2012	14.03.2016	24/01/2024 - 31/03/2028	120 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 245 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 380 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	750 MTD	NA	NA	NA	NA	Unit is complying presently

# 12517

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/ Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ interlocking system/ separate energy meter/ logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
95	-	Dev Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.558261 , Longitude : 76.18614	Granted vide No. 11701 dated 16.02.2009	16.02.2009	30.12.2019	09/01/2024 - 31/03/2028	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 230 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	850 MTD	NA	NA	NA	NA	Unit is complying presently
96	-	Dhanpat Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.56904 , Longitude : 76.18968	Granted vide No. 4124 dated 13.01.2012	13.01.2012	13.09.2012	08/01/2024 - 31/03/2028	73 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 310 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 160 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	950 MTD	NA	NA	NA	NA	Unit is complying presently
97	-	EDDY Builders Private Limited, VPO Kheri Battar, Charkhi Dadri (Old Name Ompati , Latitude : 28.3411 , Longitude : 76.105176	Granted vide NO. 6431963 dated 19.04.2019	19.04.2019	03.08.2022	03.08.22- 31.03.27	120 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 240 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 250 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1500 MTD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
98	-	Ekta Stone Crusher Village kheri Battar, Charkhi Dadri , Latitude : 28.56886 , Longitude : 76.17724	Granted vide No. 172 dated 22.06.2006	22.06.2006	23.08.2007	01.04.21-31.03.26	90 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 90 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2000 MTD	NA	NA	NA	NA	Unit is complying presently
99	-	Jai Baba Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.56934 , Longitude : 76.18834	Granted vide No. 4123 dated 13.01.2012	13.01.2012	13.09.2012	01.04.21-31.03.26	42 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 330 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 420 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 180 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1700MTD	NA	NA	NA	NA	Unit is complying presently
100	-	Jai Mahadev Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.567074 , Longitude : 76.189924	Granted vide No. 5630967 dated 13.09.2018	13.09.2018	10/29/2019	08/01/2024 - 31/03/2028	130 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 298 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 128 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	600 MTD	NA	NA	NA	NA	Unit is complying presently
101	-	Jai Shiv Shankar Stone Crusher, VPO Kheri Battar, Charkhi Dadri , Latitude : 28.557391 , Longitude : 76.189126	Granted vide No. 202 dated 28.06.2006	28.06.2006	30.03.2013	11/06/2023 - 31/03/2028	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 357 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	400 TPD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/ Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ interlocking system/ separate energy meter/ logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
102	-	Jai Shree Shyam Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.561845 , Longitude : 76.185164	Granted vide No. 299 dated 23.07.2003	23.07.2003	11.11.2004	09/01/2024 - 31/03/2028	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 220 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 430 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	750 MTD	NA	NA	NA	NA	Unit is complying presently
103	-	Jai Siya Ram Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.57047 , Longitude : 76.18317	ranted vide No. 12450 dated 17.03.2009	17.03.2009	21.05.2009	01/04/2024 - 31/03/2028	85 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 285 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 260 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 156 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1400 TPD	NA	NA	NA	NA	Unit is complying presently
104	-	Jhandewala Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.568486 , Longitude : 76.17585	Granted vide No. 5278434 dated 25.04.2018	25.04.2018	21.03.2021	21.03.21- 31.03.25	51 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1800 TPD	NA	NA	NA	NA	Unit is complying presently




Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
105	-	Krishana Stone Crusher and Supplier Village Kheri Battar Charkhi Dadri , Latitude : 28.565286 , Longitude : 76.184301	Granted on dated 17.11.2017	17.11.2017	29.07.2018	01/04/2023 - 31/03/2028	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 220 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	4000 TPD	NA	NA	NA	NA	Unit is complying presently
106	-	Krishna Stone Crusher-II, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.564879 , Longitude : 76.186896	Granted vide No. 139 dated 20.06.2006	20.06.2006	09.01.2013	01.04.21- 31.03.26	26 feet	Unit has provided shed with water sprinkler for dust suppression	Provided Wind breaking wall of about 16 feet height & 350 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 360 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 167 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	400 TPD	NA	NA	NA	NA	Unit is complying presently
107	-	Luxmi Stone Crusher, Vill. Kaliyana, Charkhi Dadri , Latitude : 28.57339 , Longitude : 76.1976	Granted vide No. 31 dated 27.07.1993	27.07.1993	10.06.2002	08/01/2024 - 31/03/2028	250 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 205 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 325 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	850 MTD	Issued ON Dated 12.03.2020	17.01.2020 to 30.05.2020	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
108	-	Maa Stone Crusher, Kaliyana, Charkhi Dadri , Latitude : 28.57372 , Longitude : 76.20456	Granted vide No. 5796116 dated 20.01.2019	20.01.2019	15.07.2020	31.03.2023-31.03.25	110 feet	Unit has provided shed with water sprinkler for dust suppression	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 88 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	200 TPH	NA	NA	NA	NA	Unit is complying presently
109	-	Mahadev stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.56667 , Longitude : 76.18853	Granted on dated 29.01.2009	29.01.2009	06.09.2012	08/01/2024 - 31/03/2028	120 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 485 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 380 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	800 MTD	NA	NA	NA	NA	Unit is complying presently
110	-	Nandu Stone Crusher, VPO Kheri Battar, Charkhi Dadri , Latitude : 28.550901 , Longitude : 76.187666	Granted on dated 29.01.2009	29.01.2009	19.03.2009	01.04.22-31.03.27	55 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 80 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	100 MTD	NA	NA	NA	NA	Unit is complying presently
111	-	Neelkanth Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.56432 , Longitude : 76.18774	Granted vide No. 423 dated 25.07.2006	25.07.2006	13.03.2008	05.04.21-31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 315 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 75 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	600 MTD	Issued on dated 16.03.2020	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/ Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ interlocking system/ separate energy meter/ logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
112	-	New Jai Shree Bala ji Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.564214 , Longitude : 76.186811	Granted on dated 16.02.2009	16.02.2009	23.01.2016	01.04.23-31.03.28	55 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 230 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 337 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 180 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2500 MTD	NA	NA	NA	NA	Unit is complying presently
113	-	Om Shivam Stone Crusher, Kaliyana, Charkhi Dadri , Latitude : 28.573475 , Longitude : 76.200381	Granted vide NO. 5145580 dated 28.03.2018	28.03.2018	01.07.2019	23.06.21-31.03.25	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 308 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 295 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	650 MTD	Issued on dated 06.10.2021	23.07.2020 TO 08.10.2021	Imposed EC of Rs. 937500 Vide order dated 08.06.2020 not deposited EC	NA	Unit is complying presently
114	-	Parvat Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.558892 , Longitude : 76.185958	Granted vide NO. 3123146 dated 09.06.2016	09.06.2016	07.01.2020	08/01/2024 - 31/03/2028	62 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 240 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 220 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	600 MTD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ interlocking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
115	-	Pooja Stone Crusher, Village Kaliyana, Charkhi Dadri , Latitude : 28.57135 , Longitude : 76.20255	Granted vide No. 2944 dated 22.09.2011	22.09.2011	30.03.2013	06.10.21-31.03.26	22 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 850 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 325 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	400 MTD	Issued on dated 13.02.2020	19.01.2020 to 13.02.2020	Imposed EC of Rs. 81250/- Vide order dated 25.11.2022 and deposited	NA	Unit is complying presently
116	-	Prithvi Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.583434 , Longitude : 76.22989	Granted vide No. 5222088 dated 25.04.2018	25.04.2018	31.08.2020	30.08.20-31.03.25	100 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 325 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2000 MTD	NA	NA	NA	NA	Unit is complying presently
117	-	Raj Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.56249 , Longitude : 76.18851	Granted vide No. 211 dated 28.06.2006	28.06.2006	30.03.2007	01.04.21-31.03.26	120 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 205 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 365 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2500 MTD	NA	NA	NA	NA	Unit is complying presently
118	-	Rajbir Stone Crusher VPO Kheri Battar, Charkhi Dadri , Latitude : 28.557 , Longitude : 76.185	Granted vide No. 3524 dated 06.10.2017	06.10.2017	07.04.2020	25.10.21-31.03.26	58 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 348 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 490 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 260 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	4000 MTD	Issued vide No. HSPCB-050004/512/2021 dated 16.09.2021	14.07.2021 to 25.09.2021 (74 Days)	Recommendation of EC of Rs. 04,62,500/- sent to HO vide letter No. 1540 dated 25.01.2024.	NA	Unit is complying presently




Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/ Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/ separate energy meter/ logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
119	-	S K Stone Crusher, Vill- Kheri Battar, Tehsil & Distt: Charkhi Dadri , Latitude : 28.335257 , Longitude : 76.11502	Granted vide No. 20881214 dated 15.03.2022	15.03.2022	18.08.2022	18.08.22-31.03.27	38 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 550 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 248 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	4000 MTD	NA	NA	NA	NA	Unit is complying presently
120	-	Salasar Stone Crusher Vill- Kheri Battar, Charkhi Dadri , Latitude : 28.551 , Longitude : 76.186	Granted vide No. 9608 dated 29.01.2009	29.01.2009	19.03.2009	24/01/2024 - 31/03/2028	32 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 80 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	600 MTD	NA	NA	NA	NA	Unit is complying presently
121	-	Sanjay Stone Crusher, Village- Kheri Battar, Charkhi Dadri , Latitude : 28.56652 , Longitude : 76.188029	Granted vide No. 7512254 dated 04.07.2020	04.07.2020	10.02.2021	10.02.21-31.03.25	76 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 650 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2000 TPD	NA	NA	NA	NA	Unit is complying presently




Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
122	-	Sanskar Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.550327 , Longitude : 76.186378	Granted vide No. 3157559 dated 06.06.2016	06.06.2016	18.05.2017	09/01/2024 - 31/03/2028	78 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	750 TPD	NA	NA	NA	NA	Unit is complying presently
123	-	Sarvotam Group, Village Kheri Battar, Charkhi Dadri , Latitude : 28.18989 , Longitude : 76.22184	Granted vide No. 3383 dated 21.09.2017	21.09.2017	12.05.2020	24/01/2024 - 31/03/2028	220 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 560 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 180 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	800 MTD	NA	NA	NA	NA	Unit is complying presently
124	-	Shakti Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.568 , Longitude : 76.188	Granted vide No. 3241153 dated 28.06.2016	28.06.2016	14.12.2017	24/01/2024 - 31/03/2028	72 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 230 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 250 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 78 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	650 MTD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
125	-	Shanti Mobile Stone Crusher, VPO Kheri Battar, Charkhi Dadri , Latitude : 28.56072 , Longitude : 76.18582	Granted vide No. 3121536 dated 01.06.2016	01.06.2016	16.08.2017	30.01.2024 - 31.03.2028	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 220 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	800 MTD	NA	NA	NA	NA	Unit is complying presently
126	-	Sheranwali Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.56122 , Longitude : 76.18755	Granted vide No. 2091 dated 30.01.2008	20.01.2008	11.01.2013	08/01/2024 - 31/03/2028	110 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 250 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 390 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	900 MTD	NA	NA	NA	NA	Unit is complying presently
127	-	Shiv Bhole Shankar Stone Crusher Village Kheri Battar, Charkhi Dadri , Latitude : 28.57345 , Longitude : 76.19479	Granted vide No. 419 dated 25.07.2006	25.07.2006	13.03.2008	09/01/2024 - 31/03/2028	102 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 387 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 330 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 157 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	850	NA	NA	NA	NA	Unit is complying presently
128	-	Shiv Ganga Stone Crusher, Kaliyana, Charkhi dadri , Latitude : 28.573312 , Longitude : 76.201866	Granted vide No. 2599 dated 22.08.2017	22.08.2017	07.01.2018	01.04.22- 31.03.27	102 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 195 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 335 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 63 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	350 MTD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
129	-	Shiv Gorakh Stone Crusher, Vill Kheri Battar, Charkhi Dadri , Latitude : 28.56218 , Longitude : 76.18848	Granted vide No. 9622 dated 29.01.2009	29.01.2009	19.03.2009	24/01/2024 - 31/03/2028	55 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 260 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 87 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	550 MTD	NA	NA	NA	NA	Unit is complying presently
130	-	Shiv Shakti Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.832583 , Longitude : 76.0757637	Granted vide No. 468817 dated 18.01.2018	18.01.2018	06.06.2018	01/04/2023 - 31/03/2028	102 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 195 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 465 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1200 MTD	NA	NA	NA	NA	Unit is complying presently
131	-	Shiv Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.56976 , Longitude : 76.18414	Granted vide No. 207 dated 28.06.2006	28.06.2006	31.03.2008	25/01/2024 - 31/03/2028	66 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 290 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 250 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 250 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	750 MTD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
132	-	Shree Dada Dhola Stone Crusher Vill Kheri Battar, Charkhi Dadri , Latitude : 28.55251 , Longitude : 76.18755	Granted vide No. 3757403 dated 27.06.2017	27.06.2017	20.09.2018	24/01/2024 - 31/03/2028	78 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 215 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 185 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	800 MTD	NA	NA	NA	NA	Unit is complying presently
133	-	Shree Partap Stone Crusher, Kaliyana, Charkhi Dadri , Latitude : 28.573518 , Longitude : 76.199868	Granted vide No. 5062654 dated 05.03.2018	05.03.2018	13.11.2020	12.11.20 to 31.03.25	115 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 820 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	300 TPH	NA	NA	NA	NA	Unit is complying presently
134	-	Shree Ram Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.33661968 , Longitude : 76.1118.75336	Granted vide No. 2007 dated 25.01.2008	25.01.2008	30.03.2013	24/01/2024 - 31/03/2028	44 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 230 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 260 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	525 MTD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ interlocking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
135	-	Shree Satyam Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.552194 , Longitude : 76.18184	Granted on dated 29.01.2009	29.01.2009	19.03.2009	08/01/2024 - 31/03/2028	55 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 80 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	700 MTD	NA	NA	NA	NA	Unit is complying presently
136	-	Shree Shyam Grit Udyog Village Kheri Battar Charkhi Dadri , Latitude : 28.5011 , Longitude : 76.1465	Granted vide No. 423 dated 25.07.2006	25.07.2006	13.03.2008	05.04.21- 31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 315 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 75 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	600 MTD	Issued on dated 16.03.2020	25.01.2020 to 16.03.2020	NA	NA	Unit is complying presently
137	-	Shree Shyam Stone Crusher Village Kheri Battar Charkhi Dadri , Latitude : 28.552194 , Longitude : 76.18184	Granted on dated 16.02.2009	16.02.2009	23.01.2016	01.04.23- 31.03.28	55 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 230 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 337 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 40 Water sprinklers for most of them not operational due to broken pipe and water sprinklers are not sufficient as per norms	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2500 MTD	Closure case recommended to HO	NA	NA	Recommended for closure to HO vide inspection no. 52884522 dated 08.12.2023 & same is under process	Recommended for closure to HO vide inspection no. 52884522 dated 08.12.2023 & same is under process
138	-	Shri Giriraj Stone Crusher, Vill. Kheri Battar, Charkhi dadri , Latitude : 28.57041 , Longitude : 76.18381	Granted vide No. 5145580 dated 28.03.2018	28.03.2018	01.07.2019	23.06.21- 31.03.25	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 308 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 295 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	650 MTD	Issued on dated 06.10.2021	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
139	-	Shri Hari Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.552126 , Longitude : 76.187598	Granted vide No. 3123146 dated 09.06.2016	09.06.2016	07.01.2020	04.01.20-31.03.24	62 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 240 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 220 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	600 MTD	NA	NA	NA	NA	Unit is complying presently
140	-	Shri Sai Baba Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.55196 , Longitude : 76.18688	Granted vide No. 2944 dated 22.09.2011	22.09.2011	30.03.2013	24/01/2024 - 31/03/2028	22 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 850 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 325 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	750 MTD	Issued on dated 13.02.2020	NA	NA	NA	Unit is complying presently
141	-	Shri Shivam Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.55282 , Longitude : 76.18681	Granted vide No. 5222088 dated 25.04.2018	25.04.2018	31.08.2020	24/01/2024 - 31/03/2028	100 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 325 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	650 MTD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
142	-	Sita Nath Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.57041 , Longitude : 76.18556	Granted vide No. 211 dated 28.06.2006	Granted vide No. 9622 dated 29.01.2009	30.03.2007	01.04.21-31.03.26	120 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 205 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 365 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2500 MTD	NA	NA	NA	NA	Unit is complying presently
143	-	Siwach Stone Crusher, Vill. Kheri battar, Charkhi Dadri , Latitude : 28.56859 , Longitude : 76.18981	Granted vide No. 3524 dated 06.10.2017	06.10.2017	07.04.2020	08/01/2024 - 31/03/2028	58 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 348 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 490 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 260 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	700 MTD	Issued on dated 16.09.2021	NA	NA	NA	Unit is complying presently
144	-	Subham Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.554403 , Longitude : 76.189477	Granted vide No. 20881214 dated 15.03.2022	15.03.2022	18.08.2022	18.08.22-31.03.27	38 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 350 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 248 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	4000 MTD	NA	NA	NA	NA	Unit is complying presently
145	-	Taj Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.56178 , Longitude : 76.18863	Granted vide No. 2945 dated 22.09.2011	22.09.2011	30.03.2013	01.03.21-31.03.25	32 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 80 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	400 MTD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
146	-	United Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.552834 , Longitude : 76.183333	Granted vide No. 7512254 dated 04.07.2020	04.07.2020	10.02.2021	10.02.21-31.03.25	76 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 650 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2000 TPD	Issued vide No. 1/166882 dated 21.06.2023	16.01.2023 to 20.05.2023 = 124 days	Imposed EC of Rs. 775000 Vide order dated 21.06.2023 and deposited Rs. 775000 on dated 28.06.2023	NA	Unit is complying presently
147	-	Venus Stone Crusher Village Kheri Battar Charkhi Dadri , Latitude : 28.55959 , Longitude : 76.18474	Granted vide No. 3157559 dated 06.06.2016	06.06.2016	18.05.2017	08/01/2024 - 31/03/2028	78 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	750 MTD	NA	NA	NA	NA	Unit is complying presently
148	-	Yash Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.575427 , Longitude : 76.194513	Granted vide No. 3383 dated 21.09.2017	21.09.2017	12.05.2020	29/12/2023 - 31/03/2028	220 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 350 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 180 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1100 MTD	Issued vide No. 1/170367/2023 dated 03.08.2023	03.05.2023 to 08.09.2023 =128 days	Imposed EC of Rs. 800000 Vide HO order and deposited Rs. 800000 on dated 09.10.2023	NA	Unit is complying presently
149	-	Jai Shri Shivam Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.564874 , Longitude : 76.186535	Granted vide No. 121 dated 16.06.2006	16.06.2006	31.03.2008	01/04/2022 - 31/03/2027	72 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 230 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 250 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 78 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	250 MTD	Closure order issued vide no. 163096/2023 dated 11.05.2023	16.01.2023 to 18.05.2023 =123 days	Recommended levy of EC of Rs. 768750 Vide letter no. 1520 dated 25.01.2024	Unit has been closed by the Board	Unit has been closed by the Board

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
150	-	New Baba Pir Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.55394 , Longitude : 76.18944	Granted vide No. 3121536 dated 01.06.2016	01.06.2016	16.08.2017	01.04.22-31.03.27	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 220 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	500 MTD	Issued vide No. HSPCB-030002/166 /2023- Planning Cell dated 11.05.2023	16.01.2023 to 18.05.2023 =123 days	Recommended levy of EC of Rs. 768750 Vide letter no. 1535 dated 25.01.2024	Unit has been closed by the Board	Unit has been closed by the Board
151	-	OmPati Stone Crusher Co., VPO Kheri Battar Charkhi Dadri , Latitude : 28.55846 , Longitude : 76.18061	Granted vide No. 2091 dated 30.01.2008	20.01.2008	11.01.2013	01/04/2022 - 31/03/2027	110 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 250 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 390 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	900 MTD	NA	NA	NA	NA	Dismantled
152	-	Shanker Stone Crusher, Village Kheri Battar, Tehsil Charkhi Dadri , Latitude : 28.571 , Longitude : 76.182	Granted vide No. 419 dated 25.07.2006	25.07.2006	13.03.2008	01.04.19-31.03.24	102 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 387 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 330 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 157 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	850	NA	NA	NA	NA	Dismantled
153	-	Hari Dass Grit udyog , Village Kheri Battar, Charkhi Dadri , Latitude : 28.57034 , Longitude : 76.18493	Granted vide No. 2599 dated 22.08.2017	22.08.2017	07.01.2018	01.04.22-31.03.27	102 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 195 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 335 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 63 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	350 MTD	NA	NA	NA	NA	Dismantled
154	-	Hanuman Stone Crusher, Vill Kheri Battar, Charkhi Dadri , Latitude : 28.56941 , Longitude : 76.18501	Granted vide No. 9622 dated 29.01.2009	29.01.2009	19.03.2009	01.04.21-31.03.26	55 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 260 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 87 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	100 MTD	NA	NA	NA	NA	Dismantled

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
155	-	Lucky Minerals Unit III 28/13 14 Vill: Kalyana, Charkhi Dadri , Latitude : 28.572698 , Longitude : 76.205117	Granted vide No. 315924 dated 01.06.2016	01.06.2016	29.07.2018	Unit found dismantled at the time of inspection	102 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 195 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 465 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	100 MTD	NA	NA	NA	NA	Dismantled
156	-	Lucky Minerals, U-II, VILL KALIYANA, Charkhi Dadri , Latitude : 28.572698 , Longitude : 76.205117	Granted vide No. 3158998 dated 01.06.2016	01.06.2016	29.07.2018	Unit found dismantled at the time of inspection	66 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 290 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 250 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 250 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	100 MTD	NA	NA	NA	NA	Dismantled
157	-	Lucky Minerals Unit-I Khasra No. 28/3/2,4/2/2,7,8 Village : Kalyana Charkhi Dadri , Latitude : 28.572665 , Longitude : 76.203147	Granted vide No. 2985 dated 01/06/2016	1/6/2016	29.07.2018	Unit found dismantled at the time of inspection	78 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 215 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 185 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	100 MTD	NA	NA	NA	NA	Dismantled
158	-	Darshana Stone Crusher, Vill. Kaliyana, Charkhi Dadri , Latitude : 28.34015 , Longitude : 76.115308	Granted vide No. 2985 dated 27.09.2011	27.09.2011	04.12.2013	Not having valid CTO & dismantled	-	The unit was closed by board & found dismantled at the time of inspection	The unit was closed by board & found dismantled at the time of inspection	The unit was closed by board & found dismantled at the time of inspection	The unit was closed by board & found dismantled at the time of inspection	The unit was closed by board & found dismantled at the time of inspection	The unit was closed by board & found dismantled at the time of inspection	The unit was closed by board & found dismantled at the time of inspection	The unit was closed by board & found dismantled at the time of inspection	Dismantled	NA	NA	NA	NA	NA	Dismantled
159	-	Baba Stone Crusher-1, Village Kaliyana, Charkhi Dadri , Latitude : 28.56681 , Longitude : 76.19818	Granted vide No. 388 dated 20.04.2012	20.04.2012	16.11.2014	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Dismantled	NA	NA	Unit dismantled	NA	NA	Dismantled
160	-	Shiv Durga Stone Crusher, Village Kheri Battar Charkhi Dadri , Latitude : 28.565898 , Longitude : 76.188518	Granted vide No. 6970045 dated 22.11.2019	22.11.2019	30.12.2019	Valid upto 31.03.24 & revocation in process	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	NA	NA	Unit found dismantled at the time of inspection	NA	NA	Dismantled
161	-	KSC Buildcon Pvt Ltd., Village Kheri Battar, Charkhi Dadri , Latitude : 28.552847 , Longitude : 76.178643	Granted vide No. 2376866 dated 07.01.2016	07.01.2016	30.09.2016	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	NA	NA	Unit found dismantled at the time of inspection	NA	NA	Unit found dismantled at the time of inspection
162	-	Anjani Stone Crusher, VPO Kheri Battar, Charkhi Dadri , Latitude : 28.56958 , Longitude : 76.17738	Granted vide No. 187 dated 26.06.2006	26.06.2006	30.03.2007	Valid upto 31.03.27 & revocation in process	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	NA	Issued on dated 11.05.2023	16.01.2023 to 20.05.2023 =125 days	Recommended levy of EC of Rs. 781250 Vide letter no. 1536 dated 25.01.2024	Unit has been closed by the Board and at present theDismantled	Unit has been closed by the Board and found dismantled

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/ Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/ separate energy meter/ logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
163	-	New Era Solutions Pvt. Ltd. Village Kheri Battar, Charkhi Dadri New Name Metro Stone Crusher , Latitude : 28.914884 , Longitude : 75.85163	Granted vide No. 840 dated 20.06.2008	20.06.2008	17.03.2009	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	NA	NA	NA	NA	NA	Dismantled
164	-	Shree Luxmi Stone Crushing Co., -II, Village Kheri Battar, Charkhi Dadri , Latitude : 28.629802 , Longitude : 76.165625	Granted vide No. 2096 dated 01.02.2008	01.02.2008	-	Not having valid CTO & Closed by Board	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	NA	Issued on dated 18.07.2010	NA	NA	The unit was closed by board & found dismantled	The unit was closed by board & found dismantled
165	-	New Sunrise Stone Crusher, Village Kheri Battar, Tehsil Charkhi Dadri , Latitude : 28.55846 , Longitude : 76.188204	Granted vide No. 1876262 dated 26.04.2015	26.04.2015	Plant & Machinery not installed	Not having valid CTE & Plant & Machinery not installed	-	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Non-Operational and not installed plant & machinery	NA	NA	Plant & Machinery not installed	NA	NA	Non-Operational and not installed plant & machinery
166	-	Shivalaya Construction Pvt Ltd Co., Village Kheri Battar, Charkhi Dadri , Latitude : 28.566251 , Longitude : 76.188204	Granted vide No. 2985 dated 27.09.2011	27.09.2011	04.12.2013	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	NA	NA	-	NA	NA	Dismantled
167	-	Aravali Hills Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.56893 , Longitude : 76.188204	Granted vide No. 406 dated 20.04.2012	20.04.2012	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	NA	NA	Plant & Machinery not installed	NA	NA	Plant & Machinery not installed
168	-	DCC Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.56619 , Longitude : 76.18533	Granted vide No. 394 dated 20.04.2012	20.04.2012	30.03.2013	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	NA	NA	NA	NA	NA	Dismantled
169	-	Himalya Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.577332 , Longitude : 76.149779	Granted vide No. 400 dated 20.04.2012	20.04.2012	Plant & Machinery not installed	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	NA	NA	NA	NA	NA	Dismantled
170	-	Maha Dev Stone Crusher Village Kaliyana , Charkhi Dadri , Latitude : 28.572605 , Longitude : 76.206037	Granted vide No. 4655975 dated 10.11.2017	10.11.2017	23.09.2018	Not having valid CTO	28 feet	Not provided Covered shed over machinery	Unit has not provided proper & adequate wind breaking wall as per norms.	Unit has provided roads for vehicular movement within the premises	Unit has provided Wetting & Cleaning of the ground provided during inspection	Unit has not provided proper green belt as per norms.	Not provided sufficient number of water sprinklers	Not provided Interlocking system of water sprinkler with stone crusher machine and not maintained logbook for water & energy consumption	No vehicle found at the time of inspection	Non-Operational	1200 MTD	Closure case recommended to HO	NA	NA	Recommended for closure to HO vide inspection no. 51386192 Dated 15.11.2023. The unit submitted representation regarding compliance of SCN to HO & same is pending for verification.	Recommended for closure to HO vide inspection no. 51386192 Dated 15.11.2023. The unit submitted representation regarding compliance of SCN to HO & same is pending for verification.
171	-	Maruti Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.56995 , Longitude : 76.18523	Granted vide No. 3163 dated 08.11.2011	08.11.2011	31.03.2013	25/01/2024 - 31/03/2026	29 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 76 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-Operational	800 MTD	NA	NA	NA	NA	Unit is complying presently, Closed its own
172	-	Vishnu Stone Crusher, Kheri Battar, Charkhi Dadri , Latitude : 28.55275 , Longitude : 76.178529	Granted vide No. 3166138 dated 07.07.2016	07.07.2016	27.07.2022	Valid upto 31.03.27 & revocation in process	39 feet	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	The unit was found closed by board at the time of inspection.	Non-Operational	1500 MTD	Issued on dated 11.05.2023	16.01.2023 to 18.05.2023 =123 days	Imposed EC of Rs. 768750 Vide order dated 19.07.2023 and deposited Rs. 768750 on dated 11.10.2023	Unit has been closed by the Board	Unit has been closed by the Board




Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
173	-	Anup Stone Crusher, Vill. Kheri Battar, Charkhi Dadri , Latitude : 28.56838 , Longitude : 76.17488	Granted vide No. 2946 dated 22.09.2011	22.09.2011	11.01.2013	10.02.21-31.03.25	52 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 400 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2500 MTD	NA	NA	NA	NA	Unit is complying presently
174	-	Bhartho Devi Stone Crusher, Village Kheri Battar, Charkhi Dadri , Latitude : 28.55106 , Longitude : 76.1856	Granted vide No. 2284599 DATED 29.10.2015	29.10.2015	06.06.2020	01.04.23-31.03.28	37 feet	Unit has provided proper cover shed over machinery	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 290 Plants and plantation plan obtained from DFO vide letter dated 03.04.2023 & same is also verified by DFO	Provided 70 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	No vehicle reported during inspection	Operational	1100 MTD	NA	NA	NA	NA	Unit is complying presently
175	-	Dhankaur Stone Crusher,Village Kheri Battar, Charkhi Dadri , Latitude : 28.56966 , Longitude : 76.17709	Granted vide No. 356 dated 13.03.2006	13.03.2006	30.03.2007	01.04.21-31.03.26	32 feet	Unit has not provided proper cover shed over machinery	Provided Wind breaking wall of about 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO vide letter dated 04.01.2021 & same is also verified by DFO	Unit has not provided sufficient number of water sprinklers.	Not provided Interlocking system of water sprinkler with stone crusher machine and not maintained logbook for water & energy consumption	No vehicle reported during inspection	Non-Operational	200	Closure case recommended to HO	NA	NA	SCN for closure and revocation of consent to operate issued to unit vide letter No. 1036-37 Dated 31.10.23. The unit is lying closed of its own due to repair and has submitted under taking that unit will start operation after verification of provisions of notification. The same has also been verified by the field officer.	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
176	-	Shiv Bhole Stone Crusher Village Kalali, Charkhi Dadri , Latitude : 28.5333 , Longitude : 76.18471	Granted vide No. 3118329 dated 05.05.2016	05.05.2016	03.01.2017	Valid upto 31.03.26	1154 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 200 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 168 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	400 MTD	Issued vide No. 4109 dated 13.02.2020	22.03.2019 to 14.02.2020	Imposed EC of Rs. 1575000 Vide order dated 16.04.2021 and deposited Rs. 1575000 on dated 16.04.2021	NA	Unit is complying presently
177	-	Jai Shree Shyam Stone Crusher, Village Kalai, Charkhi Dadri , Latitude : 28.53405 , Longitude : 76.1797	Granted vide No. 3061956 dated 07.04.2016	07.04.2016	20.12.2016	24/01/2024 - 31/03/2028	141 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 165 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	550 MTD	NA	NA	NA	NA	Unit is complying presently
178	-	Sadbhawna Stone Crusher, Village Kalali, Charkhi Dadri , Latitude : 28.53286 , Longitude : 76.179	Granted vide No. 3283 dated 09.09.2017	09.09.2017	27.01.2018	19.08.21- 31.03.26	144 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 270 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 340 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	900 MTD	Issued vide No 4153 dated 13.02.2020	04.11.2019 to 18.12.2019 & 26.10.2019 to 03.11.2019 and 19.12.2019 to 28.02.2020.	Imposed EC of Rs. 1618750 Vide order dated 28.05.2021 and deposited Rs. 1618750 on dated 31.05.2021	NA	Unit is complying presently




Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
179	-	Jai Mata Di Stone Crusher, Village Kalali, Charkhi Dadri , Latitude : 28.533516 , Longitude : 76.179246	Granted vide No. 2379202 dated 28.12.2015	28.12.2015	09.01.2017	23.03.21-31.03.25	120 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 310 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 380 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	400 MTD	Issued vide No 4323 dated 25.02.2020	NA	NA	NA	Unit is complying presently
180	-	Baljit Stone Crusher Vill-Kalali, Distt Charkhi Dadri , Latitude : 28.530254 , Longitude : 76.17961	Granted vide No. 3207437 dated 28.06.2016	28.06.2016	09.08.2018	01.04.23-31.03.28	742 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 328 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 128 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2500 MTD	NA	NA	NA	NA	Unit is complying presently
181	-	Subh Ram Stone Crusher Village Kheri Battar, Charkhi Dadri , Latitude : 28.55793 , Longitude : 76.189	Granted vide No. 3149 dated 05.10.2011	05.10.2011	21.03.2014	01.04.20-31.03.25	28 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 195 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 60 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1700 MTD	NA	NA	NA	NA	Unit is complying presently
182	-	Baba Shyam Stone Crusher, Village Kaliyana, Charkhi Dadri Lat: 28.572609 Long: 76.25050	Granted vide No. 2059 dated 26.06.2009	26.06.2009	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	NA	NA	NA	NA	NA	Dismantled
183	-	Bijender Singh Quarry Contractor Stone Crusher Village Kheri Battar Charkhi Dadri Lat: 28.5688 Long: 76.1817	Old unit (No CTE as per office record)	Old unit (No CTE as per office record)	10.06.2002	Not having valid CTO & dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	NA	NA	NA	NA	NA	Dismantled

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher not to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ interlocking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
184	-	Dalawas Stone Crusher, Vill Tiwala, Charkhi Dadri, Lat: 28.57375 Long: 76.113843	Granted vide No. 5407759 dated 02.07.2018	02.07.2018	28.11.2018	Not having valid CTO & Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Non-Operational	200 TPH	Issued vide No 4339 dated 25.02.2020 & No. 1/163113/2023 dated 14.02.2023	16.01.2023 to 16.05.2023 =121 days	Recommended levy of EC of Rs. 7562580 Vide letter no. 1521 dated 25.01.2024	closed by Board	closed by Board
185	-	Dhanluxmi Stone Crusher, Kalali, Charkhi Dadri, Lat: 28.3218244 Long: 76.41986	Granted vide No. 3157749 dated 06.06.2016	06.06.2016	15.07.2020	Valid upto 31.03.25 & revocation in process	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Non-Operational	250 MTD	Issued vide No 1/170315/2023 dated 02.08.2023	16.01.2023 to 12.09.2023 =240 days	Recommended levy of EC of Rs. 1500000 Vide letter no. 1522 dated 25.01.2024	closed by Board	closed by Board
186	-	Ganga construction company, Village Kheri Battar, Charkhi Dadri, (Unit not found during inspection)	Granted vide No. 4932884 dated 30.01.2018	30.01.2018	Not operated	Not having valid CTE & Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Non-Operational and not installed plant & machinery	NA	NA	NA	NA	NA	Plant & Machinery not installed
187	-	Haryana Stone Crusher, Village Tiwala, Charkhi Dadri, , Latitude : 28.334992 , Longitude : 76.71338	Old unit (Before notification dated 17.08.1992)	Old unit (Before notification dated 17.08.1992)	04.06.2003	12/01/2024 - 31/03/2028	910 feet	Granted vide No. 9625377 valid upto 31.3.2026	Provided Wind breaking wall of about 16 feet height & 220 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Unit has provided Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 310 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 157 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	600 MTD	Issued vide No 4181 dated 14.02.2020	04.11.2019 to 18.12.2019 & 26.10.2019 to 03.11.2019 and 19.12.2019 to 19.02.2020.	Imposed EC of Rs. 1600000 Vide order dated 27.10.2020 and deposited Rs. 1600000 on dated 27.10.2020	NA	Unit is complying presently
188	-	Jai Hanuman Stone Crusher, Village Kheri Battar, Charkhi Dadri (Unit not found during inspection)	Granted vide No. 347 dated 17.07.2008	17.07.2008	Unit not operated	Not having valid CTO & dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	NA	NA	NA	NA	NA	Dismantled
189	-	K V R Minerals Pvt Ltd Unit 2 Vill Kaliyana Charkhi Dadri , Latitude : 28.343629 , Longitude : 76.12177	Granted vide No. 5060070 dated 09.02.2018	09.02.2018	09.05.2015	Valid upto 31.03.2028	21 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 175 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Unit has provided Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 200 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 80 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	350 TPH	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
190	-	K V R Minerals Pvt. Ltd., Village Kaliyana, Charkhi Dadri , Latitude : 28.343629 , Longitude : 76.12177	Granted vide No. 4088548 dated 08.06.2017	08.06.2017	09.09.2017	Valid upto 31.03.2027	23 feet	Unit has not provided proper Covered sheds for dust suppression.	Provided Wind breaking wall of about 16 feet height & 178 feet Length and not provided telescopic chute as per norms .	Metalled road provided for Vehicular movement within premises	Unit has not provided wetting & cleaning of the ground within the premises.	Provided Green belt of 145 Plants and same is not as per plantation plan approved from DFO vide letter dated 13.01.2021	Unit has provided 24 water sprinkler and not provided sufficient number of water sprinklers for dust suppression	Not provided Interlocking system of water sprinkler with stone crusher machine and not maintained logbook for water & energy consumption	No Vehicle reported during inspection as unit lying closed.	Non-Operational	300 MTD	Closure case recommended to HO	NA	NA	Recommended for closure to HO vide inspection no. 52927048 dated 05.12.2023 & same is under process	Recommended for closure to HO vide inspection no. 52927048 dated 05.12.2023 & same is under process
191	-	Laxmi Mining Company, Village Tiwala, Charkhi Dadri Lat: 28.5672 Long: 77.119906	Granted vide No. 3311266 dated 17.08.2016	17.08.2016	07.02.2017	Valid upto 31.03.26 & revocation in process	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Non-Operational	400 MTD	Issued vide No. 4077 dated 13.02.2020	16.01.2023 to 16.05.2023	Imposed EC of Rs. 1528125 Vide order dated 12.06.2020 and deposited Rs. 1528125 on dated 30.06.2020 & Recommended levy of 756250/-	closed by Board	closed by Board
192	-	Kundu Construction CO., Village Tiwala, Charkhi Dadri Lat: 28.572 Long: 76.117	Granted vide No. 9602 dated 29.01.2009	29.01.2009	21.05.2009	Not having valid CTO & dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	NA	NA	NA	NA	NA	Dismantled
193	-	Larsen and Toubro Limited, Vill Kheri Battar Charkhi Dadri , Latitude : 28.333099 , Longitude : 76.111652	Granted vide No. 5638693 dated 12.09.2018	12.09.2018	01.05.2019	Valid upto 31.03.2024	29 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 260 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Unit has provided Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	5000 MTD	Issued vide No 1/163094/2023 dated 11.05.2023	16.01.2023 to 19.05.2023	Imposed EC of Rs. 775500 Vide order dated 01.09.2023 and deposited Rs. 775500 on dated 08.09.2023	NA	Unit is complying presently
194	-	Laxmi Stone Crusher, Village Kheri Battar, Charkhi Dadri Lat: 28.33586638 Long: 77.11385656	Granted vide No. 35 dated 02.06.2006	02.06.2006	31.03.2008	Not having valid CTO & Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Closed by Board	Non-Operational	200 MTD	Issued vide No 1/167084/2023 dated 21.06.2023	NA	NA	Closed by Board	Closed by Board

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/ separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
195	-	Nihal Stone Crusher, Village Khei Battar, Charkhi Dadri Lat: 28.565 Long: 76.185	Granted vide No. 112 dated 16.06.2006	16.06.2006	31.07.2007	Not having valid CTO & dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	NA	NA	NA	NA	NA	Dismantled
196	-	Shivam Stone Crusher, Village Kheri Battar, Charkhi Dadri	Granted vide No. 397 dated 20.04.2012	20.04.2012	Not installed	Not having valid CTE & Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Non-Operational and not installed plant & machinery	NA	NA	NA	NA	NA	Plant & Machinery not installed
197	-	Shree Laxmi Stone Crusher, Kheri Battar, Charkhi Dadri Lat: 28.568228 Long: 76.184475	Granted vide No. 1653 dated 27.12.2005	27.12.2005	Not operated	Not having valid CTO & dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Non-Operational	NA	NA	NA	NA	NA	Dismantled
198	-	Sunrise stone Crusher, Village Kheri Battar, Charkhi Dadri Lat: 28.558610 Long: 76.184577	Granted vide No. 9614 dated 29.01.2009	29.01.2009	29.03.2013	Not having valid CTO & dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Non-Operational	NA	NA	NA	NA	NA	Dismantled

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
199	-	Super White Stone Crusher, Village Tiwala, Charkhi Dadri , Latitude : 28.334991 , Longitude : 76.71337	Granted vide No. 1508 dated 17.07.2017	17.07.2017	06.02.2018	Valid upto 31.03.27	300 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 310 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Unit has provided Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	150 TPH	NA	NA	NA	NA	Unit is complying presently
200	-	Arya Stone Crusher , Jhojhu Kalan, Charkhi Dadri , Latitude : 28.519273 , Longitude : 75.998983	Granted vide No. 3361891 Dated 2.9.2016	2.6.2016	29.10.2019	25.10.19-31.03.24	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 250 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 360 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 130 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-Operational	100 MT/D	Issued vide No 4697-4700 Dated 16.3.2020	20.1.2020-17.3.2020	Imposed EC of Rs. 300000 Vide order dated 08.06.20 not deposited EC	NA	Unit is complying presently, Closed its own
201	-	Avtar & Company Stone Crusher, Village Jhojhu Kalan, Charkhi Dadri , Latitude : 28.49764 , Longitude : 76.15373	Granted vide No. 2297397 Dated 13.10.2015	13.10.2015	25.4.2016	01.04.21-31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 255 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 245 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 160 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1800 MT/D	NA	NA	NA	NA	Unit is complying presently
202	-	Baba Hari Dass Stone Crushing Co Vill-Birhi Kalan, Charkhi Dadri , Latitude : 28.615755 , Longitude : 76.140889	Granted vide No. 3501583 Dated 6.12.2016	6.12.2016	19.5.2017	01.04.21-31.03.26	35 feet	Unit has not provided proper Covered sheds for dust suppression.	Provided Wind breaking wall of about 16 feet height & 340 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 190 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 115 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Closed by Board	200 MT/D	closure case recommended to HO vide No. 1310 dt 2.12.2023	09.10.2023 to 18.12.2023 =70-26(GRAP period)=44 Days	Imposed EC of Rs. 275000/- Vide order dated 21.12.2023 and deposited EC Rs. 275000/- on 11.01.2024.	Closed by Board	Closed by Board
203	-	Baba Raghu Nath Stone Crusher Vill-Birhi Kalan, Charkhi Dadri , Latitude : 28.609568 , Longitude : 76.139991	Granted vide No. 3206365 Dated 27.6.2016	27.6.2016	18.7.2017	01/01/2024 - 31/03/2028	40 feet	Unit has provided proper Covered sheds for dust suppression.	Provided Wind breaking wall of about 16 feet height & 370 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 250 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-operational	750 MT/D	NA	11.10.2023 to 11.12.2023 =61-26(GRAP period)=35 Days	Imposed EC of Rs. 218750/- Vide order dated 21.12.2023 and not deposited EC.	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
204	-	Baba Shyam Crushing Co Vill Jhoju Kalan, Charkhi Dadri , Latitude : 28.497149 , Longitude : 76.157605	Granted vide No. 5082046 Dated 15.2.2018	15.2.2018	2.10.2018	03.08.21-31.03.26	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 230 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 285 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 140 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	3000 MT/D	NA	NA	NA	NA	Unit is complying presently
205	-	Bhai Ji Stone Crusher Village Ramalwas, Charkhi Dadri , Latitude : 28.499361 , Longitude : 76.149556	Granted vide No. 4109398 Dated 27.4.2017	27.4.2017	3.4.2018	25/01/2024 - 31/03/2028	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 200 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 325 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	850 MT/D	Issued vide No 1126 Dated 12.6.2019	29.4.19-21.6.19	Imposed EC of Rs. 421875 Vide order dated 24.12.2019 and deposited Rs. 421875 on dated 11.11.2019	NA	Unit is complying presently
206	-	Chander Mukhi Stone Crusher, Kila/Khasra No. 102//23 & 104//3/1, Asawari, Patwari Halka 83, Charkhi Dadri , Latitude : 28.5355 , Longitude : 76.17822	Granted vide No. 12451 Dated 17.3.2009	17.3.2009	21.1.2013	01.04.21-31.03.26	500 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 245 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 428 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1000 MTD	NA	NA	NA	NA	Unit is complying presently
207	-	Dada Shakti Stone Crusher Vill-Birhi Kalan, Charkhi Dadri , Latitude : 28.607624 , Longitude : 76.1401165	Granted vide No. 3172039 Dated 8.6.2016	8.6.2016	19.5.2017	10/01/2024 - 31/03/2028	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 340 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 240 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	750 MT/D	NA	NA	NA	NA	Unit is complying presently
208	-	Gitesh Stone Crusher Vill-Birhi Kalan, Distt Charkhi Dadri , Latitude : 28.603857 , Longitude : 76.138952	Granted vide No. 3172151 Dated 9.6.2016	9.6.2016	28.3.2017	01/04/2022 - 31/03/2027	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 350 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 210 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 90 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	400 MT/D	Issued vide No 4413 Dated 27.2.2020	4.11.2019-18.12.2019 & 26.10.2019-3.11.2019 AND 19.12.2019-18.3.2020	Imposed EC of Rs. 1656250 Vide order dated 08.06.2020 and deposited Rs. 1656250 on dated 15.06.2020	NA	Unit is complying presently
209	-	Indian Stone Crusher, Jhoju Kalan, Charkhi Dadri , Latitude : 28.495667 , Longitude : 76.155408	Granted vide No. 5145797 Dated 28.3.2018	28.3.2018	15.7.2020	Not having valid CTO & dismantled	50 feet	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-Operational	NA	Issued vide No 872 Dated 9.5.2019	28.4.2019-28.5.2019	Imposed EC of Rs. 234375 Vide order dated 14.11.2019 and deposited Rs. 234375 on dated 09.12.2019	NA	Dismantled

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
210	-	Jai Baba Jamma Giri Stone Crusher, Vill. Birhi Kalan, Charkhi Dadri , Latitude : 28.607536 , Longitude : 76.139411	Granted vide No. 3616559 Dated 3.1.2017	3.1.2017	not obtained	Not having valid CTO & dismantled	-	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Dismantled	Non-Operational	NA	Issued vide No 7755 Dated 11.6.2018	NA	NA	NA	Dismantled
211	-	Jai Baba Jamma Giri Stone Crusher, Vill. Birhi Kalan, Charkhi Dadri , Latitude : 28.607636 , Longitude : 76.139411	Granted vide No. 3172091 dated 08.06.2016	08.06.2016	16.12.2017	01/01/2024 - 31/03/2028	54 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 250 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-operational	750 MTD	Closure order issued vide no. 4347 dated 25.02.2020	25.03.2019 to 18.03.2020	Imposed EC of Rs. 190625/- Vide order dated 25.11.2022 and deposited	NA	Unit is complying presently
212	-	Jai Dada Budha Stone Crusher, Village Birhi Kalan, Charkhi Dadri , Latitude : 28.599282 , Longitude : 76.153726	Granted vide No. 3165592 Dated 2.6.2016	2.6.2016	18.1.2017	01.04.21-31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 350 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 330 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1700 MT/D	NA	NA	NA	NA	Unit is complying presently
213	-	Jai Hind Stone Crushing Co., Village Birhi Kalan, Charkhi Dadri , Latitude : 28.605863 , Longitude : 76.139633	Granted vide No. 3280981 Dated 23.7.2016	23.7.2016	17.2.2017	01.04.21-31.03.26	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 240 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 170 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	800 MTD	Issued vide No. 4534 Dated 5.3.2020	19.10.2022-1.1.2023	Imposed EC of Rs. 325000 vide order dated 12.01.2024 but not deposited	NA	Unit is complying presently
214	-	Jai Mata Di Stone Crusher, Village Birhi Kala, Charkhi Dadri , Latitude : 28.533466 , Longitude : 76.179315	Granted vide No. 3165767 Dated 2.6.2016	2.6.2016	18.1.2017	01.04.21-31.03.26	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 360 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 470 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1800 MT/D	Issued vide No 4323 Dated 25.2.2020	NA	NA	NA	Unit is complying presently
215	-	Jai Shivam Stone Crusher Village Pandwan, Charkhi Dadri , Latitude : 28.616439 , Longitude : 76.162705	Granted vide No. 2629 Dated 23.8.2017	23.8.2017	26.7.2018	01.04.23-31.03.28	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 260 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 290 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1200 MTD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ interlocking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
216	-	Jai Shree Ram Stone Crusher Village Manakawas Charkhi Dadri , Latitude : 28.630911 , Longitude : 76.168219	Granted vide No. 9604 Dated 29.1..2009	29.1.2009	19.3.2009	01.04.23-31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 315 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 180 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	250 MTD	NA	NA	NA	NA	Unit is complying presently
217	-	Jai Shree Shyam Stone Crusher Vill-Jhojhu Kalan, Charkhi Dadri , Latitude : 28.49693 , Longitude : 76.15373	Granted vide No. 2441233 Dated 18.12.2015	18.12.2015	27.6.2016	10/01/2024 - 31/03/2028	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 315 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 270 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	850 MTD	NA	NA	NA	NA	Unit is complying presently
218	-	Jai Shree Shyam Stone Crusher, Vill-Pichopa Kalan, Charkhi Dadri , Latitude : 28.503195 , Longitude : 76.152287	Granted vide No. 5036952 Dated 8.2.2018	8.2.2018	1.4.2019	22.08.21-31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 315 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 200 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	3500 MTD	NA	NA	NA	NA	Unit is complying presently
219	-	Jhojhu Stone Crusher, Village Jhojhu Kalan, Charkhi Dadri , Latitude : 28.49786 , Longitude : 76.15549	Granted vide No. 3598 DT Dated 24.7.2007	24.7.2007	21.5.2009	14.12.19-31.03.24	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 300 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 195 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	150 MT/D	Issued vide No 1068-72 Dated 4.6.2019	29.4.2019-21.6.2019	Imposed EC of Rs. 421875 Vide order dated 2019 and deposited Rs. 421875 on dated 28.10.2019	NA	Unit is complying presently
220	-	Kanhalya Stone Crusher Vill-Birhi Kalan, Charkhi Dadri , Latitude : 28.60889 , Longitude : 76.14006	Granted vide No. 3143622 Dated 02.06.2016	2.6.2016	15.7.2016	01/01/2024 - 31/03/2028	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 370 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 285 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	600 MT/D	NA	19.10.2022 to 01.01.2023 = 75-22 (GRAP period) = 53 days	Imposed EC of Rs. 325500/- vide order dated 12.01.2024 but not deposited	NA	Unit is complying presently




Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
221	-	Karan Stone Crusher, Village Asawari, Charkhi Dadri , Latitude : 28.55442 , Longitude : 76.14017	Granted vide No. 1973 Dated 23.1.2008	23.1.2008	17.3.2009	18.11.21-31.03.24	200 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 270 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 420 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1200 MTD	Issued vide No. HSPCB-50004/499/2021-Publicity Cell dated 31.08.2021	23.07.2021 to 25.09.2021 (65 Days)	Recommendation of EC of Rs. 04,06,250/- sent to HO vide letter No. 1539 dated 25.01.2024.	NA	Unit is complying presently
222	-	Maa Pitambara Mines And Cruhsers LLP, Vill Mankawas, Charkhi Dadri , Latitude : 28.633537 , Longitude : 76.169682	Granted vide No. 5258494 Dated 9.5.2018	9.5.2018	1.6.2019	30.01.2024 - 31.03.2028	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 270 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 182 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1200 MTD	NA	NA	NA	NA	Unit is complying presently
223	-	Maha Laxmi Stone Mills, Vill Mankawas, Charkhi Dadri , Latitude : 28.633178 , Longitude : 76.168507	Granted vide No. 5207755 Dated 4.4.2018	4.4.2018	4.6.2019	30.01.2024 - 31.03.2028	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 230 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 180 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 80 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1400 MTD	Issued vide No 37527/2021 Dated 4.5.2021	23.3.2021-17.5.2021	Imposed EC of Rs. 350000/- vide order dated 28.01.2022 and deposited by the unit	NA	Unit is complying presently
224	-	Mahadev Stone Crusher, Birhi Kalan, Charkhi Dadri , Latitude : 28.609674 , Longitude : 76.138763	Granted vide No. 3357018 Dated 30.9.2016	30.9.2016	2.10.2018	01.04.23-31.03.28	90 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 290 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 380 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 115 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1200 MTD	NA	NA	NA	NA	Unit is complying presently
225	-	Mahaluxmi Stone Crusher Village Birhi Kalam, Charkhi Dadri , Latitude : 28.610786 , Longitude : 76.139212	Granted vide No. 3175155 dated 08.06.2016	08.06.2016	22.08.2017	01.04.19-31.03.24	90 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 245 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 290 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	550 MTD	Issued vide No 395 dated 20.04.2018	19.10.2022 to 01.01.2023 = 74-22 (GRAP period) = 52 days & 08.02.2023 to 17.03.2023 = 38 days	Imposed EC of Rs. 237500/- vide order dated 12.01.2024 and Rs. 325000/- vide order dated 13.01.2024 but not deposited	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
226	-	Mayur Stone Crusher, Village Birhi Kala, Charkhi Dadri , Latitude : 28.608907 , Longitude : 76.140478	Granted vide No. 3327328 dated 30.08.2016	30.08.2016	18.01.2017	01.04.21-31.03.26	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 280 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 258 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 160 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1700 MTD	NA	NA	NA	NA	Unit is complying presently
227	-	Murliwala Stone Crushing Mills, Vill. Jhohu Kalna, Charkhi Dadri , Latitude : 28.485661 , Longitude : 76.143406	Granted vide No. 3396793 dated 28.09.2016	28.09.2016	19.01.2017	01.04.21-31.03.24	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 310 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 240 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1800 MTD	NA	NA	NA	NA	Unit is complying presently
228	-	NECC Mines & Mineral, Village Manakawas, Charkhi Dadri , Latitude : 28.632135 , Longitude : 76.167686	Granted vide No. 3370984 Dated 29.9.2016	29.9.2016	7.2.2017	01.04.21-31.03.26	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 200 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 229 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2000 MT/D	NA	NA	NA	NA	Unit is complying presently
229	-	NECC Mining Corporation Unit 2, Village Pandwan Charkhi Dadri , Latitude : 28.614952 , Longitude : 76.161624	Granted vide No. 326 Dated 18.7.2017	18.7.2017	23.11.2017	01/04/2024 - 31/03/2027	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 290 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 272 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1800 MT/D	NA	NA	NA	NA	Unit is complying presently
230	-	NECC Mining Corporation, Village Pandwan, Charkhi Dadri , Latitude : 28.61474 , Longitude : 76.160548	Granted vide No. 328 Dated 18.7.2017	18.7.2026	23.11.2017	01/04/2024 - 31/03/2027	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 335 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 290 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1800 MT/D	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/ separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
231	-	NECC Roadways, Village Pandwan, Charkhi Dadri , Latitude : 28.615901 , Longitude : 76.160498	Granted vide No. 330 Dated 18.7.2017	18.7.2017	23.11.2017	01/04/2024 - 31/03/2027	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 300 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 130 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 145 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1800 MT/D	NA	NA	NA	NA	Unit is complying presently
232	-	Neel Kanth Stone Crusher Mill, Village Jhojhu Kalan, Charkhi Dadri , Latitude : 28.486557 , Longitude : 76.142372	Granted vide No. 3471386 Dated 18.12.2016	18.12.2016	7.2.2017	Not having valid CTO & dismantled	30 feet	Unit was found dismantled at the time of inspection.	Unit was found dismantled at the time of inspection.	Unit was found dismantled at the time of inspection.	Unit was found dismantled at the time of inspection.	Unit was found dismantled at the time of inspection.	Unit was found dismantled at the time of inspection.	Unit was found dismantled at the time of inspection.	Unit was found dismantled at the time of inspection.	Non-Operational	NA	NA	NA	NA	NA	Dismantled
233	-	Neelkanth Mahadev Grit Udyog Vill-Birhi Kalan, Charkhi Dadri , Latitude : 28.604664 , Longitude : 76.139804	Granted vide No. 3275994 Dated 15.7.2016	15.7.2016	12.5.2017	01/01/2024 - 31/03/2028	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 360 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 180 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	750 MT/D	NA	NA	NA	NA	Unit is complying presently
234	-	New Avtar Stone Crusher, Vill-Pichopa Kalan, Charkhi Dadri , Latitude : 28.538899 , Longitude : 76.089353	Granted vide No. 5036794 Dated 5.2.2018	5.2.2018	30.4.2019	30.01.2024 - 31.03.2028	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 370 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 188 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 115 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1400 MTD	NA	NA	NA	NA	Unit is complying presently
235	-	New Rapid Stone Crusher old Name Jai baba Shyam Stone Crusher, Birhi Kalan, Charkhi Dadri , Latitude : 28.609588 , Longitude : 76.139908	Granted vide No. 2344884 Dated 4.11.2015	4.11.2015	17.5.2016	01/01/2024 - 31/03/2028	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 340 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 280 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	750 MT/D	Issued vide No 4405 Dated 27.2.2020	4.11.2019-18.12.2019 & 26.10.2019-3.11.2019 AND 19.12.2019-18.3.2020	Imposed EC of Rs. 1656250 Vide order dated 22.06.2020 and deposited Rs. 828126 on dated 23.06.2020 (Submitted 50 %)	NA	Unit is complying presently
236	-	Om Shiv Stone Crusher, Village Jhojhu Kalan, Charkhi Dadri , Latitude : 28.4953 , Longitude : 76.15334	Granted vide No. 3084621 Dated 28.4.2016	28.4.2016	22.6.2017	10/01/2024 - 31/03/2028	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 330 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 310 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	750 MT/D	Closure order issued vide no. 1064 dated 04.06.2019	29.4.2019-21.6.2019	Imposed EC of Rs. 421875 Vide order dated 22.10.2019 and deposited Rs. 421875 on dated 11.11.2019	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
237	-	Pritam Stone Crusher, Aswari, Charkhi Dadri , Latitude : 28.799522 , Longitude : 76.124419	Granted vide No. 3154 Dated 5.10.11	5.10.11	12.12.2015	10.1.2024-31.3.2028	500 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 225 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 385 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	200 MT/D	NA	NA	NA	NA	Unit is complying presently
238	-	Purpal Stone Crusher, Village Birhi Kala, Charkhi Dadri , Latitude : 28.608239 , Longitude : 76.141785	Granted vide No. 3299425 dated 27.07.2016	27.07.2016	28.03.2017	01.04.21-31.03.26	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 315 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 410 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1500 MTD	NA	NA	NA	NA	Unit is complying presently
239	-	Rajesh Stone Crusher, Pichopa Kalan, Charkhi Dadri , Latitude : 28.5325 , Longitude : 76.0891	Granted vide No. 5069908 Dated 15.2.2018	15.2.2018	6.12.2018	01.04.23-31.03.28	470 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 395 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 265 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2500 MT/D	NA	NA	NA	NA	Unit is complying presently
240	-	Rudhra Stone Crusher, Village Jhohju Kalan, Charkhi Dadri , Latitude : 28.53762 , Longitude : 76.201883	Granted vide No. 3960487 Dated 27.3.2017	27.3.2017	2.1.2018	01/04/2022 - 31/03/2027	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 380 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	300 MT/D	NA	NA	NA	NA	Unit is complying presently
241	-	Sangwan Stone Crusher, Vilage Birhi Kalan, Charkhi Dadri , Latitude : 28.84815 , Longitude : 76.5464	Granted vide No. 7069184 dated 04.12.2019	04.12.2019	30.12.2019	01/01/2024 - 31/03/2028	90 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 285 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 297 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	750 MTD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
242	-	Shiv Bhole Stone Crusher Vill-Asawari, Charkhi Dadri , Latitude : 28.533582 , Longitude : 76.184439	Granted vide No. 3035 dated 30.09.2011	30.09.2011	14.06.2016	25.08.21-31.03.26	500 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 300 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 350 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1000 MTD	Issued vide No 4327 dated 25.02.2020 & No. 1/15626/2021 dated 12.01.2021	NA	NA	NA	Unit is complying presently
243	-	Shiv Shakti Grit Udyog, Village Birhi Kala, Charkhi Dadri , Latitude : 28.610259 , Longitude : 76.139208	Granted vide No. 3165474 dated 02.06.2016	02.06.2016	18.01.2017	01.04.21-31.03.26	90 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 300 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 595 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 125 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1800 MTD	NA	NA	NA	NA	Unit is complying presently
244	-	Shiv Shakti Stone Crusher Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.832583 , Longitude : 76.0757637	Granted vide No. 5070397 dated 13.02.2018	13.02.2018	13.03.2020	10/01/2024 - 31/03/2028	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 253 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 90 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1200 MTD	Issued vide No 4517 dated 05.03.2020	NA	NA	NA	Unit is complying presently
245	-	Shiv Shankar Stone Crusher Vill-Birhi Kalan, Charkhi Dadri , Latitude : 28.604583 , Longitude : 76.139016	Granted vide No. 3416020 dated 27.01.2017	27.01.2017	09.07.2018	01/01/2024 - 31/03/2028	80 feet	Unit has provided proper Covered sheds for dust suppression.	Unit has not provided proper & adequate wind breaking wall as per norms.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 280 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 140 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-operational	600 MTD	Closure order issued vide no. 7722 dated 22.05.2018	20.10.2022 to 01.01.2023 =73-22(GRAP period =51 Days	Imposed EC of Rs. 318750 vide order dated 12.01.2024 but not deposited	NA	Unit is complying presently
246	-	Shiv Stone Crusher, Village Jhaju Kalan, Charkhi Dadri , Latitude : 28.4982 , Longitude : 76.1592	Granted vide No. 3697075 Dated 9.1.2017	9.1.2017	7.1.2018	10/01/2024 - 31/03/2028	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 284 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 310 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 160 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1250 MT/D	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/ separate energy meter/ logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
247	-	Shiva Stone Crusher, Village Birhi Kalan, Charkhi Dadri , Latitude : 28.607476 , Longitude : 76.139843	Granted vide No. 3172060 dated 08.06.2016	08.06.2016	12.07.2017	06/05/2023 - 31/03/2028	100 feet	Unit has provided proper Covered sheds for dust suppression.	Provided Wind breaking wall of 16 feet height & 350 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 285 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-operational	1200 MTD	NA	11.10.2023 to 11.12.2023 =61-26(GRAP period)=35 Days	Imposed EC of Rs. 218750 vide order dated 21.12.2023 but not deposited	NA	Unit is complying presently
248	-	Shree Radhe Stone Crusher, Birhi Kalan, Charkhi Dadri , Latitude : 28.84816 , Longitude : 76.59641	Granted vide No. 4104510 dated 27.04.2017	27.04.2017	21.08.2019	01/01/2024 - 31/03/2028	100 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 350 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 560 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 180 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	750 MTD	NA	NA	NA	NA	Unit is complying presently
249	-	Shree Ram Stone Crusher, Vill. Mankawas, Charkhi Dadri , Latitude : 28.62986 , Longitude : 76.16616	Granted vide No. 348 Dated 9.6.2004	9.6.2004	31.3.2008	09.02.23- 31.03.27	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 280 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 138 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	250 MTD	Issued vide No 4696 Dated 16.3.2020	19.08.2021 to 24.03.2023	Imposed EC of Rs. 768750 Vide order dated 19.08.2021 and deposited Rs. 384375 on dated 21.01.2022 (Submitted 50 %)	NA	Unit is complying presently
250	-	Shree Shyam Stone Crusher Village Jhojhu Kalan, Charkhi Dadri , Latitude : 28.534031 , Longitude : 76.17939	Granted vide No. 3487229 Dated 18.1.2017	18.1.2017	28.7.2017	10/01/2024 - 31/03/2028	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 295 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 200 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 115 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	450 MT/D	Issued vide No 66048 Dated 20.9.2021	23.7.2021- 25.9.2021	Imposed EC of Rs. 406250 Vide order dated -- and deposited Rs. 406250 on dated 30.04.22	NA	Unit is complying presently
251	-	Shri Ram Stone Crusher, Village Jhojhu Kalan, Charkhi Dadri , Latitude : 28.5525 , Longitude : 76.1886	Granted vide No. 3428754 dated 24.10.2016	24.10.2016	25.03.2017	25/02/2022 - 31/03/2026	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 370 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 209 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1700 MTD	Issued vide No 1038-42 dated 04.06.2019	17.06.2021 to 25.09.2021 = 101-67 (unit closed) = 34 days	Imposed EC of Rs. 625000 Vide order dated 28.01.2022 and deposited Rs. 312500 on dated 29.01.2022 (Submitted 50%) & imposed EC of Rs. 421875/- which is deposited by the unit.	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
252	-	Shri Rattan Grit Udyog Village Birhi Kala Charkhi dadri , Latitude : 28.592062 , Longitude : 76.265289	Granted vide No. 3165987 dated 02.06.2016	02.06.2016	18.01.2017	15.05.21-31.03.26	90 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 380 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 325 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 160 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1800 MTD	NA	NA	NA	NA	Unit is complying presently
253	-	Shyam King Stone Crusher Village Jhoju Kalan Charkhi Dadri , Latitude : 28.502497 , Longitude : 76.109166	Granted vide No. 3343429 dated 30.09.2016	30.09.2016	05.12.2016	01.10.21-31.03.26	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 340 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 245 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1000 MTD	NA	NA	NA	NA	Unit is complying presently
254	-	Sohna Stone Crusher, Village Ramalwas, Charkhi Dadri , Latitude : 28.488275 , Longitude : 76.142962	Granted vide No. 3389246 dated 27.09.2016	27.09.2016	09.09.2017	01.04.21-31.03.26	60 feet	Unit has provided proper Covered sheds for dust suppression.	Provided Wind breaking wall of 16 feet height & 230 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 290 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-operational	1400 MTD	Issued vide No 1058-62 dated 04.06.2019	29.042019 to 21.06.2019 = 54 days & 19.10.2023 to 02.11.2023 =15 Days	Imposed EC of Rs. 421875 Vide order dated 22.10.2019 and deposited Rs. 421875 on dated 25.11.2019 & EC recommended to HO vide letter dated 25.01.2024 of Rs. 93750	NA	Unit is complying presently
255	-	Suraj Stone Crushing CO., Village Mankawas, Charkhi Dadri , Latitude : 28.63098 , Longitude : 76.16718	Granted vide No. 3479 dated 11.11.2011	11.11.2011	17.02.2016	27.09.22-31.03.27	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 185 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 170 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	200 MTD	Issued vide No. 4679 dated 13.03.2020	15.03.2019 to 29.04.2020 = 412-18-47-37-153 (GRAP & COVID period) = 157 days	Imposed EC of Rs. 975000 Vide order dated 19.08.2021 and deposited Rs. 487500 on dated 19.01.2022 (Submitted 50%)	NA	Unit is complying presently
256	-	Swastik Stone Crusher, Village Birhi Kalan, Charkhi Dadri , Latitude : 28.607697 , Longitude : 76.137811	Granted vide No. 3322619 dated 09.08.2016	09.08.2016	29.08.2017	01/04/2022 - 31/03/2027	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 420 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 385 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1500 MTD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
257	-	Trishul Stone Crushing Mills Vill-Jhojhu Kalan, Charkhi Dadri , Latitude : 28.48553 , Longitude : 76.14218	Granted vide No. 3387087 dated 28.09.2016	28.09.2016	27.03.2017	01.04.21-31.03.26	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 300 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 340 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 80 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1700 MTD	Closure order issued vide no. 4137 dated 13.02.2020	08.03.2019 to 14.02.2020 = 344-45-33.5 (GRAP period 78.5 days) = 265.5 days	Imposed EC of Rs. 1662500 Vide order dated 26.04.2021 not deposited EC	NA	Unit is complying presently
258	-	Uma Stone Crusher, Village Asawari, Charkhi Dadri , Latitude : 28.535168 , Longitude : 76.178107	Granted vide No. 235 dated 29.06.2006	28.09.2016	30.03.2007	13/08/2023 - 31/03/2028	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 230 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 370 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 117 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	400 MTD	NA	NA	-	NA	Unit is complying presently
259	-	Chaubisi Stone Crusher, Village Mankawas, Tehsil Charkhi Dadri , Latitude : 28.61957 , Longitude : 76.16245	Granted vide No. 3475 dated 11.11.2011	11.11.2011	13.11.2015	12/01/2024 - 31/03/2028	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 320 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 125 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1000 MTD	Issued vide No 1/163098/2023 dated 11.05.2023	16.01.2023 to 12.05.2023 = 116 days	Imposed EC of Rs. 731250 Vide order dated 03.07.2023 and deposited Rs. 731250 on dated 03.07.2023	NA	Unit is complying presently
260	-	Kumar Infra & Mining Projects, Village Jhoju Kalan, Charkhi Dadri , Latitude : 28.517939 , Longitude : 76.146773	Granted vide No. 3312681 dated 02.08.2016	02.08.2016	21.02.2017	04.03.21-31.03.25	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 240 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 210 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	500 MTD	Issued vide No 1347 dated 24.07.2019	16.01.2023 to 18.05.2023 = 123 days	Imposed EC of Rs. 768750 Vide order dated 21.06.2023 and deposited Rs. 768750 on dated 30.06.2023	NA	Unit is complying presently
261	-	Durga Stone Crusher, Vill-Pichopa Kalan, Charkhi Dadri , Latitude : 28.537535 , Longitude : 76.089479	Granted vide No. 5036840 dated 09.02.2018	09.02.2018	31.12.2018	01.04.23-31.03.28	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 230 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 249 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	250 TPH	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/ separate energy meter/ logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
262	-	Shiv Shakti Stone Crusher II Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.5537 , Longitude : 76.0825	Granted vide No. 6415 dated 19.12.2017	19.12.2017	26.07.2018	30.06.20-31.03.25	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 350 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 178 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1100 MTD	Issued vide No 4515-18 dated 05.03.2020	27.03.2019 to 28.02.2020 = 339-45-40.5 (GRAP period 85.5 days) = 253.5 days	Imposed EC of Rs. 1584375 Vide order dated 03.06.2020 and deposited Rs. 1584375 on dated 11.06.2020	NA	Unit is complying presently
263	-	Shri Laxmi Ji Stone Crusher, Pichopa Kalan, Charkhi Dadri , Latitude : 28.629802 , Longitude : 76.165625	Granted vide No. 4794565 dated 07.01.2018	07.01.2018	14.11.2019	06.11.19-31.03-24	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 240 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 163 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 90 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1200 MTD	NA	NA	NA	NA	Unit is complying presently
264	-	Ashoka Stone Crusher, Vill. Mankawas, Charkhi Dadri , Latitude : 28.63114 , Longitude : 76.16528	Granted vide No. 2819 dated 16.09.2011	16.09.2011	26.03.2014	25/01/2024 - 31/03/2028	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 166 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	800 MTD	NA	NA	NA	NA	Unit is complying presently
265	-	Bala Ji Stone Crusher, Vill. Pandwan, Charkhi Dadri , Latitude : 28.61692 , Longitude : 76.1634	Granted vide No. 3765 dated 01.12.2011	01.12.2011	21.01.2013	01.10.18-31.03.25	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 187 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	100 MTD	NA	NA	NA	NA	Unit is complying presently
266	-	Chander Stone Crusher, Village Pandwan, Charkhi Dadri , Latitude : 28.618889 , Longitude : 76.164671	Granted vide No. 3335598 dated 16.09.2016	16.09.2016	21.02.2017	17/01/2024 - 31/03/2029	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 200 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 193 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 100 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	900 MTD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
267	-	Dadri Stone Crusher Village Manakawas Tehsil Charkhi Dadri , Latitude : 28.63064 , Longitude : 76.16746	Granted vide No. 3016967 dated 29.03.2016	29.03.2016	01.07.2016	01.04.21-31.03.25	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 185 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 85 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	200 MTD	Issued vide No 6043-75 dated 29.04.2019	09.12.2019 (GRAP period)	Imposed EC of Rs. 1000000 Vide order dated 24.09.2020 not deposited EC	NA	Unit is complying presently
268	-	Hanuman Infrastructure Pvt. Ltd., Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.551639 , Longitude : 76.083365	Granted vide No. 4614081 dated 25.10.2017	25.10.2017	10.02.2018	22/01/2024 - 31/03/2028	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 310 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 315 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 150 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1500 MTD	NA	NA	NA	NA	Unit is complying presently
269	-	Haryana Stone Crusher, Village Asawari, Charkhi Dadri , Latitude : 28.54821 , Longitude : 76.17971	Granted vide No. 968 dated 09.10.2006	09.10.2006	09.01.2013	30.01.2024-31.03.2028	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 142 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 80 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	550 MTD	NA	NA	NA	NA	Unit is complying presently
270	-	Jai Baba Mungipa Stone Crusher, Pandwan, Charkhi Dadri, Latitude : 28.619224 , Longitude : 76.162767	Granted vide No. 5234369 dated 09.05.2018	09.05.2018	13.05.2019	01/04/2024 - 31/03/2029	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 180 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 110 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	850 MTD	NA	NA	NA	NA	Unit is complying presently
271	-	Jai Bajrang Bali Stone Crusher, Village Ramlawas, Charkhi Dadri , Latitude : 28.489756 , Longitude : 76.144567	Granted vide No. 3433215 dated 23.10.2016	23.10.2016	31.12.2018	05.02.20-31.03.24	50 feet	Unit has provided proper Covered sheds for dust suppression.	Unit has not provided proper & adequate wind breaking wall as per norms.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 410 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 120 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-operational	250 TPH	Issued vide No 1043-47 dated 04.06.2019	29.04.2019 to 21.06.2019 = 54 days & 19.10.2023 to 02.11.2023 =15 Days	Imposed EC of Rs. 421875 Vide HO order and deposited Rs. 421875 on dated 25.11.2019 & EC recommended to HO vide letter dated 25.01.2024 of Rs. 93750	NA	Unit is complying presently




Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ interlocking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
272	-	Jai Balaji Stone Crusher, Vill. Mankawas Charkhi Dadri , Latitude : 28.63052 , Longitude : 76.16672	Granted vide No. 9600 dated 29.01.2009	29.01.2009	07.02.2013	01/04/2024 - 31/03/2029	70 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 211 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 108 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	700 MTD	NA	NA	NA	NA	Unit is complying presently
273	-	Jai Hanuman Stone Crusher, Village Pandwan, Charkhi Dadri , Latitude : 28.61809 , Longitude : 76.16354	Granted vide No. 3153 dated 05.10.2011	05.10.2011	18.01.2017	21/01/2024 - 31/03/2028	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 200 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 156 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	500 MTD	NA	NA	NA	NA	Unit is complying presently
274	-	Laxmi Stone Crusher, Vill. Mankawas, Charkhi Dadri , Latitude : 28.63002 , Longitude : 76.16563	Granted vide No. 9616 dated 29.01.2009	29.01.2009	13.10.2015	01.04.21- 31.03.26	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 200 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 200 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	400 MTD	NA	NA	NA	NA	Unit is complying presently
275	-	Om Shivam Stone Crusher, Village Asawari, Charkhi Dadri , Latitude : 28.55562 , Longitude : 76.14452	Granted vide No. 846 dated 20.06.2008	20.06.2008	19.03.2009	18.11.21- 31.03.24	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 230 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 415 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-operational	650 MTD	Issued vide No 581/2021 dated 06.10.2021	NA	NA	NA	Unit is complying presently, Closed its own
276	-	Om Stone Crusher, Mankawas, Charkhi Dadri	Granted vide No. 3474841 dated 18.01.2017	18.01.2017	25.03.2017	01.04.21- 31.03.26	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 120 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 80 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2000 MTD	NA	NA	NA	NA	Unit is complying presently

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
277	-	Panchmukhi Stone Crusher, Village Mankawas, Charkhi Dadri , Latitude : 28.63248 , Longitude : 76.16487	Granted vide No. 3028453 dated 31.03.2016	31.03.2016	06.05.2016	01.10.20-31.03.25	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 150 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 80 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	250 MTD	NA	NA	NA	NA	Unit is complying presently
278	-	Pritam Sangwan Stone Crusher, Village Asawari, Charkhi Dadri , Latitude : 28.535081 , Longitude : 76.176195	Granted vide No. 3207727 dated 28.06.2016	28.06.2016	07.01.2018	09.05.22-31.03.27	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 150 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 75 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	350 MTD	NA	NA	NA	NA	Unit is complying presently
279	-	Shiv Shanti Stone Crusher, Village Mankawas, Charkhi Dadri , Latitude : 28.63062 , Longitude : 76.16586	Granted vide No. 2315111 dated 13.10.2015	13.10.2015	09.11.2015	01/04/2024 - 31/03/2029	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 200 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 200 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	500 MTD	NA	NA	NA	NA	Unit is complying presently
280	-	Shivalik Stone Crusher, Village Mankawas, Charkhi Dadri , Latitude : 28.63141 , Longitude : 76.16787	Granted vide No. 1027 Dated 30.12.2003	30.12.2003	15.1.2007	01.04.22-31.03.27	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 110 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 90 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	200 MTD	NA	NA	NA	NA	Unit is complying presently
281	-	Shivalya Grit Udyog, Village Mankawas, Charkhi Dadri , Latitude : 28.628753 , Longitude : 76.166135	Granted vide No. 1547 dated 10.12.2007	10.12.2007	15.12.2017	01/04/2024 - 31/03/2029	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 180 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 191 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	500 MTD	NA	NA	NA	NA	Unit is complying presently




Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
282	-	Shree Balaji Stone Crusher, Village Mankawas, Charkhi Dadri, Latitude : 28.63268, Longitude : 76.16544	Granted vide No. 3224 dated 18.10.2011	18.10.2011	08.05.2017	25/01/2024 - 31/03/2028	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 190 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 190 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	750 MTD	NA	NA	NA	NA	Unit is complying presently
283	-	Surya Stone Crusher Vill-Pichopa Kalan, Charkhi Dadri, Latitude : 28.551699, Longitude : 76.08242	Granted vide No. 4924376 dated 10.01.2018	10.01.2018	5594128	24.11.21- 31.03.26	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 310 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 280 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 95 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	3500 MTD	Issued vide No 1/61503/2021 dated 31.08.2021	NA	NA	NA	Unit is complying presently
284	-	Thadeshri Stone Crusher Vill-Mankawas, Charkhi dadri, Latitude : 28.63167, Longitude : 76.16521	Granted vide No. 2360201 dated 20.11.2015	20.11.2015	25.04.2016	01.04.21- 31.03.25	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 200 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 142 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 90 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	1000 MTD	NA	09.12.2019 (Operating during GRAP period)	Imposed EC of Rs. 1000000 Vide order dated 22.09.2020 and deposited Rs. 500000 on dated 17.11.2020 (Submitted 50%)	NA	Unit is complying presently
285	-	kanshi Ram Stone Crusher, Village Mankawas, Charkhi Dadri, Latitude : 28.63169, Longitude : 76.16838	Granted vide No. 280 dated 29.05.2002	29.05.2002	03.02.2004	01.04.23- 31.03.28	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 210 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 180 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 105 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	2000 MTD	Issued vide No 1/163110/2023 dated 11.05.2023	16.01.2023 to 12.05.2023 = 116 days	Imposed EC of Rs. 725000 Vide order dated 21.06.2023 and deposited Rs. 725000 on dated 12.07.2023	NA	Unit is complying presently
286	-	Gawar Construction Ltd., Village Mankawas, Charkhi Dadri, Latitude : 28.63162, Longitude : 76.16637	Granted vide No. 9624 dated 29.1.2009	29.1.2009	19.3.2009	01.04.23- 31.03.28	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of 16 feet height & 170 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 230 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 250 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Operational	200 MT/D	Issued on dated 11.5.2023	16.1.2023- 12.5.2023	Imposed EC of Rs. 731250 Vide order dated 21.06.2023 and deposited Rs. 731250 on dated 28.06.2023	NA	Unit is complying presently
287	-	Anjani Mata Stone crusher Village Pichopa Kalan, Charkhi Dadri, Latitude : 28.55136, Longitude : 76.09074	Granted vide No. 431 dated 25.07.2006	25.07.2006	10.01.2008	Valid upto 31.03.24 & revocation in process	30 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	200 MTD	Issued vide No 1/163121/2023 dated 11.05.2023	16.01.2023 to 16.05.2023 =121 days	Recommended levy of EC of Rs. 756250 Vide letter no. 1523 dated 25.01.2024	Unit has been closed by the Board	Unit has been closed by the Board

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/ logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
288	-	Ashu Stone Crusher Vill. Manakawas, Charkhi Dadri , Latitude : 28.62931 , Longitude : 76.16593	Granted vide No. 2019 dated 28.01.2008	28.01.2008	04.12.2013	Valid upto 31.03.24 & revocation in process	100 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	400 MTD	Issued vide No 1/163118/2023 dated 11.05.2023	16.01.2023 to 12.05.2023 =117 Days	Recommended levy of EC of Rs. 731250 Vide letter no. 1526 dated 25.01.2024	Unit has been closed by the Board	Unit has been closed by the Board
289	-	Baba Hanuman Minerals Vill-Jhojhu Kalan, Charkhi Dadri , Latitude : 28.496749 , Longitude : 76.155916	Granted vide No. 3250222 Dated 1.7.2016	1.7.2016	6.12.2016	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	NA	NA	NA	NA	Dismantled
290	-	Baba Hanuman Stone Crusher, Village Mankawas, Charkhi Dadri , Latitude : 28.62832 , Longitude : 76.16411	Granted vide No. 3340 Dated 3.11.2011	3.11.2011	22.12.2015	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	NA	NA	NA	NA	Dismantled
291	-	Bhawani Stone Crusher, Village Jhojhu Kalan, Charkhi Dadri , Latitude : 28.497356 , Longitude : 76.150203	Granted vide No. 3303676 Dated 30.8.2016	30.8.2016	9.1.2018	Not having valid CTO & Closed by Board	70 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	450 MTD	Issued vide No 1018 Dated 4.6.2019	NA	NA	Unit has been closed by the Board	Unit has been closed by the Board
292	-	Chander Bhan Stone Crusher, Village Asawari, Charkhi Dadri , Latitude : 28.55116 , Longitude : 76.14046	Granted vide No. 3037 Dated 30.9.2011	30.9.2011	21.5.2012	Not having valid CTO & Closed by Board	70 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	NA	Issued vide No 163108 Dated 11.5.2023	NA	NA	NA	Dismantled
293	-	Chaudhary Stone Crusher Vill-Birhi Kalan, Distt Charkhi Dadri , Latitude : 28.6036 , Longitude : 76.136005	Granted vide No. 3600 dated 12.10.2017	12.10.2017	15.05.2018	Not having valid CTO & dismantled	--	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	NA	NA	NA	NA	Dismantled
294	-	Chirag Stone Crusher, Village Birhi Kalan, Charkhi Dadri , Latitude : 28.607425 , Longitude : 76.141398	Granted vide No. 3338583 dated 19.08.2016	19.08.2016	17.11.2017	01/04/2022 - 31/03/2027	80 feet	Unit has not provided proper Covered sheds for dust suppression.	Provided Wind breaking wall of 16 feet height & 300 feet Length and telescopic chute about three feet below the Wind breaking wall	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 325 Plants and plantation plan obtained from DFO & same is also verified by DFO	Not provided sufficient number of water sprinklers	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Closed by Board	280 MTD	Issued vide No 4343 dated 25.02.2020	11.10.2023 to 19.12.2023 =69-26(GRAP period)=43 Days	Imposed EC of Rs. 268750/- Vide order dated 21.12.2023 and not deposited EC	Closed by Board	Closed by Board
295	-	Dada Gosai Stone Crushing Mills, Mankawas, Charkhi Dadri , Latitude : 28.62828 , Longitude : 76.16504	Granted vide No. 6618 Dated 10.9.2007	10.9.2007	8.9.2015	Valid upto 31.03.24 & revocation in process	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	Issued vide No 1/1631117/2023 dt 11.5.2023	16.01.2023 to 12.05.2023 =117 days	Recommended levy of EC of Rs. 731250 Vide letter no. 1533 dated 25.01.2024	NA	Dismantled
296	-	Dehli Stone Crusher, Village Mankawas, Charkhi Dadri , Latitude : 28.63039 , Longitude : 76.16512	Granted vide No. 2448106 Dated 7.1.2016	7.1.2016	25.4.2016	Valid upto 31.03.24 & revocation in process	-	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	NA	NA	NA	NA	NA	Dismantled

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
297	-	Dev Dahiya Stone Crusher, Village Jhoju Kala Charkhi Dadri , Latitude :28.5732 , Longitude : 76.208	Granted vide No. 3448570 Dated 7.2.2017	7.2.2017	16.05.2019	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	Issued vide No 9011 Dated 13.5.2019	NA	NA	NA	Dismantled
298	-	Dev Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.558261 , Longitude : 76.18614	Granted vide No. 2159571 Dated 27.9.2015	27.9.2015	9.11.2015	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	NA	NA	NA	NA	Dismantled
299	-	Dosti Stone Crusher, Village Asawari, Charkhi Dadri , Latitude : 28.54845 , Longitude : 76.17875	Granted vide No. 9628 Dated 29.1.2009	29.1.2009	30.3.2013	Not having valid CTO & Closed by Board	70 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	85 MT/D	Issued vide No 1670-72 Dated 29.05.2014	NA	NA	Unit has been closed by the Board	Unit has been closed by the Board
300	-	Gau Mata Stone Crusher, Pichopa Kalan, Charkhi Dadri , Latitude : 28.551561 , Longitude : 76.081835	Granted vide No. 5376046 Dated 2.7.2018	2.7.2018	14.11.2019	Valid upto 31.03.27 & revocation in process	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	Issued vide No 61664 Dated 31.8.2021	NA	NA	NA	Dismantled
301	-	Goyat Stone Crusher, Village Pandwan Charkhi Dadri , Latitude : 28.622506 , Longitude : 76.163098	Granted vide No. 3292 dated 11.09.2017	11.09.2017	25.06.2019	Not having valid CTO & dismantled	-	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	NA	Issued vide No 1/8091/2020 dated 12.11.2020	NA	NA	NA	Dismantled
302	-	Hari Dass Stone Crusher Vill. Asawari Charkhi Dadri , Latitude : 28.570385 , Longitude : 76.185179	Granted vide No. 3473 dated 11.11.2011	11.11.2011	09.01.2015	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	Issued vide No 1742 dated 13.09.2019	NA	NA	NA	Dismantled
303	-	Himalya Stone Crusher Village Jhoju Kalan, Charkhi Dadri , Latitude : 28.5216309 , Longitude : 76.150838	Granted vide No. 3419094 dated 03.01.2017	03.01.2017	17.11.2017	Not having valid CTE & Plant & Machinery not installed	-	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Non-operational and not installed plant & machinery	NA	Issued vide No 1033-37 dated 04.06.2019	29.04.2019 to 21.06.2019 = 54 days	Imposed EC of Rs. 421875 Vide order dated 15.11.2029 not deposited EC	NA	Plant & Machinery not installed
304	-	Jai Baba Thakur Dass Stone Crusher Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.53175 , Longitude : 76.09069	Granted vide No. 3229495 dated 06.04.2016	06.04.2016	16.05.2017	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	NA	NA	NA	NA	Dismantled
305	-	Jai Bajrang Bali Stone Crusher, Village Mankawas, Charkhi Dadri , Latitude : 28.627984, Longitude : 76.164989	Granted vide No. 9626 dated 29.01.2009	29.01.2009	23.11.2019	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	Issued vide No 4105 dated 13.02.2020	23.11.2019 to 14.02.2020 = 84-26-29 (GRAP period)=29 days	Imposed EC of Rs. 181250 Vide order dated 09.07.20 and deposited Rs. 181250 on dated 10.07.20	NA	Dismantled
306	-	Jai Bhawani Stone Crusher, Ramakwas, Charkhi Dadri , Latitude : 28.497083 , Longitude : 76.150397	Granted vide No. 3814459 dated 09.05.2017	09.05.2017	11.06.2018	Not having valid CTO & Closed by Board	50 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	100 MTD	Issued vide No s4185 dated 14.02.2020	NA	NA	Unit has been closed by the Board	Unit has been closed by the Board

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers/ inter locking system/ separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
307	-	Jai Parkash Associates Ltd., Village Mehra, Charkhi Dadri , Latitude : 28.558235 , Longitude : 76.1674	Granted vide No. 1916 dated 17.01.2008	17.01.2008	17.03.2009	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	NA	NA	NA	NA	Dismantled
308	-	Jai Parkash Associates Ltd., Village Mehra, Khasra No. 78//3 (8K-0M), Charkhi Dadri , Latitude : 28.558235 , Longitude : 76.1674	Granted vide No. 1920 dated 17.01.2008	17.01.2008	17.03.2009	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	NA	NA	NA	NA	Dismantled
309	-	Jai Parkash Associates Ltd., Village Mehra, Khasra No. 89//10 (8K-0M), Charkhi Dadri , Latitude : 28.558241 , Longitude : 76.167	Granted vide No. 9588 dated 29.01.2009	29.01.2009	13.05.2009	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	NA	NA	NA	NA	Dismantled
310	-	Jai Parkash Associates Ltd., Village Mehra, Khasra No. 89//1, Charkhi Dadri , Latitude : 28.558241 , Longitude : 76.167	Granted vide No. 9588 dated 29.01.2009	29.01.2009	13.05.2009	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	NA	NA	NA	NA	Dismantled
311	-	Jyoti Stone Crushers Village Pandwan Charkhi Dadri , Latitude : 28.614222 , Longitude : 76.162595	Granted vide No. 5147236 dated 24.04.2018	24.04.2018	26.07.2018	Not having valid CTO & dismantled	-	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	NA	Issued vide No 1524 dated 19.10.2020	NA	NA	NA	Dismantled
312	-	K.M.P Stone Crusher, Vill Pichopa Kalan, Charkhi Dadri , Latitude : 28.539506 , Longitude : 76.08865	Granted vide No. 5109346 dated 26.03.2018	26.03.2018	12.06.2019	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	Issued vide No 714 dated 16.06.2020	NA	NA	NA	Dismantled
313	-	Luxmi Stone Crusher, Asawari, Charkhi Dadri , Latitude : 28.53612 , Longitude : 76.1769	Granted vide No. 3157 dated 05.10.2011	05.10.2011	21.01.2013	Not having valid CTO & Closed by Board	50 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	80 MTD	Issued vide No 163123/2023 dated 11.05.2023	16.01.2023 to 18.05.2023 =123 days	Recommended levy of EC of Rs. 768750 Vide letter no. 1532 dated 25.01.2024	Unit has been closed by the Board	Unit has been closed by the Board
314	-	Mahadev Stone Crusher, Village Mankawas, Charkhi Dadri , Latitude : 28.567585 , Longitude : 76.18856	Not obtained CTE and closed by the Board on 04.01.2010.	Not obtained CTE and closed by the Board on 04.01.2010.	Not obtained CTE and closed by the Board on 04.01.2010.	Not obtained CTE and closed by the Board on 04.01.2010.	-	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Non-operational and not installed plant & machinery	NA	NA	NA	NA	NA	Plant & Machinery not installed
315	-	Mahadev Stone Crushing Co., Village Jhoju Kalan, Charkhi Dadri , Latitude : 28.486071 , Longitude : 76.142128	Granted vide No. 3387106 dated 28.09.2016	28.09.2016	02.01.2018	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	Issued vide No 1048-52 dated 04.06.2019	29.04.2019 to 21.06.2019 = 54 days	Imposed EC of Rs. 421875 Vide order dated 14.11.2019 not deposited EC	NA	Dismantled
316	-	Mahan Stone Crusher, Tikan Khurd, Charkhi Dadri , Latitude : 28.54921 , Longitude : 76.28843	Old unit (Before notification dated 17.08.1992)	Old unit (Before notification dated 17.08.1992)	10.06.2002	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	NA	NA	NA	NA	Dismantled




Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
317	-	Maruti Stone Crusher, Pandwan Charkhi Dadri (Old Name M/s Maruti Stone Crusher, Village Mankawas, Charkhi Dadri), Latitude : 28.56995, Longitude : 76.18523	Granted vide No. 3155 dated 05.10.2011	05.10.2011	30.07.2017	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	NA	NA	NA	NA	Dismantled
318	-	N K Builders & Stone Crusher Vill-Birhi Kalan, Charkhi Dadri, Latitude : 28.598239, Longitude : 76.138952	Granted vide No. 3247611 dated 29.06.2016	29.06.2016	01.04.2017	Not having valid CTO & dismantled	--	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	NA	NA	NA	NA	Dismantled
319	-	Om Stone Crusher, Asawari, Charkhi Dadri, Latitude : -, Longitude : -	Granted vide No. 5136936 dated 28.02.2018	28.02.2018	Not obtained	Not having valid CTE & Plant & Machinery not installed	-	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Non-operational and not installed plant & machinery	NA	NA	NA	NA	NA	Plant & Machinery not installed
320	-	Peer Baba Stone Crusher, Village Asawari, Charkhi Dadri, Latitude : 28.536242, Longitude : 76.175489	Granted vide No. 3151 dated 05.10.2011	05.10.2011	31.03.2013	Not having valid CTO & dismantled	-	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	NA	NA	16.01.2023 to 18.05.2023 = 123 Days	Recommended levy of EC of Rs. 768750 Vide letter no. 1530 dated 25.01.2024	NA	Dismantled
321	-	Pokhar Stone Crusher, Vill. Ramalwas, Charkhi Dadri, Latitude : 28.49682, Longitude : 76.15	Granted vide No. 3156 dated 05.10.2011	05.10.2011	20.10.2014	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	Issued vide No. 1023-27 dated 04.06.2019	29.04.2019 to 21.06.2019 = 54 days	Imposed EC of Rs. 421875 Vide order dated 14.11.19 and not deposited EC	NA	Dismantled
322	-	R. K. Carriers India Private Limited, Village Mehrda Charkhi Dadri, Latitude : 28.555347, Longitude : 76.175	Granted vide No. 3422227 dated 24.10.2016	24.10.2016	22.11.2017	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	NA	NA	NA	NA	Dismantled
323	-	Rapid Stone Crusher Vill-Birhi Kalan, Charkhi Dadri, Latitude : 28.60902, Longitude : 76.13947	Granted vide No. 3062016 dated 18.04.2016	18.04.2016	07.07.2016	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	NA	NA	NA	NA	Dismantled
324	-	Rattan Stone Crusher, Village Pandwan, Charkhi Dadri, Latitude : , Longitude :	Granted vide No. 3478 dated 11.11.2011	11.11.2011	Not obtained	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	NA	NA	NA	NA	Dismantled
325	-	Sajjan Singh Stone Crusher, Village Pichopa Kalan, Charkhi Dadri, Latitude : 28.552927, Longitude : 76.091306	Granted vide No. 957-58 dated 07.10.2004	07.10.2004	16.09.2005	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	NA	NA	NA	NA	Dismantled
326	-	Shanker Stone Crusher, Village Jhojhu Kalan, Charkhi Dadri, Latitude : 28.190769, Longitude : 76.611725	Granted vide No. 3418167 dated 31.10.2016	31.10.2016	10.05.2018	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	Issued vide No 1029 dated 04.06.2019	NA	NA	NA	Dismantled
327	-	Shiva Stone Crushing Mills, Village Jhojhu Kalan, Charkhi Dadri, Latitude : 28.607476, Longitude : 76.139843	Granted vide No. 3387058 dated 11.10.2016	11.10.2016	30.01.2018	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	Issued vide No 877 dated 09.05.2019	NA	NA	NA	Dismantled

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment cum suppressing system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
328	-	Shree Balaji Stone Crusher, Village Pichopa Kalan, Charkhi Dadri, Latitude : 28.55199, Longitude : 76.09076	Granted vide No. 136 dated 14.06.2006	14.06.2006	07.10.2015	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	NA	NA	NA	NA	Dismantled
329	-	Shree Balaji Stone Crushing Co. Village Jhohju Kalan, Charkhi Dadri, Latitude : 28.55398, Longitude : 76.082667	Granted vide No. 3417725 dated 31.10.2016	Not available	18.01.2017	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	Issued vide No. 1053-57 dated 04.06.2019	NA	NA	NA	Dismantled
330	-	Shree Ganesh Stone Crusher, Village Asawari, Charkhi Dadri, Latitude : 28.5361, Longitude : 76.1773	Granted vide No. 9594 dated 29.01.2009	29.01.2009	19.03.2009	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	NA	NA	NA	NA	Dismantled
331	-	Shree Ganpati Stone Crushing Mills, Village Ramalwas, Charkhi Dadri, Latitude : 28.5703, Longitude : 76.1867	Granted vide No. 3578298 dated 03.01.2017	03.01.2017	07.09.2020	Valid upto 31.03.25 & revocation in process	80 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	3000 MTD	Issued vide No 882 dated 09.05.2019	29.04.2019 to 28.05.2019 = 30 days	Imposed EC of Rs. 234375 Vide order dated 21.11.2019 and deposited Rs. 234375 on dated 26.12.2019	Unit has been closed by the Board	Unit has been closed by the Board
332	-	Shree Mahadev Stone Crusher, Village Pichopa Kalan, Charkhi Dadri, Latitude : 28.5325832, Longitude : 76.0756637	Granted vide No. 9578 dated 29.01.2009	29.01.2009	25.11.2017	Valid upto 31.03.26 & revocation in process	30 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	200 MTD	Issued vide No. 1/0431 dated 03.08.2023	03.05.2023 to 29.08.2023 =119 days	Recommended levy of EC of Rs. 743750 Vide letter no. 1527 dated 25.01.2024	Unit has been closed by the Board	Unit has been closed by the Board
333	-	Shree Shyam Grit Udyog Vill-Ramalwas, Charkhi Dadri, Latitude : 28.501, Longitude : 76.147	Granted vide No. 3268395 dated 27.07.2016	27.07.2016	11.03.2018	Valid upto 31.03.27 & revocation in process	30 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	300 TPH	Issued vide No 4193 dated 14.02.2020 & No. 63102/2023 dated 11.05.2023	16.01.2023 to 18.05.2023 =123 days	Recommended levy of EC of Rs. 768750 Vide letter no. 1534 dated 25.01.2024	Unit has been closed by the Board	Unit has been closed by the Board
334	-	Shri Dada Devi Nath Stone Crusher, Village Pichopa Kalan, Charkhi Dadri, Latitude : 28.5325832, Longitude : 76.0756637	Granted vide No. 3409108 dated 06.10.2016	06.10.2016	30.06.2017	Not having valid CTO & Closed by Board	40 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	200 MTD	issued vide No., 4241-4244 dated 17.02.2020	NA	NA	Unit has been closed by the Board	Unit has been closed by the Board
335	-	Shri Ganesh Ji Stone Crusher Vill Pichopa Kalan Charkhi dadri, Latitude : 28.542649, Longitude : 76.089912	Granted vide No. 321 dated 17.07.2017	17.07.2017	26.07.2018	Not having valid CTO & Closed by Board/Dismantled	-	The unit was found Closed by Board/Dismantled at the time of inspection.	The unit was found Closed by Board/Dismantled at the time of inspection.	The unit was found Closed by Board/Dismantled at the time of inspection.	The unit was found Closed by Board/Dismantled at the time of inspection.	The unit was found Closed by Board/Dismantled at the time of inspection.	The unit was found Closed by Board/Dismantled at the time of inspection.	The unit was found Closed by Board/Dismantled at the time of inspection.	The unit was found Closed by Board/Dismantled at the time of inspection.	Non-operational	NA	Issued vide No 3128-31 dated 31.10.2019 & No. 1/163101/2023 dated 11.05.2023	NA	NA	NA	The unit was closed by board & found dismantled
336	-	Shyam Grit Udyog Village Pichopa Kalan Charkhi Dadri, Latitude : 28.552, Longitude : 76.0883	Granted vide No. 3268395 dated 27.07.2016	27.07.2016	29.08.2017	Valid upto 31.03.26 & revocation in process	30 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	250 MTD	Issued vide No 4193 dated 14.02.2020 & No. 1/170479/2023 dated 04.08.2023	03.05.2023 to 29.08.2023 =119 days	Recommended levy of EC of Rs. 743750 Vide letter no. 1524 dated 25.01.2024	Unit has been closed by the Board	Unit has been closed by the Board

Sr No.	Respondent No.	Name and address of the unit & GPS Coordinate	CTE Status	Date of establishment/ setting up of the Stone Crusher (Grant of CTE)	Date of first operation after establishment (First CTO Granted to Stone Crusher)	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher )	Status of Covered shed/Dust containment system/.	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Covering of Vehicle.	Operational Status	Production capacity as per latest CTO and as per on site conditions	Date of closure, if any	Violation of environmental norms in past period, if any	Environment Compensation Status	Action Taken	Remarks
337	-	Suman Stone Crusher, V.P.O- Pichopa Kalan, Charkhi Dadri , Latitude : 28.5325832 , Longitude : 76.0756637	Granted vide No. 5715225 dated 10.11.2018	10.11.2018	17.10.2019	Valid upto 31.03.25 & revocation in process	300 feet	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	The unit was found Closed by Board at the time of inspection.	Non-operational	250 MTD	Issued vide No 4189 dated 14.02.2020 & No. 1/170149/2023 dated 29.07.2023	17.10.2019 to 19.02.2020 =126-45-36 (GRAP period) = 45 days	Imposed EC of Rs. 281250 & 181250 Vide order dated 15.06.2020 and deposited Rs. 281250 & 181250 on dated 16.06.2020 & 27.10.2023	Unit has been closed by the Board	Unit has been closed by the Board
338	-	Surender Stone Crusher, Village Pichopa Kalan, Charkhi Dadri , Latitude : 28.5325832 , Longitude : 76.0756637	Not having valid CTE & Plant & Machinery not installed	Not available	Not available	Not having valid CTE & Plant & Machinery not installed	-	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Non-operational and not installed plant & machinery	NA	NA	NA	NA	NA	Plant & Machinery not installed
339	-	Trimbakeshwar Stone Crusher, Village Jhojhu Kalan, Charkhi Dadri , Latitude : 28.485338 , Longitude : 76.143883	Granted vide No. 3599 dated 12.10.2017	12.10.2017	27.01.2018	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	Issued vide No 1014-19 dated 04.06.2019	NA	NA	NA	Dismantled
340	-	V K Stone Crushing Co Vill-Birhi Kalan, Charkhi Dadri , Latitude : 28.6098 , Longitude : 76.1388	Granted vide No. 3501081 dated 05.12.2016	05.12.2016	16.02.2018	Not having valid CTO & dismantled	-	TheDismantled/Plant & Machinery not installed at the time of inspection.	TheDismantled/Plant & Machinery not installed at the time of inspection.	TheDismantled/Plant & Machinery not installed at the time of inspection.	TheDismantled/Plant & Machinery not installed at the time of inspection.	TheDismantled/Plant & Machinery not installed at the time of inspection.	TheDismantled/Plant & Machinery not installed at the time of inspection.	TheDismantled/Plant & Machinery not installed at the time of inspection.	TheDismantled/Plant & Machinery not installed at the time of inspection.	Non-operational	NA	NA	NA	NA	NA	Dismantled Plant & Machinery
341	-	Vijay Stone Crusher, Village Asawari, Charkhi Dadri , Latitude : 28.55005 , Longitude : 76.139633	Granted vide No. 3036 dated 30.09.2011	30.09.2011	Plant & Machinery not installed	Not having valid CTE & Plant & Machinery not installed	-	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Plant & Machinery not installed	Non-Operational and not installed plant & machinery	NA	NA	NA	NA	NA	Plant & Machinery not installed
342	-	Vikas Stone Crusher, Mankawas, Charkhi Dadri , Latitude : 28.62698 , Longitude : 76.16418	Granted vide No. 2820 dated 16.09.2011	16.09.2011	23.01.2016	Not having valid CTO & dismantled	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of about 16 feet height & 260 feet Length and telescopic chute about three feet below the Wind breaking wall.	Metalled road provided for Vehicular movement within premises	Unit has provided Wetting & Cleaning of the ground provided during inspection	Provided Green belt of 300 Plants and plantation plan obtained from DFO & same is also verified by DFO	Provided 135 Water sprinklers for dust suppression	Interlocking system of water sprinkler system with stone crusher machine provided and maintained logbook for water & energy consumption	Provided Covered vehicle during inspection	Non-operational	200 MTD	NA	NA	NA	NA	Unit is complying presently, Closed its own
343	-	Vishwakarma Stone Crusher, Village Jhojhu Kalan, Charkhi Dadri , Latitude : 28.5216309 , Longitude : 76.150838	Granted vide No. 3428902 dated 23.10.2016	23.10.2016	Not obtained	Not having valid CTO & dismantled	-	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Unit found dismantled at the time of inspection	Non-operational	NA	Issued vide No. 887 dated 09.05.2019	NA	NA	NA	Dismantled