



क्षेत्रीय कार्यालय, उत्तर प्रदेश प्रदूषण नियंत्रण बोर्ड
REGIONAL OFFICE, U. P. POLLUTION CONTROL BOARD

दूरभाष: / Ph. : 0532-2569727

आवास विकास परिषद कालोनी, सेक्टर-10, योजना संख्या-3, झुंसी, प्रयागराज - 221506
Avas Vikas Parishad Colony, Sector-10, Scheme No. 3, Jhansi, Prayagraj.

संदर्भ सं०..... G/00135/O.A. 203/2021-22

दिनांक..... 17/05/2022

To,
The Registrar,
National Green Tribunal
Principal Bench,
New Delhi
E-Mail- judicial-ngt@gov.in

E-Mail/Registered Post

Subject: - Compliance of direction issued by Hon'ble National Green Tribunal in Original Application No. 203/2021 Devidas Khatri Versus Union of India & Ors. in order dated 01-02-2022.

Sir,

With reference to the above subject mentioned above, this is to inform you that in compliance of order issued on 01-02-2022 by Hon'ble National Green Tribunal in Original Application No. 203/2021 Devidas Khatri Versus Union of India & Ors. The compliance report is submitted for your kind perusal and necessary action please.

Your Sincerely


(R. K. Singh)
Regional Officer

Copy to:-

1. Commissioner, Prayagraj Division Prayagraj for information.
2. Member Secretary, U.P. Pollution Control Board Lucknow for information.
3. Sri Pradeep Misra, Advocate Hon'ble Supreme Court/NGT, New Delhi for perusal and necessary action please.
4. Chief Law Officer, U.P. Pollution Control Board Lucknow for information.
5. Chief Environmental Officer (Circle-2), U.P. Pollution Control Board Lucknow for information.


Regional Officer

Report of Joint Committee in Compliance to the Hon'ble NGT order dated 01.02.2022 in Original Application No.203/2021 in the Matter of "Devidas Khatri Vs Union of India &Others."

The Hon'ble National Green Tribunal Principal Bench vide order dated 01-02-2022 constituted a joint committee of Commissioner Prayagraj, CPCB, State PCB, SEIAA, UP and Nominated Member of Secretary Agriculture.

The relevant para of said order, is reproduced hereunder: -

"We note that mining of silica sand as well as washing plants involve environmentally hazards activities, having adverse health impacts. The observation of the Committee show large scale deficiencies in conducting mining and washing operations, storage and transportation. The failures of the Project Proponents (PPs) include unscientific treatment of waste water, absence of flow meters, absence of demarcation, absence of proper approach roads, failure to control fugitive emissions, unscientific storage of overburden, absence of record about expenditure under CER plans, absence of health record, absence of monitoring stations, absence of display boards and CCTV cameras, absence of adequate green belts. However, remedial action is hardly adequate to ensure compliance and to protect environment and public health.

It is not clear whether any requisite Environmental Clearance (EC) has been granted for mining and whether the EIA reports which are said to have been submitted have been duly appraised. There is also no proper assessment of compensation, corresponding to the damage caused to the environment and public health. 8 6. According to the applicant, there are more than 500 silica sand washing units but only 54 are mentioned in the report. There is need to take remedial action for ensuring compliance of environmental norms by stopping hazardous activity till compliance. CCTV cameras, monitoring stations, green belts and all other safeguards need to be established. The applicant seek permission to file all photographs/videos with the District Magistrate, Prayagraj within one week, which may be done.

Since further remedial action is required in the light of above report and observations made by us, we constitute a joint Committee with the Divisional Commissioner, Prayagraj as Chairman and the Chief Conservator of Forest, Allahabad and nominees of CPCB, State PCB, SEIAA UP and Secretary, Agriculture (an expert in soil conservation) as members to ensure that all washing units/mining leases conduct their activities in accordance with the statutory procedures and environmental norms and compensation is assessed and recovered for the past violations. The Committee may undertake visit to the sites within two months and after coordinated remedial action furnish a report, keeping in mind the earlier report as well as observations made hereinabove by e-mail at judicialngt@gov.in preferably in the form of searchable PDF/ OCR Support PDF and not in the form of Image PDF. List for further consideration on 18.05.2022. A copy of this order be forwarded to the Divisional Commissioner, Prayagraj, Chief Conservator of Forest, Prayagraj, CPCB, State PCB, SEIAA UP and Secretary, Agriculture UP by e-mail.

In compliance of Hon. NGT order dated 01.02.2022 Commissioner, Prayagraj constituted a committee of following members as follows: -

1.	Commissioner Prayagraj	Chairman
2.	Chief Conservator Forest, Prayagraj	Member
3.	Member of CPCB	Member
4.	Member of UPPCB	Member
5.	Member of SEIAA	Member
6.	Nominated Member of Secretary Agriculture	Member

1. The first meeting of joint committee was held on dated 15.03.2022 to review the compliance of directions issued by Hon. NGT. Commissioner Prayagraj also reviewed the concerned departments i.e. UPPCB and Mining Department for the strict compliance of conditions imposed by SEIAA and consent issued by UPPCB. The Commissioner Prayagraj also directed to the chief forest conservator along with Deputy Director Agriculture for finding solutions of afforestation in existing mining area, washing units as well as abandoned mining areas of Shankargrah Block according to geographical conditions so as to foster ecological condition of the area.

The Commissioner Prayagraj also directed to Mining Department be vigilant and to take strict action against any illegal mining activities found. Minutes of Meeting dated 15.03.2022 (Annexure No. 1)

2. As per minutes of review meeting dated 15.03.2022 the compliance report submitted by Mining Deptt. and R.O., UPPCCB.(Annexure No. 2)
3. The second meeting to review the compliance & directions given in meeting dated 15.03.2022 was held on dated 11.04.2022(Annexure No. 3)
4. As per minutes of review meeting dated 11.04.2022 the compliance report submitted by Mining Deptt. and regional officer UPPCCB.(Annexure No. 4)
5. As per compliance report of mining department and R.O., UPPCB weigh bridge & CCTV Cameras has been established in all seven running mines. Geo Coordinates with proper demarcation also has been completed.

R.O, UPPCB Prayagraj informed to Chairman of committee that in compliance of conditions imposed in consent to operate letter of 41 existing and running units water meter has been installed on the inlet source of water. Kaccha Pits are being replaced by Pucca Pits& logbook for water meter, Raw Material, Finished Products & Manpower is being started to maintain.

6. The chairman of the committee, Commissioner Prayagraj directed to Mining Officer, Revenue Department, Agriculture Department and Forest Department to constitute a joint team which will survey the complete area of Shankargrah for restoration of abandoned Mines with forestation. The forest department was directed by Chairman to prepare a plan for restoration and forestation of abandoned mines and to mention the techniques and methodology that can be used for aforesaid work.
7. As per the directions of the Commissioner Prayagraj, District Magistrate Prayagraj has constituted a 05 member committee vide letter dated 22.04.2022 headed by SDM, Bara, Prayagraj for making work plan in the area of Shankargrah Block for forestation of ongoing and abandoned mining leases along with silica washing units. The committee has been directed to complete the working plan for all the silica leases and washing units in next 03 months. (Annexure No. 5)

In compliance of the said order a project was prepared specially to increase the forest cover in existing operational lease and abandoned lease and silica washing units. The committee is preparing specific action plan for each unit. A model of the said action plan is annexed (Annexure No. 6)

8. A site visit of Commissioner Prayagraj along with the officers of the constituted committee was done on dated 12.05.2022. Commissioner Prayagraj visited mines area as well as washing plants. Photographs are annexed as **(Annexure No. 7)** After random site visit Commissioner Prayagraj also constituted 04 committees for verifying each plants & mines and prepared a check list for the inspection by the committee. Annexure of check list **(Annexure No.8)**
9. The committee were directed to check to each and every point of directions issued by Hon. NGT and submit their report in check list form within 02 days after site visit. Committee surveyed the area of Shankargrah and found only seven running mines and 41 established silica sand washing units. The report and photographs of survey of 04 committee is annexed **(Annexure No. 9)**

As per the compliance reports and field verification it is found that the total no. of operational mines are 07 & silica washing plants are 41.

In compliance of the order Hon. NGT through site visits and survey of the areafindings and direction issued in **silica mining leases& washing units**






S. N	Details of Area	Committees finding Summarised	Directions issued
1	07 Running Silica Mining Lease Area	<p>1. In all the lease area Weigh Bridge, CCTV, DisplayBoard, Environment Clearance, Common Facility & Maintenance of records, Pillars with coordinates, Approach Road, Present Benching Status in mining area were found as per directions</p> <p>2. Green Belt/Plantation, needs to be improved</p>	<p>1. Mining Officer has issued directions to all the lease holders to follow the Mining Plan for plantation yearly as well as unit specific action plan for afforestation prepared by committee headed by SDM, Bara, Prayagraj. (Annexure No. 10)</p>
2	41 Silica Washing Units	<p>1. Water Flow Meter installation, Rain Water Harvesting, Record Keeping, UPPCB Consent, Display Board, CGWA Consent for above 10 KLD Water use were found as per direction issued.</p> <p>2. 02 Units need to convert water storage tank from unlined to lined storage tank & 05 units were found to be under construction.</p> <p>3. Out of 41 silica washing units 06 units were closed by UPPCB for non compliance and 02 units were closed due to their own reasons.</p> <p>4. More plantations is required in existing Green Belt area of the units.</p>	<p>R.O., UPPCB Prayagraj has :-</p> <p>(i) issued directions for completion of unlined storage tank in 15 days.</p> <p>(ii) issued directions to all the washing units to follow the plantation as per Consent order as well as unit specific action plan for afforestation prepared by committee headed by SDM, Bara, Prayagraj.</p> <p>(iii) Direction issued to convert temporary boundary wall to permanent boundary wall structure in next 03 months.</p> <p>(iv) to prepare a monthly register for periodic health check-ups. (Annexure No. 11)</p>

		<p>5. The temporary Boundary wall to be replaced by permanent boundary walls.</p> <p>6. Maintenance of the records of Health Check up as during the visit it was found that Health check up were done but records were not maintained.</p>	
--	--	--	--

Committee Recommendations

1. In all the silica mining leases area should be demarcated for yearly plantation with signage as per mining plan.
2. Installed weigh bridge at the mining site should be fully integrated with centralised command centre situated in Directorate of Geology & Mining like the weigh bridges installed at washing units of said leases are integrated with centralised command centre situated in Directorate of Geology & Mining.
3. R.O., UPPCB in consultation with UP Ground Water Department explore the possibility of minimising ground water use by increasing sedimentation tanks of the washing units in a scientific manner, to develop a eco-friendly model for silica washing units within a period of 03 months.
4. The committee formed by District Magistrate Prayagraj by his order dated 22.04.2022 including Revenue Department, Forest Department, R.O., UPPCB, Agriculture, Mining Department to prepare a working plan for the eco-restoration of the abandoned Mines. the committee in next 06 months shall prepare a work plan for eco-restoration of the abandoned mines of Shankargrah area of Prayagraj. **Annexed as Annexure. no. 5**

The joint committee report in compliance to the Hon. NGT order dated 01.02.2022 in O.A. No. 203/2021 is being submitted for kind perusal

Name of the Committee Members			Signature
1.	Commissioner Prayagraj	Chairman	
2.	Chief Conservator Forest, Prayagraj	Member	
3.	Member of CPCB	Member	
4.	Member of UPPCB	Member	 R.O. UPPCB
5.	Member of SEIAA	Member	
6.	Nominated Member of Secretary Agriculture	Member	 DDSC

Annex. 1

me
24/03/2022

मा0 राष्ट्रीय हरित अधिकरण (एन0जी0टी0), नई दिल्ली में योजित ओ0ए0 नं0 203/2021 देवीदास खत्री बनाम यूनियन ऑफ इण्डिया एवं अन्य में पारित आदेश दिनांक 01.02.2022 के अनुपालन में दिनांक 16.03.2022 को मण्डलायुक्त की अध्यक्षता में आयोजित बैठक का कार्यवृत्त :-

मा0 राष्ट्रीय हरित अधिकरण (एन0जी0टी0), नई दिल्ली में योजित ओ0ए0 नं0 203/2021 देवीदास खत्री बनाम यूनियन ऑफ इण्डिया एवं अन्य में पारित आदेश दिनांक 01.02.2022 के अन्तर्गत अधोहस्ताक्षरी की अध्यक्षता में कृत कार्यवाही की समीक्षा हेतु आयुक्त कार्यालय, प्रयागराज में दिनांक 16.03.2022 साँय 5:00 बजे बैठक आयोजित की गयी। उक्त बैठक में निम्नलिखित अधिकारियों द्वारा प्रतिभाग किया गया :-

- 1-श्री हर्ष देव पाण्डेय, अपर जिलाधिकारी (प्रशासन), प्रयागराज।
- 2-श्री जे0पी0 मीना, वैज्ञानिक-'घ' केन्द्रीय प्रदूषण नियंत्रण बोर्ड, क्षेत्रीय निदेशालय, लखनऊ।
- 3-श्री जय प्रकाश, संयुक्त निदेशक, भूतत्व एवं खनिकर्म विभाग, क्षेत्रीय कार्यालय, प्रयागराज।
- 4-श्री राघवेन्द्र कुमार, खनन अधिकारी, प्रयागराज।
- 5-श्री अखिलानन्द पाण्डेय, उप कृषि निदेशक (भू0सं0), प्रयागराज मण्डल, प्रयागराज।
- 6-श्री रमेश कुमार सिंह, क्षेत्रीय अधिकारी, उ0प्र0 प्रदूषण नियंत्रण बोर्ड, प्रयागराज।
- 7-मुख्य वन संरक्षक, प्रयागराज।

मा0 राष्ट्रीय हरित अधिकरण (एन0जी0टी0), नई दिल्ली में योजित ओ0ए0 नं0 203/2021 देवीदास खत्री बनाम यूनियन ऑफ इण्डिया एवं अन्य में पारित आदेश दिनांक 01.02.2022 का मुख्य कार्यकारी अंश निम्नवत् है :-

Since further remedial action is required in the light of above report and observations made by us, we constitute a joint Committee with the Divisional Commissioner, Prayagraj as Chairman and the Chief Conservator of Forest, Allahabad and nominees of CPCB, State PCB, SEIAA UP and Secretary, Agriculture (an expert in soil conservation) as members to ensure that all washing units/mining leases conduct their activities in accordance with the statutory procedures and environmental norms and compensation is assessed and recovered for the past violations. The Committee may undertake visit to the sites within two months and after coordinated remedial action furnish a report, keeping in mind the earlier report as well as observations made hereinabove by e-mail at judicial-ngt@gov.in preferably in the form of searchable PDF/ OCR Support PDF and not in the form of Image PDF.

List for further consideration on 18.05.2022.

बैठक के दौरान अधोहस्ताक्षरी द्वारा सभी सम्बन्धित विभाग के अधिकारियों से शंकरगढ़ क्षेत्र में खनन की अद्यतन प्रगति हेतु विभिन्न विभागों की समीक्षा की गयी एवं एजेण्डा बिन्दु के सापेक्ष कार्यवाही किये जाने हेतु निर्देशित किया गया है, जो निम्नानुसार है :-

1- सर्वप्रथम अधोहस्ताक्षरी द्वारा शंकरगढ़ क्षेत्र में कितने खनन पट्टे हैं तथा किन-किन स्थानों पर सिलिका वाशिंग की खुदाई का कार्य चल रहा है, के संबंध में जानकारी प्राप्त की गयी। संयुक्त निदेशक, भूतत्व एवं खनिकर्म विभाग द्वारा अवगत कराया गया कि वर्तमान में कुल 7 लीज होल्डर्स हैं, जिनके द्वारा शंकरगढ़ क्षेत्र में विभिन्न स्थानों पर सिलिका सैण्ड के खनन का कार्य किया जा रहा है।

2- केन्द्रीय प्रदूषण नियंत्रण बोर्ड, क्षेत्रीय निदेशालय, लखनऊ से जे0पी0 मीना, वैज्ञानिक-‘घ’, जिनके द्वारा आन लाइन के माध्यम से बैठक में प्रतिभाग किया गया। उनके द्वारा अवगत कराया गया कि इकाईयों द्वारा पूर्ण रूप से शर्तों का अनुपालन नहीं किया जा रहा है। उनके द्वारा शर्तों का अनुपालन कराया जाना आवश्यक है। इस सम्बन्ध में संबंधित अधिकारियों को निर्देशित किया गया कि वे इसकी गहनतापूर्वक जांच कर लें, यदि इकाईयों द्वारा शर्तों का अनुपालन नहीं किया जा रहा है, तो दोषियों के विरुद्ध कठोर कार्यवाही करते हुए शर्तों का शत-प्रतिशत अनुपालन सुनिश्चित कराया जाए। कृत कार्यवाही की आख्या दिनांक 25.03.2022 को अधोहस्ताक्षरी के समक्ष प्रस्तुत की जाए।

3- क्षेत्रीय अधिकारी, उ0प्र0 प्रदूषण नियंत्रण बोर्ड, प्रयागराज द्वारा अवगत कराया गया कि कुल 38 इकाईयां सिलिका सैण्ड की वाशिंग हेतु स्थापित एवं संचालित हैं, जिनको बोर्ड से संचालन हेतु सहमति निर्गत किया गया है। अधोहस्ताक्षरी द्वारा इन इकाईयों को निर्गत सहमति में अधिरोपित शर्तों के अनुपालन के संबंध में पूछा गया। क्षेत्रीय अधिकारी, उ0प्र0 प्रदूषण नियंत्रण बोर्ड, प्रयागराज द्वारा अवगत कराया गया कि उक्त इकाईयां सूक्ष्म श्रेणी की हैं तथा उनके द्वारा सहमति शर्तों का अनुपालन किया जा रहा है, जिसमें वृक्षारोपण लगाना, दीवार बनवाना तथा जल दोहन स्रोतों पर वाटर मीटर स्थापित किया जाना शामिल है। क्षेत्रीय अधिकारी, उ0प्र0 प्रदूषण नियंत्रण बोर्ड, प्रयागराज को निर्देशित किया गया कि दिनांक 25.03.2022 तक समस्त इकाईयों द्वारा अनुपालन की अद्यतन स्थिति से अवगत कराना सुनिश्चित करें।

4- इसी प्रकार खनन अधिकारी, प्रयागराज को निर्देशित किया गया कि पर्यावरणीय स्वीकृति में अधिरोपित शर्तों का अनुपालन किया जा रहा है अथवा नहीं से अवगत कराया जाए। संयुक्त निदेशक, भूतत्व एवं खनिकर्म विभाग, क्षेत्रीय कार्यालय,

प्रयागराज को निर्देशित किया गया कि दिनांक 25.03.2022 तक पर्यावरणीय क्षतिपूर्ति में अधिशेषित शर्तों को सापेक्ष किन-किन शर्तों का अनुपालन हो रहा है, की वस्तुस्थिति से अवगत कराएं।

6- उप कृषि निदेशक (भू0सं0), प्रयागराज मण्डल, प्रयागराज से पूछा गया कि पूर्व में जो खनन कार्य किया गया है, उनके जनित गड्ढों में किस प्रकार से भराई का कार्य किया जा सकता है तथा चूक्षारोपण आदि का कार्य किस प्रकार से किया जा सकता है। इस सम्बन्ध में कार्ययोजना तैयार कर दिनांक 25.03.2022 तक प्रस्तुत किये जाने के निर्देश दिये गये।

6- अवैध खान के बारे में खान अधिकारी से पूछे जाने पर उनके द्वारा बताया गया कि कहीं पर अवैध खनन नहीं हो रहा है। समय-समय पर अवैध खनन की जांच खनन विभाग द्वारा की जाती है, यदि कहीं भी अवैध खनन पाया जाता है तो उनके विरुद्ध कार्यवाही की जाती है। इस सम्बन्ध में खनन विभाग के सम्बन्धित अधिकारियों को निर्देशित किया गया कि खनन क्षेत्रों का नियमित रूप से निरीक्षण/जांच की जाए। जहां कहीं भी अवैध खनन पाया जाए तो उसमें लिप्त अधिकारियों/कर्मचारियों एवं व्यक्तियों के विरुद्ध नियमानुसार कठोर कार्यवाही की जाए तथा यह भी सुनिश्चित किया जाए कि किसी भी क्षेत्र में किसी भी दशा में अवैध खनन न होने पाए।

7- खान अधिकारी को निर्देशित किया गया कि स्पाट पर सिलिका सैण्ड का गिलान एम0एम0-11 द्वारा किये जा रहे परिवहन की डिटेल निकलवाकर की जाए तथा यह भी निर्देशित किया गया कि खनन स्थल पर फ्लोमीटर लगाया जाए। सभी खनन क्षेत्रों में नियमानुसार सी0सी0 टी0वी0 कैमरा आदि होना सुनिश्चित किया जाए। किसी भी क्षेत्र में मानक के विपरीत खनन कार्य न होने पाए।

8- खान अधिकारी द्वारा बताया गया कि शंकरगढ़ के 46 गांव में छोटे-छोटे खनन क्षेत्र हैं, जहां पर कोई पट्टा संचालित नहीं है। इस सम्बन्ध में खनन विभाग के अधिकारियों को निर्देशित किया गया कि इन क्षेत्रों का निरीक्षण कर लें यदि अवैध खनन पाया जाता है, तो उसके विरुद्ध नियमानुसार कार्यवाही की जाए। उक्त क्षेत्रों में खनन कार्य हेतु पट्टा दिये जाने के सम्बन्ध में कार्ययोजना तैयार कर नियमानुसार कार्यवाही की जाए।

9- संयुक्त निदेशक, भूतत्व एवं खनिकर्म विभाग, क्षेत्रीय कार्यालय, प्रयागराज को निर्देशित किया गया कि प्रश्नगत खनन क्षेत्रों के सम्बन्ध में राज्य स्तरीय पर्यावरण

प्रभाव निर्धारण प्राधिकरण, उ०प्र०, लखनऊ द्वारा विगत वर्ष में मा० एन०जी०टी० को जिनती रिपोर्ट भेजी गयी है, उसकी प्रति प्राप्त कर दिनांक 25.03.2022 तक उपलब्ध करायी जाए।


10- बैठक में उपस्थित अधिकारियों को निर्देश दिये गये कि वे अपने-अपने विभाग की कार्ययोजना तैयार कर दिनांक 25.03.2022 तक प्रस्तुत करें।


(संजय गोयल) 23/3/22
मण्डलायुक्त, प्रयागराज।

संख्या: 2564 (i) / 30-17-2021 दिनांक: 24 / 03 / 2022

प्रतिलिपि: निम्नलिखित को सूचनार्थ एवं आवश्यक कार्यवाही हेतु तथा संबंधित को अनुपालनार्थ प्रेषित :-

- 1- जिलाधिकारी, प्रयागराज।
- 2- डॉ० अजय मिश्रा, सदस्य, एस०ई०ए०सी०-1, उ०प्र०।
- 3- श्री जे०पी० मीना, वैज्ञानिक-‘घ’ केन्द्रीय प्रदूषण नियंत्रण बोर्ड, क्षेत्रीय निदेशालय, लखनऊ।
- 4- श्री हर्ष देव पाण्डेय, अपर जिलाधिकारी (प्रशासन)/प्रभारी अधिकारी खनन प्रयागराज।
- 5- श्री जय प्रकाश, संयुक्त निदेशक, भूतत्व एवं खनिकर्म विभाग, क्षेत्रीय कार्यालय, प्रयागराज।
- 6- श्री राघवेन्द्र कुमार, खान अधिकारी, प्रयागराज।
- 7- श्री अखिलानन्द पाण्डेय, उप कृषि निदेशक(भू०सं०), प्रयागराज मण्डल, प्रयागराज।
- ✓ 8- श्री रमेश कुमार सिंह, क्षेत्रीय अधिकारी, उ०प्र० प्रदूषण नियंत्रण बोर्ड, प्रयागराज।
- 9- मुख्य वन संरक्षक, प्रयागराज।


(संजय गोयल) 23/3/22
मण्डलायुक्त, प्रयागराज।

Annex. 2




मा0 राष्ट्रीय हरित अधिकरण (एन0जी0टी0), नई दिल्ली में योजित ओ0ए0 नं0-203/2021 देवीदास खत्री बनाम यूनियन ऑफ इण्डिया एवं अन्य में पारित आदेश दिनांक 01.02.2022 के अनुपालन में मण्डलायुक्त, प्रयागराज की अध्यक्षता में आयोजित बैठक दिनांक 16.03.2022 सायं 05:00 बजे में दिये गये निर्देशों के क्रम में स्थलीय जाँच आख्या/कार्ययोजना।

मा0 आयुक्त महोदय द्वारा दिये गये निर्देश के अनुपालन में प्रश्नगत सिलिका सैण्ड क्षेत्रों की संयुक्त रूप से दिनांक 23.03.2022 व दिनांक 24.03.2022 को स्थलीय निरीक्षण किया गया। जाँच आख्या/कार्ययोजना निम्नवत् है:-

- जनपद प्रयागराज के तहसील बारा में स्वीकृत सिलिका सैण्ड के खनन पट्टाधारकों द्वारा मा0 एन0जी0टी0, नई दिल्ली में दायर ओ0ए0 संख्या-203/2021 देवीदास खत्री बनाम यूनियन ऑफ इण्डिया व अन्य में पारित आदेश दिनांक 19.08.2021 के क्रम में गठित कमेटी द्वारा दिये गये सुझाव/कमियों को दूर किये जाने के सम्बन्ध में जिलाधिकारी, कार्यालय खनन अनुभाग, प्रयागराज द्वारा जारी किये गये नोटिस के अनुपालन में पट्टेधारकों द्वारा मौके पर अनुपालन किया गया है, के सम्बन्ध में सभी खनन क्षेत्रों को देखा गया। खनन क्षेत्रवार आख्या निम्नवत् है:-

क्र0 सं0	पट्टा क्षेत्र एवं पट्टाधारक का नाम	स्थलीय निरीक्षण के दौरान सुझाव/कमियों के सापेक्ष पायी गयी स्थिति	अभ्युक्ति
1	ग्राम जनवा/मे0 चावला सिलिका सैण्ड ट्रेडिंग कंपनी पा0 श्री दर्शन लाल चावला व अन्य	<ol style="list-style-type: none"> निरीक्षण के दौरान खनन क्षेत्र में सभी सीमा स्तम्भ संरक्षित पाये गये तथा सभी सीमा स्तम्भ पर भू-निर्देशांक अंकित किया हुआ पाया गया। स्वीकृत खनन क्षेत्र में खनन के उपरान्त हुए गड्ढा/पिट में वर्षा ऋतु का जल भराव पाया गया। उक्त जल का उपयोग वहाँ लगाये गये पौधों को सिंचित किये जाने में पाया गया। खनन क्षेत्र की गहराई अधिकांश स्थानों पर औसतन 1-3 मीटर की पायी गयी, जो अभी अपने न्यूनतम स्तर पर है जिसमें बेंच बनाने की आवश्यकता नहीं है। स्वीकृत खनन क्षेत्र के निकास/प्रवेश मार्ग पर धर्मकांटा स्थापित पाया गया। धर्मकांटा पर जाँच के समय निकासी की गयी उपखनिज की मात्रा का लेखा-जोखा का रजिस्टर उपलब्ध नहीं कराया गया। खनन क्षेत्र में खनन के समय निकाले गये टॉप स्वायल व्यवस्थित पाया गया तथा कुछ क्षेत्र में रिक्लेमेशन/रिस्टोरेशन का कार्य किया जाना पाया गया। खनन क्षेत्र में दो स्थानों पर डिस्प्ले बोर्ड स्थापित पाया गया, जिसमें खनन पट्टा सम्बन्धी सभी विवरण उपलब्ध थे। स्वीकृत खनन क्षेत्र के प्रवेश/निकासी मार्ग के पास सी0सी0टी0वी0 कैमरा स्थापित व संचालित होना पाया गया। खनन क्षेत्र में ओवर बर्डन हार्ड रॉक नहीं देखा गया। 	पट्टेधारक को धर्मकांटा पर उपखनिज की निकासी की गयी मात्रा के लेखा-जोखा का रजिस्टर रखने हेतु निर्देशित किया गया।


 25/3/2022
 न.प्र.सि.
 आयुक्त महोदय
 प्रयागराज


2	ग्राम लखनौटी/मे० चावला सिलिका सैण्ड ट्रेडिंग कम्पनी प्रा० श्री दर्शन लाल चावला व अन्य	<ol style="list-style-type: none"> 1. निरीक्षण के दौरान खनन क्षेत्र में सभी सीमा स्तम्भ संरक्षित पाये गये तथा सभी सीमा स्तम्भ पर भू-निर्देशांक अंकित किया हुआ पाया गया। 2. स्वीकृत खनन क्षेत्र में खनन के उपरान्त हुए गढ़वा/पिट में जल भराव होना नहीं पाया गया। खनन क्षेत्र की गहराई अधिकांश स्थानों पर औसतन 1-3 मीटर की पायी गयी, जो अभी अपने न्यूनतम स्तर पर है जिसमें बेंच बनाने की आवश्यकता नहीं है। 3. स्वीकृत खनन क्षेत्र के निकास/प्रवेश मार्ग पर धर्मकांटा स्थापित पाया गया। धर्मकांटा पर जॉच के समय निकासी की गयी उपखनिज की मात्रा का लेखा-जोखा का रजिस्टर उपलब्ध पाया गया। 4. खनन क्षेत्र में खनन के समय निकाले गये टॉप स्वायल व्यवस्थित पाया गया। 5. खनन क्षेत्र में तीन स्थानों पर डिस्ले बोर्ड स्थापित पाया गया, जिसमें खनन पट्टा सम्बन्धी सभी विवरण उपलब्ध थे। 6. स्वीकृत खनन क्षेत्र के प्रवेश/निकासी मार्ग के पास सी०सी०टी०वी० कैमरा स्थापित व संचालित होना पाया गया। 7. खनन क्षेत्र में ओवर बर्डन हार्ड रॉक को व्यवस्थित रूप से भण्डारित किया जाना पाया गया। 8. पट्टेधारक द्वारा पौधा रोपण किया गया है जिसका विवरण मौके पर वर्षवार डिस्ले में भी किया गया है, जहाँ 2017 से अब तक किये गये पौधा रोपण का विवरण है। 	-
3	ग्राम-सोनौरी, बांकीपुर, छतहरा घुरेहठा/श्रीमती निर्मल रानी पत्नी स्व० योगेन्द्र चावला	<ol style="list-style-type: none"> 1. निरीक्षण के दौरान खनन क्षेत्र में सभी सीमा स्तम्भ संरक्षित पाये गये तथा सभी सीमा स्तम्भ पर भू-निर्देशांक अंकित किया हुआ पाया गया। 2. स्वीकृत खनन क्षेत्र में खनन के उपरान्त हुए गढ़वा/पिट में जल भराव होना नहीं पाया गया। खनन क्षेत्र का अधिकांश हिस्सों में अभी खनन नहीं हो रहा है। 3. स्वीकृत खनन क्षेत्र के निकास/प्रवेश मार्ग पर धर्मकांटा स्थापना का कार्य हो रहा है। 4. खनन क्षेत्र में डिस्ले बोर्ड स्थापित पाया गया, जिसमें खनन पट्टा सम्बन्धी सभी विवरण उपलब्ध थे। 5. स्वीकृत खनन क्षेत्र के प्रवेश/निकासी मार्ग के पास सी०सी०टी०वी० कैमरा स्थापित किया गया था, जो क्षतिग्रस्त पाया गया। 6. पट्टेधारक द्वारा खनन क्षेत्र में पौधा रोपण किया गया है। 	पट्टेधारक को धर्मकांटा स्थापित किये जाने तथा सी०सी०टी०वी० कैमरा तत्काल संचालित किये जाने के निर्देश दिये गये।
4	ग्राम-जनवा/श्री अभिनन्दन तिवारी पुत्र श्री के०बी० तिवारी	<ol style="list-style-type: none"> 1. निरीक्षण के दौरान खनन क्षेत्र में सभी सीमा स्तम्भ संरक्षित पाये गये तथा सभी सीमा स्तम्भ पर भू-निर्देशांक अंकित किया हुआ पाया गया। 2. स्वीकृत खनन क्षेत्र में खनन के उपरान्त हुए गढ़वा में जल भराव होना नहीं पाया गया। 3. स्वीकृत खनन क्षेत्र के निकास/प्रवेश मार्ग पर धर्मकांटा स्थापित पाया गया। धर्मकांटा पर जॉच के समय निकासी की गयी उपखनिज की मात्रा का लेखा-जोखा का रजिस्टर उपलब्ध नहीं कराया गया। 	पट्टेधारक को धर्मकांटा पर उपखनिज की निकासी की गयी मात्रा के लेखा-जोखा का रजिस्टर रखने हेतु निर्देशित किया गया।

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]


		<ol style="list-style-type: none"> 4. खनन क्षेत्र में डिस्प्ले बोर्ड स्थापित पाया गया, जिसमें खनन पट्टा सम्बन्धी सभी विवरण उपलब्ध थे। 5. स्वीकृत खनन क्षेत्र के प्रवेश/निकासी मार्ग के पास सी0सी0टी0वी0 कैमरा स्थापित किया गया था, जो क्षतिग्रस्त पाया गया। 6. खनन क्षेत्र के कुछ हिस्सा में स्थायी घरों का निर्माण होना पाया गया, जहाँ जॉच के समय लोगों का निवास किया जाना देखा गया। साथ ही खनन क्षेत्र के कुछ हिस्सों में कृषि कार्य किया जाना देखा गया। पट्टेधारक द्वारा इस सम्बन्ध में अवगत कराया गया कि स्वीकृत पट्टा क्षेत्र के कुछ हिस्सों का भूमिधरी पट्टा तहसील स्तर से जारी किया गया है। खनन क्षेत्र में सुरक्षा के दृष्टिगत ऐसी स्थिति नहीं होनी चाहिए। उक्त के सम्बन्ध में सम्बन्धित उपजिलाधिकारी से आख्या प्राप्त किया जाना समीचीन होगा। 	
5	ग्राम-जनवॉ/मे0 मोदी मिनरल्स उद्योग प्रो0 श्रीमती अमिता गुप्ता पत्नी श्री द्वारिका प्रसाद गुप्ता	<ol style="list-style-type: none"> 1. निरीक्षण के दौरान खनन क्षेत्र में सभी सीमा स्तम्भ संरक्षित पाये गये तथा सभी सीमा स्तम्भ पर भू-निर्देशांक अंकित किया हुआ पाया गया। 2. स्वीकृत खनन क्षेत्र में खनन के उपरान्त हुए गड्ढों में जल भराव होना नहीं पाया गया। 3. स्वीकृत खनन क्षेत्र के निकास/प्रवेश मार्ग पर धर्मकांटा स्थापित पाया गया। धर्मकांटा पर जॉच के समय निकासी की गयी उपखनिज की मात्रा का लेखा-जोखा का रजिस्टर उपलब्ध नहीं कराया गया। 4. खनन क्षेत्र में डिस्प्ले बोर्ड स्थापित पाया गया, जिसमें खनन पट्टा सम्बन्धी सभी विवरण उपलब्ध थे। 5. स्वीकृत खनन क्षेत्र के प्रवेश/निकासी मार्ग के पास सी0सी0टी0वी0 कैमरा स्थापित किया गया। 6. खनन क्षेत्र के कुछ हिस्सा में जॉच के समय प्लाटिंग का कार्य किया जाना देखा गया। पट्टेधारक द्वारा इस सम्बन्ध में अवगत कराया गया कि स्वीकृत पट्टा क्षेत्र, जो निजी कास्तकारों की जमीन में ही स्वीकृत की गयी थी, उन्हीं कुछ कास्तकारों द्वारा कोई कम्पनी को प्लाटिंग किये जाने हेतु विक्रय कर दी गयी है। उक्त के सम्बन्ध में पट्टेधारक द्वारा मा0 उच्च न्यायालय में रिट योजित की गयी है, जो न्यायालय में विचाराधीन है। 	-
6	ग्राम-पूराबल्दू/श्री अशोक कुमार बाजपेयी	<ol style="list-style-type: none"> 1. निरीक्षण के दौरान खनन क्षेत्र में सभी सीमा स्तम्भ संरक्षित पाये गये तथा सभी सीमा स्तम्भ पर भू-निर्देशांक अंकित किया हुआ पाया गया। 2. स्वीकृत खनन क्षेत्र में खनन के उपरान्त हुए गड्ढा/पिट में जल भराव नहीं पाया गया। खनन क्षेत्र की गहराई अधिकांश स्थानों पर औसतन 1-3 मीटर की पायी गयी, जो अभी अपने न्यूनतम स्तर पर है जिसमें बेंच बनाने की आवश्यकता नहीं है। 3. स्वीकृत खनन क्षेत्र के निकास/प्रवेश मार्ग पर धर्मकांटा स्थापित पाया गया। धर्मकांटा पर जॉच के समय निकासी की गयी उपखनिज की मात्रा 	-

		<p>का लेखा-जोखा का रजिस्टर मौजूद होना पाया गया।</p> <p>4. खनन क्षेत्र में खनन के समय निकाले गये टॉप स्वायल व्यवस्थित पाया गया तथा कुछ क्षेत्र में रिक्लेमेशन/रिस्टोरेशन का कार्य किया जाना पाया गया।</p> <p>5. खनन क्षेत्र में दो स्थानों पर डिस्पले बोर्ड स्थापित पाया गया, जिसमें खनन पट्टा सम्बन्धी सभी विवरण उपलब्ध थे।</p> <p>6. स्वीकृत खनन क्षेत्र के प्रवेश/निकासी मार्ग के पास सी0सी0टी0वी0 कैमरा स्थापित व संचालित होना पाया गया।</p> <p>7. पट्टाधारक द्वारा खनन क्षेत्र में पौधा रोपण किया जाना पाया गया।</p>	
7	ग्राम-उठगी तरहार / श्री राजीव कुमार चावला	<p>1. निरीक्षण के दौरान खनन क्षेत्र में सभी सीमा स्तम्भ संरक्षित पाये गये तथा सभी सीमा स्तम्भ पर भू-निर्देशांक अंकित किया हुआ पाया गया।</p> <p>2. स्वीकृत खनन क्षेत्र में खनन के उपरान्त हुए एक गद्दा/पिट में जल भराव होना नहीं पाया गया। खनन क्षेत्र का अधिकांश हिस्सों में अभी खनन नहीं हो रहा है।</p> <p>3. स्वीकृत खनन क्षेत्र के निकास/प्रवेश मार्ग पर धर्मकांटा स्थापना का कार्य हो रहा है।</p> <p>4. खनन क्षेत्र में डिस्पले बोर्ड स्थापित पाया गया, जिसमें खनन पट्टा सम्बन्धी सभी विवरण उपलब्ध थे।</p> <p>5. स्वीकृत खनन क्षेत्र के प्रवेश/निकासी मार्ग के पास सी0सी0टी0वी0 कैमरा स्थापित किया गया था, जो क्षतिग्रस्त पाया गया।</p> <p>6. पट्टेधारक द्वारा खनन क्षेत्र में पौधा रोपण किया गया है।</p>	पट्टेधारक को धर्मकांटा स्थापित किये जाने तथा सी0सी0टी0वी0 कैमरा तत्काल संचालित किये जाने के निर्देश दिये गये।

2. पट्टेधारकों द्वारा खनन पट्टा हेतु लिये गये पर्यावरणीय अनापत्ति प्रमाण पत्र में वर्णित शर्तों का अनुपालन किया जा रहा है। पर्यावरणीय अनापत्ति प्रमाण पत्र में दी गयी शर्त के अनुसार छः माह में इसकी अनुपालन आख्या पर्यावरण निदेशालय, उ0प्र0, लखनऊ (State Level Environment Impact Assessment Authority, Uttar Pradesh-SEIAA) को सीधे प्रेषित की जाती है। जाँच के समय मौके पर कुछ पट्टेधारकों द्वारा पर्यावरण निदेशालय को भेजी गयी रिपोर्ट की प्रति उपलब्ध करायी गयी। (संलग्नक-1)

3. जनपद प्रयागराज की तहसील बारा में निदेशालय स्तर से गठित टीम के साथ जनपदीय खनन अधिकारी तथा राजस्व विभाग के सहयोग से उपयुक्त सिलिका सैण्ड के खनन क्षेत्रों का चिन्हिकरण किये जाने का लगातार प्रयास किया जा रहा है, जिससे अब तक नये 09 क्षेत्रों का चिन्हिकरण किया जा चुका है तथा उन क्षेत्रों को डी0एस0आर0 में सम्मिलित करते हुये सभी क्षेत्रों को विज्ञापित किया गया। उक्त विज्ञापित के क्रम में 07 क्षेत्र व्यवस्थित हो चुके हैं तथा उनकी ई0सी0 की कार्यवाही प्रक्रियाधीन है। सिलिका सैण्ड के 02 क्षेत्रों के लिए जो ई-निविदाये प्राप्त हुई थी, वो अन्य 07 क्षेत्रों में प्राप्त ई-निविदा की औसत दर से कम होने के कारण राजस्वहित में पुनः विज्ञापित किया गया है, जिसकी कार्यवाही प्रक्रियाधीन है।

उक्त के अतिरिक्त निदेशालय स्तर से गठित टीम के साथ जनपदीय खनन अधिकारी तथा राजस्व विभाग के सहयोग से अन्य 07 उपयुक्त सिलिका सैण्ड के खनन क्षेत्रों को चिन्हित किया गया है, जिसको डी0एस0आर0 में सम्मिलित किये जाने की कार्यवाही की जा रही है।



4. भूतत्व एवं खनिकर्म विभाग, उ०प्र० शासन, लखनऊ द्वारा जारी शासनादेश संख्या-616/86-2018-371/2005 दिनांक 20.03.2018 द्वारा प्रदेश में अवैध खनन/परिवहन पर अंकुश लगाये जाने हेतु प्रत्येक जनपद में जनपद स्तरीय कार्यबल (टॉस्कफोर्स) का गठन किया गया है। उसी क्रम में जिलाधिकारी, प्रयागराज द्वारा तहसील स्तरीय टॉस्क फोर्स, जिसमें सम्बन्धित तहसील के उपजिलाधिकारी पदेन अध्यक्ष, सम्बन्धित पुलिस क्षेत्राधिकारी, उपसम्भागीय परिवहन अधिकारी एवं खान निरीक्षक/सर्वेक्षक पदेन सदस्य का गठन किया गया है। उक्त के अतिरिक्त अवैध खनन/परिवहन पर प्रभावी अंकुश लगाये जाने हेतु जिलाधिकारी, प्रयागराज द्वारा खनिज विभाग की पृथक से सचल दल का गठन किया गया है, जिसमें भूतपूर्व सैनिक की सेवा ली जा रही है। उक्त सचल दल द्वारा लगातार क्षेत्र में भ्रमणशील रहकर अवैध परिवहन पर पूरी तरह से अंकुश लगाया गया है, जिससे बिना खनिज प्रपत्र के कोई भी वाहन न जा सके।

जनपद प्रयागराज के तहसील बारा में कुछ क्षेत्रों में अवैध खनन की शिकायतें पूर्व में प्राप्त हुई थी जिसमें 07 प्रकरणों में प्रथम सूचना रिपोर्ट सम्बन्धित थाने में पंजीकृत कराया गया है, साथ ही साथ जनपद स्तरीय टॉस्क फोर्स एवं तहसील स्तरीय टॉस्क फोर्स जो उपजिलाधिकारी की अध्यक्षता में गठित है के माध्यम से साप्ताहिक/पाक्षिक कार्यवाही समय-समय पर की जाती है। जिलाधिकारी प्रयागराज द्वारा दिये गये निर्देश के क्रम में विभाग द्वारा किये गये प्रवर्तन कार्य की दैनिक सूचना जिलाधिकारी प्रयागराज एवं निदेशक, भूतत्व एवं खनिकर्म को प्रेषित की जाती है। इस वित्तीय वर्ष 2021-22 में अब तक अवैध खनन/परिवहन में की गयी कार्यवाही का विवरण निम्नवत् है:-

क्र०सं०	वित्तीय वर्ष 2021-22 में अवैध परिवहन में निरुद्ध वाहनों की संख्या	अवैध परिवहन में पाये गये वाहनों के विरुद्ध दर्ज एफ०आई०आर० की संख्या	शास्ति के रूप में वसूली गयी कुल धनराशि	पर्यावरणीय क्षति के रूप में वसूली की गयी धनराशि
1	2	3	4	5
1	618	33	रु० 35.45लाख	रु० 60.00 लाख

5. खनन पट्टाधारक द्वारा सिलिका सैण्ड का खनन कर अपने-अपने वाशिंग प्लांट में प्रोशेसिंग किये जाने के उपरान्त नियमानुसार सिलिका सैण्ड का विभिन्न क्षेत्रों/प्रदेशों में स्थापित इससे सम्बन्धित ईकाईयों में प्रेषण किया जाता है तथा प्रेषण के समय प्रपत्र ई-एम०एम० 11 जारी किया जाता है। पट्टाधारक द्वारा प्रेषण किये गये प्रपत्र ई०एम०एम०-11 विवरण इसप्रकार है:-

पट्टाधारक का नाम	माह					कुल प्रेषित मात्रा
	अक्टूबर	नवम्बर	दिसम्बर	जनवरी	फरवरी	
1	2	3	4	5	6	7
मे० चावला सिलिका सैण्ड ट्रेडिंग कम्पनी पा० श्री दर्शन लाल चावला व अन्य	3000	5000	4300	2511	3800	18611
मे० चावला सिलिका सैण्ड ट्रेडिंग कम्पनी पा० श्री दर्शन लाल चावला व अन्य	2500	3000	2700	3000	3200	14400
श्रीमती निर्मल रानी पत्नी स्व० योगेन्द्र चावला	2500	2000	750	2500	2800	10550
श्री अभिनन्दन तिवारी पुत्र श्री के०बी० तिवारी	1500	1000	1500	1000	1100	6100


मे0 मोदी मिनरल्स उद्योग प्रो0 श्रीमती अमिता गुप्ता पत्नी श्री द्वारिका प्रसाद गुप्ता	1400	800	800	900	700	4600
श्री अशोक कुमार बाजपेयी	10500	9000	8500	5500	9500	43000
श्री राजीव कुमार चावला	-	500	-	500	-	1000


उपरोक्तानुसार आख्या महोदय की सेवा में सूचनार्थ एवं आवश्यक कार्यवाही हेतु सादर प्रेषित।


संलग्नक-


- पर्यावरण निदेशालय को प्रस्तुत अनुपालन आख्या की प्रति।
- स्थलीय फोटोग्राफ।


(राधेश्याम)
वरिष्ठ मानचित्रकार
क्षे0का0प्रयागराज।


25/03/22
(राघवेंद्र सिंह)
खान अधिकारी
प्रयागराज।


25/03/22
(मिथिलेश कुमार पाण्डेय)
जिला खान अधिकारी
प्रयागराज।


25/03/22
(जय प्रकाश)
संयुक्त निदेशक/प्रभारी अधिकारी
क्षेत्रीय कार्यालय, प्रयागराज।


25/3/22
(मिथिलेश कुमार पाण्डेय)
जिला खान अधिकारी
प्रयागराज।

Kanhaiya Lal Sethi

Mines Owner : Silica Sand Mines

Village-Janwa, P.O. Shankargarh, Teh.Bara, Dist. Allahabad (U.P.)

Corr. Address : 43/1, S.P. Marg, Civil Lines, Allahabad - 211001 (U.P.)

Dated: 21.01.2021

To,
Regional Officer,
Ministry of Environment & Forest,
(Central Region), Kendriya Bhavan,
5th Floor, Sector-H, Aliganj,
Lucknow-226024

Sub: Compliance of the stipulated Environmental Conditions/Safeguards in the Environment Clearance Letter and Environmental Monitoring Report of Janwa Silica Sand Mine, Village-Janwa, Tehsil: Bara & District- Allahabad, Uttar Pradesh Leased Area-17.75 Hectare. (1.4.2018 - 31.3.2020)

Ref: Environment Clearance Letter No. 1803-parya/SEAC/967/2011/TA (M) Dated 11.11.2014

Dear Sir,

This has reference to the State Level Expert Environment impact Assessment Authority Uttar Pradesh (U.P) EC letter No. 1803-parya/SEAC/967/2011/TA (M) Dated 11.11.2014 vide which we have been asked to submit the Compliance with the specific and general conditions.


In view of above, we are approaching you by submitting a copy of the following information documents for your kind perusal:

1. Point-wise compliance of the stipulated environment conditions/safeguards.
2. Environmental monitoring report.

We fully assure you that we will comply with all conditions as specified in the Environment clearance granted us.

Thanking you

Yours Sincerely,


Shri Kanhaiya Lal
(Authorised Signatory)

Copy to:

The member Secretary, SEIAA, U.P. Govt., Lucknow




TABLE OF CONTENT

S. No.	Description
1.	Introduction of the Project
1.	Compliance of Specific and General Conditions for Operation and Construction Phase

LIST OF ANNEXURE

Annexure	Description
Annexure-1	Mining plant & progressive mine closure plant of Janwa Silica Sand Mine
Annexure-2	Deed of Transfer of Mining Lease
Annexure-3	Approved Khasra Map of Vill. Janwa
Annexure-4	Surface Plan
Annexure-5	DM Letter
Annexure-6	EC Clearance Letter
Annexure-7	Production
Annexure-8	Plantation
Annexure-9	UPPCB Compliance report of Air and Water
Annexure-10	Rain Water Harvesting photographs
Annexure-11	Fencing Photographs
Annexure-12	Ambient Air Quality Report
Annexure-13	CGWA NOC
Annexure-14	Water Consent
Annexure-15	Air Consent
Annexure-16	Dust Suppressing Photographs
Annexure-17	Water Flow Meter
Annexure-18	News Paper Advertisement

[Handwritten signature]

**Environmental Compliance Report of
Stipulated Environmental Conditions of
Environmental Clearance**

For
Janwa Silica Sand Mine

**Situated at Janwa,
Village- Janwa, Tehsil- Bara,
Distt.- Allahabad (U.P.)**

Leased Area-17.75 Hectare

Submission to
Ministry of Environment and Forests **(MOEF)**

PROPONENT
SHRI KANHAIYA LAL



Annex-2

दूरभाष: / Pn. : 0532-2559121

क्षेत्रीय कार्यालय, उत्तर प्रदेश प्रदूषण नियंत्रण बोर्ड REGIONAL OFFICE, U. P. POLLUTION CONTROL BOARD

आवास विकास परिषद कालोनी, सेक्टर-10, योजना संख्या-3, झुंसी, प्रयागराज - 221506
Avas Vikas Parishad Colony, Sector-10, Scheme No. 3, Jhansi, Prayagraj,

roprayagraj@uppcb.in

संदर्भ सं० 670/492/सां०/33/2022

दिनांक 22/03/22

सेवा में,

सूची संलग्न
(सिलिका वाशिंग इकाई-41)

विषय: जल (प्रदूषण निवारण तथा नियंत्रण) अधिनियम 1974 की धारा 25/26 तथा वायु (प्रदूषण निवारण तथा नियंत्रण) अधिनियम 1981 की धारा 21/22 के अन्तर्गत निर्गत सहमति आदेश की शर्तों के अनुपालन के संबंध में।

महोदय,

कृपया उपरोक्त विषय का संदर्भ ग्रहण करने का कष्ट करें। अवगत कराना है कि आपकी सिलिका सैण्ड वाशिंग इकाई को उपरोक्त अधिनियमों के अन्तर्गत संचालन हेतु सहमति आदेश निर्गत किया गया है। निर्गत सहमति आदेश के शर्तों की बिन्दुवार अनुपालन आख्या अपेक्षित है। यह भी अवगत कराना है कि तहसील-बारा के अन्तर्गत शंकरगढ़, जनवां एवं लालापुर आदि क्षेत्रों में स्थापित/संचालित सिलिका वाशिंग इकाईयों एवं खनन पट्टों के संबंध में मा० एन०जी०टी० नई दिल्ली में दायर ओ०ए० सं० 203/2021 देवीदास खत्री बनाम यूनियन ऑफ इण्डिया व अन्य में पारित आदेश दिनांक 01.02.2022 की अनुपालन आख्या मा० एन.जी.टी. में अग्रिम तिथि से पूर्व दायर की जानी है।

अतः आपको निर्देशित किया जाता है कि अपने सिलिका सैण्ड वाशिंग इकाई में कराये गये वृक्षारोपण, परिसर की बाउंड्रीवाल एवं जल आपूर्ति के स्रोतों पर वाटर मीटर की स्थापना के विवरण के साथ-साथ निर्गत सहमति आदेश की शर्तों की अनुपालन आख्या एक सप्ताह में प्रेषित करना सुनिश्चित करें, अन्यथा की स्थिति में इस कार्यालय द्वारा निर्गत सहमति आदेश को खण्डित करते हुए पर्यावरणीय क्षतिपूर्ति अधिरोपित किये जाने की संस्तुति कर दी जायेगी, जिसके लिए आप स्वयं उत्तरदायी होंगे।

भवदीय,

22/3/22

(आर०के० सिंह)
क्षेत्रीय अधिकारी

प्रतिलिपि: मुख्य पर्यावरण अधिकारी (वृत्त-2), उ०प्र० प्रदूषण नियंत्रण बोर्ड, लखनऊको सूचनार्थ प्रेषित।

22/3/22

क्षेत्रीय अधिकारी

AEK

S. No.	Application Name	Industry Address
1	CHAWLA SILICA SAND TRADING CO.	SHIVRAJPUR, BARA, PRAYAGRAJ
2	CHAWLA SILICA SAND TRADING CO. (CRUSHING & WASHING)	LAKHNAUTI, BARA, PRAYAGRAJ
3	CHAWLA SILICA SAND TRADING CO.	GARHA, BARA, PRAYAGRAJ
4	QUALITY MINERALS DEVELOPMENT CORPORATION	KAITHA, BARA, PRAYAGRAJ
5	QUALITY MINERALS DEVELOPMENT CORPORATION	GARWA, SHEORAJPUR, PRAYAGRAJ
6	NAVEEN SILICA SAND	KAITHA, BARA, PRAYAGRAJ
7	MODI MINERAL UDYOG	BIHARIYA, BARA, PRAYAGRAJ.
8	NARAYAN DUTT TIWARI (SILICA WASHING PLANT)	BENIPUR, SHANKARGRAH, PRAYAGRAJ
9	SRI GIRDHARI LAL CHAWLA & SONS	BENIPUR, SHANKARGRAH, PRAYAGRAJ
10	HARSH MINERALS	KACHARI BARA PRAYAGRAJ
11	BARAWHITE STONE HEIGHTS PVT LTD	PARVEJABAD, PRAYAGRAJ
12	AGRAWALS MINES AND MINERALS. (CRUSHING & WASHING)	CHIRRI BARA, PRAYAGRAJ
13	KRISHNA MINERALS	BENIPUR, PRAYAGRAJ
14	ASHOK KUMAR BAJPAI	BARGARHI, SHIVRAJPUR, PRAYAGRAJ
15	BABA VIGHNESHWAR MINERLS (NARAYAN ENTERPRISES)	BARGARHI, SHIVRAJPUR, PRAYAGRAJ
16	SRI GIRDHARI LAL CHAWLA & SONS	KAITHA, LAKHANPUR SHANKARGRAH, PRAYAGRAJ
17	GURU DAYAL SINGH & CO. (SILICA)	KAITHA, SHANKARGRAH, BARA, PRAYAGRAJ
18	VANDANA SINGH (STONE/SILICA WASHING PLANT)	BANKIPUR, BARA, PRAYAGRAJ

19	SILICA KHANIJ UDYOG	KAITHA, BARA, PRAYAGRAJ
20	SILICA KHANIJ UDYOG	KAITHA, SHIVRAJPUR, BARA, PRAYAGRAJ
21	SILICA KHANIJ UDYOG	LAKHANPUR, BARA, PRAYAGRAJ
22	NEW TRIVENI MINERALS	LAKHANPUR, BARA, PRAYAGRAJ
23	ADISHWARA CONSTRUCTION & MINERALS CO.	PARVEJABAD, BARA, PRAYAGRAJ
24	PRAYAG QUALITY SAND	PRATAPPUR, BARA, PRAYAGRAJ
25	MA JAGADAMBA & CO.	BIHARIYA, BARA, PRAYAGRAJ
26	ANUPAM ENTERPRISES	GARHA KATRA SHANKARGARH BARA PRAYAGRAJ
27	JAI SHREE TRADING COMPANY	PRATAPPUR, BARA, PRAYAGRAJ ALLAHABAD
28	SHREE BHAGWAN DASS INDUSTRUES	SHIVRAJPUR, BARA, PRAYAGRAJ ALLAHABAD
29	GUPTA ENTERPRISES	SHIVRAJPUR, SHANKARGARG, PRAYAGRAJ
30	JAI SHREE TRADING COMPANY	KAITHA, BARA, PRAYAGRAJ
31	JAI SHREE TRADING COMPANY	RAMNA, BARGARI, PRAYAGRAJ
32	ALLAHABAD SAND	BARDARI, BARA, PRAYAGRAJ
33	GLASS AND FOUNDRY SAND	BARGARI, BARA, PRAYAGRAJ
34	OM LUXMI MINERALS	KACHARI, BARA, PRAYAGRAJ
35	OM LAXMI INDUSTRIES	KACHARI, BARA, PRAYAGRAJ
36	ASHA DEVI (SILICA WASHING PLANT)	KAITHA, SHIVRAJPUR, PRAYAGRAJ
37	KR MINERALS BARGARI, BIHARIYA, SHANKARGRAH, PRAYAGRAJ-21210	BARGARI, BIHARIYA, SHANKARGRAH, PRAYAGRAJ-21210

38	S B S ENTERPRISES	LAKHNAUTI, BARA, PRAYAGRAJ
39	SITA DEVI (SILICA WASHING PLANT)	LEDAR, BARA, PRAYAGRAJ
40	LAXMI MINERAL MANUFACTURER AND TRADERS	GARHA KATRA, SHANKARGRAH, PRAYAGRAJ
41	BADRI PRASAD AMAR NATH	SHIVRAJPUR, BARA, PRAYAGRAJ

Annex: 3

11/04/2022
12/04/2022

मा0 राष्ट्रीय हरित अधिकरण (एन0जी0टी0), नई दिल्ली में योजित ओ0ए0 नं0 203/2021 देवीदास खत्री बनाम यूनियन ऑफ इण्डिया एवं अन्य में पारित आदेश दिनांक 01.02.2022 के अनुपालन में दिनांक 11.04.2022 को मण्डलायुक्त, प्रयागराज की अध्यक्षता में आयोजित बैठक का कार्यवृत्त :-

मा0 राष्ट्रीय हरित अधिकरण (एन0जी0टी0), नई दिल्ली में योजित ओ0ए0 नं0 203/2021 देवीदास खत्री बनाम यूनियन ऑफ इण्डिया एवं अन्य में पारित आदेश दिनांक 01.02.2022 के अनुपालन में अधोहस्ताक्षरी की अध्यक्षता में कृत कार्यवाही की समीक्षा हेतु आयुक्त कैम्प कार्यालय, प्रयागराज में दिनांक 11.04.2022 सोंय 5:00 बजे बैठक आयोजित की गयी। उक्त बैठक में निम्नलिखित अधिकारियों द्वारा प्रतिभाग किया गया :-

- 1-मुख्य वन संरक्षक, प्रयागराज।
- 2-श्री हर्ष देव पाण्डेय, अपर जिलाधिकारी (प्रशासन), प्रयागराज।
- 3-श्री जय प्रकाश, संयुक्त निदेशक, भूतत्व एवं खनिकर्म विभाग, क्षेत्रीय कार्यालय, प्रयागराज।
- 4-श्री मिथिलेश पाण्डेय, खनन अधिकारी, प्रयागराज।
- 5-डॉ0 अनूप कुमार मिश्रा, राज्य स्तरीय पर्यावरण अधिप्रभाव मूल्यांकन प्राधिकारी, प्रयागराज।
- 6-श्री ए0के0 त्रिपाठी, वैज्ञानिक-‘ग’, केन्द्रीय प्रदूषण नियंत्रण बोर्ड, क्षेत्रीय निदेशालय, लखनऊ।
- 7-श्री अखिलानन्द पाण्डेय, उप कृषि निदेशक भूमि संरक्षण, प्रयागराज मण्डल, प्रयागराज।
- 8-श्री रमेश कुमार सिंह, क्षेत्रीय अधिकारी, उ0प्र0 प्रदूषण नियंत्रण बोर्ड, प्रयागराज।

मा0 राष्ट्रीय हरित अधिकरण (एन0जी0टी0), नई दिल्ली में योजित ओ0ए0 नं0 203/2021 देवीदास खत्री बनाम यूनियन ऑफ इण्डिया एवं अन्य में पारित आदेश दिनांक 01.02.2022 का मुख्य कार्यकारी अंश निम्नवत् है :-

Since further remedial action is required in the light of above report and observations made by us, we constitute a joint Committee with the Divisional Commissioner, Prayagraj as Chairman and the Chief Conservator of Forest, Allahabad and nominees of CPCB, State PCB, SEIAA UP and Secretary, Agriculture (an expert in soil conservation) as members to ensure that all washing units/mining leases conduct their activities in accordance with the statutory procedures and environmental norms and compensation is assessed and recovered for the past violations. The Committee may undertake visit to the sites within two months and after coordinated remedial action furnish a report, keeping in mind the earlier report as well as observations made hereinabove by e-mail at judicial-ngt@gov.in preferably in the form of searchable PDF/ OCR Support PDF and not in the form of Image PDF.

List for further consideration on 18.05.2022:


CCT
22/4/22

बैठक के दौरान अधोहस्ताक्षरी द्वारा सम्बन्धित विभागों के अधिकारियों के साथ शंकरगढ़ क्षेत्र में खनन की अद्यतन प्रगति हेतु समीक्षा की गयी एवं एजेंडा बिन्दु के सापेक्ष कार्यवाही किये जाने हेतु निर्देशित किया गया, जो निम्नानुसार है :-

- 1- सर्वप्रथम खनन अधिकारी, प्रयागराज द्वारा अवगत कराया गया कि वर्तमान में कुल 07 खनन पट्टे शंकरगढ़ क्षेत्र में चिन्हित एवं संचालित हैं, जिनमें सिलिका सैण्ड का खनन कार्य संचालित हो रहा है। खनन पट्टों को निर्गत पर्यावरणीय स्वीकृति में अधिरोपित शर्तों के अनुपालन में खनन पट्टेदारों द्वारा वेब कैमरा, वृक्षारोपण, डिमारकेशन इत्यादि के कार्य पूर्ण कर लिये गये हैं।
- 2- अधोहस्ताक्षरी द्वारा खनन अधिकारी, राजस्व विभाग, कृषि विभाग एवं वन विभाग के उपस्थित अधिकारियों को निर्देशित किया गया कि एक संयुक्त टीम का गठन कर लिया जाय, जिसमें वन विभाग के रेंजर तथा राजस्व विभाग के उपजिलाधिकारी स्तर से कम के अधिकारी न हों। संयुक्त टीम द्वारा सर्वे कर लिया जाय तथा पूर्व में प्रयोग में लायी गयी माइन्स (परित्यक्त माइन्स) के गड्ढों को भरने के लिए तथा वृक्षारोपण का कार्य कराये जाने के लिए कार्ययोजना तैयार कर ली जाय। इस कार्य हेतु सैटेलाइट मैपिंग की भी सहायता ली जाए। परित्यक्त माइन्स में वृक्षारोपण का कार्य किये जाने हेतु वन विभाग के अधिकारियों द्वारा इस आशय का प्रस्ताव दिया जाए कि किस प्रकार की पद्धति पर आधारित वृक्षारोपण का कार्य उक्त भूमि पर किया जा सकता है।
- 3- क्षेत्रीय अधिकारी, उ०प्र० प्रदूषण नियंत्रण बोर्ड, प्रयागराज द्वारा अवगत कराया गया कि वर्तमान में कुल 41 इकाईयां सिलिका सैण्ड की वाशिंग हेतु स्थापित हैं, जिनमें से 36 इकाईयां संचालित हैं। इस सम्बन्ध में निर्देशित किया गया कि क्षेत्रीय अधिकारी, उ०प्र० प्रदूषण नियंत्रण बोर्ड, प्रयागराज सभी संचालित वाशिंग प्लाण्ट के सम्बन्ध में खनन विभाग से भी अभिमत प्राप्त करेंगे। यह भी निर्देशित किया गया कि समस्त इकाईयां द्वारा मा० एन०जी०टी० द्वारा दिये गये निर्देशों का पूर्ण अनुपालन जैसे-जल स्रोतों पर वाटर मीटर लगाना, कच्चे गड्ढों के स्थान पर वाटर साइक्लिंग हेतु मक्के गड्ढे बनाया जाना, वृक्षारोपण का कार्य किया जाना तथा जल उपयोग के आंकलन हेतु वाटर मीटर लगाया जाना इत्यादि सुनिश्चित कर लिया जाए।
- 4- खनन अधिकारी, प्रयागराज को निर्देशित किया गया कि बैठक दिनांक 16.03.2022 में दिये गये निर्देश के क्रम में उपलब्ध करायी गयी अनुपालन आख्या में सिलिका सैण्ड के स्वीकृत पट्टा के सम्बन्ध में स्पष्ट रूप से सभी के लिए उल्लेख किया जाए कि वर्तमान में Bench की आवश्यकता नहीं है।
- 5- बैठक में उपस्थित संबंधित अधिकारियों को निर्देशित किया गया कि मा० एन०जी०टी० के आदेश दिनांक 01.02.2022 के पैरा-7 में दिये गये निर्देश के सम्बन्ध में अपने विभाग से संबंधित कार्यवाही/अनुपालन आख्या की Synopsis/सारांश उपलब्ध कराएं, ताकि उसका उपयोग मा० एन०जी०टी० को प्रेषित की जाने वाली आख्या में किया जा सके।

5- अधोहस्ताक्षरी द्वारा खनन अधिकारी को निर्देशित किया गया कि समस्त खनन पट्टों की खनन क्षमता का वार्षिक विवरण तैयार कर पूर्ण विवरण के साथ प्रस्तुत किया जाय। पर्यावरणीय अनापत्ति में स्वीकृत पट्टों के लिए जो अनुमन्त्र मात्रा है, उसके सापेक्ष प्रपत्र ई0 एम0एम0-11 की निकासी हुई है अथवा नहीं, इस सम्बन्ध में खनन अधिकारी, प्रयागराज जांच कर अवगत कराएं। क्षेत्रीय अधिकारी, उ0प्र0 प्रदूषण नियंत्रण बोर्ड, प्रयागराज को निर्देशित किया गया कि खनन पट्टों से निकलने वाले खनिज के वाशिंग द्वारा खनिज उत्पादन की साम्यता के दृष्टिगत समस्त वाशिंग इकाईयों में भण्डारण हेतु लागबुक बना लिया जाए एवं एम0एम0-11 का मिलान कर लिया जाए।

7- बैठक में उपस्थित अधिकारियों को निर्देशित किया गया कि उपरोक्त निर्देशों के सम्बन्ध में अपने-अपने विभाग की अनुपालन आख्या दिनांक 25.04.2022 तक प्रस्तुत करें।



(संजय गोयल) 16/4/22

मण्डलायुक्त, प्रयागराज।

संख्या: 2854 - 62/30-17-2021 दिनांक: 18/04/2022

प्रतिलिपि: निम्नलिखित को सूचनार्थ एवं आवश्यक कार्यवाही हेतु तथा संबंधित को अनुपालनार्थ प्रेषित :-

- 1-जिलाधिकारी, प्रयागराज।
- 2-मुख्य वन संरक्षक, प्रयागराज।
- 3-श्री हर्ष देव पाण्डेय, अपर जिलाधिकारी (प्रशासन), प्रयागराज।
- 4-श्री जय प्रकाश, संयुक्त निदेशक, भूतत्व एवं खनिकर्म विभाग, क्षेत्रीय कार्यालय, प्रयागराज।
- 5-श्री मिथिलेश पाण्डेय, खनन अधिकारी, प्रयागराज।
- 6-डॉ0 अजय मिश्रा, सदस्य, एस0ई0ए0सी0-1, उ0प्र0, लखनऊ।
- 7-श्री ए0के0 त्रिपाठी, वैज्ञानिक-'ग', केन्द्रीय प्रदूषण नियंत्रण बोर्ड, क्षेत्रीय निदेशालय, लखनऊ।
- 8-श्री अखिलानन्द पाण्डेय, उप कृषि निदेशक भूमि संरक्षण, प्रयागराज मण्डल, प्रयागराज।
- ✓ 9-श्री रमेश कुमार सिंह, क्षेत्रीय अधिकारी, उ0प्र0 प्रदूषण नियंत्रण बोर्ड, प्रयागराज।




(संजय गोयल) 16/4/22

मण्डलायुक्त, प्रयागराज।

Annex-4

मा0 राष्ट्रीय हरित अधिकरण (एन0जी0टी0), नई दिल्ली में योजित ओ0ए0 नं0-203/2021 देवीदास खत्री बनाम यूनियम ऑफ इण्डिया एवं अन्य में पारित आदेश दिनांक 01.02.2022 के अनुपालन में दिनांक 11.04.2022 को मण्डलायुक्त, प्रयागराज की अध्यक्षता में आयोजित बैठक के कार्यवृत्त की अनुपालन आख्या:-

क्र0 सं0	कार्यवृत्त के बिन्दु/विवरण	अनुपालन आख्या
1	2	3
1.	बिन्दु-2 खनन अधिकारी, राजस्व विभाग, कृषि विभाग एवं वन विभाग के उपस्थित अधिकारियों को निर्देशित किया गया कि एक संयुक्त टीम का गठन कर लिया जाय, जिसमें वन विभाग के रेंजर तथा राजस्व विभाग के उपजिलाधिकारी स्तर से कम के अधिकारी न हों। संयुक्त टीम द्वारा सर्वे कर लिया जाय तथा पूर्व में प्रयोग में लायी गयी मान्ड्रा (परित्यक्त माइन्स) के गड्डों को भरने के लिए तथा वृक्षारोपण का कार्य कराये जाने के लिए कार्ययोजना तैयार कर ली जाय। इस कार्य हेतु सैटेलाइट मैपिंग की भी सहायता ली जाए। परित्यक्त माइन्स में वृक्षारोपण का कार्य किये जागे हेतु वन विभाग के अधिकारियों द्वारा इस आशय का प्रस्ताव दिया जाए कि किस प्रकार की पद्धति पर आधारित वृक्षारोपण का कार्य उक्त भूमि पर किया जा सकता है।	आदेशानुसार टीम गठित करायी जा रही है।
2.	बिन्दु-4 खनन अधिकारी, प्रयागराज को निर्देशित किया गया कि बैठक दिनांक 16.03.2022 में दिये गये निर्देश के क्रम में उपलब्ध करायी गयी अनुपालन आख्या में सिलिका सैण्ड के स्वीकृत पट्टा के सम्बन्ध में स्पष्ट रूप से सभी के लिए उल्लेख किया जाए कि वर्तमान में Bench की आवश्यकता नहीं है।	जनपद प्रयागराज के तहसील बारा स्थित 07 स्वीकृत/संचालित सिलिका सैण्ड के खनन पट्टों की जाँच की गयी। उक्त के अनुसार समस्त खनन क्षेत्र में खनन की गहराई अधिकांश स्थानों पर औसतन 1 से 3 मीटर पायी गयी है जो अभी अपने न्यूनतम स्तर पर है, जिसमें बैच बनाने की आवश्यकता नहीं है।
3.	बिन्दु-5 बैठक में उपस्थित सम्बन्धित अधिकारियों को निर्देशित किया गया कि मा0 एन0जी0टी0 के आदेश दिनांक 01.02.2022 के पैरा-7 में दिये गये निर्देश के सम्बन्ध में अपने विभाग से सम्बन्धित कार्यवाही/ अनुपालन आख्या की Synopsis/सारांश उपलब्ध कराए ताकि उसका उपयोग मा0 एन0जी0टी0 को प्रेषित की जाने वाली आख्या में किया जा सके। मा0 राष्ट्रीय हरित अधिकरण (एन0जी0टी0), नई दिल्ली में योजित ओ0ए0 नं0 203/2021 देवीदास खत्री बनाम यूनियन ऑफ इण्डिया एवं अन्य में पारित आदेश दिनांक 01.02.2022 खनन विभाग से सम्बन्धित कार्यकारी अंश निम्नवत् है:- Mining leases conduct their activities in accordance with the statutory procedures and environmental norms and compensation is assessed and recovered for the past violations.	सिलिका सैण्ड के स्वीकृत सभी 07 खनन क्षेत्रों में अनुमोदित खनन योजना एवं पर्यावरण रक्षता प्रमाण पत्रों में उल्लिखित शर्तों के अनुसार खनन कार्य किया जा रहा है। समस्त सिलिका सैण्ड के पट्टेधारक द्वारा अनुपालन आख्या पर्यावरण एवं वन मंत्रालय, क्षेत्रीय कार्यालय, मध्य क्षेत्र, लखनऊ को प्रत्येक छः माह पर प्रेषित की जाती है।


 21/4/2022
 प्रयागराज
 मण्डलायुक्त







क्र. सं.	परिहायक का विवरण / नाम	पर्यावरण स्वच्छता प्रयाग पत्र में स्वीकृत मात्रा (घनमीटर में प्रतिवर्ष)	पट्टा वर्ष 2020-21 व 2021-22 में निकासी की गयी मात्रा घनमीटर में
1	2	3	4
1.	श्री. बाबल सिंह सं. 10 टूटिंग कम्पनी घा. 10 श्री दर्शन लाल घा. 10 व अन्य नि. 42 एम्. 10 वसु सं. 2 प्रयागराज (घाम-जनक)	17,440 घ0मी0	02 पट्टा वर्ष में स्वीकृत मात्रा-34,880 घ0मी0 के सापेक्ष-25,768 घ0मी0 मात्रा की निकासी की गयी है, जो अनुमत्य मात्रा से कम है।
2.	श्री. बाबल सिंह सं. 10 टूटिंग कम्पनी घा. 10 श्री दर्शन लाल घा. 10 व अन्य नि. 42 एम्. 10 वसु सं. 2 प्रयागराज (घाम-जनक)	1,00,000 घ0मी0	02 पट्टा वर्ष में स्वीकृत मात्रा-2,00,000 घ0मी0 के सापेक्ष-47,796 घ0मी0 मात्रा की निकासी की गयी है, जो अनुमत्य मात्रा से कम है।
3.	श्री. मनीष निर्मल शर्मा घा. 10 वसु सं. 11 घा. 10 व अन्य नि. 11 प्रयागराज	40,000 घ0मी0	02 पट्टा वर्ष में स्वीकृत मात्रा-80,000 घ0मी0 के सापेक्ष-43,837 घ0मी0 मात्रा की निकासी की गयी है, जो अनुमत्य मात्रा से कम है।
4.	श्री. अजय कुमार सं. 10 टूटिंग कम्पनी घा. 10 श्री दर्शन लाल घा. 10 व अन्य नि. 42 एम्. 10 वसु सं. 2 प्रयागराज	16,667 घ0मी0	02 पट्टा वर्ष में स्वीकृत मात्रा-33,334 घ0मी0 के सापेक्ष-27,672 घ0मी0 मात्रा की निकासी की गयी है, जो अनुमत्य मात्रा से कम है।
5.	श्री. अजय कुमार सं. 10 टूटिंग कम्पनी घा. 10 श्री दर्शन लाल घा. 10 व अन्य नि. 42 एम्. 10 वसु सं. 2 प्रयागराज	16,667 घ0मी0	02 पट्टा वर्ष में स्वीकृत मात्रा-33,334 घ0मी0 के सापेक्ष-11,222 घ0मी0 मात्रा की निकासी की गयी है, जो अनुमत्य मात्रा से कम है।
6.	श्री. अजय कुमार सं. 10 टूटिंग कम्पनी घा. 10 श्री दर्शन लाल घा. 10 व अन्य नि. 42 एम्. 10 वसु सं. 2 प्रयागराज	3,00,000 घ0मी0	02 पट्टा वर्ष में स्वीकृत मात्रा-6,00,000 घ0मी0 के सापेक्ष-1,29,300 घ0मी0 मात्रा की निकासी की गयी है, जो अनुमत्य मात्रा से कम है।
7.	श्री. राजीव कुमार सं. 10 टूटिंग कम्पनी घा. 10 श्री दर्शन लाल घा. 10 व अन्य नि. 42 एम्. 10 वसु सं. 2 प्रयागराज	40,000 घ0मी0	02 पट्टा वर्ष में स्वीकृत मात्रा-80,000 घ0मी0 के सापेक्ष-6,621 घ0मी0 मात्रा की निकासी की गयी है, जो अनुमत्य मात्रा से कम है।

उपरोक्तानुसार अनुपालन आख्या महोदय की सेवा में सादर प्रेषित।


(राधेश्याम)
वरिष्ठ मानचित्रकार
क्षेत्र 0 का 0 प्रयागराज।


(राधवेन्द्र सिंह)
खान अधिकारी,
प्रयागराज।


19/4/22
(मिथिलेश कुमार पाण्डेय)
जिला खान अधिकारी,
प्रयागराज।


21/4/22
(हर्ष देव पाण्डेय)
अपर जिलाधिकारी (प्रशासन),
प्रयागराज

कार्यालय जिलाधिकारी, प्रयागराज
(खनन अनुभाग)

पत्रांक: 194 / खनन / 2022-23

दिनांक: 22/4 / 2022

आदेश

मा0 राष्ट्रीय हरित अधिकरण (एन0जी0टी0), नई दिल्ली में योजित ओ0ए0 नं0-203 / 2021 देवीदास खत्री बनाम यूनियम ऑफ इण्डिया एवं अन्य में पारित आदेश दिनांक 01.02.2022 के अनुपालन में दिनांक 11.04.2022 को मण्डलायुक्त, प्रयागराज की अध्यक्षता में सम्पन्न हुई बैठक के कार्यवृत्त के बिन्दु सं0-2 में दिये गये आदेश के अनुपालन में निम्नवत टीम का गठन किया जाता है:-

1. उपजिलाधिकारी, बारा, प्रयागराज।
2. क्षेत्रीय अधिकारी, प्रदूषण नियंत्रण बोर्ड, क्षेत्रीय कार्यालय, प्रयागराज।
3. क्षेत्राधिकारी, वन विभाग, प्रयागराज।
4. भूमि संरक्षण अधिकारी, प्रयागराज।
5. खान अधिकारी, प्रयागराज।

मा0 आयुक्त महोदय द्वारा दिये गये निर्देशानुसार संयुक्त टीम द्वारा सिलिका सैण्ड के क्षेत्रों का सर्वे कर लिया जाय तथा पूर्व में प्रयोग में लायी गयी मान्ड्स (परित्यक्त माइन्स) के गड्डों को भरने के लिए तथा वृक्षारोपण का कार्य कराये जाने के लिए कार्ययोजना तैयार कर ली जाय। इस कार्य हेतु सैटेलाइट मैपिंग की भी सहायता ली जाए। परित्यक्त माइन्स में वृक्षारोपण का कार्य किये जाने हेतु वन विभाग के अधिकारियों द्वारा इस आशय का प्रस्ताव दिया जाए कि किस प्रकार की पद्धति पर आधारित वृक्षारोपण का कार्य उक्त भूमि पर किया जा सकता है।

उक्त निर्देश का कड़ाई से अनुपालन सुनिश्चित करते हुये, आख्या/कार्ययोजना 15 दिवस के अन्दर उपलब्ध कराना सुनिश्चित करें।

(संजय कुमार खत्री)
जिलाधिकारी, प्रयागराज।

१६

पत्रांक व दिनांक उपरोक्त।

प्रतिलिपि-निम्नलिखित को सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-

1. मा0 आयुक्त, प्रयागराज मण्डल, प्रयागराज।
2. मुख्य वन संरक्षक, प्रयागराज।
3. वन संरक्षक / प्रभारी प्रभागीय निदेशक, सामाजिक वानिकी प्रभाग, प्रयागराज।
4. अपर जिलाधिकारी (प्रशासन), प्रयागराज।
5. उपजिलाधिकारी, बारा, प्रयागराज।
6. क्षेत्रीय अधिकारी, प्रदूषण नियंत्रण बोर्ड, क्षेत्रीय कार्यालय, प्रयागराज।
7. भूमि संरक्षण अधिकारी, प्रयागराज।
8. खान अधिकारी, प्रयागराज।

(संजय कुमार खत्री)
जिलाधिकारी, प्रयागराज।

१६

कार्यालय उपजिलाधिकारी बारा, प्रयागराज

पत्रांक 3654/एस0टी0 बारा

दिनांक 17 मई 2022

सेवा में,

जिलाधिकारी
प्रयागराज

महोदय,

मा0 एन0जी0टी0 के निर्देशन एवं मण्डलायुक्त महोदय के आदेश के क्रम में तहसील बारा में किये गये/किये जा रहे खनन के भू-भाग पर पट्टेदारों द्वारा उक्त भूमि के पुनरुद्धार हेतु खनित भू-भाग एवं वाशिंग प्लान्ट के आस-पास वृक्षारोपण कराये जाने हेतु वन विभाग एवं राजस्व विभाग की संयुक्त टीम द्वारा स्थल चिन्हीकरण का कार्य किया गया है। कुछ भाग पर पट्टेदारों द्वारा वृक्षारोपण प्रारम्भ भी किया जा चुका है। उदहरण स्वरूप ग्राम जनवा के खनिज पट्टा स्थल एवं ग्राम कैथा एवं बिहरिया के वाशिंग प्लान्ट पर किये गये एवं प्रस्तावित वृक्षारोपण के नजरी नक्शों की छाया प्रतियां अवलोकनार्थ संलग्न कर सादर प्रेषित की जा रही है। अन्य खनिज पट्टों/वाशिंग प्लान्ट पर भी इसी प्रकार की कार्यवाही करायी जा रही है।


उपजिलाधिकारी
बारा, प्रयागराज

प्रतिलिपि:- माननीय मण्डलायुक्त महोदय प्रयागराज को सादर अवलोकनार्थ।

उपजिलाधिकारी
बारा, प्रयागराज

क्षेत्र 1. मे० चावला सिलिण्ड्र ड्रेडिंग कम्पनी प्रा-श्री दर्शन लाल चावला व अन्य
 नि-42 रस०सो० बालू रोड, प्रयागराज - जनवरी

गाय सं० - 7, 8, 9, 11, 15, 25, 44, 45, 46, 47, 50, 51, 55
 56, 57, 96, 305, 306, 307, 309 कुल क्षेत्रफल - 5.47 हे०
 सम्पूर्ण परदा अवधि के मध्य - 1 हेक्टेयर = 1000 पौधे



प्रस्तावित वृक्षारोपण की विधि -

क्षरित परिदृश्या	I	II	III
को हुर पौड	50	27	-
प्रस्तावित पौड	70	55	55

परिदृश्या
 रोपण का भाग
 पर उपरोक्त
 पौडों की सं० - 86

विश्व प्रकाश
 लिखपाल
 क्षेत्र.....
 तहसील-बालू, प्रयागराज
 22/01/2022

महेश्वर
 क. द.

क्षेत्रीय उच्च अधिकारी
 संकरगढ़ रोज-प्रयागराज

UP PCB/...

संपुक्ल निरीक्षण रिपोर्ट

महोदय:-

क्षेत्रीय भ्रमण के दौरान राजस्व विभाग व वन विभाग की संपुक्ल टीम द्वारा ग्राम-जमवाँ, परगना व तहसील खारा, जिला-पयागराज के स्वामीप व अभिलेखीप जांच किया गया। जिसमें विदित हुआ कि आ.सं० 7, 8, 9, 11, 15, 25, 44, 45, 46, 47, 50, 51, 55, 56, 57, 96, 305, 306, 307, 309 का कुल क्षेत्रफल 5.470 हे० भूमि पर 20 वर्ष (09-09-2014 - 08-09-2034) तक सिलिका सैंड के खनन हेतु पदण में चावला सिलिका सैंड ट्रेडिंग कंपनी प्रो० भी दर्शन-चावला व अम्य सैं० पर राज्य० सी ब्यारु रीड पयागराज के नाम हुआ था जिस पर सिलिका सैंड के खनन का कार्य अपने निर्धारित सीमा के अन्दर ही रडा है। कुल लीज क्षेत्र में 77 चौ० लगे हुए पाये। जिसमें लगभग 180 चौ० लगभग हे० भूमि उपलब्ध है जो करील परिलका सिध से लगाया जा सकता है।

अतः रिपोर्टीमान की सेवा में सादर प्रेषित है।

UPPCB/11/4/2014

दिनांक 15/11/2014

वेन...
तहसील खारा, जिला पयागराज

मह-तजार
क. र.

क्षेत्रीय वन अधिकारी
शंकरगढ़ रेंज-पयागराज

संपुर्ण निरीक्षण रिपोर्ट

=====

प्रश्नवृत्त:

आपके आदेश के क्रम में दिनांक 21-04-2022 ई० की क्षेत्रीय भ्रमण के दौरान राजम व विभाग व वनविभाग की संपुर्ण टीम द्वारा गताम-कैथा - पर० व लड० द्वारा, पिन्ना - प्यागराज वा स्पर्शीप व अशिलेखीप जाँच किया। जिसमें पड पाया गया कि गताम - कैथा की आ० सं० 37/1, 38/1, 39/1 व 32/2/1 का कुल रकबा 1.141 हे० भूमि व गताम - लखनपुर की आ० सं० 749/2, 768/2, 773 का कुल रकबा 0.913 हे० भूमि पर श्री गिरधारी लाल पावला रोड बस के नाम वाशिंग लॉट बना है। उक्त वाशिंग लॉट में लागभग 38 पौंचे लग डूरा पाये। जिसमें लागभग 220 पौंचे लागभे डूरा भूमि उपलब्ध है। जो हरि ए यदिष्का विधि से लागपा जा सकता है।

अतः रिपोर्ट श्रीमान जी के सेवा में सादर उपलब्ध है।


U.P.P.E.B. Officer


विकास अधिकारी
महंत लाल
व. 2.
सेवा-प्यागराज
राजसिंह-बाप, प्रधानाध्यक्ष




क्षेत्रीय वन अधिकारी
शंकरगढ़ रेंज - प्यागराज


Annex-7















सेवा में,
आयुक्त,
प्रयागराज मण्डल,
प्रयागराज।

पत्रांक- 1641 /30-2022
महोदय,

दिनांक 14/05/2022

कृपया अपने कार्यालय आदेश संख्या-2115/पी0ए0 दिनांक 12.05.2022 का सन्दर्भ ग्रहण करने का कष्ट करें जिसके अन्तर्गत मा0 राष्ट्रीय हरित अधिकरण (एन0जी0टी0) में योजित ओ0ए0 नं0 203/2021 देवीदास खत्री बनाम यूनियन ऑफ इण्डिया एवं अन्य में पारित आदेश दिनांक 01.02.2022 के अनुपालन में शंकरगढ़ क्षेत्र में खनन क्षेत्र तथा वाशिंग प्लांटों का सूक्ष्मता से एवं बृहद निरीक्षण किये जाने हेतु अधोहस्ताक्षरी एवं श्री जय प्रकाश, संयुक्त निदेशक, खनन प्रयागराज मण्डल की दो सदस्यीय समिति का गठन किया गया है।

महोदय के उक्त आदेश के अनुपालन में समिति द्वारा चेकलिस्ट के अनुसार शंकरगढ़ क्षेत्र में एक सिलिका सैंड खनन क्षेत्र एवं 09 वाशिंग प्लांटों का सूक्ष्मता से एवं बृहद स्थलीय निरीक्षण किया गया, जिसकी अनुपालन आख्याएं इस पत्र के साथ संलग्न कर सादर अवलोकनार्थ प्रेषित है।

संलग्नक-यथोक्त।

AC (A)

स्.

आमुस्त

(संजय गौयल)

मण्डलायुक्त, प्रयागराज

भवदीय,
14/05/22
(पुष्प राज सिंह)
अपर आयुक्त (प्रशासन),
प्रयागराज मण्डल, प्रयागराज।

I- Shree Ashok Kumar Bajpevee S/O Late D.N. Bajpevee, (Res.-109, Parerahat Rambag), Lease Area-Teh- Bara, vill- Purabuldu Prayagraj.

Checklist for Mining Area

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Presence of pillars	Yes	-	-
2.	Geo-co-ordinated on pillars	Yes	-	-
3.	Approach Road Status	Yes	-	Temporary
4.	Fugitive Emission	Yes	-	Not proper Arrangement for fugitive emission.
5.	Storage of overburden/Top Soil Management status	Yes	-	-
6.	Display Board	Yes	-	-
7.	CCTV camera	-	No	CCTV camera installed at stone crushing plant. about 845 meter far from lease area near main road.
8.	Green Best / plantation	Yes	-	25 plants and tree seen
9.	weigh Bridge	Yes	-	Outside of the mining area about 845 meter near main road.
10.	Benching in Mining Area Depth up to 3 meters of pit.	Yes	-	In Mining Area Less than 3 meter pits seen
11.	Transporation- Dust Supperssion Measures (water Sprinking)	-	No	water Sprinker not Seen in the lease area.
12.	Common Facilities- Toilets Drinking Water First Aid Box Safety Equipments	- - - -	No - No -	- Temporary Arrangement by Labours Not Seen in Spot Not Seen in Spot
13.	Record Maintenance	-	-	-

- नोट:- 1. माइनिंग लीज एरिया में सिलिका सैंड वाशिंग प्लांट स्थित है।
 2. उपस्थित प्रतिनिधि द्वारा अवगत कराया गया कि सिलिका वाशिंग करने में प्राकृतिक जल प्रयोग किया जाता है। जोकि उनकी लीज एरिया के अन्तर्गत स्थित है।
 3. अस्थाई वाटर फ्लो मीटर पम्पिंग सेट के साथ लगा हुआ देखा गया।
 4. लीज एरिया में मजदूरों की रहने की स्थायी व्यवस्था नहीं की गयी है। (इसोपडी में है)

14/05/22
 (जय प्रकाश)
 संयुक्त निदेशक,
 भूतत्व एवं खनिकर्म निदेशालय,
 उ०प्र०, लखनऊ

14/05/22
 (पुष्प राज सिंह)
 अपर आयुक्त (प्रशासन)
 प्रयागराज मण्डल,
 प्रयागराज

1-M/s Krishna Minerals, Benipur, Shankargarh Prayagraj

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	Yes	-	In open area.
2.	Line/Unlined Water Storage Tanks	Yes	-	-
3.	Rain water Harvesting Pit (Kutchha-Groundwater recharge)	Yes	-	-
4.	Dust Management/Water Sprinkler System	Yes	-	Partly.
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower	Yes Yes Yes Yes Yes Yes	- - - - - -	Computrised Log Book. Not certified. By Generator. Borewell.
6.	Boundary Wall	Yes	-	Registered not properly maintain.
7.	Green Belt or Boundary	Yes	-	In back area no boundrywall.
8.	Display Board	Yes	-	-
9.	Periodic Health Check-up	-	No	-
10.	UPPCB Consent	Yes	-	-
11.	UP State Ground water Board/CGWA (If more than 10 KLD)	Yes	-	-
12.	Record Maintenance	Yes	-	Not properly maintain.
13.	Any other	-	-	-

नोट- 1-वाशिंग प्लांट पेट्रोल पम्प बाउन्ड्री से सटा हुआ है। दोनों की बाउन्ड्री एक ही है।
2-वाशिंग प्लांट प्रयागराज-बांदा रोड से सटा हुआ है।

14/05/22

(जय प्रकाश)

संयुक्त निदेशक

भूतत्व एवं खनिकर्म निदेशालय, 3050

प्रयागराज।

(जय प्रकाश)

संयुक्त निदेशक

भूतत्व एवं खनिकर्म निदेशालय,

उ०प्र०, लखनऊ

14/05/22

(पुष्प राज सिंह)

अपर आयुक्त (प्रशासन)

प्रयागराज मण्डल,

प्रयागराज

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	Yes	-	In open area. No Security major.
2.	Line/Unlined Water Storage Tanks	Yes	-	
3.	Rain water Harvesting Plt (Kuteha-Groundwater recharge)	Yes	-	-
4.	Dust Management/Water Sprinkler System	-	No	-
5.	Log Book maintenance	Yes	-	Not certified. Temporary. By Generator. Borewell.
	Energy	Yes	-	
	Water	Yes	-	
	Raw Material	Yes	-	
	Finished Products	Yes	-	
	Manpower	-	No	Registered not maintain.
6.	Boundary Wall	-	No	
7.	Green Belt or Boundary	Yes	-	Few Plant-1 Mango Tree, 2 Sheesam Tree
8.	Display Board	-	No	-
9.	Periodic Health Check-up	-	No	-
10.	UPPCB Consent	Yes	-	-
11.	UP State Ground water Board/CGWA (If more than 10 KLD)	Yes	-	-
12.	Record Maintenance	Yes	-	Not properly maintain and temporary.
13.	Any other	-	-	-

14/05/22

जय प्रकाश

संयुक्त निदेशक,

मूलत्व एवं खनिकर्म निदेशालय - 3080

प्रयागराज /

(जय प्रकाश)

संयुक्त निदेशक

मूलत्व एवं खनिकर्म निदेशालय,

उ०प्र०, लखनऊ

14/05/22

(पुष्प राज सिंह)

अपर आयुक्त (प्रशासन)

प्रयागराज मण्डल,

प्रयागराज

**3-Shri Narayan Datt Tiwari (Silica washing Plant) Benipur,
Shankargarh, Prayagraj**

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availabili ty		Remarks
		Yes	No	
1.	Flow meter Installation	Yes	-	Not Properly Maintain.
2.	Line/Unlined Water Storage Tanks	-	No	-
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)	-	No	-
4.	Dust Management/Water Sprinkler System	-	No	-
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower	Yes Yes Yes Yes Yes -	- - - - - No	Not Properly Maintain. Electricity and generator. Borewell.
6.	Boundary Wall	Yes	-	Not any Record Seen.
7.	Green Belt or Boundary	Yes	-	Not Proper. Few Plant-1 Mango Tree, 1 Mahua, 2 Uke Liptis, 1 Pipal
8.	Display Board	-	No	-
9.	Periodic Health Check-up	-	No	-
10.	UPPCB Consent	Yes	-	-
11.	UP State Ground water Board/CGWA (If more than 10 KLD)	-	-	Not Seen.
12.	Record Maintenance	Yes	-	Not properly maintain and temporary.
13.	Any other	-	-	-

- नोट- 1-वाशिंग प्लान्ट शिवराजपुर मार्केट और बस्ती के मध्य सड़क के किनारें स्थित है।
2-मौके पर उपस्थित प्रतिनिधि द्वारा अवगत कराया गया कि यह प्लांट नया बिकसित किया जा रहा है।
3-पश्चिम तरफ हाईटेंशन तार व टावर स्थित है।

14/05/22

(जय प्रकाश)

संयुक्त निदेशक

(जय प्रकाश)

संयुक्त निदेशक
भूतत्व एवं खनिकर्म निदेशालय,
उ०प्र०, लखनऊ

14/05/22

(पुष्प राज सिंह)

अपर आयुक्त (प्रशासन)
प्रयागराज मण्डल,
प्रयागराज

4-New Triveni Minerals, Lakhampur, Bara, Prayagraj

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	Yes	-	Not Properly Maintain.
2.	Line/Unlined Water Storage Tanks	Yes	-	-
3.	Rain water Harvesting Pit (Kutchha-Groundwater recharge)	-	No	-
4.	Dust Management/Water Sprinkler System	-	No	-
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower	Yes Yes Yes Yes Yes -	- - - - - No	Not Properly Maintain. Generator. Borewell. Not any Record Seen.
6.	Boundary Wall	Yes	-	Not Proper.
7.	Green Belt or Boundary	Yes	-	15 Plant and Tree Seen.
8.	Display Board	-	No	-
9.	Periodic Health Check-up	-	No	-
10.	UPPCB Consent	Yes	-	-
11.	UP State Ground water Board/CGWA (If more than 10 KLD)	-	-	Not Seen.
12.	Record Maintenance	-	No	-
13.	Any other	-	-	-

14/05/22

(जय प्रकाश)

संयुक्त निदेशक

(जय प्रकाश)

संयुक्त निदेशक

भूतत्व एवं खनिकर्म निदेशालय,
उ०प्र०, लखनऊ

14/05/22

(पुष्प राज सिंह)

अपर आयुक्त (प्रशासन)

प्रयागराज मण्डल,

प्रयागराज

5-Silca Khanij Udyog, Lakhanpur, Bara, Prayagraj

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availabili ty		Remarks
		Yes	No	
1.	Flow meter Installation	Yes	-	Not Properly Maintain.
2.	Line/Unlined Water Storage Tanks	Yes	-	-
3.	Rain water Harvesting Pit (Kutchra-Groundwater recharge)	Yes	-	Temporary Arrangement.
4.	Dust Management/Water Sprinkler System	-	No	-
5.	Log Book maintenance	-	No	-
	Energy	Yes	-	Generator.
	Water	Yes	-	Borewell.
	Raw Material	Yes	-	
	Finished Products	Yes	-	
	Manpower	Yes	-	6 Person But No report Maintain.
6.	Boundary Wall	-	No	-
7.	Green Belt or Boundary	Yes	-	3 Plant and Tree Seen.
8.	Display Board	-	No	-
9.	Periodic Health Check-up	-	No	-
10.	UPPCB Consent	Yes	-	-
11.	UP State Ground water Board/CGWA (If more than 10 KLD)	Yes	-	-
12.	Record Maintenance	-	No	-
13.	Any other	-	-	-

14/05/22

(जय प्रकाश)

संयुक्त निदेशक

(जय प्रकाश)

संयुक्त निदेशक

भूतत्व एवं खनिकर्म निदेशालय,

उ०प्र०, लखनऊ

14/05/22

(पुष्प राज सिंह)

अपर आयुक्त (प्रशासन)

प्रयागराज मण्डल,

प्रयागराज

6- Adhishwar Construction and Mineral Co. Parvejabad, Bara, Prayagraj

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	-	No	-
2.	Line/Unlined Water Storage Tanks	Yes	-	Natural Water Storage.
3.	Rain water Harvesting Pit (Kutch-Groundwater recharge)	-	No	Temporary Arrangement.
4.	Dust Management/Water Sprinkler System	-	No	-
5.	Log Book maintenance	-	No	-
	Energy	Yes	-	Generator.
	Water	Yes	-	Natural Water Storage/Pit.
	Raw Material	Yes	-	
	Finished Products	Yes	-	
	Manpower	-	No	No any Information
6.	Boundary Wall	-	No	-
7.	Green Belt or Boundary	Yes	-	3 Plant and Tree Seen.
8.	Display Board	-	No	-
9.	Periodic Health Check-up	-	No	-
10.	UPPCB Consent	Yes	-	-
11.	UP State Ground water Board/CGWA (If more than 10 KLD)	-	No	-
12.	Record Maintenance	-	No	-
13.	Any other	-	-	-

14/05/22
(जय प्रकाश)
(संयुक्त निदेशक)
(जय प्रकाश)
संयुक्त निदेशक
भूतत्व एवं खनिकर्म निदेशालय,
उ०प्र०, लखनऊ

14/05/22
(पुष्प राज सिंह)
अपर आयुक्त (प्रशासन)
प्रयागराज मण्डल,
प्रयागराज

7- Vandana Singh (Stone Silica Washing Plant), Bankipur, Bara, Prayagraj

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	-	No	-
2.	Line/Unlined Water Storage Tanks	-	No	-
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)	-	No	Dry Water Pit Seen. Temporary Arrangement.
4.	Dust Management/Water Sprinkler System	-	No	-
5.	Log Book maintenance	-	No	-
	Energy	Yes	-	Generator.
	Water	Yes	-	Hand pump.
	Raw Material	-	No	-
	Finished Products	-	No	-
	Manpower	-	No	No any Information
6.	Boundary Wall	yes	-	Temporary.
7.	Green Belt or Boundary	-	No	-
8.	Display Board	-	No	-
9.	Periodic Health Check-up	-	No	-
10.	UPPCB Consent	Yes	-	-
11.	UP State Ground water Board/CGWA (If more than 10 KLD)	-	No	-
12.	Record Maintenance	-	No	-
13.	Any other	-	-	-

14/05/22
 (जय प्रकाश)
 संयुक्त निदेशक
 (जय प्रकाश)
 संयुक्त निदेशक
 भूतत्व एवं खनिकर्म निदेशालय,
 उ०प्र०, लखनऊ

14/05/22
 (पुष्प राज सिंह)
 अपर आयुक्त (प्रशासन)
 प्रयागराज मण्डल,
 प्रयागराज

8- Jay Shree Trading Company ,Bargari, Prayagraj

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	-	No	-
2.	Line/Unlined Water Storage Tanks	-	No	-
3.	Rain water Harvesting Pit (Kutchha-Groundwater recharge)	-	No	Dry Water Pit Seen. Temporary Arrangement.
4.	Dust Management/Water Sprinkler System	-	No	-
5.	Log Book maintenance	-	No	-
	Energy	Yes	-	Generator.
	Water	-	No	.
	Raw Material	Yes	-	
	Finished Products	-	No	
	Manpower	-	No	No any Information
6.	Boundary Wall	yes	-	Temporary.
7.	Green Belt or Boundary	Yes	-	12 Plant and Tree Seen.
8.	Display Board	-	No	-
9.	Periodic Health Check-up	-	No	-
10.	UPPCB Consent	Yes	-	-
11.	UP State Ground water Board/CGWA (If more than 10 KLD)	-	No	
12.	Record Maintenance	-	No	-
13.	Any other	-	-	-

14/05/22
(जय प्रकाश)
संयुक्त निदेशक
(जय प्रकाश)
संयुक्त निदेशक
भूतत्व एवं खनिकर्म निदेशालय,
उ०प्र०, लखनऊ

14/05/22
(पुष्प राज सिंह)
अपर आयुक्त (प्रशासन)
प्रयागराज मण्डल,
प्रयागराज

9- Bara White Stone Heights PVT. Ltd. Parvejabad, Prayagraj

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	-	No	-
2.	Line/Unlined Water Storage Tanks	-	No	Dry Water Pit Seen.
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)	-	No	Temporary Arrangement.
4.	Dust Management/Water Sprinkler System	-	No	-
5.	Log Book maintenance	-	No	-
	Energy	Yes	-	Generator.
	Water	-	No	.
	Raw Material	Yes	-	
	Finished Products	-	No	
	Manpower	-	No	No any Information
6.	Boundary Wall	-	No	-
7.	Green Belt or Boundary	-	No	-
8.	Display Board	-	No	-
9.	Periodic Health Check-up	-	No	-
10.	UPPCB Consent	Yes	-	-
11.	UP State Ground water Board/CGWA (If more than 10 KLD)	-	No	
12.	Record Maintenance	-	No	-
13.	Any other	-	-	-

14/05/22
(जय प्रकाश)
संयुक्त निदेशक
(जय प्रकाश)
संयुक्त निदेशक
भूतत्व एवं खनिकर्म निदेशालय,
उ०प्र०, लखनऊ

14/05/22
(पुष्प राज सिंह)
अपर आयुक्त (प्रशासन)
प्रयागराज मण्डल,
प्रयागराज

Annex - 8,9

सवा में

मण्डलायुक्त
प्रयागराज


पत्रांक :- 374/खनन


महोदय

कृपया कार्यालय मण्डलायुक्त, प्रयागराज के कार्यालय आदेश संख्या 2117/पी0ए0 दिनांक 12.05.2022 का संदर्भ ग्रहण करने का कष्ट करें, जिसके द्वारा मा0 राष्ट्रीय हरित अधिकरण(एन0जी0टी0) नई दिल्ली में योजि ओ0ए0 नं0 203/2021 देवीदास खत्री बनाम यूनियन ऑफ इण्डिया एवं अन्य में पारित आदेश दिनांक 01.02.2022 के अनुपालन में मण्डलायुक्त की अध्यक्षता में गठित समिति द्वारा दिनांक 18.05.2022 को जबाब प्रस्तुत किया जाना है।

उक्त के क्रम में आप द्वारा दिये गये निर्देश के अनुपालन में आवंटित 03 खनन क्षेत्र एवं 11 वांशिग प्लांट यूनिट का निरीक्षण दिनांक 13.05.2022 को किया गया। निरीक्षण हेतु निर्धारित चेकलिस्ट में दिये गये विन्दु की स्थिति की जाँच मौके पर की गयी। निर्धारित चेकलिस्ट पर की गयी जाँच रिपोर्ट संलग्न कर आवश्यक कार्यवाही हेतु सादर प्रेषित है।

सलग्नक: यथापार।


13/05/22
मिथिलेश कुमार पाण्डेय
जिला खान अधिकारी
प्रयागराज।


13/5/22
हर्षदेव पाण्डेय
अपर जिलाधिकारी, प्रशासन
प्रयागराज।

AC (A)

६०.

आयुक्त

(संजय गौयल)

मण्डलायुक्त, प्रयागराज



कार्यालय मण्डलायुक्त प्रयागराज



पत्रांक 2117/प्र/ए

दिनांक 12.05.2022

आवश्यक/महत्वपूर्ण/समयबद्ध

कार्यालय आदेश

मा0 राष्ट्रीय हरित अधिकरण (एन0जी0टी0) नई दिल्ली में योजित ओ0ए0 नं0 203/2021 देवीदास खत्री बनाम यूनियम ऑफ इण्डिया एवं अन्य में पारित आदेश दिनांक 01.02.2022 के अनुपालन में मण्डलायुक्त की अध्यक्षता में गठित समिति द्वारा दिनांक 18.05.2022 को जवाब प्रस्तुत किया जाना है।

मा0 एन0जी0टी0 के निर्देशों के आलोक में एन0जी0टी0 द्वारा गठित समिति की बैठक अधोहस्ताक्षरी की अध्यक्षता में दिनांक 16.03.2022 को एवं तत्पश्चात दिनांक 11.04.2022 को की जा चुकी है। साथ ही साथ गठित समिति के साथ दिनांक 12.05.2022 को स्थल निरीक्षण भी किया जा चुका है। अधोहस्ताक्षरी की अध्यक्षता में गठित समिति के साथ स्थल निरीक्षण किए जाने से शंकरगढ़ क्षेत्र में खनन क्षेत्र तथा वाशिंग प्लांटों का सूक्ष्मता से एवं वृहद निरीक्षण किए जाने के उद्देश्य से निम्न प्रकार दो सदस्यीय समिति का गठन किया जाता है।

- 1- श्री हर्षदेव पाण्डेय, अपर जिलाधिकारी, प्रशासन प्रयागराज।
- 2- श्री मिथलेश पाण्डेय, जिला खनन अधिकारी, प्रयागराज।

उपरोक्त समिति द्वारा शंकरगढ़ क्षेत्र में हो रहे खनन (खनन पट्टा सूची के अनुसार) एवं वाशिंग प्लांटों (वाशिंग प्लांट सूची के अनुसार) संलग्न चेक बिन्दुओं तथा अधोहस्ताक्षरी की अध्यक्षता में एन0जी0टी0 कमेटी की सम्पन्न बैठक दिनांक 16.03.2022 एवं दिनांक 11.04.2022 में उल्लिखित किए गए बिन्दुओं के आलोक में करते हुए अपनी संयुक्त सुस्पष्ट निरीक्षण आख्या विलम्बतम दिनांक 14.02.2022 तक प्रस्तुत की जाएगी।

संलग्न

- 1- खनन पट्टा की सूची।
- 2- वाशिंग प्लांटों की सूची।
- 3- चेक लिस्ट।
- 4- बैठक का कार्यवृत्त दिनांक 16.03.2022 एवं दिनांक 11.04.2022।

(संजय गोयल)

मण्डलायुक्त प्रयागराज।

प्रतिलिपि- निम्नलिखित को सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित।

- 1- श्री हर्षदेव पाण्डेय, अपर जिलाधिकारी, प्रशासन प्रयागराज।
- 2- श्री मिथलेश पाण्डेय, जिला खनन अधिकारी, प्रयागराज।
- 3- जिलाधिकारी, प्रयागराज।

(संजय गोयल) 12/5/22


मण्डलायुक्त प्रयागराज।

Checklist for Mining Area - Udagi Porhar - Area.
3.59 Hec.

Visit of Distt/Tehsil Level Task Force L/O - Shri Ragesh Kr. Chawla.

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Presence of pillars	✓	-	-
2.	Geo-Co-ordinates on pillars	✓	-	Mentioned on Pillar.
3.	Approach Road Status	✓	-	Morum Road.
4.	Fugitive Emission	-	✓	Not Applicable.
5.	Storage of overburden/Top Soil Management Status	-	-	No overburden in Area.
6.	Display Board	✓	-	Mentioned the lease details. all
7.	CCTV Camera	✓	-	-
8.	Green Belt/Plantation	✓	-	Improvement required
9.	Weigh Bridge	✓	-	Exit Route.
10.	Benching in Mining Area Depth Up to 3 metres of Pit	-	-	Not required at this time. Depth < 3m
11.	Transportation - Dust Suppression Measures (Water Sprinkling)	-	-	Work is not going on Lease Holder representative confirm that, they use water tanker.
12.	Common Facilities			
	Toilets	✓	-	Temporary
	Drinking Water	✓	-	-
	First Aid Box	✓	-	-
	Safety Equipments	✓	-	-
13.	Record Maintenance	✓	-	Register Available.

Note:- Above Inspection Carried out on 13/05/22.


13/05/22
District Mines officer
Prayagraj.



13/5/22
ADM(E)


Checklist for Mining Area - 7000000 - Area - 14.57 Hectare

Visit of Distt/Tehsil Level Task Force - L/O - Shri Abhinandan Tiwari

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Presence of pillars	✓	-	-
2.	Geo-Co-ordinates on pillars	✓	-	Mentioned on pillar.
3.	Approach Road Status	✓	-	Pucca Road
4.	Fugitive Emission	-	✓	Not Applicable.
5.	Storage of overburden/Top Soil Management Status	✓	-	Improvement Required.
6.	Display Board	✓	-	on Lease Site.
7.	CCTV Camera	✓	-	Near By weigh Bridge
8.	Green Belt/Plantation	✓	-	Inadequate.
9.	Weigh Bridge	✓	-	Exit Route of Mines.
10.	Benching In Mining Area Depth Up to 3 metres of Pit	-	-	Depth is not more than 3mts. As of No bench not required.
11.	Transportation - Dust Suppression Measures (Water Sprinkling)	-	-	Road is pucca, because of this not dust raise.
12.	Common Facilities Toilets Drinking Water First Aid Box Safety Equipments	✓ ✓ ✓ ✓	- - - -	Temporary Available - - work is not going on.
13.	Record Maintenance	✓	-	Register Available.

Note:- Above Inspection Carried out on 13-05-2022.


 13/05/22
 District Mine Officer
 Prayagraj.



 13/5/22
 ADM (F)


Checklist for Mining Area - January - Area - 19.73 Hectares

Visit of Distt/Tehsil Level Task Force L/O - M/s - Modi Mineral Udyog
 pro - Smt. Amrita Gupta

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Presence of pillars	✓	-	-
2.	Geo-Co-ordinates on pillars	✓	-	Mentioned on pillars.
3.	Approach Road Status	✓	-	Pucca Road.
4.	Fugitive Emission	-	✓	Not Applicable.
5.	Storage of overburden/Top Soil Management Status	-	-	No overburden at site.
6.	Display Board	✓	-	on site.
7.	CCTV Camera	✓	-	on site/ weigh bridge
8.	Green Belt/Plantation	✓	-	Inadequate, Improvements required.
9.	Weigh Bridge	✓	-	Exit Route.
10.	Benching In Mining Area Depth Up to 3 metres of Pit	-	-	Mining depth is not more than 3mtr.
11.	Transportation -Dust Suppression Measures (Water Sprinkling)	-	-	Road is pucca.
12.	Common Facilities			
	Toilets	✓	-	Temporary.
	Drinking Water	✓	-	Available.
	First Aid Box	✓	-	Available.
	Safety Equipments	✓	-	-
13.	Record Maintenance	✓	-	Register Available.

Note:- Above Inspection carried out on 13/05/2022.


 13/05/22
 District Mines officer
 Prayagraj.



 13/5/22
 ADM(E)


Checklist for Washing Plants Area - Lakhamati.

Visit of Distt/Tehsil Level Task Force IN/N - chawla Silica Sand Trading Co.,
(Crushing & Washing)

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓	-	-
2.	Line/Unlined Water Storage Tanks	✓	-	-
3.	Rain water Harvesting Pit (Kutchra-Groundwater recharge)	✓	-	-
4.	Dust Management/Water Sprinkler System	✓	-	-
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower	✓ ✓ ✓ ✓ ✓	- - - - -	Register available.
6.	Boundary Wall	✓	-	-
7.	Green Belt or Boundary	✓	-	-
8.	Display Board	✓	-	Mentioned on Board.
9.	Periodic Health Check-up	✓	-	-
10.	UPPCB Consent	✓	-	Done by CHC.
11.	UP State Ground water Board/CGWA (If more than 10 KLD)	✓	-	-
12.	Record Maintenance	✓	-	-
13.	Any other	-	-	N/A.

Note:- Above Inspection carried out on 13/05/22.


13/05/22
District Mines officer
Prayagraj.



13/5/22
ADM (E)

Checklist for Washing Plants Area - Shivorepur.

Visit of Distt/Tehsil Level Task Force W/N - Chawla Silica Sand Trading

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓	-	-
2.	Line/Unlined Water Storage Tanks	✓	-	-
3.	Rain water Harvesting Pit (Kutchha-Groundwater recharge)	✓	-	As per designed.
4.	Dust Management/Water Sprinkler System	✓	-	Improvement required
5.	Log Book maintenance			
	Energy	✓	-	-
	Water	✓	-	-
	Raw Material	✓	-	-
	Finished Products	✓	-	-
	Manpower	✓	-	-
6.	Boundary Wall	✓	-	In front site not complete
7.	Green Belt or Boundary	✓	-	Some improvement required
8.	Display Board	✓	-	Details Mentioned.
9.	Periodic Health Check-up	✓	-	-
10.	UPPCB Consent	✓	-	-
11.	UP State Ground water Board/CGWA (If more than 10 KLD)	✓	-	-
12.	Record Maintenance	✓	-	All registers available
13.	Any other	-	-	N/A

Note :- Above site inspection carried out on 13/05/22



 13/05/22
 District Mines officer
 Prayagraj.


 13/5/22
 ADM(E)

Checklist for Washing Plants Area - Bihariya.

Visit of Distt/Tehsil Level Task Force W/N - Modi Mineral Udyog.

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓	—	—
2.	Line/Unlined Water Storage Tanks	✓	—	—
3.	Rain water Harvesting Pit (Kutchra-Groundwater recharge)	✓	—	Kutchra
4.	Dust Management/Water Sprinkler System	✓	—	—
5.	Log Book maintenance			
	Energy	✓	—	—
	Water	✓	—	—
	Raw Material	✓	—	—
	Finished Products	✓	—	—
	Manpower	✓	—	—
6.	Boundary Wall	✓		
7.	Green Belt or Boundary	✓		
8.	Display Board	✓		
9.	Periodic Health Check-up	—	—	Done by CHC.
10.	UPPCB Consent	✓	—	—
11.	UP State Ground water Board/CGWA (If more than 10 KLD)	✓	—	—
12.	Record Maintenance	✓	—	—
13.	Any other	—	—	—


13/05/22
DHO - pragraj.


13/5/22
ADM (E)

Checklist for Washing Plants Area - Kachari

Visit of Distt/Tehsil Level Task Force W/A - Harsh Minerals.

Sl. No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓	—	—
2.	Line/Unlined Water Storage Tanks	✓	—	—
3.	Rain water Harvesting Pit (Kutchra-Groundwater recharge)	✓	—	—
4.	Dust Management/Water Sprinkler System	—	—	No work is going on
5.	Log Book maintenance	✓	—	—
	Energy	✓	—	—
	Water	✓	—	—
	Raw Material	✓	—	—
	Finished Products	✓	—	—
	Manpower	✓	—	—
6.	Boundary Wall	✓	—	Front area is not Green
7.	Green Belt or Boundary	✓	—	—
8.	Display Board	✓	—	—
9.	Periodic Health Check-up	—	—	Done by CHS.
10.	UPPCB Consent	✓	—	—
11.	UP State Ground water Board/CGWA (If more than 10 KLD)	✓	—	—
12.	Record Maintenance	✓	—	—
13.	Any other	—	—	—

13/05/22
DHO - Prayagraj

13/5/22
ADM (E)

Checklist for Washing Plants Area - pratappur.

Visit of Distt/Tehsil Level Task Force W/N - Prayas Quality Sand.

Sl. No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓	-	-
2.	Line/Unlined Water Storage Tanks	✓	-	unlined.
3.	Rain water Harvesting Pit (Kutchra-Groundwater recharge)	✓	-	Kutchra.
4.	Dust Management/Water Sprinkler System	✓	-	-
5.	Log Book maintenance			
	Energy	✓	-	-
	Water	✓	-	-
	Raw Material	✓	-	-
	Finished Products	✓	-	-
	Manpower	✓	-	-
6.	Boundary Wall	✓	-	-
7.	Green Belt or Boundary	✓	-	-
8.	Display Board	✓	-	-
9.	Periodic Health Check-up	✓	-	-
10.	UPPCB Consent	✓	-	-
11.	UP State Ground water Board/CGWA (If more than 10 KLD)	✓	-	-
12.	Record Maintenance	✓	-	-
13.	Any other	-	-	-

13/05/22
A no. p. 7.

13/5/22
ADM (E)

Checklist for Washing Plants Area - pratappur

Visit of Distt/Tehsil Level Task Force W/H - Jai Shree Grading Comps

Sl. No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	-	-	N/A - No Spring.
2.	Line/Unlined Water Storage Tanks	✓	-	-
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)	✓	-	-
4.	Dust Management/Water Sprinkler System	✓	-	-
5.	Log Book maintenance			
	Energy	✓	-	
	Water	✓	-	
	Raw Material	✓	-	
	Finished Products	✓	-	
	Manpower	✓	-	
6.	Boundary Wall	✓	-	Sheet Boundary.
7.	Green Belt or Boundary	✓	-	-
8.	Display Board	✓	-	-
9.	Periodic Health Check-up	✓	-	Done ^{by} EHC
10.	UPPCB Consent	✓		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)	-	-	Not required
12.	Record Maintenance	✓	-	-
13.	Any other	-	-	-

13/05/22
DMO - P.


13/5/22
ADM (E)


Checklist for Washing Plants Area - Garha Katra.

Visit of Distt/Tehsil Level Task Force W/N - Laxmi Minerals Manufactures
Graders.

Sl. No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓	—	—
2.	Line/Unlined Water Storage Tanks	—	—	Constructing is going on.
3.	Rain water Harvesting Pit (Kutchha-Groundwater recharge)	—	—	—
4.	Dust Management/Water Sprinkler System	—	—	—
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower	— — — — —	— — — — —	No work started
6.	Boundary Wall	✓	—	partial open in back side.
7.	Green Belt or Boundary	✓	—	Improvement required.
8.	Display Board	✓	—	—
9.	Periodic Health Check-up	—	—	Done by CHC.
10.	UPPCB Consent	✓	—	—
11.	UP State Ground water Board/CGWA (If more than 10 KLD)	✓	—	—
12.	Record Maintenance	—	—	—
13.	Any other	—	—	—

Note :- Inspection Carried out on 13/05/22.


13/05/22
District Mines officer
Prayagraj


13/5/22
A.M.C.E.

Checklist for Washing Plants Area - Gorwa, Shivrajpur.

Visit of Distt/Tehsil Level Task Force W/N - Quality Minerals Development Corporation.

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓	-	-
2.	Line/Unlined Water Storage Tanks	✓	-	-
3.	Rain water Harvesting Pit (Kutchra-Groundwater recharge)	✓	-	Kutchra Temporary.
4.	Dust Management/Water Sprinkler System	✓	-	Temporary Arrangement.
5.	Log Book maintenance	-	-	Electronically,
	Energy	✓	-	Register.
	Water	✓	-	- do.
	Raw Material	✓	-	- do -
	Finished Products	✓	-	- do -
Manpower	✓	-	- do -	
6.	Boundary Wall	✓	-	Half Pucca Boundary Wall is covered with Green cloth. Improvement required.
7.	Green Belt or Boundary	✓	-	Improvement required.
8.	Display Board	✓	-	Not proper (Small in size)
9.	Periodic Health Check-up	-	-	Mentioned by employee but evidence not available.
10.	UPPCB Consent	✓	-	-
11.	UP State Ground water Board/CGWA (if more than 10 KLD)	-	-	Applied.
12.	Record Maintenance	✓	-	Registers available.
13.	Any other	-	-	Improvement needed in approach Road.

Note:- Above Inspection Carried out on 13/05/22.


13/05/22
District Mines officer
Prayagraj.


13/5/22
ADM (E)

Checklist for Washing Plants Area - Lakhnauli

Visit of Distt/Tehsil Level Task Force WIN - SBS Enterprises.

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation			
2.	Line/Unlined Water Storage Tanks			
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)			
4.	Dust Management/Water Sprinkler System			Construction
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower			New plant going on. No person present at work
6.	Boundary Wall			
7.	Green Belt or Boundary			
8.	Display Board			No site
9.	Periodic Health Check-up			
10.	UPPCB Consent			
11.	UP State Ground water Board/CGWA (If more than 10 KLD)			
12.	Record Maintenance			
13.	Any other			

Note: - Inspection carried out on 13/05/22.

[Signature]
13/05/22
District Mines Officer,
Prayagraj.

[Signature]
13/5/22
ADM (E)


Checklist for Washing Plants Area - Kachari

Visit of Distt/Tehsil Level Task Force Washing plant Name - OM Laxmi Mineral

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation			
2.	Line/Unlined Water Storage Tanks			
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)			
4.	Dust Management/Water Sprinkler System			
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower			
6.	Boundary Wall			
7.	Green Belt or Boundary			
8.	Display Board			
9.	Periodic Health Check-up			
10.	UPPCB Consent			
11.	UP State Ground water Board/CGWA (If more than 10 KLD)			
12.	Record Maintenance			
13.	Any other			

During visit at site
 Gate was closed. No
 work carried out on
 site.

Note:- Above Inspection Carried out on 13/05/22.


 13/05/22
 District Mines officer
 Prayagraj.


 13/5/22
 ADM (E)

Checklist for Washing Plants Area - Bihariya.

Visit of Distt/Tehsil Level Task Force W/H - MA Jagdamba & Co.

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation			
2.	Line/Unlined Water Storage Tanks			
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)			
4.	Dust Management/Water Sprinkler System			
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower			
6.	Boundary Wall			
7.	Green Belt or Boundary			
8.	Display Board			
9.	Periodic Health Check-up			
10.	UPPCB Consent			
11.	UP State Ground water Board/CGWA (If more than 10 KLD)			
12.	Record Maintenance			
13.	Any other			

During Inspection -
No work is going on.
Plant was closed.

Note: - Above inspection carried out on 13/05/22.

[Signature]
13/05/22
District Mines Officer
Prayagraj.

[Signature]
13/5/22
ADM(E)


Checklist for Washing Plants Area - Kachori


Visit of Distt/Tehsil Level Task Force W/H - OM LAXMI INDUSTRIES.

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation			
2.	Line/Unlined Water Storage Tanks			
3.	Rain water Harvesting Pit (Kutchra-Groundwater recharge)			
4.	Dust Management/Water Sprinkler System			
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower			Site, main gate No work carried
6.	Boundary Wall			
7.	Green Belt or Boundary			
8.	Display Board			
9.	Periodic Health Check-up			
10.	UPPCB Consent			
11.	UP State Ground water Board/CGWA (If more than 10 KLD)			
12.	Record Maintenance			
13.	Any other			

During visit of
 was closed to
 site, main gate
 No work carried

Note:- Above inspection carried out on 13/05/22.


 13/05/22
 District Mines officer
 Prayagraj


 13/5/22
 ADM(E)

कार्यालय प्रभागीय निदेशक, सामाजिक वानिकी वन प्रभाग, प्रयागराज
पत्रांक 3968 / 15-1 दिनांक, प्रयागराज, 13, मई 2022
सेवा में,

आयुक्त
प्रयागराज मण्डल
प्रयागराज।

विषय- खनन पट्टा स्थल एवं वाशिंग प्लांट का संयुक्त निरीक्षण आख्या।
संदर्भ:- आपका कार्यालय आदेश पत्रांक 2116/पी0ए0 दिनांक 12.05.2022।
महोदय,

उपरोक्त संदर्भित पत्र के अनुपालन में दिनांक 13.05.2022 को संलग्न खनन पट्टो एवं वाशिंग प्लांटो की सूची के अनुसार स्थलों का संयुक्त निरीक्षण चेक लिस्ट में अंकित बिन्दुओं के अनुसार किया गया है। स्थलवार रिपोर्ट आज निरीक्षण दौरान पायी गयी स्थिति के अनुसार है। उक्त स्थलों की संयुक्त सुस्पष्ट आख्या निर्धारित प्रपत्र में प्रेषित है।
संलग्नक-उपरोक्तानुसार।

(वांछित 11 स्थलों की निरीक्षण आख्या मूल में)

भवदीय

(रमेश चन्द्र)

वन संरक्षक/प्रभारी प्रभागीय निदेशक,
सामाजिक वानिकी प्रभाग
प्रयागराज।

NGT.

A.C. (A)

Sw.

14/5/22

-14.0

(संजय गोयल)

आयुक्त, प्रयागराज


Checklist for Washing Plants


Visit of Distt/Tehsil Level Task Force

Gurudoyal Singh & Co. (Silica)

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	yes		
2.	Line/Unlined Water Storage Tanks	yes		
3.	Rain water Harvesting Pit (Kutchra-Groundwater recharge)		NO	
4.	Dust Management/Water Sprinkler System	yes		
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower	+	NO	
6.	Boundary Wall		NO	सामने बनी है।
7.	Green Belt or Boundary		NO	
8.	Display Board	yes		
9.	Periodic Health Check-up		NO	डॉक्टर जिम्मेदार
10.	UPPCB Consent		NO	अधिक मौजूद नहीं था।
11.	UP State Ground water Board/CGWA (If more than 10 KLD)		NO	
12.	Record Maintenance		NO	
13.	Any other			


कोहील वन अधिकारी
रेंज-प्रयागराज


15/05/22
खान अधिकारी
प्रयागराज


उप प्रदेशीय वन विकास
प्रियंका सिंह
सा० वा० वन प्रभाग-प्रयागराज


प्रभागीय निदेशक
सामाजिक वानिकी वन प्रभाग
प्रयागराज

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Jai Shree Trading Company

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	yes		
2.	Line/Unlined Water Storage Tanks	yes		
3.	Rain water Harvesting Pit (Kutchra-Groundwater recharge)	yes		
4.	Dust Management/Water Sprinkler System		NO	
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower		NO	
6.	Boundary Wall	yes		आधे भाग भेदे
7.	Green Belt or Boundary	yes		
8.	Display Board		NO	
9.	Periodic Health Check-up		NO	
10.	UPPCB Consent	yes		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)		NO	
12.	Record Maintenance		NO	
13.	Any other			

[Signature]
वन अधिकारी
प्रयागराज

[Signature]
13/05/22
खान अधिकारी
प्रयागराज

[Signature]
उप प्रभार वन अधिकारी
प्रयागराज
सां. वन प्रभाग-प्रयागराज

[Signature]
प्रभागीय निदेशक
सामाजिक वानिकी वन प्रभाग
प्रयागराज

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Shri Girdharilal Chauhan & Sons

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	yes		
2.	Line/Unlined Water Storage Tanks	yes		
3.	Rain water Harvesting Pit (Kutchha-Groundwater recharge)	—	NO	
4.	Dust Management/Water Sprinkler System	yes		
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower		NO	
6.	Boundary Wall	yes		अधे मज में है।
7.	Green Belt or Boundary	yes		
8.	Display Board		NO	
9.	Periodic Health Check-up		NO	
10.	UPPCB Consent	yes		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)	yes		
12.	Record Maintenance	yes		1-03-2022 से उपलब्ध
13.	Any other			


क्षेत्रीय वन अधिकारी
रेंज-प्रयागराज

13/05/22
वन अधिकारी
प्रयागराज


उप प्रभोगीय वनाधिकारी
प्रयागराज
सा० वा० वन प्रभाग-प्रयागराज

प्रभागीय निदेशक
सामाजिक वानिकी वन प्रभाग
प्रयागराज


Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force


Shahdol (Silica washing plant)


Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation		NO	
2.	Line/Unlined Water Storage Tanks		NO	
3.	Rain water Harvesting Pit (Kutchra-Groundwater recharge)		NO	
4.	Dust Management/Water Sprinkler System		NO	
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower		NO	
6.	Boundary Wall		NO	
7.	Green Belt or Boundary		NO	
8.	Display Board		NO	
9.	Periodic Health Check-up		NO	
10.	UPPCB Consent		NO	
11.	UP State Ground water Board/CGWA (If more than 10 KLD)		NO	
12.	Record Maintenance		NO	
13.	Any other			

विशेषा से समय प्लॉट चेक पाया गया स्थानीय अधिकारियों से पूछने पर बताया गया कि कंटेनर ठीक मशीन से चल रहे।


 क्षेत्रीय वन अधिकारी
 नंदरैंज-प्रयागराज

8/11/22
 13/05/22
 क्षेत्र अधिकारी
 प्रयागराज


 उप-प्रदेशीय वन अधिकारी
 प्रयागराज
 सां. बा० वन प्रभाग-प्रयागराज


 प्रभागीय निदेशक
 सामाजिक वानिकी वन प्रभाग
 प्रयागराज

Checklist for Washing Plants


Visit of Distt/Tehsil Level Task Force


Quality mineral development
corporation

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	yes		
2.	Line/Unlined Water Storage Tanks	yes		
3.	Rain water Harvesting Pit (Kutchha-Groundwater recharge)		NO	
4.	Dust Management/Water Sprinkler System	yes		
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower	yes		
6.	Boundary Wall		NO	
7.	Green Belt or Boundary		NO	
8.	Display Board		NO	
9.	Periodic Health Check-up		NO	
10.	UPPCB Consent	yes		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)			10 KLD के कम
12.	Record Maintenance	yes		
13.	Any other			


13/5/22
वन अधिकारी
प्रभाग-प्रयागराज


13/5/22
खान अधिकारी
प्रभाग-प्रयागराज


उप प्रभागीय कर्ताधिकारी
13/5/22
सा० बा० वन प्रभाग-प्रयागराज


प्रभागीय निदेशक
सामाजिक वानिकी वन प्रभाग
प्रयागराज

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force


Asha Devi (Assistant Secretary to S.O.)

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation		NO	
2.	Line/Unlined Water Storage Tanks		NO	
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)		NO	
4.	Dust Management/Water Sprinkler System		NO	
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower		NO	
6.	Boundary Wall		NO	
7.	Green Belt or Boundary		NO	
8.	Display Board		NO	
9.	Periodic Health Check-up		NO	
10.	UPPCB Consent	-	-	लॉट बंद का मोड पर केरि अधिक उपस्थित नहीं किया।
11.	UP State Ground water Board/CGWA (If more than 10 KLD)	-	-	
12.	Record Maintenance	-	-	
13.	Any other			


 प्रमुख वन अधिकारी
 वन विभाग-प्रयागराज

13/05/22
 वन अधिकारी
 प्रयागराज


 उप प्रभारी वन अधिकारी
 प्रयागराज
 रा. वन विभाग-प्रयागराज


 प्रयागीय निदेशक
 सामाजिक अधिकार वन प्रभाग
 प्रयागराज

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force


Sirena Khanij Vidyog

Sl No.	Check Points	Avallablilty		Remarks
		Yes	No	
1.	Flow meter Installation	yes		
2.	Line/Unlined Water Storage Tanks	yes		
3.	Rain water Harvesting Pit (Kutchha-Groundwater recharge)	yes		
4.	Dust Management/Water Sprinkler System		NO	
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower		NO	
6.	Boundary Wall	yes		
7.	Green Belt or Boundary		NO	
8.	Display Board		NO	
9.	Periodic Health Check-up		NO	
10.	UPPCB Consent	yes		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)	yes		
12.	Record Maintenance		NO	
13.	Any other			


वन अधिकारी
प्रयागराज

13/05/22
खान अधिकारी
प्रयागराज


उप प्रभाग वन अधिकारी
प्रयागराज
सा. वा. वन प्रभाग-प्रयागराज


प्रभागीय निदेशक
सामाजिक वनिकी वन प्रभाग
प्रयागराज

Checklist for Washing Plants


Visit of Distt/Tehsil Level Task Force


Silica Khanis Udyog

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation		NO	
2.	Line/Unlined Water Storage Tanks	yes		
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)		NO	
4.	Dust Management/Water Sprinkler System		NO	
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower		NO	
6.	Boundary Wall		NO	
7.	Green Belt or Boundary		NO	
8.	Display Board		NO	
9.	Periodic Health Check-up		NO	
10.	UPPCB Consent	yes		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)	-	-	10KLD से कम
12.	Record Maintenance		NO	
13.	Any other			


13/5/22
वन अधिकारी
राज-प्रयागराज


13/05/22
खान अधिकारी
प्रयागराज


उप प्रभागीय वन अधिकारी
प्रयागराज
सा. वा. वन प्रभाग-प्रयागराज



प्रभागीय निदेशक
सामाजिक वन प्रभाग
प्रयागराज

Checklist for Washing Plants


Visit of Distt/Tehsil Level Task Force


Naveen Silita Sand.

Sl No.	Check Points	Avallability		Remarks
		Yes	No	
1.	Flow meter Installation	yes		
2.	Line/Unlined Water Storage Tanks		NO	
3.	Rain water Harvesting Pit (Kutch-Groundwater recharge)	yes		
4.	Dust Management/Water Sprinkler System	yes	NO	
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower		NO	
6.	Boundary Wall	yes		
7.	Green Belt or Boundary	yes		
8.	Display Board		NO	
9.	Periodic Health Check-up		NO	
10.	UPPCB Consent	yes		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)		NO	10 KLD से कम
12.	Record Maintenance		NO	
13.	Any other			


 नवेन सिल्टा
 प्रमुख अधिकारी
 प्रयोगशाला - प्रयागराज

दिनांक
 13/05/22
 स्थान अधिकारी
 प्रयागराज


 उप निदेशक
 प्रयोगशाला
 स.० ज.० वन प्रभाग-प्रयागराज


 प्रभागीय निदेशक
 सामाजिक कार्यो वन प्रभाग
 प्रयागराज


Checklist for Mining Area

Visit of Distt/Tehsil Level Task Force *Ms Chavola Silica Sand Grinding Company (Lakshmi)*

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Presence of pillars	yes		
2.	Geo-Co-ordinates on pillars	yes		
3.	Approach Road Status	yes		
4.	Fugitive Emission		NO	H/A
5.	Storage of overburden/Top Soil Management Status	yes		
6.	Display Board	yes		
7.	CCTV Camera	yes		
8.	Green Belt/Plantation	yes		
9.	Weigh Bridge	yes		
10.	Benching In Mining Area Depth Up to 3 metres of Pit	yes		
11.	Transportation -Dust Suppression Measures (Water Sprinkling)	yes		
12.	Common Facilities Toilets Drinking Water First Aid Box Safety Equipments	yes		
13.	Record Maintenance	yes		


 क्षेत्रीय वन अधिकारी
 शंकरगढ़ रेंज-प्रयागराज


 13/05/22
 खान अधिकारी
 प्रयागराज


 उपनिरीक्षक वन अधिकारी
 प्रयागराज
 सा० वा० वन प्रभाग-प्रयागराज



 प्रभागीय निदेशक
 सामाजिक वानिकी वन प्रभाग
 प्रयागराज


Checklist for Mining Area


Visit of Distt/Tehsil Level Task Force


Spot: Normal Rain (Sonpuri, Bikanpur, Chatahara, Gurehda)

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Presence of pillars	yes	-	
2.	Geo-Co-ordinates on pillars	yes	-	
3.	Approach Road Status	yes	-	
4.	Fugitive Emission	-	-	N/A
5.	Storage of overburden/Top Soil Management Status		NO	
6.	Display Board	yes	-	
7.	CCTV Camera	yes	-	
8.	Green Belt/Plantation		NO	
9.	Welgh Bridge	yes	-	
10.	Benching In Mining Area Depth Up to 3 metres of Pit	yes	-	
11.	Transportation -Dust Suppression Measures (Water Sprinkling)	yes	-	
12.	Common Facilities Toilets Drinking Water First Aid Box Safety Equipments	yes	-	
13.	Record Maintenance	yes	-	


 क्षेत्रीय वन अधिकारी
 शंकरप्रसाद रेंज-प्रयागराज


 18/05/22
 श्वान अधिकारी
 प्रकाश राज


 20/05/2022
 उप प्रबंधक वन अधिकारी
 प्रयागराज
 सा० वा० वन प्रभाग-प्रयागराज


 प्रभागीय निदेशक
 सामाजिक वानिकी वन प्रभाग
 प्रयागराज



क्षेत्रीय कार्यालय, उत्तर प्रदेश प्रदूषण नियंत्रण बोर्ड

REGIONAL OFFICE, U. P. POLLUTION CONTROL BOARD

आवास विकास परिषद कालोनी, सेक्टर-10, योजना संख्या-3, झुंसी, प्रयागराज - 221506
 Avas Vikas Parishad Colony, Sector-10, Scheme No. 3, Jhansi, Prayagraj,
 Email-roprayagraj@uppcb.in

संदर्भ सं०... (1.2.2.1.3.3) / (1.2.2.1.3.3) / 2021-2022

दिनांक... 13/05/2022

सेवा में

अपर आयुक्त महोदय (प्रशासन)
 प्रयागराज मण्डल,
 प्रयागराज।

विषय: मा0 राष्ट्रीय हरित अधिकरण में योजित ओ0ए0 संख्या 203/2021 देवीदास खत्री बनाम यूनियन ऑफ इण्डिया एवं अन्य में पारित आदेश के अनुपालन के सम्बन्ध में।

महोदय,

कृपया उपरोक्त विषयक कार्यालय आदेश संख्या 2118/पी0ए0 दिनांक 12.05.2022 कार्यालय मण्डलायुक्त महोदय, प्रयागराज का सन्दर्भ ग्रहण करने का कष्ट करें। तत्कम में सम्बन्धित इकाईयों का निरीक्षण उपजिलाधिकारी महोदय, बारा, प्रयागराज के साथ दिनांक 13.05.2022 को किया गया। निर्धारित प्रारूप में चेक लिस्ट भरकर अवलोकनार्थ एवं आवश्यक कार्यवाही हेतु सादर प्रेषित है।

संलग्नक-यथोपरि।

भवदीय,

(आर0 के0 सिंह)
 क्षेत्रीय अधिकारी

प्रतिलिपि-निम्नलिखित को सूचनार्थ एवं आवश्यक कार्यवाही हेतु सादर प्रेषित।

1. आयुक्त महोदय, प्रयागराज मण्डल, प्रयागराज।
2. उपजिलाधिकारी महोदय, बारा, प्रयागराज।

AC (A)

13/5/22
 क्षेत्रीय अधिकारी

for

आयुक्त

(संजय गौयल)

आयुक्त, प्रयागराज

Chauhan Silica Sand Trading Co., New Jammu.

Checklist for Mining Area

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Presence of pillars	✓		
2.	Geo-Co-ordinates on pillars	✓		
3.	Approach Road Status	✓		
4.	Fugitive Emission		✓	
5.	Storage of overburden/Top Soil Management Status		✓	No defined/demarcated place for top soil storage.
6.	Display Board	✓		
7.	CCTV Camera	✓		
8.	Green Belt/Plantation	✓		Approx 45 plants
9.	Weigh Bridge	✓		
10.	Benching In Mining Area Depth Up to 3 metres of Pit		✓	N.A.
11.	Transportation -Dust Suppression Measures (Water Sprinkling)		✓	
12.	Common Facilities Toilets Drinking Water First Aid Box Safety Equipments		✓	
13.	Record Maintenance	✓		Form A, B, K,

Attendance Register available but not up to date. Stock Dispatch manually maintained. Not computerized.

13/5/21
R.O.
U.P.D.C.B.

13/5/22
SDM(B)

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓		Functionality could not be checked because of no electricity
2.	Line/Unlined Water Storage Tanks	✓		
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)	✓		
4.	Dust Management/Water Sprinkler System		✓	
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower	✓	✓ ✓ ✓	No proper maintenance of records
6.	Boundary Wall	✓		
7.	Green Belt or Boundary	✓		
8.	Display Board		✓	Approx. 35 plants trees
9.	Periodic Health Check-up		✓	
10.	UPPCB Consent	✓		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)		✓	Expired on 30/09/21 More than 10 KLD extraction since 18/04/22 according to manual records.
12.	Record Maintenance		✓	
13.	Any other			

13/5/22
R.O.
UPPCB.

13/05/22
SDM(13)

Shri Bhagwan Das Industries, Shirnoli, Baram

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓		
2.	Line/Unlined Water Storage Tanks	✓		
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)	✓		
4.	Dust Management/Water Sprinkler System		✓	
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower		✓	No proper Maintenance of records
6.	Boundary Wall	✓		Incomplete
7.	Green Belt or Boundary	✓		Approx 60 Trees
8.	Display Board		✓	
9.	Periodic Health Check-up			
10.	UPPCB Consent	✓		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)		✓	Less than 10 KLD required for washing
12.	Record Maintenance		✓	
13.	Any other		—	

13/05/22
R.O.
UPPCB.

13/05/22
SDM(B)

Allahabad Sand, Bargaha, Prayagraj

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓		No Log Book
2.	Line/Unlined Water Storage Tanks	✓		
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)	✓		
4.	Dust Management/Water Sprinkler System		✓	
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower		✓	No record available No storage permission
6.	Boundary Wall		✓	
7.	Green Belt or Boundary	✓		Approx. 100 Trees
8.	Display Board		✓	
9.	Periodic Health Check-up	✓		
10.	UPPCB Consent	✓		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)		✓	
12.	Record Maintenance		✓	
13.	Any other		-	

13/1/22
R.O.
UPPCB

13/1/22
SDM(CB)

Ashok Kumar Bajpayo. Bangalore

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Avallablilty		Remarks
		Yes	No	
1.	Flow meter Installation	✓	-	Natural Source
2.	Line/Unlined Water Storage Tanks	✓	-	
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)	✓		
4.	Dust Management/Water Sprinkler System		✓	
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower		No paper Maintenance of Log Books	
6.	Boundary Wall	✓		
7.	Green Belt or Boundary	✓		Approx 500 trees in entire mining area
8.	Display Board	✓		Inside mining area
9.	Periodic Health Check-up	✓		As confirmed by labor on site
10.	UPPCB Consent	✓		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)		✓	Natural Source.
12.	Record Maintenance		✓	
13.	Any other			

13/5/22
R.O.
UPPCB.

13/05/22
SDM(B)

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓		
2.	Line/Unlined Water Storage Tanks	✓		
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)		✓	
4.	Dust Management/Water Sprinkler System		✓	
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower			No record available on plant site.
6.	Boundary Wall	✗	✓	incomplete
7.	Green Belt or Boundary	✓		Approx 40 Trees
8.	Display Board	✓		
9.	Periodic Health Check-up		✓	
10.	UPPCB Consent	✓		
11.	UP State Ground water Board/CGWA (if more than 10 KLD)		✓	
12.	Record Maintenance		✓	
13.	Any other		-	

The plant is not found operational, But water consumption found more than 5KLD to less than 10KLD.

13/5/22
R.O
UPPCB.

13/05/22
SDM(B)

K.R. Minamti, Bihariya, Shaharganj,

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation			
2.	Line/Unlined Water Storage Tanks	✓		
3.	Rain water Harvesting Plt. (Kutcha-Groundwater recharge)	✓		
4.	Dust Management/Water Sprinkler System		✓	
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower		✓	No proper maintinauce of logbook.
6.	Boundary Wall		✓	incomplete
7.	Green Belt or Boundary	✓		Total more than 70 Trees.
8.	Display Board		✓	
9.	Periodic Health Check-up		✓	
10.	UPPCB Consent	✓		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)		✓	
12.	Record Maintenance		✓	
13.	Any other			

New unit. operation not yet started.

12/1/22
R.O.
UPPCB

12/1/22
SDM(B)

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓		
2.	Line/Unlined Water Storage Tanks	✓		
3.	Rain water Harvesting Pit (Kutch-Groundwater recharge)	✓		
4.	Dust Management/Water Sprinkler System		✓	
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower			No log book maintained.
6.	Boundary Wall		✓	incomplete.
7.	Green Belt or Boundary	✓		Approx 100 trees
8.	Display Board		✓	
9.	Periodic Health Check-up		✓	
10.	UPPCB Consent	✓		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)		-	Not required Natural Source (pit)
12.	Record Maintenance		✓	
13.	Any other		-	

13/5/22
R.O.
UPPCB,

13/05/22
SDM(B)

Gupta Enterprises, Ghond, Garha Katra, Prayagraj

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓	—	
2.	Line/Unlined Water Storage Tanks	✓		
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)	✓		
4.	Dust Management/Water Sprinkler System	✓		
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower	✓		
6.	Boundary Wall	✓		
7.	Green Belt or Boundary	✓		More than 100 trees
8.	Display Board	✓		
9.	Periodic Health Check-up	✓		As per labor on site
10.	UPPCB Consent	✓		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)		Applied	Uses Less than 10 KLD.
12.	Record Maintenance	✓		
13.	Any other			

13/5/22
R.O.
UPPCB

13/05/22
SDM (B)

Badri Prasad Arora Nath Shivrajpur

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓		
2.	Line/Unlined Water Storage Tanks	✓		
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)	✓		
4.	Dust Management/Water Sprinkler System		✓	
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower	✓ ✓ ✓ ✓		
6.	Boundary Wall	✓		Incomplete
7.	Green Belt or Boundary	✓		Total approx. 50 hrs
8.	Display Board		✓	
9.	Periodic Health Check-up	✓		As confirmed by labor
10.	UPPCB Consent	✓		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)			Applied less than 10 KLD.
12.	Record Maintenance	✓		
13.	Any other			

13/1/22
R.D.
UPPCB

13/01/22
SDM

Glass and foundry Sand Bargadi, Prayagraj

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation			
2.	Line/Unlined Water Storage Tanks			
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)			
4.	Dust Management/Water Sprinkler System			
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower			
6.	Boundary Wall			
7.	Green Belt or Boundary			
8.	Display Board			
9.	Periodic Health Check-up			
10.	UPPCB Consent			
11.	UP State Ground water Board/CGWA (If more than 10 KLD)			
12.	Record Maintenance			
13.	Any other			

*Plant closed due to its own reasons
Inspection could not be conducted.*

*19/5/22
R.O. UPPCO*

*13/05/22
SDM(B)*



दूरभाष: / Ph. : 0532-2569727

क्षेत्रीय कार्यालय, उत्तर प्रदेश प्रदूषण नियंत्रण बोर्ड REGIONAL OFFICE, U. P. POLLUTION CONTROL BOARD

आवास विकास परिषद कालोनी, सेक्टर-10, योजना संख्या-3, झूंसी, प्रयागराज - 221506
Avas Vikas Parishad Colony, Sector-10, Scheme No. 3, Jhunsi, Prayagraj,
Email-roprayagraj@uppcb.in

संदर्भ सं० (100132/एएच 229) 2021-2022

दिनांक 13/05/2022

सेवा में

अपर आयुक्त महोदय (प्रशासन)
प्रयागराज मण्डल,
प्रयागराज।

विषय: मा0 राष्ट्रीय हरित अधिकरण में योजित ओ0ए0 संख्या 203/2021 देवीदास खत्री बनाम यूनियन ऑफ इण्डिया एवं अन्य में पारित आदेश के अनुपालन के सम्बन्ध में।

महोदय,

कृपया उपरोक्त विषयक कार्यालय आदेश संख्या 2118/पी0ए0 दिनांक 12.05.2022 कार्यालय मण्डलायुक्त महोदय, प्रयागराज का सन्दर्भ ग्रहण करने का कष्ट करें। तत्कम में सम्बन्धित इकाईयों का निरीक्षण उपजिलाधिकारी महोदय, बारा, प्रयागराज के साथ दिनांक 13.05.2022 को किया गया। निर्धारित प्रारूप में चेक लिस्ट भरकर अवलोकनार्थ एवं आवश्यक कार्यवाही हेतु सादर प्रेषित है।
संलग्नक-यथोपरि।

भवदीय,

(आर0 के0 सिंह)
क्षेत्रीय अधिकारी

प्रतिलिपि-निम्नलिखित को सूचनार्थ एवं आवश्यक कार्यवाही हेतु सादर प्रेषित।

1. आयुक्त महोदय, प्रयागराज मण्डल, प्रयागराज।
2. उपजिलाधिकारी महोदय, बारा, प्रयागराज।

13/5/22
क्षेत्रीय अधिकारी

Chawla Silica Sand Trading Co., New Janwa.

Checklist for Mining Area

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Presence of pillars	✓		
2.	Geo-Co-ordinates on pillars	✓		
3.	Approach Road Status	✓		
4.	Fugitive Emission		✓	
5.	Storage of overburden/Top Soil Management Status		✓	No defined/demonstrated place for top soil storage
6.	Display Board	✓		
7.	CCTV Camera	✓		
8.	Green Belt/Plantation	✓		Approx. 95 plants
9.	Weigh Bridge	✓		
10.	Benching In Mining Area Depth Up to 3 metres of Pit		✓	N.A.
11.	Transportation - Dust Suppression Measures (Water Sprinkling)		✓	
12.	Common Facilities Toilets Drinking Water First Aid Box Safety Equipments		✓	
13.	Record Maintenance	✓		Form A, T, K,

Attendance Register available but not up to date. Stock/Dispatch manually maintained. Not computerized

13/5/21
R.O.
U.P.C.B.
13/6/22
SDM(B)

Anupam Enterprises, Gorha Katra.

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓		Functionality could not be checked because of no electricity
2.	Line/Unlined Water Storage Tanks	✓		
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)	✓		
4.	Dust Management/Water Sprinkler System		✓	
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower	✓	✓ ✓ ✓	No proper maintenance of records
6.	Boundary Wall	✓		
7.	Green Belt or Boundary	✓		Approx. 35 plants/frees
8.	Display Board		✓	
9.	Periodic Health Check-up			
10.	UPPCB Consent	✓		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)		✓	Expired on 30/09/21 More than 10 KLD extraction since 12/04/22 according to manual records.
12.	Record Maintenance		✓	
13.	Any other			

13/5/22
R.O.
UPPCB.

13/05/22
SDM(B)

Shri Bhagwan Das Industries, Shirojpur, Bana

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓		
2.	Line/Unlined Water Storage Tanks	✓		
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)	✓		
4.	Dust Management/Water Sprinkler System		✓	
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower		✓	No proper Maintenance of records
6.	Boundary Wall	✓		Incomplete
7.	Green Belt or Boundary	✓		Approx 60 Trees
8.	Display Board		✓	
9.	Periodic Health Check-up			
10.	UPPCB Consent	✓		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)		✓	Less than 10 KLD required for washing
12.	Record Maintenance		✓	
13.	Any other		—	

13/5/22
R.O.
UPPCB.

13/05/22
SDM(B)

Allahabad Sand, Bargaha, Prayagraj

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓		No Log Book
2.	Line/Unlined Water Storage Tanks	✓		
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)	✓		
4.	Dust Management/Water Sprinkler System		✓	
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower		✓	No record available No storage permission
6.	Boundary Wall		✓	
7.	Green Belt or Boundary	✓		Approx. 100 Trees
8.	Display Board		✓	
9.	Periodic Health Check-up	✓		
10.	UPPCB Consent	✓		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)		✓	
12.	Record Maintenance		✓	
13.	Any other		-	

19/5/22
R.O.
UPPCB

19/5/22
SDM(B)

Ashok Kumar Bajpayee, Bargarh

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓	-	Natural Source
2.	Line/Unlined Water Storage Tanks	✓	-	
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)	✓		
4.	Dust Management/Water Sprinkler System		✓	
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower		No proper Maintenance of Log Books	
6.	Boundary Wall	✓		
7.	Green Belt or Boundary	✓		Approx 500 trees in entire mining area
8.	Display Board	✓		Inside mining area
9.	Periodic Health Check-up	✓		As confirmed by labor on site
10.	UPPCB Consent	✓		
11.	UP State Ground water - Board/CGWA (If more than 10 KLD)		✓	Natural Source
12.	Record Maintenance		✓	
13.	Any other			

13/5/22
R.O.
UPPCB

13/05/22
SDM(B)

Narayan Enterprises (Baba Vigneshwar minerals) Bargachhi, Prayagraj

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓		
2.	Line/Unlined Water Storage Tanks	✓		
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)		✓	
4.	Dust Management/Water Sprinkler System		✓	
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower			No record available on plant site.
6.	Boundary Wall	✗	✓	incomplete
7.	Green Belt or Boundary	✓		Approx 40 Trees
8.	Display Board	✓		
9.	Periodic Health Check-up		✓	
10.	UPPCB Consent	✓		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)		✓	
12.	Record Maintenance		✓	
13.	Any other		-	

The plant is not found operational, But, water consumption found more than 5KLD to less than 10KLD.

13/1/22
R.O
UPPCB.

13/1/22
SDM(B)

K.R. Minerals, Bihariya, Shantanganj

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓		
2.	Line/Unlined Water Storage Tanks	✓		
3.	Rain water Harvesting Pit (Kutchha-Groundwater recharge)	✓		
4.	Dust Management/Water Sprinkler System		✓	
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower		✓	No proper maintinanece of logbook.
6.	Boundary Wall		✓	incomplete
7.	Green Belt or Boundary	✓		Total more than 70 Trees.
8.	Display Board		✓	
9.	Periodic Health Check-up		✓	
10.	UPPCB Consent	✓		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)		✓	
12.	Record Maintenance		✓	
13.	Any other			

New unit. operation not yet started.

12/5/22
R.O.
UPPCB

12/5/22
SDM(B)

Agrawal Mines and Minerals Ramna

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓		
2.	Line/Unlined Water Storage Tanks	✓		
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)	✓		
4.	Dust Management/Water Sprinkler System		✓	
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower			No log book maintained.
6.	Boundary Wall		✓	incomplete.
7.	Green Belt or Boundary	✓		Aprox 100 Trees
8.	Display Board		✓	
9.	Periodic Health Check-up		✓	
10.	UPPCB Consent	✓		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)		-	Not required Natural Source (Pit)
12.	Record Maintenance		✓	
13.	Any other		-	

13/5/22
R.O.
UPPCB,

13/05/22
SDM (B)

Gupta Enterprises, Ghond, Garha Katra, Prayagraj

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓	—	
2.	Line/Unlined Water Storage Tanks	✓		
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)	✓		
4.	Dust Management/Water Sprinkler System	✓		
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower	✓		
6.	Boundary Wall	✓		
7.	Green Belt or Boundary	✓		More than 500 trees
8.	Display Board	✓		
9.	Periodic Health Check-up	✓		As per labor on site
10.	UPPCB Consent	✓		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)		Applied	Uses Less than 10 KLD.
12.	Record Maintenance	✓		
13.	Any other			

13/5/22
R.O.
UPPCB

13/05/22
SDM (13)

Badri Prasad Anand Nath Shivrajpur

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation	✓		
2.	Line/Unlined Water Storage Tanks	✓		
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)	✓		
4.	Dust Management/Water Sprinkler System		✓	
5.	Log Book maintenance			
	Energy	✓		
	Water	✓		
	Raw Material			
	Finished Products	✓		
	Manpower	✓		
6.	Boundary Wall	✓		Incomplete
7.	Green Belt or Boundary	✓		Total Approx. 50 trees
8.	Display Board		✓	
9.	Periodic Health Check-up	✓		As confirmed by labor on site
10.	UPPCB Consent	✓		
11.	UP State Ground water Board/CGWA (If more than 10 KLD)			Applied less than 10 KLD
12.	Record Maintenance	✓		
13.	Any other			

13/5/22
R.O.
UPPCB

13/05/22
SDM (B)

Glass and foundry Sand Bargadhi, Prayagraj

Checklist for Washing Plants

Visit of Distt/Tehsil Level Task Force

Sl No.	Check Points	Availability		Remarks
		Yes	No	
1.	Flow meter Installation			
2.	Line/Unlined Water Storage Tanks			
3.	Rain water Harvesting Pit (Kutcha-Groundwater recharge)			
4.	Dust Management/Water Sprinkler System			
5.	Log Book maintenance Energy Water Raw Material Finished Products Manpower			
6.	Boundary Wall			
7.	Green Belt or Boundary			
8.	Display Board			
9.	Periodic Health Check-up			
10.	UPPCB Consent			
11.	UP State Ground water Board/CGWA (If more than 10 KLD)			
12.	Record Maintenance			
13.	Any other			

*Plant closed due to its own reasons
Inspection could not be conducted.*

*13/5/22
R.O. UPPCB*

*13/05/22
SDM(B)*

कार्यालय जिलाधिकारी, प्रयागराज
(खनन अनुभाग)

पत्रांक: 377 / खनन / 2022-23

दिनांक: 14 / 05 / 2022

विषय:--मा10 राष्ट्रीय हरित अधिकरण (एन0जी0टी0), नई दिल्ली में योजित ओ0ए0 नं0-203/2021 देवीदास खत्री बनाम यूनियम ऑफ इण्डिया एवं अन्य में पारित आदेश दिनांक 01.02.2022 के सम्बन्ध में।

समस्त पट्टाधारक
सिलिका सैण्ड
जनपद प्रयागराज।

उपर्युक्त मा10 एन0जी0टी0 के आदेश दिनांक 01.02.2022 के अनुपालन में मा10 आयुक्त, महोदय द्वारा जनपद प्रयागराज के तहसील बारा स्थित शंकरगढ़ क्षेत्र में स्वीकृत/संचालित खनन क्षेत्रों का निरीक्षण दिनांक 12.05.2022 को कमेटी के सदस्यों के साथ किया गया। निरीक्षण के दौरान यह निर्देश दिया गया कि वर्तमान में खनन क्षेत्र में पर्याप्त वृक्षारोपण नहीं किया गया है और न ही वृक्षारोपण हेतु कोई चिन्हित स्थल आरक्षित की गयी है। उक्त के अतिरिक्त खनन योजना में दी गयी वृक्षारोपण की निर्धारित संख्या भी मौके पर मौजूद नहीं है।

अतः मा10 एन0जी0टी0 के आदेश के अनुपालन में मा10 आयुक्त महोदय द्वारा निरीक्षण के दौरान दिये गये निर्देश का अनुपालन कड़ाई से करते हुये, अनुमोदित खनन योजना में निर्धारित वर्षवार वृक्षारोपण कराना सुनिश्चित करें।


खान अधिकारी,
प्रयागराज।

पत्रांक व दिनांक उपरोक्त।

प्रतिलिपि-निम्नलिखित को सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-

1. मण्डलायुक्त, प्रयागराज मण्डल, प्रयागराज को सादर सूचनार्थ प्रेषित।
2. जिलाधिकारी, प्रयागराज को सादर सूचनार्थ प्रेषित।
3. अपर जिलाधिकारी (प्रशासन), प्रयागराज।

/
खान अधिकारी,
प्रयागराज।



Annex- II

दूरभाष./ Ph. : 0532-2569727

क्षेत्रीय कार्यालय उत्तर प्रदेश प्रदूषण नियंत्रण बोर्ड

आवास विकास परिषद कालोनी, सेक्टर-10, योजना संख्या-3, झूँसी, प्रयागराज - 221508

Email-roprayagraj@uppcb.in

संदर्भ सं०/न०/34/सा०-229/2022

दिनांक 13/05/2022

सेवा में,

सूची संलग्न-41

विषय: मा० एन०जी०टी० नई दिल्ली में दायर ओ०ए० सं० 203/2021 देवीदास खत्री बनाम यूनियन ऑफ इण्डिया व अन्य में पारित आदेश दिनांक 01.02.2022 के संबंध में।

महोदय,

कृपया उपरोक्त विषय का संदर्भ ग्रहण करने का कष्ट करें। मा० एन०जी०टी० नई दिल्ली में दायर ओ०ए० सं० 203/2021 देवीदास खत्री बनाम यूनियन ऑफ इण्डिया व अन्य में पारित आदेश दिनांक 01.02.2022 के अनुपालन में आपके वाशिंग प्लांट का निरीक्षण इस कार्यालय द्वारा दिनांक 12.05.2022 को आयुक्त महोदय, प्रयागराज मण्डल, प्रयागराज एवं अन्य सम्बन्धित अधिकारियों के साथ किया गया। निरीक्षण के दौरान इकाई में कच्चे माल एवं फिनिश प्रोडक्ट का लागबुक, बोरवेल का प्रतिदिन वाशिंग में प्रयुक्त किये जा रहे जल का लागबुक, पीरिआडिक हेल्थ चेकअप का विवरण, मैनपावर का लागबुक आदि मेंटेन नहीं किया गया है।

उपरोक्त परिपेक्ष्य में आपको निर्देशित किया जाता है कि इकाई में स्थापित सभी जल स्रोतों पर नियमानुसार वाटर मीटर की स्थापना कर उक्त का लागबुक मेंटेन किया जाए साथ ही रा-मैटेरियल, फिनिश प्रोडक्ट का लागबुक, बोरवेल का प्रतिदिन वाशिंग में प्रयुक्त किये जा रहे जल का लागबुक, पीरिआडिक हेल्थ चेकअप का विवरण, मैनपावर का लागबुक मेंटेन किया जाए साथ ही परिसर के चारों तरफ बाउण्ड्री वाल का निर्माण, 33 प्रतिशत भूभाग पर वृक्षारोपण, डिस्प्ले बोर्ड की स्थापना, रेन वाटर हार्वेस्टिंग पिट की स्थापना तथा वाशिंग प्लांट में जल के पुनःचक्रण हेतु पक्के पिट/सेटलिंग टैंक की स्थापना का कार्य करते हुए अनुपालन आख्या इस कार्यालय में दो सप्ताह में प्रेषित किया जाना सुनिश्चित करें, अन्यथा की स्थिति में जल एवं वायु अधिनियमों के प्राविधानों के अन्तर्गत आपको निर्गत सहमति आदेश को निरस्त किये जाने के साथ-साथ इकाई के विरुद्ध नियमानुसार अग्रिम कार्यवाही प्रारम्भ कर दी जायेगी, जिसके लिए आप स्वयं उत्तरदायी होंगे।

भवदीय,


13/05/2022

क्षेत्रीय अधिकारी

प्रतिलिपि: निम्न को सादर सूचनार्थ प्रेषित।

1. आयुक्त महोदय, प्रयागराज मण्डल, प्रयागराज।
2. मुख्य पर्यावरण अधिकारी, वृत्त-2, उ०प्र० प्रदूषण नियंत्रण बोर्ड, लखनऊ।


13/05/2022

क्षेत्रीय अधिकारी