

ACTION TAKEN REPORT

Ref: Compliance in reference to the order of Hon'ble NGT dated 06/05/2022 and 11/04/2022 in OA 85/2021 (CZ) of Dr Tarun Singh Chauhan v/s State of Madhya Pradesh & Ors.

In compliance to the orders of Hon'ble NGT dated 06/05/2022 and 11/04/2022, site visit was conducted by the officials of MPPCB, RO Bhopal on 23/05/2022 and 26/04/2022 and observations noted during the visit are as follows:

1. The overflow of septic tank is observed discharging into the nallah.
2. As per the information provided by the builder, the overflow is proposed to connect to the municipal sewer line laid under the AMRUT project.
3. During the inspection dated 26/04/2022, the construction work of laying of pipeline from DK Cottage colony to sewerage system laid down under AMRUT project was observed and it was informed that this pipeline will connect the inlet of septic tank with the sewerage system of Nagar Nigam Bhopal.
4. During the inspection dated 23/05/2022, the above work of laying of pipeline was found stopped.
5. Photographs taken during the inspection are attached as per **Annexure- 1.**


(Jainendra Chandel)
Chemist
RO MPPCB, Bhopal



(Adarsh Malviya)
Assistant Engineer (C)
RO, MPPCB Bhopal


(Brajesh Sharma)
Regional Officer
RO, MPPCB Bhopal

Annexure – 1

Photographs taken during inspection dated 26/04/2022 in compliance to the orders of Hon'ble NGT in OA 85/2021 (CZ)

Dr Tarun Singh Chauhan v/s State of Madhya Pradesh & Ors :






26.04.2022 14:56
23.18303, 77.44549



26.04.2022 14:51
23.18304, 77.44542



GPS Map
Camera Lite

17, Tilak Nagar, Gulmohar Colony, Bhopal, Madhya Pradesh 462016, India

Latitude
23.18299545°

Longitude
77.44549091°

Local 02:51:58 PM
GMT 09:21:58 AM

Altitude 425.41 meters
Tuesday, 26-04-2022



Laying of Sewage line found stopped on inspection dated 23/05/2022

