

**BEFORE THE NATIONAL GREEN TRIBUNAL  
PRINCIPAL BENCH, NEW DELHI  
ORIGINAL APPLICATION NO. 523 OF 2022**

**IN THE MATTER OF:**

Sayed Mehmood Ali Chisti

...Applicant

Versus

State of M.P.

...Respondent(s)

**INDEX**

Sr No.	Description	Pg No.
1.	Updated Status Report on behalf of Respondent i.e., MPPCB dated 19.01.2023 in compliance of Order dated 14.12.2022 passed by the Hon'ble NGT, Principal Bench, New Delhi in OA No. 523 Of 2022	1-4
2.	Annexures	5-7

**FILED BY**



**RAGHAV SHARMA**

Advocate for Respondent i.e., MPPCB Address:  
Basement, B5-202, Safdarjung Enclave, New  
Delhi - 110029

Ph. No.: (+91)-8527066461;

Email:raghav@srcolegal.in

# निरीक्षण प्रतिवेदन

1


विषय:- नगर पालिका हरदा की ठोस अपशिष्ट डम्पिंग साइट का निरीक्षण

संदर्भ:- क्षेत्रीय अधिकारी महोदय द्वारा दिनांक 19/01/2023 को दिये गये निर्देश।

उपरोक्त विषयांतर्गत माननीय एनजीटी प्रिसिंपल बैंच द्वारा प्रकरण क्रं. 523/2022 (सईद मो. अली चिश्ती विरुद्ध म.प्र. राज्य व अन्य) में दिनांक 14/12/2022 के पालन बावत् नगर पालिका परिषद् हरदा द्वारा डम्पिंग साइट पर किये जा रहे सुधार कार्य के संबंध में नगर पालिका हरदा की ठोस अपशिष्ट डम्पिंग साइट का निरीक्षण अधोहस्ताक्षरकर्ता द्वारा दिनांक 19/01/2023 को किया गया। निरीक्षण के दौरान नगर पालिका परिषद् हरदा की ओर से श्री विवेक द्विवेदी, उपयंत्री एवं श्री राकेश चौबे, राजस्व निरीक्षक उपस्थित थे। निरीक्षण दौरान निम्नानुसार स्थिति पायी गयी :-

1. डम्पिंग साइट वार्ड क्रं.-31, मुक्ति धाम के पास स्थित है। डम्पिंग साइट के चारों ओर आवारा जानवरों की आवाजाही को रोकने के लिए कटीले तारों की फेंसिंग की गयी है।
2. डम्पिंग साइट के निकटस्थ स्थित मटेरियल रिकवरी सेंटर जिसकी क्षमता 12 टन/दिन की है, जोकि पूर्ण रूप से कार्यरत पाया गया। डम्पिंग साइट में अपशिष्ट के भंडारण के पूर्व हरदा नगर से एकत्रित किये जाने वाला नगर अपशिष्ट पृथक करने के पश्चात् बायोक्म्पोस्टिंग के माध्यम से खाद तैयार किया जाना पाया गया।
3. मटेरियल रिकवरी सेंटर में कम्पोस्टिंग करने के पश्चात् इनर्ट कचरों को ही डम्पिंग साइट में डम्प करने हेतु भेजा जाना पाया गया।
4. निरीक्षण के दौरान डम्पिंग साइट पर किसी भी जानवरों को नहीं देखा गया तथा मटेरियल रिकवरी सेंटर में कार्यरत कर्मियों की सुरक्षा का ध्यान रखते हुए गम-बूट, हेलमेट तथा हैंडग्लोब्स प्रदान किये गये।
5. डम्पिंग साइट पर तथा साइट के निकटतम किसी भी प्रकार के अपशिष्ट का जलाना नहीं पाया गया।
6. निरीक्षण के दौरान लिए गये फोटोग्राफ्स संलग्न है।

निरीक्षण प्रतिवेदन आपकी ओर अग्रिम कार्यवाही हेतु प्रेषित है।



(डॉ. आनंद द्विवेदी)

वैज्ञानिक

क्षे का., म.प्र.प्र.नि.बो., मण्डीदीप

### INSPECTION REPORT

Subject: Inspection of solid waste dumping site of Municipality Harda

Reference: Instructions given by the Regional Officer dated 19/01/2023.

Regarding the improvement work being done by Municipal Council Harda at the dumping site solid waste of Municipality Harda, the inspection of the dumping site was done by the undersigned on 19.01.2023 in compliance of order dated 14/12/2022 passed by the Hon'ble NGT, Principal Bench in Case no. 523/2022 (Syed Mohd Ali Chishti vs. State of MP and others). Mr. Vivek Dwivedi, Deputy Engineer and Mr. Rakesh Choubey, Revenue Inspector were present on behalf of Municipal Council Harda during the inspection. During the inspection the following situation was found:


1. Dumping Site Ward no. 31 is located near Mukti Dham. Barbed wire fencing has been done around the dumping site to prevent the movement of stray animals.

2. Material Recovery Center located near the dumping site with a capacity of 12 Tons/day which was found fully functional. Before the storage of waste at the dumping site, Manure was found to be prepared through biocomposting after separating the municipal waste to be collected from Harda town.
3. After composting in the Material Recovery Center, only the inert waste was found to be sent to the dumping site for dumping.
4. No animals were seen at the dumping site during the inspection and keeping in mind the safety of the personnel working in the Material Recovery Center, gum-boots, helmets and hand gloves were being provided.
5. No burning of any kind of waste was found at the dumping site and near the site.
6. Photographs taken during the inspection are attached.  
The inspection report is forwarded to you for further action.

SD

(Dr. Anand Dwivedi)

Scientist  
Regional Officer, M.P.P.C.B, Mandideep

A handwritten signature in black ink, appearing to read 'J. Sharma', with a horizontal line underneath it.

**(TRUE TYPED COPY)**



नगर पालिका परिषद् हरदा द्वारा संचालित तोस अपशिष्ट प्रसंस्करण इकाई



कचरे को अलग – अलग (पृथकीकरण) करना



गीला कचरा प्रसंस्करण इकाई



मटेरियल रिकवरी केंद्र



बायो कम्पोस्टिंग खाद



प्रसंस्करण इकाई में कार्यरत श्रमिकों हेतु सुरक्षा उपकरण